

PARTS BOOK

Version 1.0



ISO 9001 Certification of Quality System

FORTUNA

Series 5



- 1) For at most use with easiness, please certainly read this manual before starting use.
- 2) Keep this manual in safe place for reference when the machine breaks down.



SUNSTAR MACHINERY CO., LTD.



- 1. Thank you for purchasing our product. Based on the rich expertise and experience accumulated in industrial sewing machine production, SUNSTAR will manufacture industrial sewing machines, which deliver more diverse functions, high performance, powerful operation, enhanced durability, and more sophisticated design to meet a number of user's needs.
- 2. Please read this user's manual thoroughly before using the machine. Make sure to properly use the machine to enjoy its full performance.
- 3. The specifications of the machine are subject to change, aimed to enhance product performance, without prior notice.
- 4. This product is designed, manufactured, and sold as an industrial sewing machine. It should not be used for other than industrial purpose.



USER'S MANUAL



CONTENTS

1. Safety instruction · · · · · · · · · · · · · · · · · · ·
2. Precautions before use · · · · · · · · · · · · · · · · · · ·
3. Locating and using parts of the controller box · · · · · · · · · · · · · · · · · · ·
4. Installation · · · · · · · · · · · · · · · · · · ·
5. Wiring and grounding · · · · · · · · · · · · · · · · · · ·
6. Connection the earth wire of the sewing machine and motor \cdot · · · 23
7. Things to be checked after installation · · · · · · · · · · · · · · · · · · ·
8. Program unit part names and method of use · · · · · · · · · · · · · · · · · · ·
9. Simple operation unit part names and method of use · · · · · · 40
10. Fortuna series 5 full function software method of use · · · · · 45
11. Breakdown and troubleshooting · · · · · · · · · · · · · · · · · · ·
12. How to place for controller · · · · · · · · · · · · · · · · · · ·
13. Block diagram · · · · · · · · · · · · · · · · · · ·
* Parts Book · · · · · · · · · · · · · · · · · ·

1

SAFETY INSTRUCTION

Be sure to read and keep in mind the following instructions before you install and use thr FORTUNA SERVO MOTOR.

1) Use and Purpose

This product is designed, manufactured, and sold as an industrial sewing machine. It should not be used for other than industrial purpose.

2) Working Environment

- (1) Power Source
 - It is desirable that voltage of the power source be kept within the range of $\pm 10\%$ of the rated voltage.
 - It is desirable that frequency of the power source be kept within the rage of $\pm 10\%$ of the rated frequency. (50/60Hz)
 - The SERVO MOTOR can be expected to work normaly only in case the foregoing things are kept.
- 2 Electromagnetic Noise
 - It is desirable that those equipments causing strong electromagnetic field or high frequency not use the same electrical outlet as this on and stay away from it.
- ③ Temperature and Humidity
 - Keep the ambient temperature above 5 degrees and below 40 degrees Centigrade.
 - Never use it outdoors and avoid direct ray of light.
 - Keep it away from an hot object like a stove.
 - Keep the ambient humidity above 30% and below 95%.
- 4 Never use it near gases and explosives.
- ⑤ Do not use it at a spot located 1,000m or higer above sea-level.
- (6) Keep the storage temperature higher than 25 degrees below zero and lower than 55 degrees Centigrade when not in use.

3) Installation

Follow the instruction carefully when installing it.

- ① Be sure to start installing it after pulling the power plug off the outlet.
- ② Fix the cable so that it may not move, and do not allow the moving parts like belts to be interfered with.(keep distance of at least 25mm from them.)
- ③ Be sure to have the Controller, the Motor and the sewing Machine grounded.
- (4) Be sure that the voltage of power source fits the specification of the Controller before the power is on
- (5) Be sure to use Safety Extra Low Voltage when an extra item or an accessory is fitted into the Controller.

4) Disassembly

- ① Indisassembling it, be sure to wait at least 360 seconds before taking any action after pulling the plug off the power source after turning it off.
- ② When pulling off the plug from the power source, be sure to hole the plug itself instead of the wire connected to the plug.



5) Service and Maintenance

- ① Make sure that service and maintenance are carried out by a skilled technician.
- ② Never try to operate with the Motor and the Controller open.
- (3) When inserting a thread into or touching the machine, be sure to turn the power off and step down from the platform.
- (4) Be sure to use standard products specified for replacement of parts.

6) Other Safety Instructions

- 1 Tack care not to let your fingers touch any moving parts including belts.
- ② In case of remodelling or fitting of additional device, be sure to follow safety standards and do not ever try to go ahead based on your own judgments.
- ③ Do not try to operate with the safety device removed.
- 4 Take care not to let water or coffee or something like those admitted into the Controller or the Motor.
- (5) Never drop the Controller or the Motor to the ground.


*The instructions presented above are for the safer and more proper operation of the Fortuna Servo Motor. Ignoring such instructions could cause damage to the machine or physical injury of the user. Please follow all the instructions when operating the machine.

PRECAUTIONS BEFORE USE


1. Do not turn on the power while stepping on the pedal.




2. Turn off the power when leaving the servomotor overnight.



3. Turn off the power when servicing the servomotor or changing the needle.




4. Be sure to keep the servomotor securely grouned.




5. Do not connect multiple servomotor power plugs to the same power strip.



6. Install the servomotor away from noise sources, such as high-frequency equipments and welding machines.



7. Avoid electrical shock when servicing the controller box. (Wait for 6 minutes before opening the cover after turning off the power.)




8. When an error message "Er" sppears on the digital display, take a note of the "Er" code, and then turn on and off before resuming operation(Contact the local dealer if "Er" message persists on the display)






9. Adjust the belt tension to the optimum level.




Belt-tension adjustment should be performed after the motor is mounted on the table : First, loosen both the upper and lower anchoring bolts(\mathbb{D},\mathbb{Q}). The belt tension will then be adjusted by the weight of servo motor itself. Fasten both anchoring bolts.

10. Clean it every two or three weeks so that no dirt or a dirty substance may be piled up.




11. When replacing the fuse, use a standard item, opening the cover as shown in the diagram.

12. Make the length of the cable connected with an outside parts like stand-up pedal as short as possible.




F1	250V/6.3A
F2	250V/6.3A
F3	250V/6.3A
F4	250V/1A




LOCATING AND USING PARTS OF THE CONTROLLER BOX

1) Left and right side of control box



2) Rear panel



① Caution



WARNING ^カ コ



Hazardous voltage will cause injury. Be sure to wait at least 360 seconds before opening this cover after turn off main switch and unplug power cord.

고압 전류에 의해 감전될 수 있으므로 커버를 열 때는 전원을 내리고 전원 플러그를 뽑고 나서 360초간기다린 후 여십시오.


- ② Motor
- ③ AC INPUT




4

INSTALLATION

- 1) Mounting your Servo Motor on the table
 - ① Make sure that the holes are bored on the table as shown in the figure.



② Insert three motor-fixing bolts through the three holes on the table. Attach the motor base padded with vibration-proof rubber, and slide flat and spring washers over the bolt stems, and then fasten the bolts with nuts.



3 Make sure that the center of motor pulley is matched to that of the sewing machine before tightening the motor-fixing bolts and nuts.


2) Assembling the belt cover and adjusting the belt tension

(1) Belt cover assembling procedure

① Upon the completion of the motor mounting, bring the two pulleys of motor and sewing machine closer to each other, by pulling back the sewing machine. You can then mount the belt easily as shown in the figure.




Make sure that the power is off before assembly.



② Place the belt cover 'B', making sure that the belt cover does not contact the belt, and then fasten the cover with the fixing screw.




Do not remove the belt cover. If a finger slips into the belt, it might be broken or cut off.



(2) Adjusting the belt tension

- ① Optimum Tension Level: The optimum tention level is achieved when the belt is pushed by 5-10mm when the top surface portion of the belt at about 30-50mm above the tabletip is pressed by a finger with a force of ~1 kgm/sec² or 1 Newton.
- ② Adjusting the Tension Level: If the tension level is out of the optimum range, adjust the tension as follows. First, loosen both the upper and lower nuts for the anchor bolt, letting the belt be stretched by the motor weight itself. Second, tighten the upper nut only to the extent that the motor does not move. Third, fasten the bottom nut tightly so that the motor is securely fixed.





3) Mounting and adjusting the foot-lift solenoid

(1) SunStar KM-235 Model

- ① Attach the main power switch first since the power switch is located normally in between the solenoid brackets.
- ② By referring to the figure on the right and the mounting instructions enclosed in the packaging box, locate the insertion surface of the oil pan, and then attach the foot-lift solenoid.

No.	Solenoid No.	Applicable Models
1	SPF-2	KM-235A, B

(2) SunStar KM-250 Model

- ① First, assemble a panel for the attachment of presser foot solenoid on the back of KM-250.
- ② Attach the presser foot solenoid to a bracket "A".
- 3 Attach the bracket "A" with the presser foot solenoid to the panel above.
- Attch a crank to a solenoid shaft and then connect it to a sewing machine.
- ⑤ Place a cover on the solenoid.

(3) SunStar Special-specification models

The same mounting procedure for KM-235 model is applicable for other models listed below.

No.	Solenoid No.	Applicable Models
1		KM-750-7, KM-750BL-7
2	SPF-3	KM-790-7, KM-790BL-7
3		KM-857-7, KM-867-7
4	SPF-4	KM-560-7
5	SPF-6	KM-957-7, KM-967-7
6	SPF-8	KM-757-7
7	SPF-9	KM-640BL-7


(4) Adjusting the stroke(Gap) of the automatic foot-lift solenoid


① Check point


Check to make sure that the stroke-adjusting screw is located at the center of the solenoid axis, i.e., the solenoid should be assembled in parallel with the bottom surface of the table. If the solenoid is not in paralle, make an adjustment so that the screw is in parallel with the center of the solenoid axis using the connection link-fixing screw.


② Adjusting Procedure

The vertical travel distance of the presser foot can be adjusted by the stroke-adjusting screw. First, Loosen the two fixing screws, and adjust the vertical stroke using the stroke-adjusting screw loosening and tightening the stroke-adjusting screw will decrease and increase the vertical stroke of the presser foot respectively. After the adjustment, fasten the fixing screw tightly.










4) Mounting the position sensor (Synchronizer) and setting the film

(1) Mounting the position sensor(Synchronizer)


① SunStar thread-cutting sewing machine.

All SunStar thread-cutting sewing machines are equipped with a position sensor. Users, therefore, are required to the adjust the film position, if necessary, as shown in the figure.



② All other sewing machines(including other manufacturers' brands)


First, attach the position sensor-mounting adapter to the upper shaft of the sewing machine. Second, attach the position sensor-fixing plate to the body of the sewing machine as shown below in the figure. Third, secure the position sensor to the adapter with the fixing screws.






(2) Adjusting the film of the position sensor

① Assemble the films and position sensor in the order as shown in the figure.




② Upon the completion of the assembling, position the needle shaft tight at the rising point from the lowest needle position by manually rotating the pulley. Loosen the film-fixing screw, and adjust the DOWN film so that the film-adjsting line and the sensor housing calibration line are matched. Tighten the film-fixing screw just to the extent that the film can not be rotated. Likewise, position the thread take-up at the highest position. Loosen the film-fixing screw, and adjust the UP film as shown in the figure, while using caution not to move the DOWN film which is already adjusted earlier. Tighten the adjusted film with the fixing screw.



(3) Adjustion the films of reverse rotation sewing machines

*For reverse-rotation sewing machines, the film-adjusting lines located at right edge of the "UP" and "DOWN" film should be matched to the center line of the sensor.







After adjustment the film of the position detector, be sure to rotate the motor for 3~5 seconds by pedalling so that the Controller may remember location of the film.

5) How to equip and adjust a built-in location detector(synchronizer)

- How to equip the built-in location detector (synchronizer)
 - ▶ In case of a SunStar thread trimmer


 When a built-in location detector(synchronizer) for the sewing machine with the SunStar thread trimmer is equipped, all that the users need to do is to simply adjust the location of magnetic for detection according to their needs.









- (2) How to adjust the magnet of the location detector
 - ① Assemble the detector in order following the pictures.




② Once assembling is completed, power the controller on and step on the pedal. At this time, make sure that the needle moves up and down. Stop the needle at a desired location by moving the magnet back and forth along the location where the needle stops.



(3) How to adjust a location detector in case of a reverse rotation sewing machine *It is the same as that used for the normal rotation direction








After adjusting a location detector, rotate the motor by stepping on the pedal for 3~5 seconds so that a controller can remember the location.

6) Mounting the Program Unit(P/U)


(1) SunStar KM-235 Sewing Machine

First, attach the P/U bracket to the P/U using three fixing screws and a supporting bolt with nut attached on it as shown in the figure. Second, securely attach the P/U to the head of the sewing machine using two fixing screws and washers, keeping a 3~4mm distance between the bottom surface of the nut and the base of the supporting bolt.



(2) Other SunStar thread-machine

First, attach the P/U bracket to the P/U using the four fixing screws. Second, attach the P/U to the main body of the sewing machine using the three bracket-fixing screws as shown in the figure.






Fix the cable using the cable tie so that cable is not in the way of the belt.




7) An example of installing the SunStar sewing machine




WIRING AND GROUNDING


- 1) Specification of the power plug
 - (1) Single phase 100V~120V



(2) Single phase 200V~240V



(3) Three phase 200V~240V



*Be sure to connect Protective Earth


2) Specification of electric current in wiring of power plug

Be sure to use wiring materials which can stand electric current of higher than 15A.




3) Name and description on the outside connector of control box


① Standard solenoid connector




(4) Tension-release and auxiliary solenoid




② Foot-lift solenoid





(5) Switch and lamp(Used in twin-needle sewing machine)



4) How to change the electric voltage supplied for solenoid (The factory installed setting is: J2)

- **This is to make the movement of solenoid smooth in times of fluctuation in the incoming electric voltage.
- ① Set Value for electric voltage supplied (for 220V series) for Solenoid against the incoming voltage.

For 30V-regular Solenoid

Incoming Voltage	Set Value
Below 210V	J5
210V~230V	J6
Above 230V	J7

For 24V-regular Solenoid

Incoming Voltage	Set Value
Below 180V	J5
180V~190V	J6
Above 190V	J7


② Set Value for electric voltage suplied (for 110V series) for Solenoid against the incoming voltage.

For 30V-regular Solenoid

Incoming Voltage Set Value

For 24V-regular Solenoid Incoming Voltage Set Value

Below 100V	J5	Below 90V	J5
100V~120V	J6	90V~100V	J6
Above 120V	J7	Above 100V	J7
, r .			
Setting of pin			





6


CONNECTION THE EARTH WIRE OF THE SEWING MACHINE AND MOTOR

Method

Connect the motor and sewing machine using the ground wire (green, green/yellow) as shown in the figure. Make sure that the factory-connected ground wire between the controller box and motor is securely in place.



Failure to ground the motor can cause abnormal operations, such as overspeed rotation or unwanted stitching.



7

THINGS TO BE CHECKED AFTER INSTALLATION

1) Before the power is on...


- ① Make sure that the incoming voltage is in accordance with that shown in the name plate of the Control box.
- (2) Check whether the following connectors are connected.
 - Connector for incoming AC power source
 - Connector for motor power
 - Connector for motor encoder
 - · Connector for pedal
 - Connector for position detector
 - Connector for others (option, knee-lift, program unit etc.)
- (3) Check to see whether the belts are in touch with the wiring.
- 4) Check the tensile strength of the belts.
- (5) Check to see the fixing nuts for pulley are tightly fastened.
- (6) Check whether the sewing machines are right kinds (Chain Stitch S/M, Lock Stitch S/M)
- (?) Check the rated voltage for Solenoid (Refer to "How to change the electric voltage supplied for Solenoid"))

2) After the power is on...

- (1) Check whether the lamp for the position detector is on. (Except in the case of built-in position detector)
- (2) Check whether the program unit is working.
- (3) Check the direction of rotation of the Sewing Machine.
 - In case the direction of rotation is not right, action shall be taken to change set it right, referring to "the methods of changing the program and the list of changing functions" (N. 65 in Group "A")
- (4) Check to see whether there are abnormal heat, smell or noise nearby.
 - In case there are, turn the power off and call our regional office.

PROGRAM UNIT PART NAMES AND METHOD OF USE

1) Program unit part names



2) Program Unit Method of Use

(1) 4-Digit Displayer and 2-Digit Displayer Functions and Method of Use A. 4-Digit Displayer and 2-Digit Displayer Functions

① When you turn the power on, you will see a screen as shown in the figure. The 4-digit displayer shows the start and end B/T sewing and the 2-digit displayer shows the current abbreviation for the letters or numbers shown in the 4-digit displayer (bt: the abbreviation for back tack),

<Initializing screen>



<Example of error detection>



<Example of selection of number 2 item in Group A>



② The 4-digit displayer shows the error number for each type of error discovered and also shows the programmed value after it has been programmed. The 2-digit displayer shows the number of the parameter specific item's content or name which is shown in the 4-digit displayer.



The 4-digit displayer and 2-digit displayer show the current condition. Therefore the user should always check it before using the machine.




B. Method of Use: 4-Digit Displayer and 2-Digit Displayer a. Method to change the start and end B/T stitch numbers

In order to change the start B/T stitch numbers which is programmed when you first purchase this machine, you must use the (A), (B) buttons. If you want to change the end B/T stitch numbers, you must use the (C), (D) buttons.

The program range is from 0 to 9.
 (Ex: How the screen looks when changing both start and end B/T stitch numbers to 4).



b. Method to check or change the specifics of the parameter





- Be aware that if you don't press after changing the programmed value for the parameter item, the value will not be saved.
- When the B, C, or D group selection is completed, users should turn off the machine first and restart to secure the selected group.
- If the user changes the programmed value from the parameter specifics carelessly, the user may cause break down or physical damage to the machine. The user must therefore be well-trained before changing the parameter group.

(2) Method of Use: 1/2 Stitch Button Function

- ① When necessary, make $\frac{1}{2}$ stitches by pressing the $\frac{1}{2}$ stitch (4) button.
- ② When the needle plate makes a down stop, shortly press the $\frac{1}{2}$ stitch ($\frac{1}{2}$) button once and the needle plate will make an up stop.

And when the needle plate makes an up stop, shortly press the $\frac{1}{2}$ stitch ($\frac{1}{2}$) button once and the needle plate will make a down stop.



Be aware that if you are continuously pressing the $\frac{1}{2}$ ($\textcircled{\blacksquare}$) button, the machine will keep on moving at the $\frac{1}{2}$ stitch ($\textcircled{\blacksquare}$) speed.

(3) Method of Use: Start B/T Button

This button is used when the user wants to prevent threads from loosening at the end of the sewing work. If the user presses this button in sequence, the location on the lights will change. This button offers the following three functions.



When sewing starts, B/T sewing does not operate.



When sewing starts, B/T sewing is operated with the





When sewing starts, B/T sewing is operated with the

button.

Using the A, B buttons in the 4-digit displayer, the user can program the B/T number of stitches he/she wants.



Be aware that if the start B/T stitch is set to '0' in the 4-digit displayer, the start B/T sewing is impossible.

(4) Method of use: End B/T Button

This button is used when the user wants to prevent threads from loosening at the end of the sewing work. If the user presses this button in sequence, the location on the lights will change. This button offers the following three functions.



When sewing ends, B/T sewing does not operate.



When sewing ends, B/T sewing can be operated with the

button.



When sewing ends, B/T sewing can be operated with the

button.

Using the C, D buttons in the 4-digit displayer, the user can program the B/T number of stitches he wants.



Be aware that if the end B/T stitch is set to '0' in the 4-digit displayer, the start B/T sewing is impossible.

(5) Method of Use: The Needle Plate Position Selection Button When the Sewing Machine Stops

When the user turns the power on, one of the up stop or down stop lights in the program unit panel needle plate is always left on. The user can change the stop location by pressing the button.



When machine stops while sewing, the needle plate makes an up stop.





When machine stops while sewing, the needle plate makes a down stop.





(6) Method of Use: The Presser Foot-lift Location Selection Button When the Sewing Machine Stops

When the user turns the power on, one of the up stop or down stop lights in the program unit panel presser foot-lift is always left on. The user can change the stop location by pressing the button.



When the machine stops while sewing, the presser foot-lift stops at the top.





When the machine stops while sewing, the presser foot-lift stops at the bottom.





If the user uses the automatic up stop function of the presser foot-lift when the sewing machine stops while sewing, it may cause damage to it because it has been left up for an unnecessarily long time. Be aware that to prevent the foot-presser solenoid from being damaged, it is programmed to automatically come down when a certain amount of time passes.

(7) Method of Use: Automatic Thread Trimmer and Wiper Selection Buttons

These buttons offer the function of automatic trimming and wiping after sewing. By pressing these buttons in sequence, the user can use one of the following three functions. The light shows the function that is currently being used.



Automatic trimmer and wiper do not operate



Only automatic trimmer function is operate



Both automatic trimmer and wiper operate

(8) Method of Use: Counter Program Button

A. Count Function Program Method

After enabling the count function in the parameter specific items, go back to the initial screen. Press the count button. If the light goes on, the user can use the count function.






B. Method of Use: Count Specific Functions

The count button is a button programmed to check the production quantity. In order to operate the functions you want, the user needs to program a few specific items.


- ① This is a function that checks the production quantity. If you want to use this function, first program the value what you want in the parameter. Ex. B-35 (Item no. 35 in Group B).
 - 0: Program the outer counter switch
 - 1: Program the automatic count after thread trimming
 - ** The initial value is programmed to be '0.' When there is no outer counter switch the count function does not operate.



- ② Program the parameter B-36 item and you can select the type of production quantity counter.
 - 1: Ascending counter (Up counter)
 - 0: Descending counter (Down counter)
- *The initial value is programmed to be "1."
- ③ Program the counter function by pressing the counter button. If you press the button you can check and program the specific information.
 - Cn: Current count quantity
 - rn: Current remaining quantity
 - %: Production rate
 - tn: Quantity of total programmed work (Initial value: 100)
 - *If you press the button continously, you can see the specific information mentioned above in order. The user can set up the current count quantity(Cn) and the quantity of total programmed work (tn).
- After the total work quantity has been done, you can program items
 B-37 or
 B-38 or
 - 0 : programming that enables sewing when the buzzer rings after work is done.
 - 1: programming that enables sewing when the buzzer rings after work is done but only after the user presses the button.
 - 2 : programming that enables sewing after work is done, even when the buzzer doesn't ring

<B-38 item programmed value>

- 0 : After count is over, it does not automatically change to the initial programmed value
- 1 : After count is over, it automatically changes to the initial programmed value.



<Current work quantity>



<Remaining work quantity>



<Production rate>



<Total programmed work quantity>





If the user programs item B-38 to '0' even after the count is over, it will continue to increase or decrease. Therefore, if the user wants to initialize it, he/she must reset the Cn value.

(9) Method of Use: Sewing Material Edge Sensor Selection Button

A. Method of Use: Edge Sensor Function

After programming the edge sensing function in the sewing material from the parameter specific items, press the button. If the light goes on, you can start using the edje sensor function.




B. Method of Use of Sewing Material Edge Sensor's Specific Functions

The sewing material edge sensor selection button has a function that enables the machine to stop when it senses the end of a sewing material. If you want to operate a particular function, you must program a few specific items.

- ① User must change item A-40 programmed value according to the characteristic of the installed sensor.
 - 0: When edge sensing, 5V output (Active High) should be the initial value
 - 1: When edge sensing, 0V output (Active Low)
- ② After sensing, you can set up the movement to item A-41, A-42. <Item A-41: the number of stitches it will sew after it senses the edge>
 - 0~225: after sensing, the machine will sew as many stitches as it has been programmed to sew.

<Item A-42: the sewing speed after it senses the edge of material>

• 20~2000RPM: this item sets up the speed of the stitches set to be sewn after it senses the edge.






- ③ After sensing the edge of sewing material and the machine has sewn the number of stitches at the programmed speed, the user needs to select item A-43 to change the operation.
 - 0 : to stop after sewing the programmed stitch numbers.
 - 1 : to operate automatic thread trimming function after sewing the programmed stitch numbers.



(10) Method of Use: Pattern Work Selection Button

A. Method to Set Up the Pattern Work Function


This function is used when you need to continuously work on a sewing material. If the light goes on after pressing the button, you can use the pattern sewing function.



B. Method of Use of Pattern Sewing Specific Functions

- ① Cautionary words when using the pattern function
 - Before using the pattern function, finish the trimming work and turn on the pattern switch light.
 - If the user presses the pattern switch twice when he/she is not using the pattern function, the light will go off and he/she will be able to go back to normal sewing. However, if the pattern mode has not been completely finished, the pattern light will not go off
 - The pattern function sewing speed will be the programmed speed.
 - The value set in each pattern mode is not erased when the power is turned off. Therefore, if you want to use the same pattern again, press the same mode again to use it. However, if the program is initialized, all the formerly programmed information will be erased and the user must reset the information again.
- ② Method of use: PATTERN function
- (a) first press the hatten button and select the pattern sewing function.
- (b) Select the pattern you want and the light will go on the pattern you selected.
- © If you press the button, the screen will change and you can use the stitches of each side of the pattern you chose to program the value.
 - < Method to program the value of each pattern side >
 - Method by using the (C), (D) buttons
 - Inputting directly the number of stitch the user wants by using the buttons C and D.
 This method is used when the user already knows the length of the stitches he/she is choosing.
 - Method using the pedal movement
 - This is a function used when the user does not know the stitch length and sews directly to check the number of stitches for the pattern he/she wishes to program. If the user presses on the pedal after the programming screen comes on, the pedal can program the number of stitches by using the accelerating and decelerating characteristics through the pedal's sensors. The standard for choosing the number of stitches here is slower than the normal sewing speed and the programmed pattern sewing speed.
 - Method using the A button and 1/2 stitch button
 - This function is used when the user needs to make small adjustments at the end of the pattern work. It allows the user to check and program the pattern length while he/she sews at a slow speed or sews half stitches.

<Screen showing thef programming of stitch numbers for each side>



- P: When the AUTO light is off, the machine stops when the pedal is released while sewing.
- A: When the AUTO light is on, the machine will finish sewing the pattern section even if user releases pedal while sewing.

- d After programming is finished, press the button and save the set up value. Then press the button. After the stitch numbers of each side disappear from the screen, you can start sewing with the programmed value in the pattern sewing function.
- © The pattern sewing speed is constant because it sews at a programmed speed not by the acceleration or deceleration of the pedal. If you press the pedal after pressing the button and see the light blink, sewing will continue until it is finished even if you release the pedal.



- After setting each side of the stitches, the user must press the button to save the programmed value.
- When the pattern has more than one side, the pattern work only operates for the number of stitches programmed for each side.

3 Specific items of each pattern

	A convenient pattern for straight sewing at constant speed for a definite length. The sides can be set from 0 to 999 stitches.	
	A convenient pattern for repetitive 3-sided sewing. Each side can be set from 0 to 999 stitches.	
	A convenient pattern for 4-sided sewing. Each side can be set from 0 to 999 stitches. (Used often in square sewing)	
0 123/40	A convenient pattern when forward/backward sewing is needed continually. forward/backward sewing is possible 9 times. Also each side can be set from 0 to 999 stitches. (This pattern is used for continuous work on back tags of leather belt rings).	
	A convenient pattern when the user wants to make many-sided patterns. The user can make patterns of up to 20 sides. Each side can be set from 0~999 stitches.	

- 4 Method of Use: Chain function (pattern linking function)
 - First press the PATTERN button and select the pattern sewing function
 - Next, press the CHAIN button.
 - If you press the button, the screen will change as the figure shows on the right. You can change the number of chains with buttons , .
 - If you want to program the number of chains in the pattern you want, use buttons and, to go to the item you want and press the pattern button.
 - After programming the chain numbers as explained above, press the button and the change of value will be saved. Then press the button to come out from the chain programming screen.
 - If you operate the programmed sewing work, the pattern with the blinking light is the current work being done and the pattern with the light on continuously is the next programmed pattern.
- *If the user presses the when using the pattern sewing function, the old light will go on and the machine will automatically sew the programmed pattern section even if the user releases the pedal.





- After programming the chain function and pressing the button, the set up value is saved.
- If you change the pattern program while sewing, it will sew with the new programmed pattern.
- If the last chain pattern is finished, it will automatically go to the first sewing pattern.



(11) Method of Use: Constant Speed Sewing (AUTO) Selection Button

This button is used to choose the sewing speed. It offers two functions according to where the light turns on.



- · When the light is blinking
- If the user presses on the pedal, the machine will sew at the programmed sewing speed.



- · When the light is off
- The machine will sew according to the amount of pressure given to the pedal by the user.



This button works in a different way when using the pattern function. Please refer to section 10).

(12) Method of Use: Sewing Speed Program Changing Button A. Method to Check Sewing Speed

If you want to check the current programmed sewing speed, you must press the \bigcirc button. If you briefly press the \bigcirc button \bigcirc button once, the screen shown on your right will appear briefly and then return to the initial screen.




* The speed on the screen is the limit of the maximum sewing speed.



The maximum speed and minimum speed limits can be changed by changing the parameter's specific items.

B. Sewing Speed Changing Method

- ① When you want to change the sewing speed, you can see the screen that shows the current sewing speed by pressing the \triangle button or \bigcirc button.
- ② If you see the current speed on the screen, you can change the speed by using the \triangle and $\widehat{\nabla}$ button before going back to the initial screen.
 - When you press the buttons twice in sequence: The sewing speed increases/decreases by 40RPM.
 - When you keep pressing the button: The sewing speed increases/decreases rapidly.





- -Be aware that if you don't press the \triangle or ∇ button, the screen will automatically go back to the initial screen.
- -The maximum speed and minimum speed limits can be changed by changing the parameter's specific items.


13) Start and End Backtack Stitch Correction Method

- * Since backtack stitches may vary according to the type of sewing machine, use the following stitch correction method.
- ** To adjust the stitch fast and clean, users should check the stitch condition before commencing the correction.
- ① Classification according to backtack sewing condition
 - ** The backtack sewing condition can be classified as follows (When A: 3 stitches, B: 3 stitches, C: 3 stitches, D: 3 stitches)

A. When one more or less stitch than the set stitch number is sewn

Classification	Sewing condition where few backtack stitches are sewn	Correct backtack sewing condition	Sewing condition where more backtack stitches are sewn
Start backtack Sewing condition	When sides A and B each have one less stitch sewn	When sides A and B each have 3 stitches correctly sewn	When sides A and B each have one more stitch sewn
End backtack Sewing condition	When sides C and D each have one less stitch sewn	When sides C and D each have 3 stitches correctly sewn	When sides C and D each have one more stitch sewn

B. When one more or one less stitch is sewn than the programmed stitch number






The figures above show each representative sewing condition. And there may be some differences according to the conditions of the sewing machine and it is normal that two types of conditions occur at the same time.



- (2) Start/End B/T stitch number correction method
 - ** The method to correct B/T stitch numbers may differ according to the user. However it is basically done in the following order.

A. When the machine sews one less or one more stitch than the programmed number of stitches.

- (a) First, fully check the B/T sewing condition
 - : Commence sewing and check the current sewing condition. Refer to the figure above.



- ⑤ If you have checked the sewing condition, first correct the stitch number that differs by one or more stitches to the programmed stitch number.
 - * Correction method for stitch numbers with more than one stitch difference
 - Program range: -6 stitches ~ 6 stitches
 - Program unit: 1 stitch
 - Method to apply correct stitch number (program using buttons A, B, C and D).

Side A programmed value	3(programmed stitch number) + (3-actual stitch number sewn on side A)
Side B programmed value	3(programmed stitch number) + (3-actual stitch number sewn on side B)
Side C programmed value	3(programmed stitch number) + (3-actual stitch number sewn on side C)
Side D programmed value	3(programmed stitch number) + (3-actual stitch number sewn on side D)


- After programming, press the one and buttons simultaneously.
- Ex) When there is one less Start or End B/T stitch sewn.



(a~d) and make corrections.



- a In the initial screen use buttons (A), (B), (C), (D) to change it from "3 3 3 3" to "4 4 4 4."
- b After programming it to "4 4 4 4" press the button. Then press the 1/2 stitch button. You will see the letters "bt-C" and the buzzer will ring three times and the screen will automatically return to the initial screen.
- c The changed initial screen will continue to display the wanted B/T programmed value of "3 3 3 3." d Recommence sewing and check the corrected stitch number
- e If the corrected sewing condition continues to show more than one stitch difference, repeat steps
- ** The example above is an explanation of when one B/T stitch number comes less than one
- * When there is more than one stitch is added or missing, you can correct the stitch number as explained above.






- ** The stitch number correction value program range is between -6 stitches to 6 stitches. You cannot see the currently applied correction value on the initial screen. If you want to see the currently applied correction value, press the button and then the button and either check the programmed value of each side or check items 30(side A's correction value), 31(side B's correction value), 32(side C's correction value) and 33(side D's correction value) from Group B of the parameter.
- * If each side's corrected value has been corrected to the minimum or maximum value limit (between -6 stitches to 6 stitches) and the sewing condition is still not correct, reduce the B/T sewing speed.
- ** Generally, you can correct in the manner mentioned above when there is more than one stitch difference. And you can correct when there is less than one stitch difference with the item mentioned in the next page.

B. When the machine sews less than a stitch more or less than the one programmed.

ⓐ If there are still problems with the B/T sewing condition even after correcting the stitch numbers for more than one stitch difference based on item "A," refer to figure (1)-B and check the sewing condition again.



- (b) Look at the sewing condition and make the correction as follows:
 - * Program range for making stitch corrections for less than one stitch:(Prog+Auto)
 - -6 stitches ~ 6 stitches
 - Program unit: 0.05 stitches (Corrections are done by dividing one stitch into 20 parts).
 - Initial program: A(00.30), B(00.30), C(00.40), D(00.40)
 - Correct stitch number application method (use C and D buttons for programming).
- * When the stitch length comes out short(the third stitch of sides A and B/ the 1st stitch of sides C and D)

Side A program value	(Currently programmed corrected value)	
	+ (01.00-the length of the 3rd stitch sewn in side A)	
Side B program value	(Currently programmed corrected value)	
	+ (01.00-the length of the 3rd stitch sewn in side B)	
Side C program value	(Currently programmed corrected value)	
	+ (01.00-the length of the 1st stitch sewn in side C)	
Side D program value	(Currently programmed corrected value)	
	+ (01.00-the length of the 1st stitch sewn in side D)	

* < When the stitch comes out less than one stitch longer> (the last stitch of sides A and B/ and the first stitch of sides C and D)

ia the mot sutth of sid		
Side A program value	(currently programmed correction value)	
	- the length of the extra part of the stitch sewn on side A	
Side B program value	(currently programmed correction value)	
	- the length of the extra part of the stitch sewn on side B	
Side C program value	(currently programmed correction value)	
	- the length of the extra part of the stitch sewn on side C	
Side D program value	(currently programmed correction value)	
	- the length of the extra part of the stitch sewn on side D	
A		




The shadowed part is the currently saved correct value.

• After programming, press the button and save the programmed value.

Ex) When the Start/End B/T stitch length is shorter than the programmed stitch length (by around half a stitch).

- a In the initial screen, press the button and then also press the button.
- b The screen will then go to the stitch number correction screen. Using the buttons you can change the length of each side (A,B,C and D) in this screen.
- c If you have finished programming the new correction values to sidesA, B, C and D, press the
- button and save the corrected value. If you press the 🗪 button, you will return to the initial screen. (A:00.30, B:00.30, C:00.40, D:00.40) → (A:00.50, B:00.50, C:00.75, D:00.75)
- d Commence sewing and check the B/T sewing condition.
- e If the corrected sewing condition still shows differences between the programmed value, the repeat steps (a~d) and continue correction.



<When the stitch length comes out short>







<When the stitch length is less than one stitch>











- * If each side's corrected value has been corrected to the minimum or maximum value limit (between -6 stitches to 6 stitches) and the sewing condition is still not correct, reduce the B/T sewing speed.
- ※ Generally, you can correct for when there is more than one stitch difference with item A. However, with item B, you can correct when there is either more or less than one stitch difference.
- Make sure to press the button and save the programmed value when you finish programming sides A, B, C and D's new correction value.



(14) Method of Use: Inertia Tuning Function

- ① The inertia tuning function enables the machine to save the gain value of the motor that matches the loaded inertia. If you simultaneously press buttons \bigcirc and \bigcirc , you will see the inertia tuning screen. Then, you will see the words "TUNE" blinking.
- ② When the screen changes, you must press the pedal until the buzzer rings. If you release the pedal before the buzzer rings the inertia tuning won't be completed. Therefore, you must press on the pedal until the buzzer rings.
 - (When doing inertia tuning, the sewing machine will operate and stop $10\ \mathrm{times}$).
- ③ When inertia tuning is completed, the buzzer will ring and it will automatically return to the initial screen.

<Inertia tuning initial screen>
A B C D E F
<Initial screen>
A B C D E F



Inertia tuning can only be carried out when the controller is attached to the sewing machine for the first time and when the sewing machine does not accelerate or decelerate quickly.


(15) How to Use the Edge Sensor (Fabric Edge Sensor)

A. Applicable Fortuna Model

- ① Fortuna Series 3: Full Function Type (using the switch and lamp connector port)
- ② Fortuna Series 4: Full Option Type (using the switch and lamp connector port)

B. Installation


- ① Install the edge sensor bracket on the head of the sewing machine as in the figures below.
- ② Attach the edge sensor to the installed edge sensor bracket.



R12 10 60 < KM-750,790 >

< KM-235,250 >

- ③ Install the edge sensor box (ass'y), which is connected to the edge sensor, on the table.
- ④ Link the edge sensor connector to the switch and lamp (or option 1) connector.



< Fortuna Series 3 >




C. Edge Sensor Program Setting

① Turn the power on while pressing simultaneously. "PrEn" is displayed with a "beep" sound and then disappears.	
② Programs should be modified after trimming is completed.	000000
③ Press first, and then press © simultaneously. Then the program modification mode appears as shown in the right figure.	[-] [II]
④ Use ⑤, ⑥ to set the code number at 52. Use ⑥, ⑥ to change the value from 2, the default value, to 12 and then press ⑥ to save the new value.	ABOD EF
(5) When the program setting is done, press to turn off the blinking lamp and use the sewing machine.	

D. Edge Sensor Setting

- ① First make sure that there is no fabric below the sensor, and set the operating mode of the rear side of the sensor at L.ON.
- ② Press on the P/U and check if the LED is blinking.
- (3) Check if the STB (yellow) LED is turned on, when there is a fabric below the sensor.
- ④ If the STB (yellow) LED is not turned on, switch the operating mode to Operating D.ON and begin the setting (depending on types of fabric).
- (5) Adjust the volume of SENS to make OPL (red) turned off while fabric is below the sensor, and make OPL (red) turned on when it is removed (it doesn't matter whether the STB LED is turned on or not).
- (6) Check whether a signal alarm is issued in line with the presence of fabric under the sensor.



E. Use of the Edge Sensor

① Press ® to turn on the lamp.	
② During sewing while the lamp is on, if the sewing needle comes near to the edge of fabric (some 2cm between the needle and the edge of fabric), a "beep" sound is issued and the sewing stops.	
③ Move the pedal to the neutral position and press it again. Then the sewing is resumed according to the number of stitches previously set under Prog Group "A" on the P/U (the number of stitches to be made after sensing the fabric edge) and the sewing speed previously set under No. 42.	
[Note] The default number of stitches to be made after edge sensing is three stitches and can depending on user choice. The sewing speed can be set at the range of 24 to 2040spm. The default speed is 200spm. If the pedal is pressed continuously, the sewing machine above.	n.
④ When a trimming is programmed to be conducted after the low-speed sewing is completed, the backtack sewing will be performed according to the number of backtack stitches defined on the P/U, followed by trimming.	

F. Edge Sensor Deactivation

① Press to turn off the edge sensor. Then the edge sensor is deactivated.



G. Edge Sensor Program Modification

① Programs should be modified only after trimming is conducted.
② Press 📦 first, and then press 🛦 simultaneously. Then the program modification mode is displayed as shown in the right figure.
③ Use ⑤, ⑥ to enter the code number to be modified, and use ⑥, ⑩ to enter the desired value. Press ⑥ to save the new value.
① When the modification is completed, press to turn off the blinking lamp and then use the sewing machine.



⑤ The edge sensor-related programs are located in Group A, and the code numbers and descriptions are displayed as below.

Group	Code #	Scope	Stage	Description	Remarks
	40	0/1		Select types of fabric sensor	
A	41	0 ~ 64	1 stitch	Set the number of stitches to be made after sensing the fabric edge	
	42	24 ~ MAX, SPM	40 spm	Set the speed of sewing after sensing the fabric edge	


* When using patterns, trimming is automatically conducted after the set number of stitches is made.



If the machine is initialized, all data is returned to default values.


SIMPLE OPERATION UNIT PART NAMES AND METHOD OF USE

1) Names of Each Part in the Simple Operation Unit



2) Simple Program Unit Method of Use

(1) Initializing





- When you initialize, you change all the original values that the sewing machine had when it was manufactured in the factory. Initialize only when absolutely necessary.
- When initializing, you must run the motor for more than 5 seconds at the speed of 1000RPM in order to make the synchronizer to work properly.



(2) Programming the Start B/T Sewing Conditions with Button

This button is used when the user wants to prevent threads from loosening at the end of the sewing work. If the user presses this button in sequence, the location on the lights will change as shown in the figures below. This button offers the following three functions.



When sewing starts, B/T sewing does not operate.



When sewing starts, B/T sewing can be done

button.





When sewing starts, B/T sewing can be done



button.

Use the A, B button to program the number of B/T stitches in the 4-digit displayer.



Be aware that if the end B/T stitch number is set to '0' in the 4-digit displayer, the user will be unable to operate start B/T sewing.

(3) Programming the Start B/T Sewing Conditions with Button B

This button is used when the user wants to prevent threads from loosening at the end of the sewing work. If the user presses this button in sequence, the location on the lights will change as shown in the figures below. This button offers the following three functions.



When sewing starts, B/T sewing does not operate.



When sewing starts, B/T sewing can be operated



button.



When sewing starts, B/T sewing can be operated



button.


Use the C, D button to program the number of B/T stitches in the 4-digit displayer.



Be aware that if the end B/T stitch number is set to '0' in the 4-digit displayer, the user will be unable to carry out start B/T sewing.


(4) Programming the Needle Plate Position when Sewing Stops with Button C

When you turn the power on, one of needle plate's up stop and down stop lights in the simple operation unit will always be on. If you press the button you can select the stopping location.



(5) Programming the Presser Foot-lift Location when Sewing Stops with the Button

When you turn the power on, one of presser foot-lift's up stop and down stop lights in the simple operation unit will always be on. If you press the button you can select the stopping location.



(6) Programming the Automatic Thread Trimmer and Wiper Movements with the Button

This button programs the automatic trimmer and wiper after sewing. If the user presses this button in sequence, the location on the lights will change as shown in the figures below. This button offers the following three functions.



Automatic trimmer and wiper are not operating.



Only the automatic trimmer is operating



Both the automatic trimmer and wiper are operating

(7) Programming the Start and End B/T Stitches

① Press the appropriate button for 0.5 seconds for the place you wish to program the new B/T stitch value. The light will blink in that place.

• Programming buttons for number of start B/T stitches: buttons

• Programming buttons for number of end B/T stitches: buttons

© D

② If the number is blinking, you can change the programmed value by pressing the appropriate button.

(Ex: If you press the A button for 0.5 seconds, the first number in the screen will blink).

③ If programming is completed, press the same button for 0.5 seconds once more and you will return to the initial screen.

(Ex: Changing the value of A, B, C, D from 3, 3, 3, 3 to 4, 4, 4, 4)



Be aware that if you don't press the button for 0.5 seconds, the screen will not return to the B/T stitch programming screen but will remain in the sewing conditions program change (items 1~4 functions) section.




(8) Sewing Speed and Rotating Direction Programming Method



Be aware that if you don't press the button for 0.5 seconds, the screen will not return to the B/T programming screen but will remain in the sewing conditions programming screen (Items 1~4 functions).

(9) Method to Change Parameter Specific Items




⑥ If you completed your selection, press the to save the value you chose.	
⑦ You can change other specific items of the parameter in the same manner.	



- Be aware that if you changed the specific items of the parameter and didn't press the button, the changed value will not be saved.
- If you change the parameter specific items carelessly, this may cause breakdown or physical damage to the machine. Therefore, the user must be well-trained before changing items in the parameter group.

(10) Start and End B/T Stitch Number Correction Method



(11) Method of Use of the Inertia Tuning Function

①The inertia tuning function is to find the motor's gain value that match the weights inertia. Press buttons E/Prg and D simultaneously to return to the initial screen of the inertia tuning.	<inertia initial="" screen="" tuning=""></inertia>
② If the initial screen comes on, press the pedal until you hear the buzzer ring. (During inertia tuning the sewing machine will operate and stop 10 times).	<initial screen=""></initial>
③ If the inertia tuning is completed, the buzzer will ring and the initial screen will come on at the same time.	



Inertia tuning is carried out only when the controller is attached to the sewing machine for the first time and when the sewing machine is unable to accelerate or decelerate quickly.


10

FORTUNA SERIES 5 FULL FUNCTION SOFTWARE METHOD OF USE

1) Basic Functions of the Fortuna Series 5 Full Function Software

(1) Initializing

This function is used when the user randomly changes the parameter's programmed value, and forgets the original program contents.



Method of initializing: Turn the power on by simultaneously pressing the buttons in the figure above which are the start B/T button + end B/T button + needle plate up/down stop button.



- If you initialize, all the changes made by the user are changed to the original values programmed when the machine was delivered from the factory, therefore only change the value if absolutely necessary.
- After initializing, rotate the machine for 1000RPM or more for approximately 5 seconds. You must make the machine remember the location of the FILM.

(2) Sewing Machine Up/Down Stop Location Automatic Recalling Function

When first purchasing the controller, if the user steps on the pedal for 5 seconds and runs the motor before beginning the sewing work, the machine will automatically remember the sewing machine's up/down stop location. However, when using a synchronizer this step is not necessary.

(3) Method of Use and Functions of the Program Unit and the General Control Box's Simple Operation Box.

When there is a program unit(P/U), use it to program or change all the functions of the machine. When there is no program unit, use the general control box operation panel to program or change all the functions of the machine.

* For detailed information on the method of use of program units and simple operation panel refer to the explanation in the last section.

(4) Function Parameter

Parameter group	Functions
① Group A	General functions of the sewing machine
② Group B	All types of output, Full-on Time/PWM Duty, checking input/output operations, sewing machine models and thread trimming sequence programming
3 Group C	Pedal acceleration/deceleration curve, slow starting speed and input/output port change related parameters
4 Group D	All types of gain parameter related motor control

^{*} If the specific items of the parameter are changed carelessly, they could cause breakdown or damage the machine. Therefore the user must be well-trained before using it.

2) Fortuna Series 5 Full Function Software Specific Parameters

(1) Group A Parameter: General functions of sewing machine

No.	Function	Initial value	Range	Step
1	Minimum speed of pedal (limit of sewing machine's minimum speed)	200spm	20~510	2spm
2	Maximum speed of pedal (limit of sewing machine's maximum speed)	4000spm	40~9960	40spm
3	Thread trimmer speed (Sewing machine speed from beginning to end of thread trimming when using CAM type)	300spm	20~510	2spm
4	Program Unit + 1 stitch speed (Wey's performance speed)	100spm	20~510	2spm
5	Lifting of needle plate with button A, dropping speed (Ļ-'s performance speed)	300spm	20~510	2spm
6	Pedal degree of acceleration (Pedal Curve)	255	1~255	1
	(;When the maximum speed is put in 255 steps)			
7	Start Back-Tack Speed	1700spm	20~2000	10spm
8	End Back-Tack Speed	1700spm	20~2000	10spm
9	Thread trimming operation time (The A24 used in PNEUMATIC = must be 1) (The Solenoid operation time)	100ms	4~1020	(When doing an aging test, the value is equal to the running time)
10	Tension release operation time (The A24 used in PNEUMATIC = must be 1)	200ms	4~1020	(When doing an aging test, the value is equal to the thread trimming time)
11	Tension release time (In CAM type, the used A24 = must be 0) (In CAM type, the tension release is the value of the moving CAM angle)	255	0~255	
12	Waiting time for the next operation after thread trimming (This is the delaying time to carry out the next operation after thread trimming is finished)	4ms	4~1020	
13	Wiper operation time (Wiper Solenoid operating time)	48ms	4~1020	4ms
14	Waiting time after wiper operation(presser foot-lift etc.)	40ms	4~1020	4ms
15	Automatic presser foot-lift delaying time	100ms	4~1020	4ms
16	Automatic presser foot- lift maintaining time (After programmed time the presser foot-lift is automatically released)	300×0.1sec	5~1000	0.5sec
17	Automatic presser foot-lift drop waiting time for next operation (The delaying time, or the time that the foot-presser lift is maintained, the pedal is started until the presser foot-lift drops and the sewing machine is started)	100ms	4~1020	4ms
18	Selection for automatic foot-presser lift after thread trimming	0	0/1	1=lift selection
19	Selection for pedal thread trimming position	0	0/1/2	0=step backward thread trimming 1=1 step backward thread trimming 2=thread trimming at neutral position
20	The maximum sewing speed for the KM-1060BL-7 presser foot-lift with mutual crossing quantity of 4.8 ~ 7.0[mm]	2000spm	200~2000	10spm
21	Delaying time for complete release of KM-1060BL-7 B/T Solenoid	200ms	4~1020ms	4ms
22	Select to operate 2 start B/T (0	0/1	Choose between 1 or 2
23	Select to operate 2 end B/T	0	0/1	Choose between 1 or 2
24	Selection of thread trimming conditions (selection according to sewing machine type)	0	0/1/2	0=CAM type machine 1= thread trimming after up-stop 2=thread trimming after low-stop
25	Whether or not to use default sequence when A24 = 1 (This is a sequence determined on A9,A10 value)	0	0/1	0=B-55 exclusive sequence is used 1= default sequence is used





No.	Function	Initial value	Range	Step	
26	Selection of B/T Solenoid operation position	0	0/1	0= lower position 1= upper position	
27	Setting the maximum sewing speed of the machine according to presser foot-lift height of the KM-1060BL sewing machine.	?	?	program P1xx → P2xx → P3xx in order Less than P1xx:3500[spm] Less than P2xx:3000[spm] Less than P3xx:2500[spm] More than P3xx: A20[spm]	
28	Needle bar's automatic stop at the highest position	0	0/1		
29	Pedal analog filtering difference	15	1~200	1	
30	When using an angle 2-needle, select the semi-automatic corner operation	0	0/1	1=selection of semi-automatic	
31	Speed when selecting a semi-automatic corner (parameter used only when used after selecting number 30)	200spm	20~2000	10spm	
32	After selecting the left needle the first sewing stitch (parameter used only when used after selecting number 30)	3 stitches	0~255	1 stitch	
33	After selecting the left needle the second sewing stitch (parameter used only when used after selecting number 30)	3 stitches	0~255	1 stitch	
34	After selecting the right needle the first sewing stitch (parameter used only when used after selecting number 30)	3 stitches	0~255	1 stitch	
35	After selecting the right needle the second sewing stitch (parameter used only when used after selecting number 30)	3 stitches	0~255	1 stitch	
36	Maintaining time for the left/right needle solenoid (After the programmed time the solenoid is automatically released)	450×0.1sec	50~1000	0.5sec	
37	NOT USED				
38	NOT USED				
39	Stopping function during AUTO mode and while pedal is neutral	1	0/1	0=does not stop 1=stops	
40	Selection of type of N-stitch Sensor	0	0 : active high	1 : active low	
41	The number of stitches done after the N-stitch Sensor has finished sensing. (After sensing, it will sew the programmed number of stitches and stop)	3 stitches	0~255	1 stitch	
42	N-stitch sewing speed	1000spm	20~2000	10spm	
43	Selection of One Touch function \rightarrow replaced by AUTO Key function (Used in the sewing mode that uses the auto function)	0	0/1	1=Auto Mode	
44	Selection of One Touch function → replaced by AUTO sewing mode programming (If there is no thread trimming signal when selected, sewing will continue even if user releases pedal)	0	0/1	1=One-Shot Mode	
45	One-Shot sewing speed \rightarrow When using AUTO function, it is programmed with the speed Up/Dn Key	2000spm	40~9960	40spm	
46	N-stitch sewing mode selection \rightarrow a sewing mode that inputs a sensor signal in the edge sensor port and uses it as an edge sensor	0	0/1	1=N-stitch Mode	
47	Selection of pre-stitch function (When selected it will perform only the programmed stitches before the actual sewing work starts)	0	0/1	1=selection	
48	Pre-stitch number of stitches	3 stitches	0~255	1 stitch	
49	Pre-stitch speed	2000spm	20~2000	10spm	
50	Selection of start B/T operating conditions (0: if pedal is released during back tack, it will stop) (1: if pedal is released during back tack, the work will still be completed) (2: it will perform the exact amount of back tack stitches)		0 : B/T stop function selected 1 : B/T work completion 2 : B/T exact stitch performance		
51	Selection of end back tack performance condition (It will perform the exact amount of stitches for end back tack)	0	0/1	1= exact stitch performance	
52	Back tack initial first stitch speed during back tack exact performance	200spm	20~1000	10spm	



No.	Function	Initial value	Range	Step	
53	Change between B/T and switch with buttons A or B during sewing	0	0/1	1= Select with button B	
54	Selection of button A function	2	O: Only B/T operates I: Lift and drop needle plate with one movement. Lift needle plate with one movement. Drop needle plate with two movements Slow performance when stopped (1/2 stitch speed)		
55	Selection of Button B function	0	B/T delete insertion Lift and drop needle plate with one movement Slow performance when stopped (1/2 stitch speed) Only B/T operates		
56	Selection of speed during manual back tack during sewing	0	0/1	0 : current sewing speed 1: initial reverse speed	
57	NOT USED				
58	Thread Trimming Sequence Selection of SunStar Chain Stitch Machine	1	0/1	1	
59	Thread Trimming Sequence Selection of other Company chain Stitch Machine	0	0/1	1	
60	Selection of reverse rotation after trimming	0	0/1	1:selection of reverse direction	
61	Reverse rotation distance when selecting reverse rotation after thread trimming	20degree	0~250	1degree	
62	When machine stops fix pulley (When machine stops fix the motor by force)	0	0/1	1: fix when machine stops	
63	Power to fix the A number 62 Pulley	40	10~100	1	
64	Distance recovered after fixing A number 62 Pulley and rotating it by force	20degree	10~100	1degree	
65	Select the motor rotating direction (Clockwise /counterclockwise	1	0/1	1 : clockwise 0 : counterclockwise	
66	Target speed: If this speed is reached or passed, a signal saying "Target speed has been reached" will appear. (As an interior Port it is alloted and used in the 'C' GROUP-Default is auxiliary)	1000spm	40~9960	40spm	
67	Delay start setup	0	0/1	0=normal start 1=Delay start	
68	Delay start time duration setup	3	3~250	1×100[ms]	
69	Setup of needle bar's stop at the lowest position after trimming when the pedal is pressed	0	0/1	0=disabled 1=enabled	
70	Setup of the duration of needle bar's stop at the lowest position after trimming when the pedal pressed	100	100~250	1[ms]	
71~77	Not Used	-	-	-	
78	Start Backtack ON Duration	4[ms]	4~1020[ms]	45 1	
79	Start Backtack OFF Duration	4[ms]	4~1020[ms]	4[ms] (Parameter run when the Backtack	
80	End Backtack ON Duration	4[ms]	4~1024[ms]	accuracy function is used)	
81	End Backtack OFF Duration	100[ms]	4~1020[ms]	1	
82	Stitch width reduction during backtacking	0	0/1	0=disabled 1=enabled	
83	Sewing speed screen display	0	0/1	0=disabled 1=enabled	
84	Not Used	-	-	-	
85	Not Used	-	-	•	
86	Not Used	-	-	•	





- (2) Group B Parameter: All types of output, Full-on Time/PWM Duty, checking input/output operations, sewing machine models and thread trimming sequence programming.
 - * These are functions not used by general users and must be regulated by an A/S technician.

No.	Function	Initial value	Range	Step
1	Back Tack Solenoid Initial Full On Time	1020ms	4~1020	4ms
2	Presser Foot-Lift Solenoid Initial Full On Time	200ms	4~1020	4ms
3	T/T Solenoid Initial Full On Time	100ms	4~1020	4ms
4	Wiper Solenoid Initial Full On Time	100ms	4~1020	4ms
5	Tension Release Solenoid Initial Full On Time	100ms	4~1020	4ms
6	Left Solenoid Initial Full On Time (For Twin Needle)	100ms	4~1020	4ms
7	Right Solenoid Initial Full On Time (For Twin Needle)	100ms	4~1020	4ms
8	Auxiliary Solenoid Initial Full On Time	100ms	4~1020	4ms
9	Left LED Initial Full On Time (For Twin Needle)	100ms	4~1020	4ms
10	Right LED Initial Full On Time (For Twin Needle)	100ms	4~1020	4ms
11	Needle plate up-stop signal Initial Full On Time	100ms	4~1020	4ms
12	Needle plate down-stop signal Initial Full On Time	100ms	4~1020	4ms
13	Signal notifying motor running Full On Time	100ms	4~1020	4ms
14	Signal notifying target speed achieved Full On Time	100ms	4~1020	4ms
15	Back Tack Solenoid Duty Ratio	50%	0~100	10%
16	Presser Foot-Lift Solenoid Duty Ratio	20%	0~100	10
17	Thread Trimming Solenoid Duty Ratio	100	0~100	10
18	Wiper Solenoid Duty Ratio	100	0~100	10
19	Tension Release Solenoid Duty Ratio	100	0~100	10
20	Left Solenoid Duty Ratio (For Twin Needle)	50	0~100	10
21	Right Solenoid Duty Ratio (For Twin Needle)	50	0~100	10
22	Aux Solenoid Duty Ratio	100	0~100	10
23	Left LED Duty Ratio (For Twin Needle)	100	0~100	10
24	Right LED Duty Ratio (For Twin Needle)	100	0~100	10
25	Signal for up stopping needle Duty Ratio	100	0~100	10
26	Signal for low stopping needle Duty Ratio	100	0~100	10
27	Signal notifying motor running Duty Ratio	100	0~100	10
28	Signal notifying target speed reached Duty Ratio	100	0~100	10
29	NOT USED			
30	Start Back Tack A number of stitches correction value	00.30	6~6	0.05 Stitch
31	Start Back Tack B number of stitches correction value	00.30	6~6	0.05 Stitch
32	End Back Tack C stitch correction value	00.40	6~6	0.05 Stitch
33	End Back Tack D stitch correction value	00.40	6~6	0.05 Stitch
34	Selection for maintaining reverse solenoid movement when thread trimming (C Only B/T)	0	0/1	1=reverse direction maintained
35	Programming count condition	0	0/1	0=counter used
	(program whether or not automatic counter will be operated)			1=automatic counter after thread trimming
36	When automatically counting, select Up/Down count after thread	1 1	0/1	1=Up COUNT
30	trimming (thread trimming function must be enabled)	l	0/1	0=DOWN COUNT
37	When count in completeded, the next operation is programmed	0	0/1/2	0=buzzer rings, sewing is allowed 1=buzzer rings, sewing is not allowed (If you press the Prog Key, set up is cancelled) 2=No buzzer ring, sewing is allowed
38	When count is completed, select the counter auto clear/preset	0	0/1	1=AUTO CLEAR/PRESET
39	NOT USED			

^{*} Items No. 30~33: These are the items that make the number of stitches match when back tack number of stitches do not match.

Solenoid initial full on time: The time it takes to pull the solenoid to the maximum in the outset.



^{*} Solenoid Duty Ratio: The power that holds and maintains the solenoid.

No.	Function		Initial value	Range	Step
40	Checks operation of B/T solenoid	(OUTPUT00)			
41	Checks operation of P/F solenoid	(OUTPUT01)	2) 3)		
42	Checks operation of T/T solenoid	(OUTPUT02)			
43	Checks operation of W/P solenoid	(OUTPUT03)			
44	Checks operation of T/R solenoid	(OUTPUT04)			
45	Checks operation of left solenoid	*After matching the number of the solenoid being			
46	Checks operation of right solenoid	(OUTPUT06)	tested, press	s the "+1stitch([iii)"key and check
47	Checks operation of Aux. solenoid	(OUTPUT07)		of the movement	
48	Checks operation of Left LED solenoid	(OUTPUT10)	- Along with t	he output, it will s	ay "on", or "off"
49	Checks operation of Right LED solenoid	(OUTPUT11)			
50	Checks operation of needle when signal notifies up stop	(OUTPUT12)			
51	Checks operation of needle when signal notifies down stop	(OUTPUT13)			
52	Checks operation of signal notifying motor running	(OUTPUT14)			
53	Checks operation signal notifying target speed has been reached	(OUTPUT15)			
	Select [Thread trimming sequence]				
	- The default is set to '0'. If you wish to input another seque	ence apart			
54	from the thread trimming sequence provided in		0	0~64	1
	the system input the newly composed sequence numbe	r.			
	(Refer to the sequence composition method)				
55	Thread trimming sequence data writing function				
	Selecting sewing machine model				
	- write the number that fits the sewing machine model prov	vided in			
	the full function manual				1
56	- thread trimming sequence in the pertinent machine is cop	pied.	0	0~127	0~74
30	- if you want to correct the thread trimming sequence, char	nge	U	0~127	(non-order made)
	the contents of item B-55. (st However, be aware that if y	ou initialize			75~118
	the parameter, the newly programmed changes will disag	pear and			(order-made)
	the thread trimming sequence will change to that of [Suns	Star 235/250]).			(Refer to attached material)
57	Independent operation of trimming sequence		0	0/1	0=operation after trimming
37	independent operation of thirming sequence		0	0/1	1=independent operation
58	Presser foot-lift solenoid slowing down time #1		40ms	2~510ms	2ms
	(Applied only when it is full-on condition)		TOITIO	2:-0101110	LIIIO
59	Presser foot-lift solenoid slowing down time #2		30ms	2~510ms	2ms
39	(Applied only when it is PWM)		COITIO	2:0101110	LIIIO

^{*} Items No. 40~53: functions that check if solenoid and other output signals are working properly.

Select Item No. 55 and press the Enter key. Along with the buzzer sound you will see the words "Seq 55" appear on the screen.
 Thread trimming sequence composition permitting condition is now possible. You can program a thread trimming sequence to a maximum of 64 bytes. (For thread trimming sequence program method, refer to attached material).





No.	Fur	oction	Initial value	Range	Step
60	Checks the signal input INPUT00	(Button A)			
61	Checks the signal input INPUT01	(Button B)			
62	Checks the signal input INPUT02	(1/4 stitch Switch)			
63	Checks the signal input INPUT03	(2/4 stitch Switch)			
64	Checks the signal input INPUT04	(3/4 stitch Switch)			
65	Checks the signal input INPUT05	(4/4 stitch Switch)			
66	Checks the signal input INPUT06	(Left Switch)			
67	Checks the signal input INPUT07	(Right Switch)			
68	Checks the signal input INPUT10	(Manual presser foot-lift Switch)	Alono	g with the inpu	ut, it will say "on" or "off"
69	Checks the signal input INPUT11	(Counter Switch)			
70	Checks the signal input INPUT12	(PU 1/2 stitch Button)			
71	Checks the signal input INPUT13	(Safety Switch)			
72	Checks the signal input INPUT14	(Edge Sensor)			
73	Checks the signal input INPUT15	(Thread trimming not allowed)			
74	Checks the signal input INPUT20	(First step for pedal going forward)			
75	Checks the signal input INPUT21	(First step for pedal going backwards)			
76	Checks the signal input INPUT22	(Second step for pedal going backwards)			
77	Checks the solenoid movement volt	age		0~64	
78	Checks external volume value			0~64	
79	Checks the pedal analog output			0~64	
80	Checks the synchronizer signal				Increases by each rotation of the sewing machine
81	Checks the signal from encoder A/E	3			increases when sewing machine rotates clockwise decreases when sewing machine rotates in counterclockwise
82	Checks the signal from encoder R/S	ЭЛ			1) When sewing machine is rotating clockwise 101→100→110→010→ 011→001→101 2) When sewing machine is rotating counterclockwise 101 → 001 → 011 → 010→ 110 → 100 →101
83~	NOT USED				
99	NOT USED				

- ※ Items No. 60~76: functions that check individual normal movement.
- * Items No. 77~79: functions that check each analog input normal movement.
- * Item No. 80: function that checks whether the synchronizer signal is working properly.
- * Item No. 81: function that checks whether the encoder A/B is working properly.
- * Item No. 82: function that checks whether the encoder R/S/T is working properly.




No.	Function	Initial value	Range	Step
90	Sewing machine pulley size	?	0~9999	1pulse
91	Distance between up-stop ∼ low-stop			
	(the standard is the pulley's normal direction rotation)	?	0~9999	1pulse
92	Programming the upper stop location			
	(the standard is the pulley's normal direction rotation)	?	0~359	1degree
	- Not valid for model S-III			
93	Programming the low-stop location			
	(the standard is the pulley's normal direction rotation)	?	0~359	1degree
	- Not valid for model S-III			
94	Index pulse occurring position	?	0~359	1degree
	(the standard is the pulley's normal direction rotation)			
	- Turn the pulley manually and stop it in the position you want.			
95	CAM type thread release solenoid operation position ? 0~359 1deg		1degree	
	- Turn the pulley manually and stop it in the position you want.			
96	CAM type thread release solenoid release position ? 0~359 1degree		1degree	
	- Turn the pulley manually and stop it in the position you want.			
97	CAM type thread trimming solenoid operation position ? 0~359 1degree		1degree	
	- Turn the pulley manually and stop it in the position you want.			
98	CAM type thread trimming solenoid release position ? 0~359 1degree		1degree	
	- Turn the pulley manually and stop it in the position the user wants			
99	Manual and automatic set up of solenoid operation /	1	0/1	0=manual set up
	release position in CAM type thread trimming			1=automatic set up





- (3) Group C Parameter: Pedal acceleration/deceleration curve, slow starting speed and input/output port change related parameter
 - * These are functions not used by general users and must be regulated by an after-sales service engineer.

No.	Function	Initial value	Range	Step	
1	1 step section where pedal moves forward	10	0~64	1	
2	2 step section where pedal moves forward	15	0~64	1	
3	3 step section where pedal moves forward	31	0~64	1	
4	4 step section where pedal moves forward	40	0~64	1	
5	5 step section where pedal moves forward	52	0~64	1	
6	Sewing speed value in the 1 step where pedal moves forward	440spm	40~9960	40spm	
7	Sewing speed value in the 2 step where pedal moves forward	920spm	40~9960	40spm	
8	Sewing speed value in the 3 step where pedal moves forward	4000spm	40~9960	40spm	
9	Sewing speed value in the 4 step where pedal moves forward	5480spm	40~9960	40spm	
10	Sewing speed value in the 5 step where pedal moves forward	9960spm	40~9960	40spm	
11	Select slow start after thread trimming	0	0/1	1=selection	
- 11	(After performing thread trimming, start the next sewing work slowly)	0	0/1	1=5616011011	
12	Select slow start after sewing machine stops	0	0/1	1=selection	
12	(After performing sewing machine stops, start the next sewing work slowly)		0/1		
13	When starting slowly, select sewing speed change	0	0/1	1=Use C14~C18 value	
10	When starting slowly, select sewing speed change			0=Use default value	
14	The speed of the first stitch when starting slow	400spm	40~9960	40spm	
15	The speed of the second stitch when starting slow	400spm	40~9960	40spm	
16	The speed of the third stitch when starting slow	640spm	40~9960	40spm	
17	The speed of the fourth stitch when starting slow	1000spm	40~9960	40spm	
18	The speed of the fifth stitch when starting slow	1680spm	40~9960	40spm	
19	Limited maximum motor speed	3000rpm	20~3400	20rpm	
20	Synchronizer sensor rotation sensing time	40×0.1sec	5~1275	0.5sec	
21	Overload sensing time	30×0.1sec	5~1275	0.5sec	
22	Solenoid electric overflow sensing time	100ms	4~1020	4ms	
23	Power off sensing time	4ms	4~1020	4ms	
24	NOT USED				
25	Bad siginal of the Encoder A and B phase detecting number of time	4	1 ~255	1	
26	Back siginal of the Encoder R, S and T phase detecting number of time	4	1 ~255	1	
27	Bad siginal of the Encoder R, S and T phase detecting number of time	4	1 ~255	1	
28	NOT USED				
	Automatic scaling to the speed curve selected by each set mode				
29	- Mode 0 : Use a curve based on the set values from C-1 to C-10		1~2	1	
29	- Mode 1 : Scaling to the speed set at A-2	1	1~2	'	
	- Mode 2 : Scaling to the speed set using the Speed Up/Dn key				



Items No. 1~5: Equal division of pedal stroke in 64 steps, The speed curve of the pedal stroke changes according to how many steps are set up for the divided pedal stroke of each forward pedal step. (Used when adjusting pedal sensor)

- No. 20 : If a synchronizer signal comes, but the next synchronizer signal does not come within the sensing time, an error message will appear.
- * No. 21 : If a speed instruction was sent to the motor but the motor does not reach the value of the speed instruction, an error message will appear.



* This item is operated by the factory only, so general users and A/S technicians should not use it.

No.	Function		Initial value	Step
30	OUTPUT00 (B/T Solenoid)	: Low Active	0(Fixed)	
31	OUTPUT01 (P/F Solenoid)	: Low Active	1(Fixed)	
32	OUTPUT02 (T/T Solenoid)	: Low Active	2	
33	OUTPUT03 (W/P Solenoid)	: Low Active	3	
34	OUTPUT04 (T/R Solenoid)	: Low Active	4	
35	OUTPUT05 (Left Solenoid)	: Low Active	5	Output port changing function
36	OUTPUT06 (Right Solenoid)	: Low Active	6	- write the function number on the output PIN you want to
37	OUTPUT07 (AUX Solenoid)	: Low Active	7	change after referring to the
38	OUTPUT10 (Left LED)	: High Active	8	table below
39	OUTPUT11 (Right LED)	: High Active	9	
40	OUTPUT12 (Needle upper stop notifying signal)	: High Active	10	
41	OUTPUT13 (Needle lower stop notifying signal)	: High Active	11	
42	OUTPUT14 (Signal notifying motor is running)	: High Active	12	
43	OUTPUT15 (Signal notifying target has been reached)	: High Active	13	

★ A : Output PIN function

Function No.	H/W type actual output name		Function No.	H/W type actual ou	itput name
0	B/T Solenoid	(with duty)	100	inv. B/T Solenoid	(with duty)
1	P/F Solenoid	(with duty)	101	inv. P/F Solenoid	(with duty)
2	T/T Solenoid	(with duty)	102	inv. T/T Solenoid	(with duty)
3	W/P Solenoid	(with duty)	103	inv. W/P Solenoid	(with duty)
4	T/R Solenoid	(with duty)	104	inv. T/R Solenoid	(with duty)
5	Left Solenoid	(with duty)	105	inv. Left Solenoid	(with duty)
6	Right Solenoid	(with duty)	106	inv. Right Solenoid	(with duty)
7	AUX Solenoid	(with duty)	107	inv. AUX Solenoid	(with duty)
8	Left LED	(with duty)	108	inv. Left LED	(with duty)
9	Right LED	(with duty)	109	inv. Right LED	(with duty)
10	"Needle Up-stop" notifying signal	(with duty)	110	inv. Needle Up-Stopped	(with duty)
11	"Needle Down-stop" notifying signal	(with duty)	111	inv. Needle Down-Stopped	(with duty)
12	"Sewing machine running" notifying signal	(with duty)	112	inv. Motor Running	(with duty)
13	"Target speed" notifying signal	(with duty)	113	inv. Target Speed	(with duty)
14	"Trimming" notifying signal	(without duty)	114	inv. Trimming	(without duty)
15	"End Back Tack" notifying signal	(without duty)	115	inv. End Back Tack	(without duty)
16	"Emergency stop" notifiying signal	(without duty)	116	inv. Emergency Stopped	(without duty)
	- A signal appears when the motor stops for a	iny error.		-A signal appears when the motor stops for any error	
17	Roller Lift Solenoid	(without duty)	117	inv. Roller Lift Solenoid	(without duty)
18	Hemming Device Output	(without duty)	118	inv. Hemming Device Output	(without duty)
19	"First step forward pedal" notifying signal	(without duty)	119	inv. Pedal Start	(without duty)
200	Low signal	(without duty)	201	High signal	(without duty)

^{**} If an output signal has been sent twice in the OUTPUT00~OUTPUT15 output pin, the same signal will appear in two different output pins. Ex) if OUTPUT00 = 0 & OUTPUT03 = 0, then B/T signal is output from both OUTPUT00 & OUTPUT03 pin

^{**} Roller Lift Solenoid = Presser Foot-Lift solenoid + Back Tack solenoid + Roller Lift Switch

43~	NOT USED	
49	NOT USED	



^{*} When setting up other functions apart from the function numbers listed above, the pertinent output pin functions are disregarded.



No.	Function	Initial value	Step
50	INPUT00 (Button A)	0	
51	INPUT01 (Button B)	1	
52	INPUT02 (1/4 stitch Switch)	2	
53	INPUT03 (2/4 stitch Switch)	3	
54	INPUT04 (3/4 stitch Switch)	4	
55	INPUT05 (4/4 stitch Switch)	5	
56	INPUT06 (Left Sol. Switch)	6	Output port changing function
57	INPUT07 (Right Sol. Switch)	7	- Write the function number
58	INPUT10 (Presser Foot-Lift Switch)	8	on the output PIN you want
59	INPUT11 (Counter Switch)	9	to change after referring to
60	INPUT12 (P/U 1/2 stitch Switch Signal)	10	the table below
61	INPUT13 (Safety Switch Signal)	11	
62	INPUT14 (Edge Sensor Signal)	12	
63	INPUT15 (Thread trimmer not allowed Signal)	13	
64	INPUT20 (Pedal Start Signal)	16	
65	INPUT21 (Pedal Presser Foot-Lift Signal)	17	
66	INPUT22 (Pedal Trim Signal)	18	

★ B: Input PIN function

No.	Actual Hardware Output Name	No.	Actual Hardware Output Name
0	Button A Switch	100	inv Button A Switch
1	Button B Switch	101	inv Button B Switch
2	1/4 stitch Switch	102	inv 1/4 stitch Switch
3	2/4 stitch Switch	103	inv 2/4 stitch Switch
4	3/4 stitch Switch	104	inv 3/4 stitch Switch
5	4/4 stitch Switch	105	inv 4/4 stitch Switch
6	Left Solenoid Switch	106	inv Left Solenoid Switch
7	Right Solenoid Switch	107	inv Right Solenoid Switch
8	Presser Foot-Lift Switch	108	inv Presser Foot-Lift Switch
9	Counter Switch	109	inv Counter Switch
10	Program Unit 1/2 stitch Switch	110	inv Program Unit 1/2 stitch Switch
11	Safety Switch	111	inv Safety Switch
12	Edge Sensor Signal	112	inv Edge Sensor Signal
13	Thread Trimmer Signal	113	inv Trimming Disabled Signal
14	Roller Lift Switch	114	inv Roller Lift Switch
15	N_AUTO Switch	115	inv N_AUTO Switch
16	Pedal Start Signal	116	inv Pedal Start Signal
17	Pedal Presser Foot-Lift Signal	117	inv Pedal Presser Foot-Lift Signal
18	Pedal Thread Trimming Signal	118	inv Pedal Thread Trimming Signal
19	External Signal	119	inv External Signal

^{**}The hardware of input switches and sensors are done with "a point of contact/Active High" input as the standard.

^{*} When setting up other functions numbers apart from the ones listed above, the pertinent output pin functions are disregarded.



strule Caution : When any inputs PIN No. INPUT00 \sim INPUT22 are overlapped, it works as the "OR" circuit. Ex) if INPUT00 = 0 & INPUT01 = 0, then it is recognized as "button A" = INPUT00 + INPUT01.

70	Output Signal Level Collective Reverse Function		0/1	1=Output signa Collective Reverse, selection
71	71 Input Signal Level Collective Reverse Function		0/1	1=Input signal Collective Reverse, selection
72~	NOT USED			
99	NOT USED			



(4) Group D Parameter: All types of gain parameter related motor control

* These are functions not used by general users and must be regulated by an A/S technician.

No.	Function		Initial Value	Range	Step
1	speed P-gain	Kvp	30	0~30	1
2	speed D-gain	Kvd	0	0~3000	1
3	location P-gain	Крр	200	0~1000	1
4	location D-gain	Kpd	1000	0~5000	1
5	acceleration A	accelA	65	1~100	1
6	acceleration B	accelB	70	1~100	1
7	acceleration C	accelC	30	1~100	1
8	acceleration D	accelD	10	1~100	1
9	sewing machine inertia value	Inertia	40	0~255	1
10	positioning speed	Wpos	220rpm	100~510	2rpm
11	stopping speed	Wstop	75rpm	0~255	2rpm
12	Stop delaying time	StopDelay	80ms	4~1020	4ms
13	Positioning distance	DIST1	110degree	24~255	1degree
14	upper speed instruction unit	spd_unit	100spm	1~100	1spm
15	Positioning P-gain	Крр2	270	0~9999	1
16	Positioning D-gain	Kpd2	2027	0~9999	1
17	Positioning P-gain	Крр3	200	0~9999	1
18	Positioning D-gain	Kpd3	1000	0~9999	1
19	NOT USED				
20	Overload rate limit function setting		0	0/1	
21	Pre-set overload rate		100[%]	0~255[%]	In case where the rated voltage of motor is 100[%], it can be set by 1[%].
22	Pre-set overload rate limit duration		Depending on the pre-set overload rate, limit duration is automatically calculated.	Parameter exit and re-entry should be	
23~	NOT USED				
99	NOT USED				





3) Method of Use and Explanations for Specific Items of the Parameter

(1) Method of Use and Explanations for Specific Items of the Group A Parameter (General functions of sewing machine)

A. Minimum/maximum sewing speed limit set up method and thread trimming speed set up method

Item No.	Name of function	Method of use and explanation
A-1	Minimum sewing speed limit set up	This item allows user to set up the minimum sewing speed limit or the minimum sewing speed given whenthe pedal is pressed.(20~510rpm, Initial value : 200rpm)
A-2	Maximum sewing speed limit set up	This item allows user to set up the maximum sewing speed limit or the maximum sewing speed given when the pedal is pressed.(40~9960rpm, Initial value: 4000rpm)
A-3	Thread trimming speed set up	This item allows the user to set up the thread trimming speed when the thread trimming function is operating after sewing

B. Set up method of ½ stitch speed by program unit(P/U) and needle plate lift/drop by button A

Item No.	Name of function	Method of use and explanation
A-4	Set up method of stitch speed by program unit (P/U)	This item allows user to set up the stitch speed by program unit (P/U) and hence sets up the stitch operating speed. However, if set up to a rapid speed, many stitches may be sewn after pressing the button.
A-5	Set up the speed of lift/drop of needle plate with button A	This item allows user to set up the speed of lift/drop of the needle plate with button A. However, if set to a rapid speed, many stitches may be sewn after pressing the button.

C. Start B/T sewing speed and end B/T sewing speed set up method

Item No.	Name of function	Method of use and explanation
A-7	Start B/T speed set up	This item allows user to set up the start B/T speed. If the speed is changed, the stitch correction value also has to be set again.
A-8	End B/T speed set up	This item allows user to set up the end B/T speed. If the speed is changed, the stitch correction value also has to be set again.

D. Selection method of thread trimming location with pedal

Item No.	Name of function	Method of use and explanation
A-19	Start B/T speed set up	You can change the thread trimming operation through pedal position by making the following changes to the set up values. • 0 : When the pedal position is backward 2 gear, operate thread trimming(Starting set up value). • 1 : When pedal position is backward 1 gear, operate thread trimming • 2 : When pedal position is neutral, operate thread trimming.

E. Edge Sensor method of use Item No.

Item No.	Name of function	Method of use and explanation
A-40	Selection of edge sensor type	The set up method changes according to the set up parts of edge sensor • 0 : When edge is sensed and using high output sensor. • 1 : When edge is sensed and using low output sensor.
A-41	Stitches performed after edge sensor sensing	A function that programs the machine to stop after sewing a programmed amount of stitches when edge is sensed.
A-42	Sewing speed of stitches performed after edge sensor sensing	A function that programs the sewing speed after sewing a programmed amount of stitches when edge is sensed.
A-46	Selection of edge sensing sewing mode (select N-stitch mode)	A function that programs the edge sensor to operate normally, even when other sensor signals are inputted in the edge sensor port.



F. Pre-stitch function method of use and explanation

Item No.	Name of function	Method of use and explanation
A-47	Selection of pre-stitch function The pre-stitch function is a function that programs the machine to sew a certain amount of stitches before commencing the actual sewing work.(0 : disable, 1 : enable)	
A-48	Set pre-stitching stitch number This item sets the number of stitches when using the pre-stitch function (0~255 stitches, Initial value : 3 stitches)	
A-49	Set pre-stitching speed	This item sets the sewing speed when using the pre-stitch function. (20~2000rpm, Initial value: 2000rpm)

G. Method to select beginning/ending reverse sewing conditions

Item No.	Name of function	Method of use and explanation
A-50	Selection of start B/T conditions (Initial value : 1)	 The start B/T function can be one of the following three operations according to their set up value 0: If user releases pedal during B/T operation, sewing stops. 1: If user releases pedal during B/T operation, sewing stops after finishing work. 2: The exact amount of stitches is operated, notwithstanding the number of stitch corrections. However, if this function is used, B/T will no operate naturally.
A-51	Selection of end B/T conditions (Initial value : 0)	This item selects whether or not to use the end B/T's exact number of stitches function operation • 0 : exact number of stitches function disabled • 1 : exact number of stitches function enabled (If this function is used, reverse sewing will no operate naturally)
A-52	The speed of the first stitch during B/T exact performance	This item selects the speed of the initial reverse stitch when user has selected the exact number of stitches function in the B/T operation(20~1000rpm, Initial value : 200rpm)

H. Method to select buttons A/B functions

Item No.	Name of function Method of use and explanation		
A-54	Selection of button A function (Initial value : 2)	 The function of button A can be one of the following four operations according to their set up value. 0: If user presses A button while sewing, B/T sewing is operated while user keeps on pressing it. 1: If user presses the A button while sewing, B/T sewing is operated. If user stops sewing and presses A button once the needle plate is lifted. If user presses it once more, the needle plate is dropped 2: If user presses the A button while sewing, B/T sewing is operated while user keeps on pressing it. If user stops sewing and presses A button once, the needle plate is lifted. If user presses it twice consecutively, the needle plate is dropped. 3: If user presses A button while sewing, B/T sewing is operated while user keeps on pressing it. When user stops sewing and presses the A button, 1/2 stitch speed is operated. 	
A-55	Selection of button B function (Initial value : 0) The function of button A can be one of the following four operations according to their set of : This item has the function of inserting/deleting the B/T sewing when user presses to the B button where there is no B/T sewing section, B/T sewing is defined and when it is pressed where there is a B/T sewing section, B/T sewing is defined and if user presses it once more in the sewing and presses the B button, 1/2 stitch speed is operated while user 3: When sewing, B/T sewing is operated while user presses B button.		

I. Method of use of motor rotating direction selection function

Item No.	Name of function	Method of use and explanation	
A-65	Selecting the motor's rotating direction	This item sets up the set up value according to the motor's rotating direction • 0 : clockwise rotation • 1 : counterclockwise rotation(Initial value)	






(2) Group B Parameter Specific Method of Use and Explanation (All types of output, Full-on Time/PWM Duty, checking the input/output movements, sewing machine models and thread trimming sequence programming)

** These are functions not used by general users and should be regulated by an A/S technician.

**A. All types of output, Full-on Time/PWM Duty time set up method (all types of solenoids, LED and signals)



This figure explains the Full-on Time and PWM Duty. This figure shows the wave type graph where the machine maintains the power 'ON' for a certain amount of time and when that 'Full-on Time' passes, changes itself to a PWM signal with a certain duty. In other words, the certain amount of time that each device starts operating until they become completely, the output wave type maintains itself "On", and when it maintains itself operating the output becomes the duty PWM wave type to maintain operation.

B. B/T stitch correction set up method

Item No.	Name of function	Method of use and expla	anation
B-30	Start B/T A side stitch correction value	This item has the function of correcting the B/T	A 1 B 3
B-31	Start B/T B side stitch correction value	sewing stitch that has not been shaped well, and you can change the value of sides A, B, C, D.	(31/1) 2
B-32	End B/T C side stitch correction value	• The programmed value in the beginning A:3, B:3, C:4, D:4	(Nata
B-33	End B/T D side stitch correction value	• Program range : 0 ~ 9	2 3 5

- If the stitch correction values is changed using the program unit, the item value will automatically change. Reversely, if you change the programmed value of the items above, the stitch correction values will also automatically change.
- Detailed correction principles and methods of use are the same as the program unit's stitch correction method. Please refer to the program unit method of use of start/end B/T stitch correction method.

C. Counter function method of use

Item No.	Name of function	Method of use and explanation
B-35	Counter condition set up	
B-36	When using automatic counter after trimming, select increasing/decreasing counter	For detailed method of use and explanation of counter function, refer to the
B-37	After counter operation is over, set up the next operation	program unit's counter set up button method of use.
B-38	After counter operation is over, select the automatic erasing operation	



(3) Group C Parameter Specifics Method of Use and Explanation

(Pedal acceleration/deceleration curve, slow starting speed, input/output port change related parameter)

- ** These are functions not used by general users and should be regulated by an A/S technician.
- A. Pedal stroke step by step section and speed set up method

Item No.	Name of function	Beginning value	Method of use and explanation
C-1	pedal forward first step section	10	
C-2	pedal forward second step section	15	After dividing the pedal stroke to 64 steps, the pedal stroke's
C-3	pedal forward third step section	31	acceleration/deceleration curve changes according to which stroke step is programmed from pedal forward steps 1 through
C-4	pedal forward fourth step section	40	5.
C-5	pedal forward fifth step section	52	
C-6	sewing speed during pedal forward first step	440rpm	
C-7	sewing speed during pedal forward second step	920rpm	The pedal stroke's acceleration/deceleration curve changes
C-8	sewing speed during pedal forward third step	4000rpm	according to how the pedal forward step by step sewing
C-9	sewing speed during pedal forward fourth step	5480rpm	speed set up is done.
C-10	sewing speed during pedal forward fifth step	9960rpm	

B. Slow-start sewing method of use: this function allows to start the sewing slowly and the user can set up the following specific items.

Item No.	Name of function	Method of use and explanation
C-11	Slow Start after thread trimming	These items help you choose at which point you can apply slow start. If you want to apply it after thread trimming set item No. C-11 value to 1. If you want to
C-12	Slow Start after sewing machine stops	apply it after when you start sewing after stopping set item No. C-12 to 1. If both these items are set to 0, the slow starting function will not operate.
C-13	When Slow Starting, change Slow- starting speed	When using the slow start function, this item gives you the option of maintaining the same starting speed or setting up a new speed. If you want to set up a new speed, use items No. C-14~C-18 and set up a new speed.
C-14	When Slow Starting, the operation speed of beginning stitch	
C-15	When Slow Starting, the operation speed of second stitch	When the item No. C-13 set up value is "1", the slow start beginning
C-16	When Slow Starting, the operation speed of third stitch	values (the specific items that change the set up value) are
C-17	When Slow Starting, the operation speed of fourth stitch	• 1 : 400rpm • 2 : 400rpm • 3 : 640rpm • 4 : 1000rpm • 5 : 1680rpm
C-18	When Slow Starting, the operation speed of fifth stitch	

C. Motor maximum speed limit set up method

Item No.	Name of function	Method of use and explanation
C-19	Set up motor maximum speed limit	This function allows you to limit the maximum motor speed, and the starting value is set to 3000 rpm.





4) Thread Trimming Sequence Function Method of Use (Items no. 54, 55, 56 of Group B)

- Thread trimming sequence function characteristics
 - The thread trimming sequence is a user programming function of PLC control type used for thread trimming or when a special simple repetitive function is required.
 - The user composes the thread trimming sequence he wants, and can program the machine or motor's operation during thread trimming.
 - When necessary, the user can change it to exclusive mode and can program all types of special operations.
 - The program size is 64 bytes, so compose the program within this size limit.
 - The program code is composed of the command field and the data field.
 - The thread trimming related parameters are items No. 54, 55, 56 from Group B.

Item No.	Function
B-54	This item that provides the function of thread trimming sequence selection which allows the user to select and use the sequence from item No. B-55
B-55	This item provides the function of allowing the user to compose the thread trimming sequence himself.
B-56	This item provides the function of allowing the user to select other company sewing machine models, and makes automatic changes in the thread trimming sequence that fit the selected sewing machine.


(1) Thread Trimming Sequence Function Related Parameter Method of Use and Explanations A. Thread Trimming Sequence Data Input Function (Item No. B-55)

① This function allows the user to compose the thread trimming sequence himself. In order to do this, the user must first enter parameter Group B.	ABCD EF
② If the screen changes, go to the specific items and choose item No. 55 from Group B. Then the user will see the letter "Seq" blink. (Use buttons ()	ABCO BF
③ If you press the button where it says "Seq 55", you can now choose the thread trimming sequence. In the figure, you can see the command "80" which indicates the sequence start. The command "01" is a number within the sequence (01~64) of the "80" command.	
 ④ If you use buttons to increase the numbers, you can see the sequence that was set up in the start. Their contents are explained below • 01: "08" ⇒ Sequence starting code • 02: "F3" ⇒ General sequence • 03: "00" ⇒ Sequence ending code 	ABOD BF
⑤ Now the user can change the sequence function according to his objectives but the remember that the program size cannot exceed 64 bytes. Also you can set up several short sequences and then use the sequences you want by using item No. B-54. When you setting this up, each sequence must always have a starting and ending code. ※Refer to sequence code list	ABCD EF



- If you don't press the button after changing the parameter item set up value, the set up value will not be saved, so use caution when using it.
- If the specific items of the parameter are changed carelessly, they could cause breakdown or damage the machine. Therefore, the user must be well-trained before using it.


B. Thread Trimming Sequence Selection Function Method of Use (Item No. B-54)





- If you don't press the button after changing the parameter item set up value, the set up value will not be saved, so use caution when using it.
- If the specific items of the parameter are changed carelessly, they could cause breakdown or damage the machine. Therefore, the user must be well-trained before using it.

C. Thread Trimming Sequence Automatic Change According to Sewing Machine Model Selection






- If you don't press the button after changing the parameter item set up value, the set up value will not be saved, so use caution when using it.
- If the specific items of the parameter are changed carelessly, they could cause breakdown or damage the machine. Therefore, the user must be well-trained before using it.

(2) Thread Trimming Sequence Function Related Parameter Method of Use and Explanations (Economic)

A. Changing the Trimming Sequence with the Simplified Operation Panel

When changing the thread trimming sequence by using the simplified operation panel, the method is a bit different from when changing other parameters. Check the following manual and make the changes in a correct manner.



<S-5 Simplified Operation Panel>



	How to Operate	Display	Remarks
1	Press E/Prg button and A button simultaneously. Then the screen for changing parameters appears.	PrEn	Program Enable
2	Press B button, and it moves to the parameter B group.	<u> </u>	Parameter B-01
3	Use A button and B button to move to the No. 55 trimming sequence of the B group.	<u> </u>	Parameter B-55
4	Press C button when "b-55" is displayed. Then "SEQ" blinks on the screen.	559	• Sequence
5	Press C button once again, and the screen displays the starting location number of trimming sequence.	559	80": Trimming sequence start command
6	Press A button and B button to change the location number of the current trimming sequence. ex) When A is pressed, "80" is changed to "81".	80	The starting location number of trimming sequence has changed from "—80" to "-81".
7	When C button or D button is pressed, the trimming sequence location number increases or decreases. The screen displays the values stored in the concerned sequence location. ex) When C is pressed, the screen displays "83", the value which is in the second trimming sequence location.	80	• In case where Model = 88, the "83" command is stored in the second trimming location.
8	When the trimming sequence change is complete following the above procedure, press E/Prg button to store the sequence.	SER	Trimming sequence is stored.
9	 [Notice] Please make sure that in case of a simplified operation panel, the location valuence Please make sure that in case of a simplified operation panel, the functions those when they are used in other context. In order to exit the trimming sequence change mode, press "E". Then all the changes are lift you want to make several changes, press "E" one time after all changes are 	of the buttons A, B, C nanged values will be s	c, D, E are a bit different from stored.

(3) Basic Structure of Thread Trimming Sequence Program Code

A. The thread trimming sequence program code is basically composed of the command field and data field which comes according to the command field. The size of the program cannot exceed 64 bytes.

Evr	planation of function	Command	Data field				
L^1		field	1st	2nd	3rd		
PosStopUp	Needle plate up-stop after sewing given stitch numbers at given speed.	CEH	0~5000[rpm](20rpm)	0~255[stitch]			

B. The table above is an example of the program code structure. If you want to use the function "Needle plate up-stop after sewing given stitches at given speed "you must first select the command code "CE H" and set up the data value according to the command code. In other words, the given sewing speed is the first data and the given stitch numbers is the second data and both of these form the data field. Depending on the command code, there can exist a data field or exist three data in the data field.

(4) Thread Trimming Sequence Program Code List

Category	Explanation		Cmd Field	Data Field				
Calegory				1st	2nd	3rd		
	B/T Solenoid	On	81H					
	P/F Solenoid	On	82H					
	T/T Solenoid	On	83H					
	W/P Solenoid	On	84H					
	T/R Solenoid	On	85H					
	Left Solenoid	On	86H					
	Right Solenoid	On	87H					
	AUX Solenoid	On	88H					
	Left LED	On	89H					
	Right LED	On	8AH					
	Needle Up Signal	On	8BH					
	Needle Down Signal	On	8CH					
	Motor Runing Signal	On	8DH					
	Reaching Target Speed Signal	On	8EH					
	Motor Trimming Signal	On	8FH					
	Motor End Tacking Signal	On	90H					
	Emergency Stop Signal	On	91H					
	Roller Lift Solenoid	On	92H					
Output	Hemming Device Output	On	93H					
Port	Pedal Forward Step1 Signal	On	94H					
Control	B/T Solenoid	Off	98H					
(Total 40)	P/F Solenoid	Off	99H					
	T/T Solenoid	Off	9AH					
	W/P Solenoid	Off	9BH					
	T/R Solenoid	Off	9CH					
	Left Solenoid	Off	9DH					
	Right Solenoid	Off	9EH					
	AUX Solenoid	Off	9FH					
	Left LED	Off	A0H					
	Right LED	Off	A1H					
	Needle Up Signal	Off	A2H					
	Needle Down Signal	Off	АЗН					
	Motor Runing Signal	Off	A4H					
	Reaching Target Speed Signal	Off	A5H					
	Motor Trimming Signal	Off	A6H					
	Motor End Tacking Signal	Off	A7H					
	Emergency Stop Signal	Off	A8H					
	Roller Lift Solenoid	Off	A9H					
	Hemming Device Outout	Off	AAH					
	Pedal Forward Step1 Signal	Off	ABH					
	Delay by 1[ms] unit		ВОН	0~255[ms] (1ms)				
Time Delay	Delay by 2[ms] unit		B1H	0~510[ms] (2ms)				
Timo Dolay	Delay by 4[ms] unit		B2H	0~1020[ms] (4ms)				
	Delay by 0.5[s] unit		ВЗН	0~127.5[s] (0.5s)				



Category		Explanation	Cmd Field	Data Field				
Calegory				1st	2nd	3rd		
	revenues and	Mator-Holding Start	COH		7			
	Off Hold	Mater-Holding Step	C1H					
	Se: Dir CW	Set CW direction)	C2H					
	Se: Dir CCW Set CCW direction)		C3H	0 -000[
Se: Speed		Make Motor Run with given Speed	C4H	0~5000[spm]				
	0 0 10 0 1	THE RESIDENCE OF THE PROPERTY	001	(20spm)				
	Set Sod By Ped	Make Motor Run with Soeed given by pedal	C5H					
	Up Stop	Make Stop in Needle Up (stop) Make Stop in Needle Down (stop)	C6H					
	DN Stop		C7H	0.500[]	(0)			
	Up Stop InSpd	Make Uo Stop with given Speed (stop)	C8H	0~500[spm]	(2spm)			
	Dr Stop InSpd	Make Dn Stop with given Speed (stop)	C9H	0~500[spm]	(2 spm)			
	Dacc Up Edge	Decel. in Soeed at Up Edge (not s.op)	CAH	0~500[spm]	(2 spm)			
Motor	Dacc Dr Edge	Decel. in Soeed at DriEdge (not stop)	CBH	0~500[spm]	(2 sp m)			
Control	Move Up Edge	Move to Up Edge with given Speed (not stop)	CCH	0~500[spm]	(2 spm)			
	Move DnEdge	Move to Dn Edge with given Speed (not stop)	CDH	0~500[spm]	(2spm)			
	Pos Stop Up	Uo Stop after sewing given stitch with given Speed	CEH	0~5000[spm] (20spm)	0~255[stitch]			
	Pos Stop Dn	Dn Stop after sewing given stitch with given Speed	CFH	0~5000[spm]	0~255[s:itch]			
	1 08 3.0p DI	DITO DE ATTA SEWING GIVEN STICH WITH GIVEN OF SECTION	0111	(20spm)	0 255[8.11011]			
	Pos Daco Up	Dacc Dn Edge after sewing given stich with given Speed	D0H	0~5000[spm]	0~500[spm]	0~255[stirch]		
	1 30 2000 00	Pace Pri Edge and seming given directivaling from opera	Duit	(20spm)	(2spm)	0 200[0(1.01]		
	Pos Dace Dn	Dacc Up Edge after sewing given stich with given Speed	D1H	0~5000[spm]	0~500[spm]	0~255[sti.ch]		
				(20spm)	(2spm)			
	L Move Stop	Move given distance with given Speed	D2H	0~500[spm]	(2 spm)	0~357 [deg]		
	Spdlr Pos	Make motor given Sceed in given Position	D3H	0~5000[spm]	0~357[deg]			
				(20spm)				
	Random Stop	Stop randomly	D4H					
	Wait Pos1	When position alcady passed, return	E0H	0~357[dcg]				
	Wait Pos2	When position aleady passed, wait next position and then return	E1H	0~357[deg]				
	Wait Up Edge	Wai; until Up Edge detected.	E2H					
	Wait Dn Edge	Wai: until Dn Edge detected	E3H					
	Chk Pos	Check the position passed & oranch to the adoress	E4H	0~357[deg]	0~64 (address)			
Position /Speed	Chk Up Edge	Check Up Eoge detected & branch to the address	E5H	0~64 (address)				
Check	Chk Dn Edge	Check Dn Eoge detected & branch to the address	E6H	0~64 (address)				
	Cr Up Edge	Clear Up Edge FG (mark UpEdge not detecteo)	E7H					
	Cr Dn Edge	Clear Dn Edge FG (mark Dn Edge not detecteo)	E8H					
	Wait Speed	Wai: until motor speed is target speed	Е9Н	0~5000[spm] (20spm)				
	Chk Speed	Check if motor speed is target speed & branch to the address	EAH	0~357[deg]	0~64 (addresis)			

Category		Explanation	Cmd Field	Data Field			
Category		Explanation	Citia Fiela	1st	2nd	3rd	
		Button A		0 (Input Port No			
		Button B		1			
		Switch 1/4 stitch		2			
		Switch 2/4 stitch		3			
		Switch 3/4 stitch		4			
		Switch 4/4 stitch		5			
		Left Solenoid Switch		6			
		Right Solenoid Switch		7			
		Pressor Foot Lift Switch		8			
		Counter Switch	F0H	9			
		Button 1/2 switch on P/U Box		10			
		Safety Switch		11			
		Edge Sensor		12			
		Trimming Disable Switch		13			
	Waituntil	Roller lift Switch		14			
	the port signal detected	N-AUTO Switch		15			
	Gigital dolociou	Pedal Start Input		16			
		Pedal Pressor-Foot Input		17			
Input		Pedal Thread Trimming Input		18			
Port		External Input		19			
Check		Button A		0 (Port No	0~64 (address		
WaitPort		Button B		1	0~64		
		Switch 1/4 stitch		2	0~64		
		Switch 2/4 stitch		3	0~64		
		Switch 3/4 stitch		4	0~64		
		Switch 4/4 stitch		5	0~64		
		Left Solenoid Switch		6	0~64		
		Right Solenoid Switch		7	0~64		
		t Switch		8	0~64		
		Counter Switch	F1H	9	0~64		
	BrChkPort	Button 1/2 switch on P/U Box		10	0~64		
	(Check the	Safety Switch		11	0~64		
	port and	Edge Sensor		12	0~64		
	branch	Trimming Disable Switch		13	0~64		
	the given	Roller lift Switch		14	0~64		
	address)				0~64		
		N-AUTO Switch Pedal Start Input		15 16	0~64		
		·					
		Pedal Pressor—Foot Input		17	0~64		
		Pedal Thread Trimming Input		18	0~64		
	Decemb	External Input	FQ.1	19	0~64		
0	Branch	Branch to given address	F2H	0~64 (Address			
Sequence	GenSeq	General Trimming Sequence	F3H				
Control	StartSeq	Start of the sequence	80H				
	EndSeq	End of the sequence	00H				




[Caution]

- Every the conditional Branch is made to the appropriate number when it is on "No(False)"
- When makingthe sequence program, please check and use its function because the wrong sequence program can cause the mechanical trouble and the physical damage.



- (5) Examples of the Function of Thread Trimming Sequence
- Yamato Three-needle Trimming
 - 1) Timing of Thread Trimming Sequence



2 Flow Chart of Tread Trimming Sequence & Program Code

Flow chart	Code Comm. Data field				Explanation	
Flow Chart	number	field	1st	2nd	3rd	Εχριαπαιίοπ
START of Sequence	01	80				Start of Sequence
START OF Sequence	02	C8				Stop after moving to needle of upstop
Needle Up Stop with 200spm	03		200			at 200spm
<u> </u>	04	B0				Wait for 5[ms]
wait for 5ms	05		5			wait for S[ris]
T/T sol. on	06	83				Thread Trimming solenoid, On
171 301. 01	07	B0				Wait for 100[ms]
wait for 100ms	08		100			Walt for footins
T/T sol. off	09	9A				T/T sol.(off)
<u> </u>	10	B0				Wait for 5[ms]
wait for 5ms	11		5			wait for S[ms]
T/R sol. on	12	85				T/R sol.(on)
↓ 	13	B0				Wait for 100[ms]
wait for 100ms	14		100			wait for Toolins]
T/R sol. off	15	9C				T/R sol.(off)
wait for 5ms	16	B0				Wait for 5[ms]
waition sins	17		5			wait for S[ris]
W/P sol. on	18	84				W/P sol.on(on)
wait for 100ms	19	B0				Wait for 100[ms]
<u> </u>	20		100			wait for foo[fils]
W/P sol. off	21	9B				Wiper solenoid off
wait for 5ms	22	B0				Wait for E[me]
<u> </u>	23		5			Wait for 5[ms]
End of Sequence	24	00				End of Sequence

- ** Operates Presser Foot Solenoid by "Lefting Up function of Automatic Presser Foot after Trimming" being set to A18=1
- ** As every command field is displayed close to "--", it is distinguishable from Data Field
- ** All Data Fields are displayed easily enough to distinguish them from others, differently from S-II and there's no necessity of transforming the number and conversing the unit

(6) List of Codes by Machine Model - (able to choose from No. 56 of GROUP "B")

NO	ORDER NO. (Model Name)		TYPE of Sewing	T/T Solen oid type	Sewing Machine			
	GSP Code	Sub Code		1,500				
1	S5AC55-MAM-	001			KM-250A-7, KM-235A, KM-250AL-7			
2	S5AC55-MAM-	002			KM -250B-7			
3	S5AC55-LIALI-	003	Single needle	CAM	KM-750-7, KM750BL-7, KM-757BL-7, KM-757-7, KM-650-7'			
4	S5AC55-LIALI-	004	ė.		KM-560-7			
5	S5AC55-□A□-	005			KM-957-7			
6	S5AC55-MAM-	006	Double		KM-790-7, KM790BL-7, KM797-7, KM797BL-7			
7	S5AC55-NXN-	007	Chain	ELEC. Solenoid	UNION 34700, SIRUBA UTP/UTQ			
8	S5AC55-LIXLI-	008	Stitch	AIR. Solenoid	UNION 34700, YAMATO VC2700, SIRUBA UTP/UTQ			
9	S5AC55-□X□-	010			Maier Unitas D1376			
10	S5AC55-□X□-	011	Heavy	CAM	PFAFF 563			
11	S5AC55-□X□-	013	Chain	ELEC. Solenoid	YAMATO VC2700			
12	S5AC55-IIXII-	014	Single	CAM	BROTHER DB2-B737, JUKI DDL550N			
13	S5AC55-LIXLI-	016		CAM	DURKOPP 273-140042/E9			
14	S5AC55-LIXLI-	018	Single	CAM	DAE WOO DLS-640			
15	S5AC55-□X□-	019	Single	CAM	TOYOTA LS2-AD341-102			
16	S5AC55-TXT-	021	Δ	ELEC. Solenoid	STROBEL KL170-2-FD			
17	S5AC55-LIALI-	022	Single	CAM	KM -250 AU -7			
18	S5AC55-LIALI-	052	2000 BS	1200 MAG	KM-250BH-7, KM-250BL-7			
19	S5AC55-UXU-	024	Chain	AIR. Solenoid	KANSAI RX, DX, WX Series			
20	S5AC55-□X□-	025		Brone Countries went on years	DURKOPP 271-140042			
21	S5AC55-TXT-	026		ELEC. Sole noid	PEGASUS W500/UT100,400, W60 0/UT100,400			
22	S5AC55-TXT-	030	Chain	AIR. Solenoid	PEGASUS W500/UT200, W600/UT200			
23	S5AC55-LIXLI-	031	stitch	AIR. Solenoid	KANSAI RX, DX, WX Series			
24	S5AC55-□X□-	032		AIR. Solenoid	KINGTEX CT6500 -0-56M			
25	S5AC55-DAD-	033	Heavy	CAM	KM640BL-7			
26	S5AC55-MAM-	034	Heavy	CAM	KM967B-7(Roller HIGH-Post-back-tack)			
27	S5AC55−∏A∏−	036	Heavy	CAM	KM-1060BL-7, KM-1062BL-7			
28	S5AC55-LIXLI-	035	Single	CAM	TYPE of TANAKA			
29	S5AC55-UXU-	037	PUNCHING	CAM	Pastel Punching for TANAKA			
30	S5AC55-DXD-	038	Heavy	CAM	SEIKO			
31	S5AC55-TXT-	040	Chain		PEGASUS W664-01CB M/UT333			
32	S5AC55-I IXI I-	041	Chain		PEGASUS W664-08BB UT312			
33	S5AC55-LIXLI-	042	Chain	0.014	PEGASUS EX5214-83BA			
34	S5AC55-LIXLI-	045	Single Chair at tab	CAM AID Calabaid	GEMSY DINO Throad Trimming Machine for Kington			
35	S5AC55-UXU-	046	Chain stitch	AIR. Solenoid	DINO Thread Trimming Machine for Kingtex			
36	S5AC55-□A□- S5AC55-□DE-	048 49A	Heavy Chain stitch	AIR. Solenoid AIR. Solenoid	KM591BL-7 SC-7300 (Table: A-TYPE)			
38	S5AC55-LIDE-	49A 49B	Chain stitch Chain stitch	AIR. Solenoid	SC-7300 (Table : A-TTPE)			
39	S5AC55-LIALI-	050	SINGLE	CAM	KM-967-7, KM-967B-7			
40	\$5AC55-\ A\ -	050	SINGLE	CAVI	KM -506-7, KM -530-7			
41	S5AC55-□A□-	053	. ,		KM – 350A – 7			
42	\$5AC55-\(\piA\)\(\pi\)	054			KM –350B–7			
43	S5AC55-LIALI-	055			KM -857-7, KM -890-7			
44	S5AC55-□A□-	056			KM -235B			
45	S5AC55-□DE-	57A	Chain stitch	AIR. Solenoid	SC-7300 (fortinsel trimming) (Table: A-TYPE)			
46	S5AC55-□DE-	57B	Chain stitch	AIR. Solenoid	SC-7300 (fortinseltrimming) (Table : B-TYPE)			
47	S5AC55-I IDE-	58A	Chain stitch	AIR. Solenoid	SF-7500 (Table : A-TYPE)			
48	S5AC55-LIDE-	58B	Chain stitch	AIR. Solenoid	SC-7500 (Table : B-TYPE)			
49	S5AC55-□A□-	059	SINGLE	CAM	KM –867–7			
50	S5AC55-□X□-	060	-		Waist Band Device for Homan Sewing Machin			
00	\$5AC55-□DE-	061	Chain stitch	AIR. Solenoid	SC-7310 (left blade) (Table: A-TYPE)			



			GRO	OUP				8	PRO	GRAM U	INIT SET	TING			V	PULLE
		l	A			В	С	CD/T	гр/т	MEEDLE	D/F	т/т	M/D	SYNC.	Belt	Y SIZE
A2	А3	A7	A8	A24	A65	B5 6	C52	S.B/T	E.B/T	NEEDLE	P/F	T/T	W/P	I IFE	SIZE	Ф
4000	300	1700	1700	0	1	0/75	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	42"	111
4000	300	1700	1700	0	1	76	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	42"	111
2400	180	800	800	0	1	78	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	42"	80
2400	180	800	800	0	1	78	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	42"	80
2400	180	800	800	0	1	79	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	42"	80
2400	180	800	800	0	1	80	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	42"	80
6000	200	1600	1600	1	0	82	111	OFF	OFF	UP	DOWN	ON	ON	OTHER	36"	111
6000	200	1600	1600	1	0	83	111	OFF	OFF	UP	DOWN	ON	ON	OTHER	36"	111
1720	230	1600	1600	0	0	85	2	OFF	OFF	UP	DOWN	ON	ON	OTHER	NON	111
4000	230	1600	1600	0	1	86	2	ON	ON	DOWN	DOWN	ON	ON	OTHER	NON	111
4000	200	1600	1600	1	0	88	111	OFF	OFF	UP	DOWN	ON	ON	OTHER	36"	111
4000	230	1600	1600	0	1	89	2	ON	ON	DOWN	DOWN	ON	ON	OTHER	42"	111
3000	230	1600	1600	0	1	91	2	ON	ON	DOWN	DOWN	ON	ON	OTHER	42"	111
4000	230	1600	1600	0	1	93	2	ON	ON	DOWN	DOWN	ON	ON	OTHER	42"	111
4000	230	1600	1600	0	1	94	2	ON	ON	DOWN	DOWN	ON	ON	OTHER	42"	111
2480	200	1600	1600	1	0	96	111	OFF	OFF	UP	DOWN	ON	ON	OTHER	43"	111
2600	300	1600	1600	0	1	97	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	42"	111
2800	230	1600	1600	0	1	114	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	42"	11 1
5400	200	1600	1600	1	0	99	11	OFF	OFF	UP	DOWN	ON	ON	OTHER	40"	111
4800	300	1600	1600	0	0	100	11	OFF	OFF	UP	DOWN	ON	ON	OTHER	43"	111
6000	200	1600	1600	1	0	101	111	OFF	OFF	UP	DOWN	ON	ON	OTHER	36"	111
6000	230	1600	1600	2	0	102	111	OFF	OFF	UP	DOWN	ON	ON	OTHER	36"	111
6000	200	1600	1600	1	0	103	11	OFF	OFF	UP	DOWN	ON	ON	OTHER	40"	111
4480	200	1600	1600		0	104	111	OFF	OFF	UP	DOWN	ON	ON	OTHER	38"	111
2000	200	800	800	0	1	105	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	43"	60
3000	180	800	800	0	1	106	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	41"	80
3000	180	800	800	0	1	107	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	44"	90
4000	200	1600	1600	0	1	111	2	ON	ON	DOWN	DOWN	ON	ON	OTHER	44"	90
2000	230	1600	1600	0		112	2	ON	ON	DOWN	DOWN	ON	ON	OTHER	44"	80
2400	200	1600	1600	0	- U	113	2	ON	ON	DOWN	DOWN	ON	ON	OTHER	55"	80
6000 4000	230 300	1600 1600	1600 1600	2	1	118 115	111 12	OFF ON	OFF ON	UP DOWN	DOWN	ON ON	ON ON	OTHER OTHER	36" 36"	111 111
			35 1000000	1			400000								172.5	
8000	300	1600	1600	- 200	0	110	16	OFF	OFF	UP	DOWN	ON	ON	OTHER	36"	111
4000 4480	300 200	1700 1600	1700 1600	1	0	75 104	2 111	ON OFF	ON OFF	DOWN UP	DOWN	ON ON	ON ON	OTHER OTHER	42" 42"	111
2000	200	800	800	0	1	105	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	43"	60
4000	200	1600	1600	1	0	88	111	OFF	OFF	UP	DOWN	ON	ON	X	42"	111
4000	200	1600	1600	1	0	88	111	OFF	OFF	UP	DOWN	ON	ON	X	35"	111
2400	180	800	800	0	1	78	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	42"	80
3520	230	1600	1600	0	- 1	122	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	42"	111
3520	230	1600	1600	0	1	120	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	42"	111
3000	230	1600	1600	0	-	121	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	42"	111
2400	180	800	800	0	1	78	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	55"	80
3520	300	1700	1700	0	1	92	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	42"	111
4000	200	1600	1600	1	0	123	111	OFF	OFF	UP	DOWN	ON	ON	X	42"	111
4000	200	1600	1600	1	0	123	111	OFF	OFF	UP	DOWN	ON	ON	Х	35"	111
5000	200	1600	1600	1	0	124	111	OFF	OFF	UP	DOWN	ON	ON	Х	42"	111
5000	200	1600	1600	1	0	124	111	OFF	OFF	UP	DOWN	ON	ON	X	35"	111
2400	180	800	800	0	1	78	2	ON	ON	DOWN	DOWN	ON	ON	SUNSTAR	55"	60
4000	300	1700	1700	0	1	0	2	ON	ON	DOWN	DOWN	ON	ON	2.2.2.0.00	42"	111
4000	200	1600	1600	1	0	125	111	OFF	OFF	UP	DOWN	ON	ON	Х	42"	111
1000	200	1000	1000		v	120	teat 18	L			DOWN	OIN	UN	/\tau	.TŒ	631.31


BREAKDOWN AND TROUBLESHOOTING

If the machine breaks down while using the servo motor due to an unforseen change in the machine, the error indicators mentioned below will appear in the displayer of the program unit or simple program unit according to the self-checking function of the machine. The machine will then stop along with the sound of a warning buzzer. When an error indicator appears, follow the solution steps described below and resume work. If the problem is not solved after taking these measures, contact a company branch office.

Order	Error indicator	Cause of breakdown	Troubleshooting
1	SF22 Er	Safety switch error	Check safety switch cable and connector
2	PU26 Er	Trouble with program unit connection	Check program unit cable and connector
3	PU27 Er	Trouble with simple program unit connection	Check the simple program unit cable and connector
4	60 Er	This error sign is seen when the user connects the location sensor while the power is still on	Turn the power off and on again before using it.
5	61 Er	This error sign is seen when the user the user removes the location sensor while the power is still on	Turn the power off and on again before using it.
6	126 Er	This error sign is seen when the motor's rotor magnet and stator coil's electric current flow does not match	Check the condition of the motor's
7	127 Er	This error sign appears when the direction of encoders RST and the direction of AB do not match.	Check the encoder cable and the connector
8	128 Er	When there is no signal from encoders RST	Check the encoder cable and the connector
9	129 Er	When the motor is overloaded	Turn the machine manually and check the machine load
10	130 Er	When there is no signal from the location sensor	Check the location sensor cable and connector
11	131 Er	When there is an electric current overflow in the motor and problems with the connector	Check the motor cable and the connector
12	133 Er	When theelectric current overflow of the IPM stops	Turn the power off and on again before using it.


12

HOW TO PLACE FOR CONTROLLER



OREDER Ex. S5AC55-2AF refers to SERIES5, 1Phase 220V, FULL FUNCTION CONTROL BOX for normal drop feed.

BLOCK DIAGRAM



PARTS BOOK



A	Motor Parts 90
В	Control Box (FULL Function TYPE) 92
C	Control Box (Economic TYPE) 94
D	Pedal/Accessories 96
E	Synchronizer 98
F	Supplementary control box (KM-757/TC cap ribbon cutter) 100

• Remarks •

Please let us get the additional details according to the itemized list below for the better service when ordering spare parts for SunStar motors.


- *Order for spare parts for servo motor
 - 1) Serial number
 - 2) Type of control box & model name
 - 3) Electric specification (Phase, Volt)
 - 4) Machines's model name

NOTE: Parts are Subject to change in Design Without Prior Notice.

- 1. 조에 속한 파트는 개별 조립 시 제품의 파손 또는 재봉 불량이 발생될 수 있어 해당 파트에 대한 주문 시에는 조 품목으로만 구입이 가능합
- 2. 본 책자는 Parts Book으로 제작되었으므로 매뉴얼로 사용 불가합니다.
- 1. The parts classified as ass'y items may cause damage to the machine or bad sewing when they are separately assembled. Hence, when they are ordered, they can be purchased as ass'y items only.
- 2. This is a parts book. It cannot be used as a manual.



MOTOR PARTS






Ref No.	Parts No.	Name of Parts	Q' ty	Assembly No.
A-1	E E - 0 0 0 3 1 8 - 0 0	Motor ass' y	1	
A-2	E A - 0 0 0 0 8 2 - 0 0	Stator Assembly	1	
A-3	04-004R-SM5S	Frame Plug	1	
A-4	10-001C-SE55	Cable Guide Rubber A	1	
A-5	G P - 0 2 3 4 2 1 - 0 0	Connector (LLR-04)	1	
A-6	1 1 - 0 1 2 B - S E 5 5	S/V Earth Cable	1	
A-7	0 1 - 0 3 7 S - 1 7 0 1	Screw For Fixing Flate	1	
A-8	E A - 0 0 0 0 8 3 - 0 0	Rotor Assembly (SERVO 3)	1	
A-9	01-009A-1701	Bearing (# 6203)	1	
A-10	02-006A-SM5S	Bearing (# 6302)	1	
A-11	07-014C-3701	Bearing Bending Spring	1	
A-12	04-002A-SM5S	Frame Cover	1	
A-13	04-003S-SM5S	Screw For Frame Cover	4(Ass'y)	
A-14	G P - 0 2 3 5 3 9 - 0 0	Name Plate	1	
A-15	03-0000-SM5S	F. G Assembly	1	
A-16	03-004S-SM5S	Screw For F. G Assembly	2(Ass'y)	
A-17	B D - 0 0 0 4 1 3 - 0 0	Encoder Board	1	
A-18	07-001B-SM5S	Stud For Encoder P. C. B	3(Ass'y)	
A-19	15-122S-1000	Screw For Encoder P. C. B	3(Ass'y)	
A-20	07-005S-SM5S	Screw For MR Sensor	2	
A-21	1 4 - 0 1 9 C - S C 5 3	MR Sensor Cable Connector (4P)	1	
A-22	1 4 - 0 0 2 B - S C 5 3	MR Sensor Ass'y	1	
A-23	11-010B-SE55	Encoder Cable SE-04	1	
A-24	07-002A-SM5S	Encoder Cover	1	
A-25	07-004S-SM5S	Screw For Encoder Cover	3(Ass'y)	
A-26	08-002A-SE5S	Fan Cover	1	
A-27	09-031S-3701	Screw For Fixing Plate	3(Ass'y)	
A-28	08-001A-SM5S	FAN	1	
A-29	03-004S-SM5S	Screw For F,G Ass'y	1	
A-30	G P - 0 1 1 8 1 1 - 0 2	Base	1	
A-31	0 2 - 0 1 6 C - 1 7 0 1	Key (Parallel Type)	1	
A-32	03-004S-SM5S	Screw For F,G Ass'y	1	
A-33	G P - 0 1 1 8 1 2 - 0 0	Base Shaft	1	
A-34	0 4 - 0 0 2 B - 1 7 0 1	Base Rubber	3(Ass'y)	
A-35	91-0098-1701	Clamp Bolt	1	
A-36	04-0048-1701	Anchor Bolt (SET)	1	
A-37	06-001A-9000	Pulley- <i>ϕ</i> 111	1	
A-38	08-0178-3701	Fixing Nut For Pulley	1	
A-39	0 1 - 0 4 0 W - 1 7 0 1	Fixing Washer For Flywheel	1	
A-40	09-0398-3701	Screw For Holder	4(Ass'y)	



CONTROL BOX (FULL Function TYPE)






Ref No.	Parts No.	Name of Parts	Q' ty	Assembly No.
B-1	EE-001519-00	1- Phase 110V Control Box	1	, i
B-2	E E - 0 0 1 5 2 0 - 0 0	1- Phase 220V Control Box / 3- Phase 220V Control Box	1	
B-3	BD-000520-00	Power Board Ass'y(220V)	1 (Ass'y)	
B-3-1	11-007B-SE55	Cable For Power Input	1	
B-3-2	09-003A-SC51	Bridge Diode 3510	2	
B-4	BD-000518-00	CPU Board Ass' y	1 (Ass'y)	
B-4-1	10-009A-SF55	IPM (PM20CSJ060)	1 (Ass'y)	
B-5	EE-001523-00	S-5 P/U B/D Ass'y	1 (Ass'y)	
B-5-1	GP-024743-00	Front cover	1	
B-5-2	GP-024747-00	Membrane Switch	1	
B-5-3	20-010A-SE55	P/U Connector Cable(SE-013)	1	
B-5-4	30-001M-SE55	Screw For P/U Box	5(Ass'y)	
B-5-5	04-0000-SE55	P/U PCB Ass'y	1	
B-5-6	GP-024744-00	Rear cover	1	
B-6	10-111A-SE55	Control Box	1	
B-7	10-112A-SE55	Control Box Front Cover	1	
B-8	10-113A-SE55	Control Box Rear Cover	1	
B-9	10-008A-SE55	Solenoid Transformer S3	1	
B-10	10-004A-SE55	Control Box Left Side Cover	1	
B-11	10-005A-SE55	Control Box Right Side Cover	1	
B-12	GP-013180-01	Control Box Holder	1	
B-13	GP-023540-00	Name Panel Sticker	1	
B-14	01-003S-BT01	Warning Panel Sticker	1	
B-15	10-003C-SE55	Cable Rubber Guide	1	
B-16	01-020S-SF55	Sticker (MOTOR~INPUT)	1	
B-17	10-011C-SE55	Option Sticker	1	
B-18	12-005B-SE55	Assistance Signal Cable SE-008	1	
B-19	CA-002483-00	Cable For Motor Output SE-011	1	
B-20	11-006B-SE55	Solenoid Connection Cable SE-009	1	
B-21	CA-002487-00	Cable For DC Power SE-007	1	
B-22	12-003B-SE55	Solenoid Cable SE-006	1	
B-23	12-013B-SE55	Option Switch Connector Cable SE-014	1	
B-24	11-014B-SE55	Right & Left Switch Connector Cable SE-015	1	
B-25	09-007A-HB10	Cement Resistor (40W160 Q)	1	
B-26	11-015B-SE55	Resistant Connector SE-017	1	
B-26-1	10-002S-SW66	Screw For Pedal P. C. B	1	
B-27	10-003M-PT01	Screw Control Box Cover	4(Ass'y)	
B-29	10-003M-PT01	Screw For B-7	2(Ass'y)	
B-30	10-003M-PT01	Screw For B-8	2(Ass'y)	
B-31	10-003M-PT01	Screw For B-10	4(Ass'y)	
B-32	09-039S-3701	Screw For B-12	4(Ass'y)	
B-33	10-012M-PT10	Stude For B-3	4(Ass'y)	
B-34	10-002S-SW66	Screw For Pedal P. C. B	4(Ass'y)	
B-35	10-002S-SW66	Screw For Pedal P. C. B	5(Ass'y)	
B-36	09-226S-3701	Screw For Solenoid Transformer	4(Ass'y)	
B-37	10-012M-PT10	Stude For B-4	5(Ass'y)	
B-38	07-004S-SM55	Screw For Encoder Cover	2(Ass'y)	
B-39	15-022S-1000	Screw For Encoder Cover	2(Ass'y)	
B-40	G P - 0 2 4 7 4 6 - 0 0	Sticker (Main)	1	
B-41	10-024A-SE55	Control Box Left Side Cover - KANSAI	1	
B-42	10-034A-SE55	Control Box Left Side Cover - YAMATO	1	
B-43	10-044A-SE55	Control Box Left Side Cover - SIRUBA	1	
B-44	10-064A-SE55	Control Box Left Side Cover - KINGTEX	1 1	
B-45	10-046A-SE55	Control Box Left Side Cover - DINO Thread Trimming Machine	11	
B-46	91-031A-SE55	Connector (Other Company Type) - KANSAI	11	
B-47	91-013A-SE55	Connector (Other Company Type) - YAMATO	1	
B-48	91-008A-SE55	Connector (Other Company Type) - SIRUBA	1	
B-49	91-032A-SE55	Connector (Other Company Type) - KINGTEX	1	
B-50	91-046A-SE55	Connector (Other Company Type) - DINO Thread Trimming Machine	1	
B-51	BD-000519-00	Power Board Ass'y(110V)	1 (Ass' y)	



CONTROL BOX (Economic TYPE)






Ref No.	Parts No.	Name of Parts	Q' ty	Assembly No.
C-1	EE-001515-00	1- Phase 110V Control Box	1	,
C-1-1	EE-001516-00	1 - Phase 110V for other companies	1	
C-2	E E - 0 0 1 5 1 7 - 0 0	1- Phase 220V Control Box / 3- Phase 220V Control Box	1	
C-2-1	EE-001518-00	1- Phase 220V for other companies	1	
C-3	01-0000-SE55	Power Board Ass' y	1 (Ass' y)	
C-3-1	11-007B-SE55	Cable For Power Input	1	
C-3-2	09-003A-SC51	Bridge Diode 3510	2	
C-4	BD-000518-00	CPU Board Ass'y	1 (Ass' y)	
C-4-1	10-009A-SF55	IPM (PM20CSJ060)	1 (Ass'y)	
C-5-1	03-1000-SE55	S-5 OP PCB Ass'y	1	
C-5-2	10-006A-SE55	Control Box Display Panel	1	
C-5-3	G P - 0 2 4 7 7 5 - 0 0	Display Panel Membrane	1	
C-5-4	11 - 002 B - S E 5 5	Controller Cable(SE-002)	4(Ass'y)	
C-5-5	11-001B-SE55	Controller Cable(SE-001)	1	
C-6	10-111A-SE55	Control Box	1	
C-7	10-212A-SE55	Control Box Front Cover-Economic Type	1	
C-8	10-113A-SE55	Control Box Rear Cover	1 1	
C-9	10-008A-SE55	Solenoid Transformer S3	1	
C-10	10-004A-SE55	Control Box Left Side Cover	1 1	
C-11	10-005A-SE55	Control Box Right Side Cover	1	
C-12	10-007A-SE55	Control Box Holder	1 1	
C-13	GP-023540-00	Name Panel Sticker	1	
C-14	10-003S-BT01	Warning Panel Sticker	1	
C-15	10-003C-SE55	Cable Rubber Guide C	1	
C-16	01-020S-SF55	Sticker (MOTOR~INPUT)	1	
C-17	10-011C-SE55	Option Sticker	1	
C-18	11-005B-SE55	Assistance Signal Cable	1	
C-19	CA-002483-00	Cable For Motor Output SE-011	1	
C-20	11-006B-SE55	Solenoid Connection Cable SE-009	1	
C-21	CA-002487-00	Cable For DC Power SE-007	1	
C-22	12-003B-SE55	Solenoid Cable SE-006	1	
C-25	09-007A-HB10	Cement Resistor (40W160 ℚ)	1	
C-26	11-015B-SE55	Resistant Connector SE-017	1	
C-26-1	10-002S-SW66	Screw For Pedal P. C. B	1	
C-27	10-003M-PT01	Screw Control Box Cover	4(Ass'y)	
C-29	10-003M-PT01	Screw For C-7	2(Ass'y)	
C-30	10-003M-PT01	Screw For C-8	2(Ass'y)	
C-31	10-003M-PT01	Screw For C-10	4(Ass'y)	
C-32	09-0398-3701	Screw For C-12	4(Ass'y)	
C-33	10-012M-PT10	Stude For C-3	4(Ass'y)	
C-34	10-002S-SW66	Screw For Pedal P. C. B	5(Ass'y)	
C-35	10-002S-SW66	Screw For Pedal P. C. B	5(Ass'y)	
C-36	09-226S-3701	Screw For Solenoid Transformer	4(Ass'y)	
C-37	10-012M-PT10	Stude For C-4	5 (Ass'y)	
C-38	07-004S-SM55	Screw For Encoder Cover	2(Ass'y)	
C-39	15-0228-1000	Screw For Encoder Cover	2(Ass'y)	
C-40	GP-024746-00	Sticker (Main)	1	
C-41	10-024A-SE55	Control Box Left Side Cover - KANSAI	1	
C-42	10-034A-SE55	Control Box Left Side Cover - YAMATO	1	
C-43	10-044A-SE55	Control Box Left Side Cover - SIRUBA	1	
C-44	10-064A-SE55	Control Box Left Side Cover - KINGTEX	1 1	
C-45	10-046A-SE55	Control Box Left Side Cover - DINO Thread Trimming Machine	1 1	
C-46	91-031A-SE55	Connector (Other Company Type) - KANSAI	1 1	
C-47	91-013A-SE55	Connector (Other Company Type) - YAMATO Connector (Other Company Type) - SIRUBA	1	
C-48	91-008A-SE55	Connector (Other Company Type) - SINUBA Connector (Other Company Type) - KINGTEX	1	
C-49	91-032A-SE55	Connector (Other Company Type) - KINGTEX Connector (Other Company Type) - DINO Thread Trimming Machine	1	
C-50	91-046A-SE55	Connector (Other Company Type) - DINO Thread Triffining Machine Connector (Other Company Type)	1	
C-51	91-001A-SE55	Connector (Other Company Type)		

D


PEDAL/ACCESSORIES





D=1	Ref No.	Parts No.	Name of Parts	Q' ty	Assembly No.
D-2	D-1	06-0000-SE55	Pedal Unit Assembly	1 (Ass'y)	
D-3	D-2	06-1000-SE55		1	
D-3	D-3	12-009B-SE55		1	
D-5	D-3-1	11-017B-SE55		1	
D-6	D-4		Pedal Base	1	
D-6 0.6 0.0 1 M → S E 5 5 Scow (Set) SX10 CR 4(Assity) D-8 1.0 0.2 8 S − S F 5 Butter Cap For Petal Base 2(Assity) D-8-1 1.0 0.2 8 S − S C 5.3 Scow For Petal P. C. B Set 1 D-9 1.0 0.1 0 − 10 7 A − S C 5.3 Petal Holder 1 D-10 1.0 0.2 6 A − S C 5.3 Petal Holder 1 D-11 1.0 0.2 1 7 − S C 5.3 Petal Holder 1 D-11 1.0 0.2 1 7 − S C 5.3 Petal Holder 1 D-11 1.0 0.2 1 7 − S C 5.3 Petal Wagnet Holder 1 D-13 1.0 0.2 4 W − S C 5.3 Petal Wagnet Holder 1 D-13 1.0 0.2 7 0 − S C 5.3 Petal Wagnet Holder 1 D-13 1.0 0.2 7 0 − S C 5.3 Petal Wagnet Holder 1 D-14 1.1 0.1 2 C − S C 5.3 Petal Wagnet Holder 1 D-15 1.1 0.1 2 C − S C 5.3 Petal Wagnet Holder 1 D-16 1.0 <td>D-5</td> <td>06-001C-SE55</td> <td>Rubber Cap For Pedal Unit</td> <td>1</td> <td></td>	D-5	06-001C-SE55	Rubber Cap For Pedal Unit	1	
D-P	D-6	06-001M-SE55		4(Ass'y)	
D-8	D-7	10-033C-SF55		2(Ass'y)	
D-8-1 10 - 0.0 2 S - S W 6 6 Screw For P. C. B Set 1 D-9 1.0 - 1.0 7 A - S C 5 3 Pedal Magnet Holder 1 D-10 1.0 - 1.0 7 A - S C 5 3 Pedal Magnet Holder 1 D-11 1.0 - 0.2 7 C - S C 5 3 Pedal Magnet Holder 1 D-12 0.3 - 0.0 4 S - S M 5 8 Foing Dot For Pedal Magnet & film Base 2(Ass'y) D-13 1.0 - 0.2 4 W - S C 5 3 Pedal Magnet For Pedal Shaft 1 D-12 C - 3.7 0.1 Bushing For Pedal Control Lever Shaft 1 D-12 C - 3.7 0.1 Bushing For Pedal Control Lever Shaft 1 D-15 C - 3.7 0.1 Bushing For Pedal Control Lever Shaft 1 D-15 C - 3.7 0.1 Bushing For Pedal Control Lever Shaft 1 D-16 1.0 - 0.1 8 G - S C 5 3 Tenson Spring For Pedal Control Lever Shaft 1 D-16 D-15 C - 3.7 0.1 Bushing For Pedal Control Lever Shaft 1 D-16 D-16 C - 3.7 0.1 Bushing For Pedal Control Lever Shaft 1 D-17 C - 3.7 0.1 Bushing For Pedal Control Lever Shaft 1 D-18 D-18	D-8	10-028S-SC53		2	
D−9 1 0 − 10 7 A − S ∈ S ∈ S Pedal Control Lever 1 D−10 1 0 − 0 2 6 A − S ∈ S ∈ S Petal Magnet Holder 1 D−11 1 0 − 0 2 7 C − S ∈ S ∈ S Petal Magnet 1 D−12 0 3 − 0 0 4 S − S M ∈ S Petal Magnet 1 D−13 1 0 − 0 2 4 W − S ∈ S ∈ S Parallel Washer For Petal Shaft 1 D−14 1 1 − 0 1 2 C − 3 7 0 1 Bushing For Petal Control Lever Shaft 1 D−16 1 1 − 0 1 2 C − 3 7 0 1 Bushing For Petal Control Lever Shaft 1 D−16 1 0 − 0 1 8 G − S ∈ S ∈ S ∈ S ∈ S ∈ S ∈ S ∈ S ∈ S ∈ S	D-8-1	10-002S-SW66	Screw For P. C. B Set	1	
D-10	D-9			1	
D-11	D-10	10-026A-SC53	Pedal Magnet Holder	1	
D-13	D-11	10-027C-SC53	Pedal Magnet	1	
D-H	D-12	03-004S-SM5S	Fixing Bolt For Pedal Magnet & film Base	2(Ass'y)	
D-15	D-13	10-024W-SC53	Parallel Washer For Pedal Shaft	1	
D=15	D-14	11-012C-3701	Bushing For Pedal Control Lever Shaft	1	
D-16 1 0 − 0 1 8 G − S C 5 3 Tension Spring For Pedal 1 D-17 0 3 − 0 0 4 S − S M 5 S Fixing Bolt For Pedal Control Lever 1 D-18 1 0 − 0 3 0 P − S C 5 3 Stopper (B) For Pressure Spring 1 D-19 1 0 − 0 2 9 P − S C 5 3 Stopper (A) For Pressure Spring 1 D-20 1 0 − 0 1 9 G − S C 5 3 Pressure Spring For For Persser Foot 1 D-21 1 0 − 0 2 5 P − S C 5 3 Spring Guide (B) 1 D-22 1 0 − 0 2 5 P − S C 5 3 Spring Guide (B) 1 D-23 1 0 − 0 2 4 P − S C 5 3 Spring Guide (B) 1 D-24 1 0 − 0 3 1 S − S C 5 3 Spring Guide (B) 1 D-24 1 0 − 0 2 1 S − S C 5 3 Spring Guide (B) 1 D-24 1 0 − 0 2 1 S − S C 5 3 Spring Guide (B) 1 D-26 1 0 − 0 1 6 A − S C 5 3 Spring Guide (B) 1 D-27 1 8 − 0 1 6 S − 5 6 0 7 Nut For DS1 1 D-28 2 0 − 1 0 6 C − 6 1 0 0 Sticker For Jo S C S S S S S S S S S S S S S S S S S	D-15			1	
D-17				1	
D-18				1	
D−39 1.0 − 0.2 9 P − S C 5 3 Stopper (A) For Pressure Spring 1 D−20 1.0 − 0.1 9 G − S C 5 3 Pressure Spring For Presser Foot 1 D−21 1.0 − 0.2 1 0 − 0.2 5 P − S C 5 3 Pressure Spring For Thread Trimming 1 D−22 1.0 − 0.2 4 P − S C 5 3 Spring Guide (B) 1 D−24 1.0 − 0.2 4 P − S C 5 3 Spring Guide (A) 1 D−24 1.0 − 0.2 4 P − S C 5 3 Spring Guide (A) 1 D−24 1.0 − 0.2 4 P − S C 5 3 Spring Housing 2(Ass'y) D−26 1.0 − 0.2 4 P − S C 5 3 Spring Housing 1 D−27 1.8 − 0.1 6 S − 5 6 0.7 Nut For D51 1 D−28 1.0 − 0.1 6 A − S C 5 3 Pressure Control Screw For Spring(Ass'y) 2(Ass'y) D−29 1.8 − 0.1 6 S − 5 6 0.7 Nut For D51 1 D−28 1.9 − 1 0.1 6 A − 5 C 5.3 Sticker For auto Knee Lifting Solenoid 1 D−3 1.9 1 − 0.1 A − 3 7 0.1 Sticker For auto Knee Lifting Solenoid 1 D−3 1.9 1 − 0.1 A − 3 7 0.1 Self Cover (B) 1 D−3 <td>D-18</td> <td></td> <td></td> <td>1</td> <td></td>	D-18			1	
D-21	D-19			1	
D-21		10-019G-SC53		1	
D−22 1 0 − 0 2 5 P − S C 5 3 Spring Guide (B) 1 D−24 1 0 − 0 2 4 P − S C 5 3 Spring Guide (A) 1 D−24 1 0 − 0 1 6 A − S C 5 3 Spring Housing 2(Ass'y) D−26 1 0 − 0 2 1 S − S C 5 3 Spring Housing 1 D−26 1 0 − 0 2 1 S − S C 5 3 Spring Housing 1 D−27 1 8 − 0 1 6 S − 5 6 0 7 Nut For D51 1 D−28 2 0 − 1 0 6 C − 6 1 0 0 Sticker For auto Knee Lifting Solenoid 1 D−28 2 0 − 1 0 6 C − 6 1 0 0 Sticker For auto Knee Lifting Solenoid 1 D−23 1 8 − 0 2 9 C − 5 6 0 7 Belt Cover (B) 1 D−31 9 1 − 0 0 1 A − 3 7 0 1 Belt Cover (B) 1 D−32 9 1 − 0 0 1 A − 3 7 0 1 Belt Cover (New Type) (A) 1 D−33 9 1 − 0 0 1 A − 3 7 0 1 Screw For Belt Guide 1 D−34 0 7 − 0 2 7 S − 3 7 0 1 Screw For Belt Cover (B) 2 D−35 0 1 − 1 3 5 S − 1 7 0 1 Screw For Belt Cover (B) 2 D−36 9 1 − 0 2 9 S − 1 0 0 0 Scre				1	
D-24	D-22			1	
D-24				1	
D−25 1 0 − 0 1 6 A − S C 5 3 Spring Housing 1 D−26 1 0 − 0 2 1 S − S C 5 3 Pressure Control Screw For Spring(Ass'y) 2(Ass'y) D−27 1 8 − 0 1 6 S − 5 6 0 7 Nut For D51 1 D−28 2 0 − 1 0 6 C − 6 1 0 0 Sticker For auto Knee Lifting Solenoid 1 D−29 1 8 − 0 2 9 C − 5 6 0 7 Guide Bushing for Cable 1 D−30 9 1 − 0 0 1 A − 3 7 0 1 Belt Cover (R) 1 D−31 9 1 − 0 0 1 A − 3 7 0 1 Belt Cover (New Type) (A) 1 D−32 9 1 − 0 0 4 C − S A 5 3 SV Belt Guide 1 D−33 9 0 − 3 1 S − 3 7 0 1 Screw For Belt Guide 1 D−34 0 7 − 0 2 7 S − 3 7 0 1 Screw For Belt Cover (A) 2 D−35 0 1 − 1 3 5 S − 1 7 0 1 Screw For Belt Cover (B) 2 D−36 0 1 − 0 3 9 W − 1 7 0 1 Spring Washer For P/U Box Bracket 2(Ass'y) D−37 0 1 − 0 3 9 W − 1 7 0 1 Spring Washer For P/U Box 3(Ass'y) D−38 9 1 − 0 2 0 A − S E 5 5 Bracket For P/U Box 1 D−40	D-24	10-031S-SC53	Screw For Spring Housing	2(Ass'y)	
D−27	D-25	10-016A-SC53		1	
D-28	D-26	10-021S-SC53	Pressure Control Screw For Spring(Ass'y)	2(Ass'y)	
D-29	D-27	18-016S-5607	Nut For D51	1	
D−30 9 1 − 0 0 1 A − 3 7 0 1 Belt Cover (B) 1 D−31 9 1 − 1 0 1 A − S A 5 3 Belt Cover (New Type) (A) 1 D−32 9 1 − 0 0 4 C − S A 5 3 SVP Belt Guide 1 D−33 0 9 − 0 3 1 S − 3 7 0 1 Screw For Belt Guide 1 D−34 0 7 − 0 2 7 S − 3 7 0 1 Screw For Belt Cover (A) 2 D−35 0 1 − 1 3 5 S − 1 7 0 1 Screw For PVI Box 3(Ass'y) D−36 9 1 − 0 2 9 S − 1 0 0 0 Screw For PVI Box 3(Ass'y) D−37 0 1 − 0 3 9 W − 1 7 0 1 Spring Washer For PVI Box 2(Ass'y) D−39 9 1 − 0 3 0 S − 1 0 0 0 Screw For PVI Box Bracket 2(Ass'y) D−39 9 1 − 1 0 0 A − S E 5 5 Bracket For PVI Box Bracket 1 D−40 9 1 − 2 0 0 A − S E 5 5 Bracket For PVI Box 1 D−41 1 8 − 1 0 7 B − 9 0 0 0 Auto Knee Lifter Solenoid Case 1 D−42 1 8 − 1 0 8 B − 9 0 0 0 Auto Knee Lifter Solenoid Cover 1 D−43 1 8 − 1 0 9 B − 9 0 0 0 Fixer For Stroke 1 D−44 1	D-28	20-106C-6100	Sticker For auto Knee Lifting Solenoid	1	
D−31 9 1 − 1 0 1 A − S A 5 3 Belt Cover (New Type) (A) 1 D−32 9 1 − 0 0 4 C − S A 5 3 SV Belt Guide 1 D−33 0 9 − 0 3 1 S − 3 7 0 1 Screw For Belt Guide 1 D−36 0 1 − 1 3 5 S − 1 7 0 1 Screw For Belt Cover (B) 2 D−36 0 1 − 1 3 5 S − 1 7 0 1 Screw For Belt Cover (B) 2 D−37 0 1 − 0 3 9 W − 1 7 0 1 Spring Washer For P/U Box 3(Ass' y) D−37 0 1 − 0 3 0 S − 1 0 0 0 Screw For P/U Box 2(Ass' y) D−39 9 1 − 1 0 0 A − S E 5 5 Bracket For P/U Box 1 D−39 9 1 − 1 0 0 A − S E 5 5 Bracket For P/U Box 1 D−40 9 1 − 2 0 0 A − S E 5 5 Bracket For P/U Box 1 D−41 1 8 − 1 0 7 B − 9 0 0 0 Auto Knee Lifter Solenoid Case 1 D−42 1 8 − 1 0 8 B − 9 0 0 0 Auto Knee Lifter Solenoid Cover 1 D−43 1 8 − 1 0 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D−44 1 8 − 0 1 8 B − 9 0 0 0 Fixing Plate For Stroke 1 D−45 1 7 −	D-29	18-029C-5607	Guide Bushing for Cable	1	
D-32 9 1 − 0 0 4 C − S A 5 3 SV Belt Guide 1 D-33 0 9 − 0 3 1 S − 3 7 0 1 Screw For Belt Guide 1 D-34 0 7 − 0 2 7 S − 3 7 0 1 Screw For Belt Cover (A) 2 D-36 0 1 − 1 3 5 S − 1 7 0 1 Screw For Belt Cover (B) 2 D-36 9 1 − 0 2 9 S − 1 0 0 0 Screw For P/U Box 3(Ass'y) D-37 0 1 − 0 3 9 W − 1 7 0 1 Spring Washer For P/U Box Bracket 2(Ass'y) D-38 9 1 − 0 3 0 S − 1 0 0 0 Screw For P/U Box Bracket 2(Ass'y) D-39 9 1 − 1 0 0 A − S E 5 5 Bracket For P/U Box 1 D-40 9 1 − 2 0 0 A − S E 5 5 Bracket For P/U Box 1 D-41 1 8 − 1 0 8 B − 9 0 0 0 Auto Kinee Lifter Solenoid Case 1 D-42 1 8 − 1 0 8 B − 9 0 0 0 Fixing Plate For Stroke 1 D-43 1 8 − 1 0 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D-44 1 8 − 0 1 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D-45 1 7 − 0 1 7 C − 3 0 0 0 Stopper Rubber D-46 0 1 − 1 3 4 C − 1 7 0 1<	D-30	91-001A-3701	Belt Cover (B)	1	
D-33 0 9 − 0 3 1 S − 3 7 0 1 Screw For Belt Guide 1 D-34 0 7 − 0 2 7 S − 3 7 0 1 Screw For Belt Cover (A) 2 D-35 0 1 − 1 3 5 S − 1 7 0 1 Screw For Belt Cover (B) 2 D-36 9 1 − 0 2 9 S − 1 0 0 0 Screw For Belt Cover (B) 2 D-37 0 1 − 0 3 9 W − 1 7 0 1 Spring Washer For P/U Box 3(Ass'y) D-38 9 1 − 0 3 0 S − 1 0 0 0 Screw For P/U Box Bracket 2(Ass'y) D-39 9 1 − 1 0 0 A − S E 5 5 Bracket For P/U Box 1 D-40 9 1 − 2 0 0 A − S E 5 5 Bracket For P/U Box 1 D-41 1 8 − 1 0 7 B − 9 0 0 0 Auto Knee Lifter Solenoid Case 1 D-42 1 8 − 1 0 8 B − 9 0 0 0 Auto Knee Lifter Solenoid Cover 1 D-43 1 8 − 1 0 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D-44 1 8 − 0 2 3 R − 5 6 0 7 Rubber Washer 1 D-45 1 7 − 0 1 7 C − 3 0 0 0 Stopper Rubber 1 D-46 0 1 − 1 3 4 C − 1 7 0 1 Screw For D-43 2(Ass'y) D-47 1 2 − 0	D-31	91-101A-SA53	Belt Cover (New Type) (A)	1	
D−34 0 7 − 0 2 7 S − 3 7 0 1 Screw For Belt Cover (A) 2 D−35 0 1 − 1 3 5 S − 1 7 0 1 Screw For Belt Cover (B) 2 D−36 9 1 − 0 2 9 S − 1 0 0 0 Screw For P/U Box 3(Ass'y) D−37 0 1 − 0 3 9 W − 1 7 0 1 Spring Washer For P/U Box Bracket 2(Ass'y) D−39 9 1 − 1 0 0 A − S E 5 5 Bracket For P/U Box 1 D−39 9 1 − 2 0 0 A − S E 5 5 Bracket For 250 P/U Box 1 D−40 9 1 − 2 0 0 A − S E 5 5 Bracket For 250 P/U Box 1 D−41 1 8 − 1 0 7 B − 9 0 0 0 Auto Knee Lifter Solenoid Case 1 D−42 1 8 − 1 0 8 B − 9 0 0 0 Auto Knee Lifter Solenoid Cover 1 D−43 1 8 − 1 0 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D−44 1 8 − 0 2 3 R − 5 6 0 7 Rubber Washer 1 D−45 1 7 − 0 1 7 C − 3 0 0 0 Stopper Rubber 1 D−46 0 1 − 1 3 4 C − 1 7 0 1 Screw For D−43 2(Ass'y) D−47 1 2 − 0 1 5 M − 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D−48	D-32	91-004C-SA53	S/V Belt Guide	1	
D-36 0 1 − 1 3 5 5 − 1 7 0 1 Screw For Belt Cover (B) 2 D-36 9 1 − 0 2 9 S − 1 0 0 0 Screw For P/U Box 3(Ass'y) D-37 0 1 − 0 3 9 W − 1 7 0 1 Spring Washer For P/U box Bracket 2(Ass'y) D-38 9 1 − 0 3 0 S − 1 0 0 0 Screw For P/U Box Bracket 2(Ass'y) D-39 9 1 − 1 0 0 A − S E 5 5 Bracket For 2/D Box 1 D-40 9 1 − 2 0 0 A − S E 5 5 Bracket For 2/D Box 1 D-41 1 8 − 1 0 7 B − 9 0 0 0 Auto Knee Lifter Solenoid Case 1 D-42 1 8 − 1 0 9 B − 9 0 0 0 Auto Knee Lifter Solenoid Cover 1 D-43 1 8 − 1 0 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D-43 1 8 − 1 0 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D-44 1 8 − 0 2 3 R − 5 6 0 7 Rubber Washer 1 D-45 1 7 − 0 1 7 C − 3 0 0 0 Screw For D-43 2(Ass'y) D-47 1 2 − 0 1 5 M − 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D-48 0 2 − 0 0 1 A − S M 5 C Cable For Auto Knee Lifting Solenoid 1 <t< td=""><td>D-33</td><td></td><td>Screw For Belt Guide</td><td>1</td><td></td></t<>	D-33		Screw For Belt Guide	1	
D−36 9 1 − 0 2 9 S − 1 0 0 0 Screw For P/U Box 3(Ass'y) D−37 0 1 − 0 3 9 W − 1 7 0 1 Spring Washer For P/U box Bracket 2(Ass'y) D−38 9 1 − 0 3 0 S − 1 0 0 0 Screw For P/U Box 1 D−39 9 1 − 1 0 0 A − S E 5 5 Bracket For P/U Box 1 D−40 9 1 − 2 0 0 A − S E 5 5 Bracket For 250 P/U Box 1 D−41 1 8 − 1 0 7 B − 9 0 0 0 Auto Knee Lifter Solenoid Case 1 D−42 1 8 − 1 0 8 B − 9 0 0 0 Auto Knee Lifter Solenoid Cover 1 D−43 1 8 − 1 0 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D−43 1 8 − 1 0 7 C − 3 0 0 0 Stopper Rubber 1 D−44 1 8 − 0 2 3 R − 5 6 0 7 Rubber Washer 1 D−45 1 7 − 0 1 7 C − 3 0 0 0 Stopper Rubber 1 D−46 0 1 − 1 3 4 C − 1 7 0 1 Screw For D−43 2(Ass'y) D−47 1 2 − 0 1 5 M − 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D−48 0 2 − 0 0 1 A − S M 5 C Earth Cale For Auto Knee Lifting Solenoid 1 D−50			Screw For Belt Cover (A)		
D-37 0 1 − 0 3 9 W − 1 7 0 1 Spring Washer For P/U box Bracket 2(Ass'y) D-38 9 1 − 0 3 0 S − 1 0 0 0 Screw For P/U Box Bracket 2(Ass'y) D-9 9 1 − 1 0 0 A − S E 5 5 Bracket For P/U Box 1 D-40 9 1 − 2 0 0 A − S E 5 5 Bracket For P/U Box 1 D-41 1 8 − 1 0 7 B − 9 0 0 0 Auto Knee Lifter Solenoid Case 1 D-42 1 8 − 1 0 9 B − 9 0 0 0 Auto Knee Lifter Solenoid Cover 1 D-43 1 8 − 1 0 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D-44 1 8 − 0 2 3 R − 5 6 0 7 Rubber Washer 1 D-45 1 7 − 0 1 7 C − 3 0 0 0 Stopper Rubber 1 D-45 1 7 − 0 1 3 4 C − 1 7 0 1 Screw For D-43 2(Ass'y) D-47 1 2 − 0 1 5 M − 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D-48 0 2 − 0 0 1 A − S M 5 C Earth Cale For Auto Knee Lifting Solenoid 1 D-49 1 7 − 0 1 6 B − 3 0 0 0 Plug For Auto Knee Lifting Solenoid 1 D-50 0 8 − 0 1 4 C − 3 7 0 1 Tube For Cable 1	D-35		Screw For Belt Cover (B)		
D−38 9 1 − 0 3 0 S − 1 0 0 0 Screw For P/U Box Bracket 2(Ass'y) D−39 9 1 − 1 0 0 A − S E 5 5 Bracket For P/U Box 1 D−40 9 1 − 2 0 0 A − S E 5 5 Bracket For P/U Box 1 D−41 1 8 − 1 0 7 B − 9 0 0 0 Auto Knee Lifter Solenoid Case 1 D−41 1 8 − 1 0 8 B − 9 0 0 0 Auto Knee Lifter Solenoid Cose 1 D−42 1 8 − 1 0 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D−43 1 8 − 1 0 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D−44 1 8 − 0 2 3 R − 5 6 0 7 Rubber Washer 1 D−45 1 7 − 0 1 7 C − 3 0 0 0 Stopper Rubber 1 D−46 0 1 − 1 3 4 C − 1 7 0 1 Screw For D-43 2(Ass'y) D−47 1 2 − 0 1 5 M − 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D−49 0 2 − 0 0 1 A − S M 5 C Earth Cale For Auto Knee Lifting Solenoid 1 D−49 1 7 − 0 1 6 B − 3 0 0 0 Plug For Auto Knee Lifting Solenoid 1 D−50 0 8 − 0 1 4 C − 3 7 0 1 Tube For Cable 1 D−51 </td <td>D-36</td> <td>91-0298-1000</td> <td></td> <td></td> <td></td>	D-36	91-0298-1000			
D−39 9 1 − 1 0 0 A − S E 5 5 Bracket For P/U Box 1 D−40 9 1 − 2 0 0 A − S E 5 5 Bracket For 250 P/U Box 1 D−41 1 8 − 1 0 7 B − 9 0 0 0 Auto Knee Lifter Solenoid Case 1 D−42 1 8 − 1 0 8 B − 9 0 0 0 Auto Knee Lifter Solenoid Cover 1 D−43 1 8 − 1 0 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D−44 1 8 − 0 2 3 R − 5 6 0 7 Rubber Washer 1 D−45 1 7 − 0 1 7 C − 3 0 0 0 Stopper Rubber 1 D−45 1 7 − 0 1 5 M − 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D−47 1 2 − 0 1 5 M − 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D−48 0 2 − 0 0 1 A − S M 5 C Earth Cale For Auto Knee Lifting Solenoid 1 D−49 1 7 − 0 1 6 B − 3 0 0 0 Plug For Auto Knee Lifting Solenoid 1 D−50 0 8 − 0 1 4 C − 3 7 0 1 Tube For Cable 1 D−51 2 5 − 0 0 6 A − 3 2 0 0 Knee for Cable 1 D−53 1 8 − 0 1 5 S − 5 6 0 7 Ball Joint (connecting Rod 1 D			Spring Washer For P/U box Bracket	2(Ass'y)	
D-40 9 1 − 2 0 0 A − S E 5 5 Bracket For 250 P/U Box 1 D−41 1 8 − 1 0 7 B − 9 0 0 0 Auto Knee Lifter Solenoid Case 1 D−42 1 8 − 1 0 8 B − 9 0 0 0 Auto Knee Lifter Solenoid Cover 1 D−43 1 8 − 1 0 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D−44 1 8 − 0 2 3 R − 5 6 0 7 Rubber Washer 1 D−45 1 7 − 0 1 7 C − 3 0 0 0 Stopper Rubber 1 D−46 0 1 − 1 3 4 C − 1 7 0 1 Screw For D-43 2(Ass'y) D−47 1 2 − 0 1 5 M − 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D−48 0 2 − 0 0 1 A − S M 5 C Earth Cale For Auto Knee Lifting Solenoid 1 D−49 1 7 − 0 1 6 B − 3 0 0 0 Plug For Auto Knee Lifting Solenoid 1 D−50 0 8 − 0 1 4 C − 3 7 0 1 Tube For Cable 1 D−51 2 5 − 0 0 6 A − 3 2 0 0 Knee for Cable 1 D−52 1 8 − 0 1 5 S − 5 6 0 7 Ball Joing (Right) 1 D−53 1 8 − 0 1 8 B − 5 6 0 7 Nut (L) for D-54 1 D−56 1 8 −	D-38		Screw For P/U Box Bracket	2(Ass'y)	
D−41 1 8 − 1 0 7 B − 9 0 0 0 Auto Knee Lifter Solenoid Case 1 D−42 1 8 − 1 0 8 B − 9 0 0 0 Auto Knee Lifter Solenoid Cover 1 D−43 1 8 − 1 0 9 B − 9 0 0 0 Fixing Plate For Stroke 1 D−44 1 8 − 0 2 3 R − 5 6 0 7 Rubber Washer 1 D−45 1 7 − 0 1 7 C − 3 0 0 0 Stopper Rubber 1 D−46 0 1 − 1 3 4 C − 1 7 0 1 Screw For D-43 2(Ass'y) D−47 1 2 − 0 1 5 M − 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D−48 0 2 − 0 0 1 A − S M 5 C Earth Cale For Auto Knee Lifting Solenoid 1 D−49 1 7 − 0 1 6 B − 3 0 0 0 Plug For Auto Knee Lifting Solenoid 1 D−50 0 8 − 0 1 4 C − 3 7 0 1 Tube For Cable 1 D−51 2 5 − 0 0 6 A − 3 2 0 0 Knee for Cable 1 D−52 1 8 − 0 2 1 A − 5 6 0 7 Ball Joing (Right) 1 D−53 1 8 − 0 1 6 S − 5 6 0 7 Ball Joint connecting Rod 1 D−56 1 8 − 0 1 6 S − 5 6 0 7 Ball Joint (Left) 1 D−58 1	D-39		Bracket For P/U Box	1	
D-42 1 8 - 1 0 8 B - 9 0 0 0 Auto Knee Lifter Solenoid Cover 1 D-43 1 8 - 1 0 9 B - 9 0 0 0 Fixing Plate For Stroke 1 D-44 1 8 - 0 2 3 R - 5 6 0 7 Rubber Washer 1 D-45 1 7 - 0 1 7 C - 3 0 0 0 Stopper Rubber 1 D-46 0 1 - 1 3 4 C - 1 7 0 1 Screw For D-43 22(Ass'y) D-47 1 2 - 0 1 5 M - 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D-48 0 2 - 0 0 1 A - S M 5 C Earth Cale For Auto Knee Lifting Solenoid 1 D-49 1 7 - 0 1 6 B - 3 0 0 0 Plug For Auto Knee Lifting Solenoid 1 D-50 0 8 - 0 1 4 C - 3 7 0 1 Tube For Cable 1 D-51 2 5 - 0 0 6 A - 3 2 0 0 Knee for Cable 1 D-52 1 8 - 0 2 1 A - 5 6 0 7 Ball Joing (Right) 1 D-53 1 8 - 0 1 6 S - 5 6 0 7 Nut (L) for D-54 1 D-54 1 8 - 0 1 6 S - 5 6 0 7 Ball Joint (Left) 1 D-55 1 8 - 0 1 1 B - 5 6 0 7 Ball Joint (Left) 1 D-56 1 8 - 0 1 1 B - 5 6 0 7<				1	
D-43 1 8 - 1 0 9 B - 9 0 0 0 Fixing Plate For Stroke 1 D-44 1 8 - 0 2 3 R - 5 6 0 7 Rubber Washer 1 D-45 1 7 - 0 1 7 C - 3 0 0 0 Stopper Rubber 1 D-46 0 1 - 1 3 4 C - 1 7 0 1 Screw For D-43 2(Ass'y) D-47 1 2 - 0 1 5 M - 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D-48 0 2 - 0 0 1 A - S M 5 C Earth Cale For Auto Knee Lifting Solenoid 1 D-49 1 7 - 0 1 6 B - 3 0 0 0 Plug For Auto Knee Lifting Solenoid 1 D-50 0 8 - 0 1 4 C - 3 7 0 1 Tube For Cable 1 D-51 2 5 - 0 0 6 A - 3 2 0 0 Knee for Cable 1 D-52 1 8 - 0 2 1 A - 5 6 0 7 Ball Joing (Right) 1 D-53 1 8 - 0 1 8 B - 5 6 0 7 Nut (L) for D-54 1 D-55 1 8 - 0 1 6 S - 5 6 0 7 Ball Joint (Left) 1 D-56 1 8 - 0 1 1 B - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 1 9 S - 5 6 0 7 Nut For D-57 Nut For D-57 1				1	
D-44 1 8 - 0 2 3 R - 5 6 0 7 Rubber Washer 1 D-45 1 7 - 0 1 7 C - 3 0 0 0 Stopper Rubber 1 D-46 0 1 - 1 3 4 C - 1 7 0 1 Screw For D-43 2(Ass'y) D-47 1 2 - 0 1 5 M - 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D-48 0 2 - 0 0 1 A - S M 5 C Earth Cale For Auto Knee Lifting Solenoid 1 D-49 1 7 - 0 1 6 B - 3 0 0 0 Plug For Auto Knee Lifting Solenoid 1 D-50 0 8 - 0 1 4 C - 3 7 0 1 Tube For Cable 1 D-51 2 5 - 0 0 6 A - 3 2 0 0 Knee for Cable 1 D-52 1 8 - 0 2 1 A - 5 6 0 7 Ball Joing (Right) 1 D-53 1 8 - 0 1 8 B - 5 6 0 7 Nut (L) for D-54 1 D-54 1 8 - 0 1 6 S - 5 6 0 7 Ball Joint connecting Rod 1 D-55 1 8 - 0 1 6 S - 5 6 0 7 Ball Joint (Left) 1 D-57 1 8 - 0 1 1 B - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 1 9 S - 5 6 0 7 Nut For D-57 Nut For D-57 1				1	
D-45 1 7 - 0 1 7 C - 3 0 0 0 Stopper Rubber 1 D-46 0 1 - 1 3 4 C - 1 7 0 1 Screw For D-43 2(Ass'y) D-47 1 2 - 0 1 5 M - 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D-48 0 2 - 0 0 1 A - S M 5 C Earth Cale For Auto Knee Lifting Solenoid 1 D-49 1 7 - 0 1 6 B - 3 0 0 0 Plug For Auto Knee Lifting Solenoid 1 D-50 0 8 - 0 1 4 C - 3 7 0 1 Tube For Cable 1 D-51 2 5 - 0 0 6 A - 3 2 0 0 Knee for Cable 1 D-52 1 8 - 0 2 1 A - 5 6 0 7 Ball Joing (Right) 1 D-53 1 8 - 0 1 5 S - 5 6 0 7 Nut (L) for D-54 1 D-54 1 8 - 0 1 8 B - 5 6 0 7 Ball Joint connecting Rod 1 D-55 1 8 - 0 1 6 S - 5 6 0 7 Ball Joint (Left) 1 D-57 1 8 - 0 1 1 B - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 9 S - 5 6 0 7 Nut For D-57 1				1	
D-46 0 1 - 1 3 4 C - 1 7 0 1 Screw For D-43 2(Ass'y) D-47 1 2 - 0 1 5 M - 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D-48 0 2 - 0 0 1 A - S M 5 C Earth Cale For Auto Knee Lifting Solenoid 1 D-49 1 7 - 0 1 6 B - 3 0 0 0 Plug For Auto Knee Lifting Solenoid 1 D-50 0 8 - 0 1 4 C - 3 7 0 1 Tube For Cable 1 D-51 2 5 - 0 0 6 A - 3 2 0 0 Knee for Cable 1 D-52 1 8 - 0 2 1 A - 5 6 0 7 Ball Joing (Right) 1 D-53 1 8 - 0 1 5 S - 5 6 0 7 Nut (L) for D-54 1 D-54 1 8 - 0 1 8 B - 5 6 0 7 Ball Joint connecting Rod 1 D-55 1 8 - 0 1 6 S - 5 6 0 7 Nut (R) For D-54 1 D-56 1 8 - 0 1 1 B - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 9 S - 5 6 0 7 Nut For D-57 1				1	
D-47 1 2 - 0 1 5 M - 2 3 5 0 Cable For Auto Knee Lifting Solenoid 1 D-48 0 2 - 0 0 1 A - S M 5 C Earth Cale For Auto Knee Lifting Solenoid 1 D-49 1 7 - 0 1 6 B - 3 0 0 0 Plug For Auto Knee Lifting Solenoid 1 D-50 0 8 - 0 1 4 C - 3 7 0 1 Tube For Cable 1 D-51 2 5 - 0 0 6 A - 3 2 0 0 Knee for Cable 1 D-52 1 8 - 0 2 1 A - 5 6 0 7 Ball Joing (Right) 1 D-53 1 8 - 0 1 5 S - 5 6 0 7 Nut (L) for D-54 1 D-54 1 8 - 0 1 8 B - 5 6 0 7 Ball Joint connecting Rod 1 D-55 1 8 - 0 1 6 S - 5 6 0 7 Nut (R) For D-54 1 D-56 1 8 - 0 2 0 A - 5 6 0 7 Ball Joint (Left) 1 D-57 1 8 - 0 1 1 8 - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 9 S - 5 6 0 7 Nut For D-57 1				1	
D-48 0 2 - 0 0 1 A - S M 5 C Earth Cale For Auto Knee Lifting Solenoid 1 D-49 1 7 - 0 1 6 B - 3 0 0 0 Plug For Auto Knee Lifting Solenoid 1 D-50 0 8 - 0 1 4 C - 3 7 0 1 Tube For Cable 1 D-51 2 5 - 0 0 6 A - 3 2 0 0 Knee for Cable 1 D-52 1 8 - 0 2 1 A - 5 6 0 7 Ball Joing (Right) 1 D-53 1 8 - 0 1 5 S - 5 6 0 7 Nut (L) for D-54 1 D-54 1 8 - 0 1 8 B - 5 6 0 7 Ball Joint connecting Rod 1 D-55 1 8 - 0 1 6 S - 5 6 0 7 Nut (R) For D-54 1 D-56 1 8 - 0 2 0 A - 5 6 0 7 Ball Joint (Left) 1 D-57 1 8 - 0 1 1 B - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 9 S - 5 6 0 7 Nut For D-57 1				2(Ass'y)	
D-49 1 7 - 0 1 6 B - 3 0 0 0 Plug For Auto Knee Lifting Solenoid 1 D-50 0 8 - 0 1 4 C - 3 7 0 1 Tube For Cable 1 D-51 2 5 - 0 0 6 A - 3 2 0 0 Knee for Cable 1 D-52 1 8 - 0 2 1 A - 5 6 0 7 Ball Joing (Right) 1 D-53 1 8 - 0 1 5 S - 5 6 0 7 Nut (L) for D-54 1 D-54 1 8 - 0 1 8 B - 5 6 0 7 Ball Joint connecting Rod 1 D-55 1 8 - 0 1 6 S - 5 6 0 7 Nut (R) For D-54 1 D-56 1 8 - 0 2 0 A - 5 6 0 7 Ball Joint (Left) 1 D-57 1 8 - 0 1 1 8 - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 9 S - 5 6 0 7 Nut For D-57 1				1	
D-50 0 8 - 0 1 4 C - 3 7 0 1 Tube For Cable 1 D-51 2 5 - 0 0 6 A - 3 2 0 0 Knee for Cable 1 D-52 1 8 - 0 2 1 A - 5 6 0 7 Ball Joing (Right) 1 D-53 1 8 - 0 1 5 S - 5 6 0 7 Nut (L) for D-54 1 D-54 1 8 - 0 1 8 B - 5 6 0 7 Ball Joint connecting Rod 1 D-55 1 8 - 0 1 6 S - 5 6 0 7 Nut (R) For D-54 1 D-56 1 8 - 0 2 0 A - 5 6 0 7 Ball Joint (Left) 1 D-57 1 8 - 0 1 1 B - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 9 S - 5 6 0 7 Nut For D-57 1				1	
D-51 2 5 - 0 0 6 A - 3 2 0 0 Knee for Cable 1 D-52 1 8 - 0 2 1 A - 5 6 0 7 Ball Joing (Right) 1 D-53 1 8 - 0 1 5 S - 5 6 0 7 Nut (L) for D-54 1 D-54 1 8 - 0 1 8 B - 5 6 0 7 Ball Joint connecting Rod 1 D-55 1 8 - 0 1 6 S - 5 6 0 7 Nut (R) For D-54 1 D-56 1 8 - 0 2 0 A - 5 6 0 7 Ball Joint (Left) 1 D-57 1 8 - 0 1 1 B - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 9 S - 5 6 0 7 Nut For D-57 1				1	
D-52 1 8 - 0 2 1 A - 5 6 0 7 Ball Joing (Right) 1 D-53 1 8 - 0 1 5 S - 5 6 0 7 Nut (L) for D-54 1 D-54 1 8 - 0 1 8 B - 5 6 0 7 Ball Joint connecting Rod 1 D-55 1 8 - 0 1 6 S - 5 6 0 7 Nut (R) For D-54 1 D-56 1 8 - 0 2 0 A - 5 6 0 7 Ball Joint (Left) 1 D-57 1 8 - 0 1 1 B - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 9 S - 5 6 0 7 Nut For D-57 1				1	
D-53 1 8 - 0 1 5 S - 5 6 0 7 Nut (L) for D-54 1 D-54 1 8 - 0 1 8 B - 5 6 0 7 Ball Joint connecting Rod 1 D-55 1 8 - 0 1 6 S - 5 6 0 7 Nut (R) For D-54 1 D-56 1 8 - 0 2 0 A - 5 6 0 7 Ball Joint (Left) 1 D-57 1 8 - 0 1 1 B - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 9 S - 5 6 0 7 Nut For D-57 1		25-006A-3200		1 1	
D-54 1 8 - 0 1 8 B - 5 6 0 7 Ball Joint connecting Rod 1 D-55 1 8 - 0 1 6 S - 5 6 0 7 Nut (R) For D-54 1 D-56 1 8 - 0 2 0 A - 5 6 0 7 Ball Joint (Left) 1 D-57 1 8 - 0 1 1 B - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 9 S - 5 6 0 7 Nut For D-57 1				1 1	
D-55 1 8 - 0 1 6 S - 5 6 0 7 Nut (R) For D-54 1 D-56 1 8 - 0 2 0 A - 5 6 0 7 Ball Joint (Left) 1 D-57 1 8 - 0 1 1 B - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 9 S - 5 6 0 7 Nut For D-57 1				1	
D-56 1 8 - 0 2 0 A - 5 6 0 7 Ball Joint (Left) 1 D-57 1 8 - 0 1 1 B - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 9 S - 5 6 0 7 Nut For D-57 1			*	1	
D-57 1 8 - 0 1 1 B - 5 6 0 7 Solenoid Shaft Connecting Rod Solenoid 1 D-58 1 8 - 0 1 9 S - 5 6 0 7 Nut For D-57 1				1	
D-58			· · ·	1 1	
				1	
D-59 E A - 0 0 0 0 2 3 Edge Sensor Box (Ass'y) 1				1	
	D-59	E A - 0 0 0 0 2 3	Edge Sensor Box (Ass'y)	1 1	

SYNCHRONIZER






Ref No.	Parts No.	Name of Parts	Q' ty	Assembly No.
E-1	11-0000-SE55	Synchronizer Assemble (KM-235)	1	
E-2	16-301A-9000	Synchronizer Base (KM-235)	1	
E-3	16-302A-9000	Synchronizer Shaft (KM-235)	1	
E-4	16-006B-SC53	Synchronizer Cover (KM-235)	1	
E-5	12-011S-SC53	Synchronizer Film (UP)	1	
E-6	12-012S-SC53	Synchronizer Film (DOWN)	1	
E-7	12-016B-SE55	Cable For Din Connector	1	
E-8	11-006C-SC53	Fixed Bushing For Synchronizer Film	1	
E-9	11-007S-SC53	Screw For Synchronizer Film	1	
E-10	11-008W-SC53	Washer For Synchronizer Film	3(Ass'y)	
E-11	11-009S-SC53	Screw For Photo Sensor Assembly	1	
E-12	11-024P-3701	Roll Pin (3 *16)	1	
E-13	12-105B-SC53	P.C.B Holder	1	
E-14	11-200A-SE55	P.C.B Assembly	1(Ass'y)	
E-15	08-015C-3701	Clip 4N	1	
E-16	16-0088-2000	Screw For Synchronizer Cover	1	
E-17	16-010S-2000	Screw For Synchronizer Shaft	2(Ass'y)	
E-18	09-0428-3701	Screw For Cable Holder	1	
E-19	16-007B-SC53	P.C.B Holder Plate	1	
E-20	12-0000-SE55	Synchronizer Assembly (Special Type)	1	
E-21	11-7000-SE55	Synchronizer Assembly (Other Company Type)	1	
E-22	15-026M-1000	Band Clip For Cable	1	
E-23	16-301A-SC51	Synchronizer Base (Special Type)	1	
E-24	16-303A-9000	Synchronizer Shaft (Special Type)	1	
E-25	16-003B-5600	Synchronizer Cover (560)	1	
E-26	11-009S-SC53	Lock Screw For Photo Sensor Assembly	1	
E-27	06-009B-SC53	Synchronizer Base (Other Company Type)	1	
E-28	06-303A-SC51	Synchronizer Shaft (Other Company Type)	1	
E-29	06-008B-SC53	Synchronizer Cover (Other Company Type)	1	
E-30	12-105C-SC51	Lock Nut For Photo Sensor Assembly	1	
E-31	16-015A-2000	Bearing (6001z)	2	
E-32	12-102C-SC51	Stopper For Bearing	1	
E-33	12-103C-SC51	Stopper Bushing For Bearing	1	
E-34	11-011C-SC53	Connection Bushing For Synchronizer (Other Company Type)	1	
E-35	11-012S-SC53	Screw (A) For E-34 (11/32 " n=28)	1	
E-36	11-013S-SC53	Screw (B) For E-34 (5/16 " n=24)	1	
E-37	11-104C-SC51	Connection Plate For Synchronizer	1	
E-38	11-105C-SC51	Lock Rubber For Synchronizer	1	
E-39	12-101C-SC51	Fixing Plate For Cable	1	
E-40	12-104C-SC51	Screw For E-39	2(Ass'y)	
E-41	16-0108-2000	Screw For E-34	2	
E-42	12-103S-SC51	Screw For Photo Sensor Assembly (Other Company Type)	1	
E-43	09-046W-3701	Spring Washer For Photo Sensor Assembly (Other Company Type)	1	
E-44	12-104C-SC51	Screw For Bearing Stopper	3(Ass'y)	
E-45	91-007A-3701	Pedal Control Rod Assembly	1(Ass'y)	
E-46-1	91-201A-SE51	Power Source For Switch Box (1~220V)	1(Ass'y)	
E-46-2	91-201A-SE53	Power Source For Switch Box (3~220V)	1(Ass'y)	
E-46-3	91-101A-SE51	Power Source For Switch Box (1~110V)	1(Ass'y)	
E-47	91-008C-1701	Staple	5(Ass'y)	



SUPPLEMENTARY CONTROL BOX (KM-757/TC cap ribbon cutter)





Ref No.	Parts No.	Name of Parts	Q' ty	Assembly No.
F-1	EP-000223-00	SMPS 24V	1	
F-2	EP-000221-00	BLDC Motor Driver	1	
F-3	BD-000558-00	DDV B/D Ass'y	1	
F-4	GP-023512-00	Box Body	1	
F-5	C A - 0 0 2 9 0 0 - 0 0	Cooling Fan	1	
F-6	CA-002899-00	Cable for External Power Input	1	
F-7	C A - 0 0 2 8 9 7 - 0 0	Cable for Motor Power	1	
F-8	CA-002896-00	Cable for Driver Input Signal	1	
F-9	C A - 0 0 2 8 9 8 - 0 0	Cable for Driver Power	1	
F-10	EP-000207-00	Cable for Fix	1	
F-11	15-026M-1000	Cable Tie	2	
F-12	SC-000565-00	Screw for Fan(M5 × L10)	4	
F-13	10-002S-SW66	Screw for PCB(M3 ×L8)	4	
F-14	10-002S-SW66	Screw for SMPS(M3×L8)	4	
F-15	10-002S-SW66	Screw for Driver(M3 ×L8)	2	
F-16	01-003S-BT01	Caution Stcker	1	
F-17	09-023C-SC53	QC Sticker	1	
F-18		Model Sticker	1	
	I			