

INSTRUCTIONS FOR ORDERING

In ordering from this list, use ONLY the part NUMBER in the FIRST column.

The number stamped on a Sewing Machine Part is in every case the number of the single part only.

Every combination of parts sent out as such has its specific number, which, although not stamped on the parts, must be used when ordering the combination.

Each number always indicates the SAME PART in whatever list it appears, or for whatever machine.

The letters after some of the numbers indicate the style of finish only, as follows:

A—Hardened, Polished, Nickel Plated and Buffed

B—Polished, Nickel Plated and Buffed

C—Hardened Only

D—Polished Only

E—Soft, Not Polished

F—Hardened and Polished

G—Bright Rumbled and Nickel Plated

H—Blued

J—Nickel Plated Only

K—Hardened and Nickel Plated

L—Brass Plated

M—Oxidized

~~R—Phosphate Coating Formed on Surface of Iron or Steel~~

S—Cadmium Plated

T—Copper Plated

U—Zinc Plated

V—Silver Plated

W—Polished and Nickel Plated

X—Black Oxide for Iron and Steel

Y—Black Nickel Plated Only

Z—Chromium Plated

A.A—Buffed and Chromium Plated

A.B—Hardened, Polished, Buffed and Chromium Plated

A.E—Hardened, Bright Rumbled and Nickel Plated

A.F—Hardened, Bright Rumbled, Nickel Plated, Bright Rumbled and Chromium Plated

A.G—Alumilite (Plain)

A.H—Alumilite (Dyed) Color Must be Stated

A.J—Polished, Nickel Plated and Chromium Plated

A.K—Hardened, Polished, Nickel Plated and Chromium Plated

A.L—Heat Treated for Toughness

A.L.D—Heat Treated for Toughness and Polished

A.L.X—Heat Treated for Toughness and Black Oxide

INSTRUCTIONS FOR ORDERING

A.S—Black Moulded Phenolic

A.T—Beige Moulded Phenolic

A.U—Brown Moulded Phenolic

A.W—Hardened then Flame Coated with Tungsten Carbide

B.A—Chrome Nickel Satin Finish

B.B—Hardened and Chrome Nickel, Satin Finished

C.R—Hardened and Phosphate Coating Formed on Surface of Steel

F.J—Hardened, Polished and Nickel Plated

T.A—Hardened, Polished, Copper and Nickel Plated and Buffed

T.B—Copper and Nickel Plated and Polished

T.J—Copper and Nickel Plated Only

T.K—Hardened, Copper and Nickel Plated

T.L—Copper and Brass Plated

T.M—Copper Plated and Oxidized

X.C—Hardened and Black Oxide for Iron and Steel

Z.A—Hardened, Polished Nickel Plated, Buffed and Chromium Plated

Z.B—Polished, Nickel Plated, Buffed and Chromium Plated

Z.C—Hardened and Chromium Plated

~~Z.D—Polished and Chromium Plated~~

Z.G—Bright Rumbled, Nickel Plated, Bright Rumbled and Chromium Plated

Z.J—Nickel and Chromium Plated

Z.T—Copper and Chromium Plated

These letters MUST BE USED when they appear in the list; and AFTER the number as in the list.

In this series:

1 to 1500, 50001 to 51500 and 140001 to 142,000 are screw numbers

1501 to 1800 and 51500 to 51800 are nut numbers

1801 to 2000 and 51801 to 52000 are roller numbers

2001 to 50000 and 52001 to 140000 and 142001 to 190000 are Sewing Machine Parts, 190001 and upward are numbers of Electrical Parts.

The figures in the second column refer only to the plates, illustrating the parts, and are NOT TO BE USED in ordering.

Parts marked with an asterisk (*) are furnished only when repairs are made at the factory.