

## 9. THREADING ( FOR SINGLE NEEDLE)

Thread the machine as shown in Fig. 7.

A—Needle Thread, B—Upper looper Thread, C—Lower Looper Thread

Threading for seaming as shown in Fig. 12 (Blind stitch hemming) and Fig. 13 (Used the Spreader for two thread seaming instead of Upper looper), page 13.




Fig. 7.