


## 10. THREADING (FOR TWO NEEDLE)

Thread the machine as shown in Fig. 8.

- A— Left Needle Thread.
- B— Right Needle Thread.
- C— Upper Looper Thread.
- D— Lower Looper Thread.



— Fig. 8