
THIS LIST SUPERSEDES LIST OF 87-1 MACHINE ISSUED MAY 4, 1911 NUMBERING DEPARTMENT JULY 15, 1911

LIST OF PARTS COMPLETE



Machine No. 87-1

THE SINGER MANUFACTURING COMPANY



LIST OF PARTS COMPLETE

FOR

MACHINE NO. 87-1

This machine is for making embroidery, monograms, etc. Has one head, one needle and shuttle, no feed mechanism, has also embroidery hoop for holding the work, attached by means of a holder to a pantograph, which is so arranged as to enable the operator to follow any desired design in the finished work. With stand and table complete.

*2801	Arm with 450c, 2006 and 2803
2002	" Dowel Pin
138E	" Screw
15305	" Shaft
2006	" " Bushing (back)
4500	" " Set Screw
*2803	" " (front)
8300	" Side Cover
286B	" " " Thumb Screw
2007	" Spool Pin
8879	" " Washer (cloth)
32584	Balance Wheel (light rim) 2½ in. pulley
*2805	Bed
256B	Clamp Stop Motion Clamp Screw
248A	" " Stop Screw
2020	" " " Washer
*2021	" " " Flanged Bushing
15152	" " " 2021 with two
	462c
2022	Clamp Stop Motion Flanged Bushing Pin
4620	" " Set Screw
2019E	Clamp Stop Motion complete, Nos. 248A, 256B, 2020
	and 15152
2811B	Crank Connecting Rod with 2812 and two 158E
*2812	" " Cap
158E	" " Screw
375c	" " " Hinge Screw
1518E	
*2813	Face Plate
*2815	" " Tension Seat
2814	" " 2813 with 2815

15239	Face	Plate c	omplete	e, No	os. 24	18A, 13	38D, 1	560в, 2	814,
		2826	5, 2827,	282	9, 28	330, 82	238, 15	238, 32	2572
		and	two 21	02					
190B	Face		crew						
2827	"	" 7	hread (Guar	d wi	th 850	5		
8505	cc	"	«	"		vet			
2037A	Feed	Bar							
315c	"		rew Cen						
1519E	ш	"							
2038	cc	Cam W	ith 448						
448C	"		et Screw						
2040	u	-							
191c	u	0	rew						
2042B	"		Connec						
-	"	r orked	Connec	ction		ige Scr			
378c	"	"	"		1111	ige ser			
1520E	"	"	"		D -1	1			
1832				11		ler and			
2816в			Rock S						
2817в	F'eed		Rock S						
			ВВ						
2573в		Lifting	Rock !						
157B	"	"	u	ш	"	Ole	amping		
1935	"	ш	и	u	ш		ller an		
307c	"	и	u	"		ew Cer			
1513E	"	"	"	"	6	(" Nı	1t	
2044	ш	Regula	tor						
74E	u	"	Hing	ge S	crew				
747B	ee	u	Thu	mb	Scre	w			
2047в	- 66	Rock S	Shaft						
2046в	Feed	Rock S	Shaft co	mpl	ete,	Nos. 20)47B ar	nd 2048	B
2048в	"	и	" Cr	ank	with	465c.			
2049	u	u	u	"	Pin.				
465c		cc .	ee	ш		Screw.			
307c	u	"	" Sc	rew	Cent	re			
1513E	"	"			"				
35996	Hem	mer (fo	ot) 5/64 i	in. h	em .				
6267	"		der						
25888	cc		ngue						
15067	Need	le Bar .	0						
15248	"		Connect						
930E	u	"	"		"		ting Sc		
570c	и	ee	u		"		Screw		
1520E	. "	cc cc	u		"	"		Nut.	
	"	"	ш		041				
2052			"	9		with 1			
155c	"	u			ee.		rew	*** * * * * *	
15068	u		Thread						
251A	ш	ш	"	. "	Sc	rew			
15069	u	Clamp	with 2	46F.					

216	n Moodle	Clamp Canavi
49501	r weedle	Clamp Screw
691		Plate
		Derew
307		ting Rock Shaft
1513		berew Centre
		" " Nut
2056		Shaft
*2163		Crank with 1813
2057		" 2163 with two 462c
2049		" " Pin
1813		" Roller and Stud
462		" " Set Screw
15257		
15236		" Lifter
1058		" " Screw
1520	Total Control of the	" " Nut
8399	"	" Spring
2068	u	" " Bracket with 453c
453	C "	" " Set Screw
2070	и	" " Washer
49502	u	Foot
49503	и	" Hinge Pin
49504	"	" Shank
49505	и	" Spring
49506	Presser	Foot (spring, hinged) complete, Nos. 49502
		to 49505
15281	Presser	Foot for 2040
176		" Screw for 49506
286	В "	" Thumb Screw for 15281
263	B Pressur	e Regulating Thumb Screw
2073		Bobbin.
2211	u	" Retaining Spring
2212	ш	" " Rivet
*2213	и	Body with 398E, 2082, 2084, 2211 and two
		2212
*2075	Shuttle	Cover
2076	и	" Hinge Pin
2078	и	Delivery Eye Thread Guard
2080	ee	" " " Rivet
2082	"	Main Spring
398	Е "	" " Screw
2084	"	" " Steady Pin
466	C "	Tension Regulating Screw
2086	"	
	и	" Spring
2090		1 late
112		" " Screw
2208	Shuttle	complete, Nos. 112D, 466C, 2073, 2075, 2076,
		2078, 2080, 2086, 2090 and 2213

*2176A	Shuttle	Driver
2092A	· ·	" 2176A with two 457c
2049	u	" Pin
457c	"	" Set Screw
2095	u	Race Back
190c	"	" " Screw
2096	"	" Body
2093	Shuttle	Race complete, Nos. 2095, 2096 and two
		190c
158F	Shuttle	Race Screw
2994	ш	" " Slide
2995	Shuttle	Race Slide complete, Nos. 2824, 2994 and
		two 240B
2824	Shuttle	Race Slide Spring
240B	ш	" " Screw
2102	Tension	Disc
1560B	α,	Regulating Thumb Nut
32572	ш	Releasing Disc
15238	cc _	" Pin
1338D	· "	Screw Stud
8238	ш	Spring
2826	u	Thread Guard
26075	Thread	Cutter and Holder
15271	u,	Take-up Cam with 448c and 1293c
1293c	ш	" Position Screw
448c	ш	" Set Screw
2316	u	" Lever with 1822
79c	"	" " Hinge Screw
1822	"	" Roller and Stud
2829	"	" Spring
2830	"	" Regulator
248A	"	" Set Screw
2831в	Throat	Plate, large needle hole, for 2040
2832в	"	" small " " " "

PANTOGRAPH PARTS

49507	Bell Crank
49508	" " Link (left)
50111	" " " Screw
50112	" " " Thumb Screw
49509	" " " (right)
50112	" " " Thumb Screw
50113	" " Thumb Screw
49510	Connecting Rod (left)
50111	" " Screw
49527	" " Support Stud
49511	" " (right)
49512	" " Link (back)
49513	" " (front)
50114	" " " Screw
50112	" " " Thumb Screw
49514	Hand Lever
49515	" " Handle
49516	" " Pointer
49517	" " Support Stud
50115	" " Thumb Screw
49529	Hoop (large) with 49530. Old Serial No. 21697
49530	" " Bracket
49531	" Ring with 49532 and two 49533. Old
	Serial No. 21696
49532	Hoop (large) Ring Cover
49533	" " Handle (wood)
49518	" (small) with 49519
49519	" " Bracket
49521	" "Ring with 49522 and two 49523
49522	" " Cover
49523	" " Handle (wood)
49520	" Link
50116	" " Screw (back)
50114	" " (front)
793	" Thumb Screw
49524	Plate (lower) with two wood screws 5/8 in. No. 8
49525	" (upper)
212	" " Screw
49534	Pantograph (large hoop) complete, Nos. 793, 49507
	to 49517, 49520, 49524, 49525, 49527, 49529,
	49531, 50113, 50115, 50116, two each 212,
	50111, 50114 and three 50112
49528	Pantograph (small hoop) complete, Nos. 793, 49507 to
	49518, 49520, 49521, 49524, 49525, 49527,
	50113, 50115, 50116, two each 212, 50111,
	50114 and three 50112

ACCESSORIES

35676	Oiler with Cap and 35678
35677	" 35676, filled with oil
35678	" Spout, 2 inches long
8909	Wrench for 1513 and 1518
8908	" " 1520

BOBBIN WINDER (Automatic)

15072	Bobbin Position Pin
15172	Bracket (belt cover)
180в	" Screw
2447	Frame
48B	" Hinge Screw
2744	Pulley
2449	Spindle with 15072
2855	" 2449 with 2744
2840	Spool Stand Bed
2455	" " Thread Retaining Disc
2456	" " " Spring
2457	" " " Stud
2839	Spool Stand complete, Nos. 2455 to 2457 and 2840.
205A	" " Screw
2451	Spring
2452	Stop Latch
24B	" " Hinge Screw
15173	Bobbin Winder, Nos. 24B, 48B, 2447, 2451, 2452
	2855 and 15172
15174	Bobbin Winder (automatic) complete, Nos. 2839 and
	15173

STAND

ROCKING TREADLE, BALL BEARING PITMAN

25442	Band	Wheel	121/2	in. diar	n., wi	ith 972	C				
46515	ш	ш	Crank								
46537	Band	Whee	l Crai	nk an	d Pi	tman	(ball	be	ari	ng)	
		com	plete, 1	Nos. 15	20E,	1670E,	2536	1,	253	71,	
		4650	6 to 4	46509,	4651	5, 465	39 aı	nd	elev	ven	
		2536	2								
297c	Band	Wheel	Crank	Screw	Centr	e					
1507E	ee	ш	ш	u	u	Nut.					
972c	ш	и	Set Sci	rew							

25373	Belt, size 3/16 in., length 601/2 in., with 25027
25031	" Guide
507E	
1515E	" " " Nut
25027	" Hook
46525	" Shifter
34p	" " Hinge Screw
25033	" " Spring
25385	Brace with three each 297c and 1507E
46538	" Extension
116E	" " Screw
116E	" Screw (lower)
748E	" " (upper)
46526	Dress Guard
25049	Dress Guard complete, Nos. 34D, 25033, 46525 and
20010	46526
504E	Dress Guard Bolt with 1510E
1510E	" " Nut
25386	Leg with two each 25068 and 25069
25068	" Roller
25069	" " Pin
25362	Pitman Ball, size 3/16 in.
46506	" " Bearing Adjusting Screw Ring
46507	" " " " " Locking
40007	
10500	Washer (brass)
46508	Pitman Ball Bearing Ring
46509	Case
46539	100d With 25500
*25360	Dan
25371	Dushing
25361	belew Dearing
1670E	1,40
1520E	LOCK INCC
46540	Treadle
297c	" Screw Centre
1507E	" " Nut
25086	Wrench for 1507, 1510, 1515 and 1670
25200	" " 972
25270	Stand (iron work) rocking treadle, ball bearing
	pitman, complete, Nos. 504E, 507E, 25031,
	25049, 25086, 25200, 25385, 25442, 46537,
	46540, two each 748E, 25386, 46538 and four
	1165

TRIMMINGS FOR TABLE

28126	Belt He	ole Busl	hing (oval	, brass) 5	s in. x 1 in.	
28250	u u		(oval	, oxidized	1) 5/8 in. x 1	in '
2833	Drip Pa	an				
8418	Machin	e Butto	n			
8419	. "	"	Washer	(leather)		
8420	"	"			and wood	
		11/4 in	. No. 9 R.	H. B		
25070	Machin	e Cushi	on Tack (rubber).		
525	В "	Hinge	Bolt			
1518	E "	ш	" Nut			
2807	· · ·	ш	u u	Washer		
8294	ш	ш	Connecti	on		
8295	ш	ee	и	Hinge	Pin	
448	C "	u	и		ew	
8306	· ·	u	Nos. 525	B, 8294 ar	nd 8295	
8292	Machin	e Hinge	complete	, Nos. 151	8E, 2807 and	8306.
28293	Table S	upport	with thre	e wood so	crews 1 in. N	lo. 10.
28294	u	ш	Bracket	with 736	D and two	wood
		screws	1/8 in. No	. 8 R. H.	В	
736	D Table S	upport	Bracket '	Chumb So	rew	

