

THREADING CHART

- Use any type thread which is suitable for the fabric being sewn. This includes mercerized, 00, silk and synthetic threads.
- The thread is passed through rear thread guide (A) then slides between two tension discs (B) through (C) through front thread guide (D) . . . then down through needle clamp hole (E) . . . and entering from the underside of needle hole (F).
- 3. Leave thread about 2 to 3 inches past needle hole.

THREADING NEEDLE

- 1. To thread needle at point (F)
 - a. Swing work plate out of way
 - b. Depress cylinder out of way with knee lifter
 - Hold thread between index finger and thumb
 - d. End of thread must be stub



From the library of: Superior Sewing Machine & Supply LLC