

THREADING THE MACHINE

Upper Threading

Turn machine pulley over toward operator until needle bar is at its highest position.

Pass thread through threading points indicated in Fig. 9.

Draw about two inches of thread through needle eye to start sewing.

The 302U201, 302U206 and 302U406 are all threaded as indicated in Fig. 9.





Fig. 9. Threading the Machine



Lower Threading

Turn machine pulley over toward operator until needle bar is at its highest position. Pass thread through threading points indicated in Fig. 9. When threading looper, insert wire threader into front of looper eye shown at left. With threading tweezers, drop thread into wire threader opening and draw wire threader toward you from back to front through the looper eye. Draw about two inches of thread through looper to start sewing.