



Catalogue

BOBBIN CASE BOBBIN

CD-ROM for Windows XP / Me / 2000 / 98SE
Version 1.0

<http://www.towa-mfg.co.jp>
info@towa-mfg.co.jp

TOWA Industrial Co., Ltd.
Head Office & Factory Tel:81-254-22-3430 Fax: 81-254-21-1195
3-2-17 Shintomi, Shibata City, Niigata, 957-0017, Japan

TOWA Industrial (VIETNAM) Co.,Ltd. TEL. +84-8-7701870 FAX.+84-8-7701871

SHANGHAI REP.OFFICE TEL. +86-21-6275-7526 FAX.+86-21-6275-7529
2401,SHARTEX PLAZA,88 ZUNYIROAD,SOUTH SHANGHAI,CHINA,PC,200336

Copyright 2005 TOWA INDUSTRIAL Co.,Ltd.
Made in Japan

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|--------------|-------------------|----------|----------------|--------------|----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| ABLE | | | | | | |
| HB-100 | | 601 | BC-DB1 | | 13-4 | BO-400(4) |
| HB-150 | | 601 | BC-DB1 | | 8 | BO-95(2) |
| HB-300 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| HB-380 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| HB-480 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| HB-500 | | 601 | BC-DB1 | | 8 | BO-95(2) |
| HB-630 | | CAP | UNAVAILABLE | | 19-3 | BO-112(3) |
| HBS-2700 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| HBS-5000 | | 601 | BC-DB1 | | 8 | BO-95(2) |
| LT2-220BF | | ---- | ---- | | 26-3 | BO-1215MM-N |
| LTS-220ML | | ---- | ---- | | 19-3 | BO-112(3) |
| ADLER | | | | | | |
| 4 | | ---- | ---- | 005-00-242-0 | 38 | BO-45 |
| 5 | | ---- | ---- | 005-00-242-0 | 38 | BO-45 |
| 16 | | ---- | ---- | | ---- | ---- |
| 20 | | ---- | ---- | 020-00-196-0 | ---- | ---- |
| 21 | | ---- | ---- | 020-00-196-0 | ---- | ---- |
| 026 | | 305 | BC-HR2 | 061-00-056-0 | 8 | BO-95(2) |
| 37 | 037-00-151-4 | 504 | BC-31-15 | 037-00-161-4 | ---- | ---- |
| 45 | | ---- | ---- | | ---- | ---- |
| 48 | | ---- | ---- | | 34 | BO-17 |
| 56 | | ---- | ---- | | ---- | ---- |
| 58 | | ---- | ---- | | ---- | ---- |
| 61 | | ---- | ---- | 061-00-056-0 | 8 | BO-95(2) |
| 67 | 068-00-178-4 | CAP | UNAVAILABLE | 068-00-180-0 | 24-2 | BO-PF130(A) |
| 68 | 068-00-178-4 | CAP | UNAVAILABLE | 068-00-180-0 | 24-2 | BO-PF130(A) |
| 69 | 069-00-578-4 | 903 | BC-PF9076 | 069-00-580-0 | 24 | BO-PF130 |
| | 069-15-028-4 | 903NBL | BC-PF9076-NBL | 068-00-180-0 | 24-2 | BO-PF130(A) |
| | | 903M | BC-PF9076-M | | | |
| 69-373 | 069-00-578-4 | 903 | BC-PF9076 | 069-00-580-0 | 24 | BO-PF130 |
| 69-FA-373 | 069-15-028-4 | 903NBL | BC-PF9076-NBL | 069-15-030-4 | 24-2 | BO-PF130(A) |
| | 069-00-578-4 | 903 | BC-PF9076 | 069-00-580-0 | 24 | BO-PF130 |
| 76 | | ---- | ---- | 068-00-180-0 | 24-2 | BO-PF130(A) |
| 91 | 098-00-178-4 | 702 | BC-107(2) | 098-00-180-0 | 15 | BO-107(1) |
| | 098-15-005-4 | 702NBL | BC-107(2)-NBL | | 17 | BO-107(A) |
| 96 | 097-00-178-4 | 601 | BC-DB1 | 061-00-056-0 | 8 | BO-95(2) |
| 98 | 098-00-178-4 | 702 | BC-107(2) | 098-00-180-0 | 15 | BO-107(1) |
| | 098-15-005-4 | 702NBL | BC-107(2)-NBL | | 17 | BO-107(A) |
| 104 | | ---- | ---- | 005-00-242-0 | 38 | BO-45 |
| 105 | | ---- | ---- | 005-00-242-0 | 38 | BO-45 |
| 126 | | 305 | BC-HR2 | 061-00-056-0 | 8 | BO-95(2) |
| 153 | | 211 | BC-NE | | ---- | ---- |
| 153-A | | 211 | BC-NE | | ---- | ---- |
| 165 | | ---- | ---- | 005-00-242-0 | 38 | BO-45 |
| 166 | | ---- | ---- | 005-00-242-0 | 38 | BO-45 |
| 167 | 167-00-178-4 | CAP | UNAVAILABLE | 167-00-180-0 | ---- | ---- |
| 167-273 | 167-15-019-4 | CAP | UNAVAILABLE | 167-15-007-0 | ---- | ---- |
| 167-FA272 | 167-15-019-4 | CAP | UNAVAILABLE | 167-15-007-0 | ---- | ---- |
| 167-FA272NH | 167-15-019-4 | CAP | UNAVAILABLE | 167-15-007-0 | ---- | ---- |
| 167-FA273 | 167-15-019-4 | CAP | UNAVAILABLE | 167-15-007-0 | ---- | ---- |
| 168 | 167-00-178-4 | CAP | UNAVAILABLE | 167-00-180-0 | ---- | ---- |
| 169 | 167-00-178-4 | CAP | UNAVAILABLE | 167-00-180-0 | ---- | ---- |
| 196 | 097-00-178-4 | 601 | BC-DB1 | 061-00-056-0 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | 296-15-282-0 | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | | | |
| | | 601M2 | BC-DB1-M2 | 061-00-056-0 | 8 | BO-95(2) |
| | | 601-2 | BC-DB1-WH | 296-15-282-0 | 10 | BO-95(A) |
| 199 | 89-178C | 609 | BC-DBZ(1) | 061-00-056-0 | 8 | BO-95(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | 296-15-282-0 | 10 | BO-95(A) |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| | | 305 | BC-HR2 | 061-00-056-0 | 8 | BO-95(2) |
| 204 | | ---- | ---- | | ---- | ---- |
| 205 | | ---- | ---- | | ---- | ---- |
| 220 | 220-00-179-4 | ---- | ---- | 220-00-180-0 | ---- | ---- |
| 265 | | ---- | ---- | | 35 | BO-132 |
| 267 | 167-00-178-4 | CAP | UNAVAILABLE | 167-00-180-0 | ---- | ---- |
| 267-FA | 167-15-019-4 | CAP | UNAVAILABLE | 167-15-007-0 | ---- | ---- |
| 268 | 167-00-178-4 | CAP | UNAVAILABLE | 167-00-180-0 | ---- | ---- |
| 268-FA | | CAP | UNAVAILABLE | | ---- | ---- |
| 289 | 89-178C | 609 | BC-DBZ(1) | 061-00-056-0 | 8 | BO-95(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | 296-15-282-0 | 10 | BO-95(A) |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| 296 | 396-15-078-4 | 616 | BC-AD396 | 061-00-056-0 | 8 | BO-95(2) |
| | 396-15-082-4 | 616NBL6 | BC-AD396-NBL6 | 296-15-282-0 | 10 | BO-95(A) |
| | 097-00-178-4 | 601 | BC-DB1 | 061-00-056-0 | 8 | BO-95(2) |
| 381 | 396-15-078-4 | 616 | BC-AD396 | 061-00-056-0 | 8 | BO-95(2) |
| | 396-15-082-4 | 616NBL6 | BC-AD396-NBL6 | 296-15-282-0 | 10 | BO-95(A) |
| 396 | 396-15-078-4 | 616 | BC-AD396 | 061-00-056-0 | 8 | BO-95(2) |
| | 396-15-082-4 | 616NBL6 | BC-AD396-NBL6 | 296-15-282-0 | 10 | BO-95(A) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|----------------------|-------------------|----------|----------------|--------------|----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 419 | 89-178C | 609 | BC-DBZ(1) | 061-00-056-0 | 8 | BO-95(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | 296-15-282-0 | 10 | BO-95(A) |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| | | 305 | BC-HR2 | 061-00-056-0 | 8 | BO-95(2) |
| 420 | | 305 | BC-HR2 | 061-00-056-0 | 8 | BO-95(2) |
| 467 | 467-15-008-4 | ---- | ---- | 167-15-027-0 | ---- | ---- |
| 489 | 89-178C | 609 | BC-DBZ(1) | 061-00-056-0 | 8 | BO-95(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | 296-15-282-0 | 10 | BO-95(A) |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| | | 305 | BC-HR2 | 061-00-056-0 | 8 | BO-95(2) |
| 1296 | 069-00-578-4 | 903 | BC-PF9076 | 069-00-580-0 | 24 | BO-PF130 |
| | 069-15-028-4 | 903NBL | BC-PF9076-NBL | 068-00-180-0 | 24-2 | BO-PF130(A) |
| ALFA | | | | | | |
| 102 | 211297 | 302 | BC-HR306 | | 2 | BO-103(2) |
| | | 618 | BC-ALFA109 | | | |
| 109 | 211297 | 302 | BC-HR306 | | 2 | BO-103(2) |
| | | 618 | BC-ALFA109 | | | |
| 112 | 218210 | ---- | ---- | | ---- | ---- |
| 119 | 218210 | ---- | ---- | | ---- | ---- |
| 127 | 112327 | 606 | BC-DLN | | 13-4 | BO-400(4) |
| | 114757 | | | | | |
| 157 | 112327 | 606 | BC-DLN | | 13-4 | BO-400(4) |
| | 114757 | | | | | |
| | 112439 | 504 | BC-31-15 | | ---- | ---- |
| 184-303 | 145507 | C-2 | CP-PF151 | | ---- | ---- |
| 185-303 | 145507 | C-2 | CP-PF151 | | ---- | ---- |
| 185-503 | 145507 | C-2 | CP-PF151 | | ---- | ---- |
| 201:209 | 112327 | 606 | BC-DLN | | 13-4 | BO-400(4) |
| | 114757 | | | | | |
| 214:217 | 112327 | 606 | BC-DLN | | 13-4 | BO-400(4) |
| | 114757 | | | | | |
| 3242 | 218210 | ---- | ---- | | ---- | ---- |
| 3842 | 218210 | ---- | ---- | | ---- | ---- |
| 3847 | 218210 | ---- | ---- | | ---- | ---- |
| 3940 | 218210 | ---- | ---- | | ---- | ---- |
| HOUSEHOLD | | 304 | BC-HR1 | | 1 | BO-103(1) |
| ALTIN | | | | | | |
| 8332 | 8402 0266 | 604 | BC-251 | | 10 | BO-95(A) |
| 8332FA | 8410 0278 | ---- | ---- | | ---- | ---- |
| 8334 | 8402 0266 | 604 | BC-251 | | 10 | BO-95(A) |
| 8334FA | 8410 0278 | ---- | ---- | | ---- | ---- |
| ANKER PHOENIX | | | | | | |
| 29 | | 609 | BC-DBZ(1) | | 8 | BO-95(2) |
| 39 | | 609 | BC-DBZ(1) | | 8 | BO-95(2) |
| 49 | | 609 | BC-DBZ(1) | | 8 | BO-95(2) |
| 280 | | ---- | ---- | | ---- | ---- |
| 282 | | ---- | ---- | | ---- | ---- |
| 283 | | ---- | ---- | | ---- | ---- |
| 288 | | ---- | ---- | | ---- | ---- |
| 382 | | ---- | ---- | | ---- | ---- |
| 383 | | ---- | ---- | | ---- | ---- |
| 388 | | ---- | ---- | | ---- | ---- |
| 429 | | 609 | BC-DBZ(1) | | 8 | BO-95(2) |
| 499 | | 609 | BC-DBZ(1) | | 8 | BO-95(2) |
| 549 | | 609 | BC-DBZ(1) | | 8 | BO-95(2) |
| C-49 | | 609 | BC-DBZ(1) | | 8 | BO-95(2) |
| ATTILIO FORTE | | | | | | |
| AF6LGE | | 801NBL1 | BC-DBM(1)-NBL1 | | 22 | BO-DBM(A) |
| AF6 | | 903 | BC-PF9076 | | 24 | BO-PF130 |
| | | 903NBL | BC-PF9076-NBL | | 24-2 | BO-PF130(A) |
| AF7LGE | | C-2 | CP-PF151 | | ---- | ---- |
| AF7 | | C-2 | CP-PF151 | | ---- | ---- |
| AF7R | | C-2 | CP-PF151 | | ---- | ---- |
| AF72 | | C-2 | CP-PF151 | | ---- | ---- |
| AF8 | | C-2 | CP-PF151 | | ---- | ---- |
| AF8CE | | C-2 | CP-PF151 | | ---- | ---- |
| AF8CE/CF | | ---- | ---- | | ---- | ---- |
| AF8CE/CF/AR | | ---- | ---- | | ---- | ---- |
| AF82 | | C-2 | CP-PF151 | | ---- | ---- |
| AF82CE | | C-2 | CP-PF151 | | ---- | ---- |
| AF82CE/CF | | ---- | ---- | | ---- | ---- |
| AF879 | | C-2 | CP-PF151 | | ---- | ---- |
| AF87 | | C-2 | CP-PF151 | | ---- | ---- |
| AF872 | | C-2 | CP-PF151 | | ---- | ---- |
| AF8R | | C-2 | CP-PF151 | | ---- | ---- |
| AF10LGE | | C-2 | CP-PF151 | | ---- | ---- |
| AF102LGE | | C-2 | CP-PF151 | | ---- | ---- |
| BARATTO | | | | | | |
| HBA-1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| BARUDAN | | | | | | |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------------|-------------------|----------|-----------------|------------|----------|----------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| BEAM | KF220370 | 609 | BC-DBZ(1) | KF220410 | 2 | BO-103(2) |
| | KF220440 | 609NBL6 | BC-DBZ(1)-NBL6 | KF220410A | 2 | BO-103(A) |
| BEAT | KF220370 | 609 | BC-DBZ(1) | KF220410 | 2 | BO-103(2) |
| | KF220440 | 609NBL6 | BC-DBZ(1)-NBL6 | KF220410A | 6 | BO-103(A) |
| BEH | KF220370 | 609 | BC-DBZ(1) | BB | 2 | BO-103(2) |
| | BBC1 | 609NBL6 | BC-DBZ(1)-NBL6 | BBA | 6 | BO-103(A) |
| BEJ | KF220370 | 609 | BC-DBZ(1) | KF220410 | 2 | BO-103(2) |
| | BBC1 | 609NBL6 | BC-DBZ(1)-NBL6 | BBA | 6 | BO-103(A) |
| BEJM-UF | KF220370 | 609 | BC-DBZ(1) | BB | 2 | BO-103(2) |
| | KF220440 | 609NBL6 | BC-DBZ(1)-NBL6 | KF220410A | 6 | BO-103(A) |
| BEL | B-0170 | 609 | BC-DBZ(1) | B-0171 | 2 | BO-103(2) |
| | B-0170NBL | 609NBL6 | BC-DBZ(1)-NBL6 | B-0171A | 6 | BO-103(A) |
| BELL | B-0170 | 609 | BC-DBZ(1) | B-0171 | 2 | BO-103(2) |
| | B-0170NBL | 609NBL6 | BC-DBZ(1)-NBL6 | B-0171A | 6 | BO-103(A) |
| BEM | B-0170 | 609 | BC-DBZ(1) | B-0171 | 2 | BO-103(2) |
| | B-0170NBL | 609NBL6 | BC-DBZ(1)-NBL6 | B-0171A | 6 | BO-103(A) |
| BEMR | KF220370 | 609 | BC-DBZ(1) | KF220410 | 2 | BO-103(2) |
| | KF220440 | 609NBL6 | BC-DBZ(1)-NBL6 | KF220410A | 6 | BO-103(A) |
| BEMS | KF220302 | 803NBL5 | BC-DBM(Z2)-NBL5 | | 22 | BO-DBM(A) |
| | KF220370 | 609 | BC-DBZ(1) | KF220410 | 2 | BO-103(2) |
| | KF220440 | 609NBL6 | BC-DBZ(1)-NBL6 | KF220410A | 6 | BO-103(A) |
| BEMX | KF220302 | 803NBL5 | BC-DBM(Z2)-NBL5 | | 22 | BO-DBM(A) |
| | KF220370 | 609 | BC-DBZ(1) | KF220410 | 2 | BO-103(2) |
| | KF220440 | 609NBL6 | BC-DBZ(1)-NBL6 | KF220410A | 6 | BO-103(A) |
| BESR | KF220302 | 803NBL5 | BC-DBM(Z2)-NBL5 | | 22 | BO-DBM(A) |
| | KF220370 | 609 | BC-DBZ(1) | KF220410 | 2 | BO-103(2) |
| | KF220440 | 609NBL6 | BC-DBZ(1)-NBL6 | KF220410A | 6 | BO-103(A) |
| BEU | KF220370 | 609 | BC-DBZ(1) | BB | 2 | BO-103(2) |
| | BBC1 | 609NBL6 | BC-DBZ(1)-NBL6 | BBA | 6 | BO-103(A) |
| BEUF | KF220370 | 609 | BC-DBZ(1) | BB | 2 | BO-103(2) |
| | BBC1 | 609NBL6 | BC-DBZ(1)-NBL6 | BBA | 6 | BO-103(A) |
| BEX | KF220370 | 609 | BC-DBZ(1) | KF220410 | 2 | BO-103(2) |
| | KF220440 | 609NBL6 | BC-DBZ(1)-NBL6 | KF220410A | 6 | BO-103(A) |
| BERNINA | | | | | | |
| HOUSEHOLD | 0015346303 | 216 | BC-HZ12 | | ---- | ---- |
| BROTHER | | | | | | |
| B800 | 151041-001 | CAP | UNAVAILABLE | 112781-001 | 19-3 | BO-112(3) |
| BAS-23 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| BAS-26 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| BAS-36 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 159794-001 | 22-1 | BO-DBM(A)BR-H |
| BAS-47 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| BAS-301 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| BAS-302 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| BAS-303 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| BAS-304 | S15902-201 | BC | UNAVAILABLE | S15665-001 | 46 | BO-LK310(A)-KH |
| | S15903-201 | BC | UNAVAILABLE | S15666-001 | 46-1 | BO-LK310(B) |
| BAS-310 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| | S15902-201 | BC | UNAVAILABLE | S15665-001 | 46 | BO-LK310(A)-KH |
| | S15903-201 | BC | UNAVAILABLE | S15666-001 | 46-1 | BO-LK310(B) |
| BAS-311 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| | S15902-201 | BC | UNAVAILABLE | S15665-001 | 46 | BO-LK310(A)-KH |
| | S15903-201 | BC | UNAVAILABLE | S15666-001 | 46-1 | BO-LK310(B) |
| BAS-311EL | S15902-401 | BC | UNAVAILABLE | | ---- | BO-310(AN) |
| BAS-314 | S15902-201 | BC | UNAVAILABLE | S15665-001 | 46 | BO-LK310(A)-KH |
| | S15903-201 | BC | UNAVAILABLE | S15666-001 | 46-1 | BO-LK310(B) |
| BAS-316E | S15902-401 | BC | UNAVAILABLE | | ---- | BO-310(AN) |
| BAS-320 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| BAS-321 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| BAS-322 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| BAS-325 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| BAS-326 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| | S15902-201 | BC | UNAVAILABLE | S15665-001 | 46 | BO-LK310(A)-KH |
| | S15903-201 | BC | UNAVAILABLE | S15666-001 | 46-1 | BO-LK310(B) |
| BAS-330 | 152688-001 | 510-2 | BC-LK(B2) | 145265-001 | 27 | BO-LKB(A) |
| BAS-341 | S15902-201 | BC | UNAVAILABLE | S15665-001 | 46 | BO-LK310(A)-KH |
| | S15903-201 | BC | UNAVAILABLE | S15666-001 | 46-1 | BO-LK310(B) |
| BAS-350 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 159794-001 | 22-1 | BO-DBM(A)BR-H |
| BAS-360 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| BAS-361 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| BAS-370 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| BAS-375 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| BAS-400 | 117596-001 | 609 | BC-DBZ(1) | 146290-001 | 10 | BO-95(A) |
| BAS-411 | S17096-001 | 609NBL6 | BC-DBZ(1)-NBL6 | 146290-001 | 10 | BO-95(A) |
| BAS-412 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| BAS-415 | S17096-001 | 609NBL6 | BC-DBZ(1)-NBL6 | 146290-001 | 10 | BO-95(A) |
| BAS-416 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| BAS-423 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| BAS-500 | 159157-001 | 705 | BC-457 | 159158-001 | 17-4-1 | BO-LBH771-H |
| BAS-510 | 159157-001 | 705 | BC-457 | 159158-001 | 17-4-1 | BO-LBH771-H |
| BAS-555 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|--------------|-------------------|----------|----------------|------------|----------|----------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| BAS-600 | 154517-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| BAS-610 | S09280-001 | CAP | UNAVAILABLE | S09285-001 | 26-2-1 | BO-1215MM(A)-H |
| BAS-611 | S09280-001 | CAP | UNAVAILABLE | S09285-001 | 26-2-1 | BO-1215MM(A)-H |
| BAS-612 | S09279-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| BAS-700 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| BAS-701 | S15902-201 | BC | UNAVAILABLE | S15665-001 | 46 | BO-LK310(A)-KH |
| | S15903-201 | BC | UNAVAILABLE | S15666-001 | 46-1 | BO-LK310(B) |
| BAS-752 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| BAS-753 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| BAS-754 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| BAS-755 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| BAS-760 | S24904-101 | BC | UNAVAILABLE | S23848-001 | ----- | ----- |
| CB3-B913 | | ----- | ----- | | ----- | ----- |
| DB1-B760-3 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB1-B760-5 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B705-1 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B705-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B705-5 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B706-1 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B706-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B706-5 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B707-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B707-5 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B714-1 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B714-3 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B714-5 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B715-1 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B715-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B715-5 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B715-103 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B715-105 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 100376-001 | 2 | BO-103(2) |
| DB2-B715-107 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 100376-001 | 2 | BO-103(2) |
| DB2-B715-203 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B715-205 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 100376-001 | 2 | BO-103(2) |
| DB2-B715-403 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B715-405 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 100376-001 | 2 | BO-103(2) |
| DB2-B715-503 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B715-505 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 100376-001 | 2 | BO-103(2) |
| DB2-B716-1 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B716-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B716-5 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B730NBN | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B735-1 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B735-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B735-5 | S03245-001 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DB2-B735-7 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B736-1 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B736-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B736-5 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B737 | S03245-001 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B737-1 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B737-1-3 | S03245-001 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B737-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B737-5 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B737-905 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 100376-001 | 2 | BO-103(2) |
| DB2-B738-1 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B738-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B738-5 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B740 | 147790-001 | 801 | BC-DBM(1) | 117061-001 | 21-5 | BO-DBM(1)N |
| | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 159794-001 | 22-1 | BO-DBM(A)BR-H |
| DB2-B741 | 147790-001 | 801 | BC-DBM(1) | 117061-001 | 21-5 | BO-DBM(1)N |
| | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 159794-001 | 22-1 | BO-DBM(A)BR-H |
| DB2-B741-3 | 147790-001 | 801 | BC-DBM(1) | 117061-001 | 21-5 | BO-DBM(1)N |
| | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 159794-001 | 22-1 | BO-DBM(A)BR-H |
| DB2-B745-5 | 147790-001 | 801 | BC-DBM(1) | 117061-001 | 21-5 | BO-DBM(1)N |
| | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 159794-001 | 22-1 | BO-DBM(A)BR-H |
| DB2-B745-7 | 147790-001 | 801 | BC-DBM(1) | 117061-001 | 21-5 | BO-DBM(1)N |
| | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 159794-001 | 22-1 | BO-DBM(A)BR-H |
| DB2-B746 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| DB2-B746-5 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| DB2-B746-7 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| DB2-B746-8 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| DB2-B747-5 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| DB2-B747-5-0 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| DB2-B747-7 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| DB2-B747-7-0 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| DB2-B748-305 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| DB2-B748-307 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| DB2-B755-1 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|---------------|-------------------|----------|-------------|------------|----------|-----------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| DB2-B755-3 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B755-5 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B756 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B757-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B757-3-0 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B757-5 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B757-103 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B757-105 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B757-203 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B757-205 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B757-403 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B757-405 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B757-503 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B757-505 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B758 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B763-1 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B763-3 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B763-5 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B765-01 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B765-03 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B765-05 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B767 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B767-5 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B771 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B772 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B773 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B774 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B777 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DB2-B777-3 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B778 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B781 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B781-1 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B781-2 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B781-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B781-3-0 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B781-4 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B781-103 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B781-104 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B781-203 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B781-204 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B781-803 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B781-804 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B790 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B790-3 | 100369-001 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B790-3-0 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B790-5 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B790-5-0 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B790-103 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DB2-B790-105 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 100376-001 | 2 | BO-103(2) |
| DB2-B790-203 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DB2-B790-205 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 100376-001 | 2 | BO-103(2) |
| DB2-B790-303 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DB2-B790-403 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DB2-B790-503 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DB2-B790-505 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B790-603 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DB2-B790-605 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 100376-001 | 2 | BO-103(2) |
| DB2-B791-1 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B791-3 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B791-3-0 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B791-5 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DB2-B791-5-0 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DB2-B791-70-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DB2-B791-70-5 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 100376-001 | 2 | BO-103(2) |
| DB2-B791-90-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DB2-B791-90-5 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 100376-001 | 2 | BO-103(2) |
| DB2-B791-333 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B792-003 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B792-013 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|---------------|-------------------|----------|----------------|------------|-----------|--------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| DB2-B792-015 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B792-017 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B792-3 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B792-3-0 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B792-400 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B792-503 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B792-613 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B793 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B793-3 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B793-303 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B793-305 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B795 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B795-013 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DB2-B795-313 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB2-B797 | 147790-001 | 801 | BC-DBM(1) | 117061-001 | 21-5 | BO-DBM(1)N |
| | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| DB2-B797-5 | 147790-001 | 801 | BC-DBM(1) | 117061-001 | 21-5 | BO-DBM(1)N |
| | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | 117061-001 | 21-5 | BO-DBM(1)N |
| DB2-B798 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | S01587-001 | 21-7 | BO-DBM(3)N |
| DB2-B798-300 | 151845-001 | 801NBL1 | BC-DBM(1)-NBL1 | S01587-001 | 21-7 | BO-DBM(3)N |
| DB2-DD7000 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DB3-B776 | 183811-001 | ---- | ---- | S23847-001 | ALUMINIUM | UNAVAILABLE |
| | 183808-001 | ---- | ---- | | | |
| DL1-B812 | 107097-101 | BC | UNAVAILABLE | 146025-001 | 17-2 | BO-B814(A) |
| DL1-B813 | 107097-101 | BC | UNAVAILABLE | 146025-001 | 17-2 | BO-B814(A) |
| DL4-B812 | | ---- | ---- | 117480-001 | 17-2 | BO-B814(A) |
| DL4-B813 | | ---- | ---- | 117480-001 | 17-2 | BO-B814(A) |
| DP2-B771 | S20553-001 | 606NBL | BC-DLN-NBL | 146290-001 | 10 | BO-95(A) |
| DP2-B772 | S20553-001 | 606NBL | BC-DLN-NBL | 146290-001 | 10 | BO-95(A) |
| DP2-B791 | S20553-001 | 606NBL | BC-DLN-NBL | 146290-001 | 10 | BO-95(A) |
| DP2-B791-003 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 146290-001 | 10 | BO-95(A) |
| DP2-B791-005 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| DP2-B791-10-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DP2-B791-10-5 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 100376-001 | 2 | BO-103(2) |
| DP2-B791-40-3 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 117132-001 | 13-4 | BO-400(4) |
| | S03245-001 | | | 146290-001 | 10 | BO-95(A) |
| DP2-B791-40-5 | 148350-101 | 601NBL6 | BC-DB1-NBL6 | 100376-001 | 2 | BO-103(2) |
| DS112T-2 | | ---- | ---- | S00693-001 | 47 | BO-B484(A)-H |
| LE2-B861-1 | 117596-001 | 609 | BC-DBZ(1) | 146290-001 | 10 | BO-95(A) |
| | S17096-001 | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | 117596NBL9 | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| LE2-B861-7 | 117596-001 | 609 | BC-DBZ(1) | 146290-001 | 10 | BO-95(A) |
| | S17096-001 | 609NBL6 | BC-DBZ(1)-NBL6 | 100376-001 | 2 | BO-103(2) |
| | 117596NBL9 | 609NBL9 | BC-DBZ(1)-NBL9 | 146290-001 | 10 | BO-95(A) |
| LH4-B812 | 143986-101 | 702NBL | BC-107(2)-NBL | 146025-001 | 17-2 | BO-B814(A) |
| LH4-B813 | 143986-101 | 702NBL | BC-107(2)-NBL | 146025-001 | 17-2 | BO-B814(A) |
| LH4-B814 | 107097-101 | BC | UNAVAILABLE | 146025-001 | 17-2 | BO-B814(A) |
| LH4-B814-1 | 107097-101 | BC | UNAVAILABLE | 117480-001 | 17-2 | BO-B814(A) |
| LH4-B814-2 | 107097-101 | BC | UNAVAILABLE | 146025-001 | 17-2 | BO-B814(A) |
| LH4-B814-3 | 107097-101 | BC | UNAVAILABLE | 146025-001 | 17-2 | BO-B814(A) |
| LH4-B814-4 | 107097-101 | BC | UNAVAILABLE | 146025-001 | 17-2 | BO-B814(A) |
| LH4-B814-5 | 107097-101 | BC | UNAVAILABLE | 146025-001 | 17-2 | BO-B814(A) |
| LH4-B814-102 | 107097-101 | BC | UNAVAILABLE | 146025-001 | 17-2 | BO-B814(A) |
| LH4-B815 | S01870-001 | ---- | ---- | | 19-9 | BO-842(A)-H |
| | 159157-001 | 705 | BC-457 | 159158-001 | 17-4-1 | BO-LBH771-H |
| LH4-B815-5 | 107097-101 | BC | UNAVAILABLE | 159158-001 | 17-4-1 | BO-LBH771-H |
| LH4-B816 | 159157-001 | 705 | BC-457 | 159158-001 | 17-4-1 | BO-LBH771-H |
| LH4-B817 | 107097-101 | BC | UNAVAILABLE | 146025-001 | 17-2 | BO-B814(A) |
| LK3-B220 | 116828-001 | 510 | BC-LK(B) | 145265-001 | 27 | BO-LKB(A) |
| | 116828NBL | 510NBL | BC-LK(B)-NBL | | | |
| LK3-B221 | 116828-001 | 510 | BC-LK(B) | 145265-001 | 27 | BO-LKB(A) |
| | 116828NBL | 510NBL | BC-LK(B)-NBL | | | |
| LK3-B222 | 116828-001 | 510 | BC-LK(B) | 145265-001 | 27 | BO-LKB(A) |
| | 116828NBL | 510NBL | BC-LK(B)-NBL | | | |
| LK3-B223 | 116828-001 | 510 | BC-LK(B) | 145265-001 | 27 | BO-LKB(A) |
| | 116828NBL | 510NBL | BC-LK(B)-NBL | | | |
| LK3-B430-1 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B430-2 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B430-3 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B430-4 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B430-5 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B430-6 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B430-7 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B430-8 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B430-9 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B431 | 159610-101 | 510-2 | BC-LK(B2) | 145265-001 | 27 | BO-LKB(A) |
| LK3-B432 | 159610-101 | 510-2 | BC-LK(B2) | 145265-001 | 27 | BO-LKB(A) |
| LK3-B433 | 159610-101 | 510-2 | BC-LK(B2) | 145265-001 | 27 | BO-LKB(A) |
| LK3-B434 | 159610-101 | 510-2 | BC-LK(B2) | 145265-001 | 27 | BO-LKB(A) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-----------------|-------------------|----------|--------------|------------|----------|----------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| | 152690-201 | 510-3 | BC-LK(B3) | 154663-001 | 27-2 | BO-LKB(A)-2 |
| LK3-B435 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B436 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B438 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B438-2 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B438-4 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B441 | 159610-101 | 510-2 | BC-LK(B2) | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B484 | S00691-401 | BC | UNAVAILABLE | S00693-001 | 47 | BO-B484(A)-H |
| | S00690-301 | BC | UNAVAILABLE | S00871-001 | 47-1 | BO-B484 |
| LK3-B485 | S00691-401 | BC | UNAVAILABLE | S00693-001 | 47 | BO-B484(A)-H |
| | S00690-301 | BC | UNAVAILABLE | S00871-001 | 47-1 | BO-B484 |
| LK3-B486 | S00691-401 | BC | UNAVAILABLE | S00693-001 | 47 | BO-B484(A)-H |
| | S00690-301 | BC | UNAVAILABLE | S00871-001 | 47-1 | BO-B484 |
| LK3-B826 | 116828-001 | 510 | BC-LK(B) | 145265-001 | 27 | BO-LKB(A) |
| | 116828NBL | 510NBL | BC-LK(B)-NBL | 159613-001 | 27-4 | BO-LKB(A)-H |
| LK3-B827 | 116828-001 | 510 | BC-LK(B) | 145265-001 | 27 | BO-LKB(A) |
| | 116828NBL | 510NBL | BC-LK(B)-NBL | | | |
| LK3-B828 | 116828-001 | 510 | BC-LK(B) | 145265-001 | 27 | BO-LKB(A) |
| | 116828NBL | 510NBL | BC-LK(B)-NBL | 159613-001 | 27-4 | BO-LKB(A)-H |
| LS2-B837 | | ---- | ---- | 150971-001 | 31-3 | BO-1215L-N |
| | | | | 156380-001 | 31-2 | BO-1215L(A) |
| LS2-B837-5 | | ---- | ---- | 150971-001 | 31-3 | BO-1215L-N |
| | | | | 156380-001 | 31-2 | BO-1215L(A) |
| LS2-B872 | | ---- | ---- | 155484-001 | 26-2 | BO-1215MM(A) |
| LS2-B872-400 | S09278-001 | CAP | UNAVAILABLE | S09285-001 | 26-2-1 | BO-1215MM(A)-H |
| LS2-B875 | S09280-001 | CAP | UNAVAILABLE | S09285-001 | 26-2-1 | BO-1215MM(A)-H |
| LS2-B883 | S21674-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| LT2-B831-1 | 151138-001 | CAP | UNAVAILABLE | 112781-001 | 19-3 | BO-112(3) |
| LT2-B831-3 | 151138-001 | CAP | UNAVAILABLE | 112781-001 | 19-3 | BO-112(3) |
| LT2-B831-5 | | ---- | ---- | 112781-001 | 19-3 | BO-112(3) |
| LT2-B832 | 154517-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B832-1 | 151138-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B832-3 | 151138-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B832-3-0 | 159937-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B832-3-0(A) | | ---- | ---- | 148603-001 | 19-2 | BO-112(A) |
| LT2-B832-5 | | ---- | ---- | 148603-001 | 19-2 | BO-112(A) |
| LT2-B832-5-0 | 159937-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B832-400 | | ---- | ---- | 148603-001 | 19-2 | BO-112(A) |
| LT2-B832-401 | 159937-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B832-403 | 159937-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B832-405 | 159937-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B832-503 | 159937-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B832-505 | | ---- | ---- | 148603-001 | 19-2 | BO-112(A) |
| LT2-B833 | 154517-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B833-3-0 | 154517-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B835-3 | 151041-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B835-3-0 | 151044-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B835-3-0(A) | | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B835-5-0 | 151044-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B835-5-0(A) | | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B835-400 | 151044-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B835-403 | 151044-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| | 159803-001 | ---- | ---- | 112781-001 | 19-3 | BO-112(3) |
| LT2-B835-405 | 151044-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| | 159803-001 | ---- | ---- | 112781-001 | 19-3 | BO-112(3) |
| LT2-B835-500 | 151044-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B835-503 | 151044-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| | 159803-001 | ---- | ---- | 112781-001 | 19-3 | BO-112(3) |
| LT2-B835-505 | 151044-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| | 159803-001 | ---- | ---- | 112781-001 | 19-3 | BO-112(3) |
| LT2-B835-800 | 151041-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| | 159803-001 | ---- | ---- | 112781-001 | 19-3 | BO-112(3) |
| LT2-B835-900 | 151044-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| | 159803-001 | ---- | ---- | 112781-001 | 19-3 | BO-112(3) |
| LT2-B835-903 | 151044-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| | 159803-001 | ---- | ---- | 112781-001 | 19-3 | BO-112(3) |
| LT2-B835-905 | 151044-001 | CAP | UNAVAILABLE | 148603-001 | 19-2 | BO-112(A) |
| LT2-B836 | 155476-001 | CAP | UNAVAILABLE | 155484-001 | 26-2 | BO-1215MM(A) |
| LT2-B836-3 | 155476-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| LT2-B837 | | ---- | ---- | 150971-001 | 31-3 | BO-1215L-N |
| LT2-B837-300 | | ---- | ---- | 150971-001 | 31-3 | BO-1215L-N |
| LT2-B838 | | ---- | ---- | 150971-001 | 31-3 | BO-1215L-N |
| LT2-B838-5 | | ---- | ---- | 150971-001 | 31-3 | BO-1215L-N |
| LT2-B841 | S07740-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B841-1 | S07740-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B841-3 | | ---- | ---- | | ---- | ---- |
| LT2-B841-5 | | ---- | ---- | | ---- | ---- |
| LT2-B842 | S07740-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B842-1 | | ---- | ---- | | ---- | ---- |
| LT2-B842-3 | | ---- | ---- | | ---- | ---- |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------------|-------------------|----------|----------------|------------|----------|----------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| LT2-B842-5 | | ---- | ---- | | ---- | ---- |
| LT2-B842-403 | | ---- | ---- | | ---- | ---- |
| LT2-B842-405 | | ---- | ---- | | ---- | ---- |
| LT2-B842-903 | S07740-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B842-905 | S07740-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B845 | S07741-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| | S07742-001 | CAP | UNAVAILABLE | | | |
| LT2-B845-3 | S07741-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B845-5 | S07741-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B845-7 | S07741-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B845-403 | S07742-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B845-405 | S07742-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B845-407 | S07742-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B845-903 | S07742-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B845-905 | S07742-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B845-907 | S07742-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B847 | S07740-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B847-1 | S07740-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B847-401 | S07740-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B847-901 | S07740-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B848 | S07741-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| | S07742-001 | CAP | UNAVAILABLE | | | |
| LT2-B848-1 | S07741-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B848-401 | S07742-001 | CAP | UNAVAILABLE | S01928-101 | 19-10 | BO-B842(A2)-H |
| LT2-B872 | S09278-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| LT2-B872-3 | S09278-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| LT2-B872-5 | S09278-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| LT2-B872-403 | S09278-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| LT2-B872-405 | S09278-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| LT2-B872-903 | S09278-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| LT2-B872-905 | S09278-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| LT2-B875 | S09279-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| | S09280-001 | CAP | UNAVAILABLE | S09285-001 | 26-2-1 | BO-1215MM(A)-H |
| LT2-B875-3 | S09279-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| LT2-B875-5 | S09279-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| LT2-B875-7 | S09279-001 | CAP | UNAVAILABLE | 155484-101 | 26-5 | BO-B872(A) |
| LT2-B875-403 | S09280-001 | CAP | UNAVAILABLE | S09285-001 | 26-2-1 | BO-1215MM(A)-H |
| LT2-B875-405 | S09280-001 | CAP | UNAVAILABLE | S09285-001 | 26-2-1 | BO-1215MM(A)-H |
| LT2-B875-407 | S09280-001 | CAP | UNAVAILABLE | S09285-001 | 26-2-1 | BO-1215MM(A)-H |
| LT2-B875-903 | S09280-001 | CAP | UNAVAILABLE | S09285-001 | 26-2-1 | BO-1215MM(A)-H |
| LT2-B875-905 | S09280-001 | CAP | UNAVAILABLE | S09285-001 | 26-2-1 | BO-1215MM(A)-H |
| LT2-B882 | | ---- | ---- | 155484-001 | 26-2 | BO-1215MM(A) |
| LZ1-B851 | 107097-101 | BC | UNAVAILABLE | 146025-001 | 17-2 | BO-B814(A) |
| LZ2-B831 | | ---- | ---- | 112781-101 | 19-14 | BO-112(7) |
| LZ2-B842 | | ---- | ---- | S01928-101 | 19-10 | BO-B842(A2)-H |
| LZ2-B852 | 158471-001 | 705 | BC-457 | 158205-001 | 17-3-1 | BO-LBH761 |
| LZ2-B853 | 158471-001 | 705 | BC-457 | 158205-001 | 17-3-1 | BO-LBH761 |
| LZ2-B854 | 158471-001 | 705 | BC-457 | 158205-001 | 17-3-1 | BO-LBH761 |
| TA1-B75-013 | 100369-001 | 601 | BC-DB1 | 117132-001 | 13-4 | BO-400(4) |
| TA1-B621 | 100369-001 | 601 | BC-DB1 | 100376-001 | 2 | BO-103(2) |
| TA2-B621 | 100369-001 | 601 | BC-DB1 | 100376-001 | 2 | BO-103(2) |
| TA2-B622 | 100369-001 | 601 | BC-DB1 | 100376-001 | 2 | BO-103(2) |
| TA2-B623 | 100369-001 | 601 | BC-DB1 | 100376-001 | 2 | BO-103(2) |
| TZ1-B651 | 117596-001 | 609 | BC-DBZ(1) | 100376-001 | 2 | BO-103(2) |
| | S17096-001 | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | 117569NBL9 | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| TZ1-B652 | 117596-001 | 609 | BC-DBZ(1) | 100376-001 | 2 | BO-103(2) |
| | S17096-001 | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | 117569NBL9 | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| TZ1-B798 | | ---- | ---- | S01587-001 | 21-7 | BO-DBM(3)N |
| TZ1-B852 | 158471-001 | 705 | BC-457 | 158205-001 | 17-3-1 | BO-LBH761 |
| HOUSEHOLD | 128582-002 | 210 | BC-HZ10 | | ---- | ---- |
| | 128582-003 | 207 | BC-HZ7 | | | |
| | 116638-001 | 304 | BC-HR1 | 129714-001 | 5-2 | BO-103(Z)-2 |
| | 121447-001 | 307 | BC-HR4 | 129714-001 | 5-2 | BO-103(Z)-2 |
| BUTTERFLY | | | | | | |
| GC25-1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GC25-2 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GY4-1 | | 615NBL6 | BC-DBZ(3)-NBL6 | | 22 | BO-DBM(A) |
| CHANDLER | | | | | | |
| DARNER | DM-78-AS/2DL5-78 | ---- | ---- | DM110 | ---- | ---- |
| DY-337 | R1144 | 801 | BC-DBM(1) | R1143 | 21-5 | BO-DBM(1)N |
| HCH-1 | | ---- | ---- | | ---- | ---- |
| CHIKON | | | | | | |
| CK-8BL-1 | | 806NBL1 | BC-DBM(2)-NBL1 | | 22 | BO-DBM(A) |
| CK-563 | | ---- | ---- | | 26-2 | BO-1215MM(A) |
| SD-767TR | | ---- | ---- | | ---- | ---- |
| SLH-2B | | ---- | ---- | | ---- | ---- |
| SLH-767R | | ---- | ---- | | ---- | ---- |
| STH-8BL | | 806NBL1 | BC-DBM(2)-NBL1 | | 22 | BO-DBM(A) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|--------------------------|-------------------|----------|-----------------|---------------------|----------|------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| CHIYODA | | | | | | |
| LZ-201 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| LZ-301 | | 802 | BC-DBM(Z1) | | 22 | BO-DBM(A) |
| CHUAN NENG | | | | | | |
| CN-915-3 | | 801NBL1 | BC-DBM(1)-NBL1 | MEC504000DBM | 22 | BO-DBM(A) |
| CN-915-5 | MEC503000DBM | 803NBL5 | BC-DBM(Z2)-NBL5 | MEC504000DBM | 22 | BO-DBM(A) |
| CN-990-3 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| CN-990-5 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| CN-990-7 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| CN-991-3 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| CN-991-5 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| CN-991-7 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| CN-992-3 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| CN-992-5 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| CN-992-7 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| CIUCANI MOCASSINO | | | | | | |
| MC-88 | 10159/1 | ---- | ---- | | ---- | ---- |
| COLUMBIA | | | | | | |
| N430 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| N430-2 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| CONSEW | | | | | | |
| 18 | 6017 | ---- | ---- | 6018 | ---- | ---- |
| 30 | 211C | ---- | ---- | 212C | ---- | ---- |
| 99 | B-75(284) | 609-1 | BC-DBZ(C) | B74 | 5 | BO-103(Z) |
| 100 | 2110104-301B | 601NBL2 | BC-DB1-NBL2 | 182(2110104-321) | 2 | BO-103(2) |
| | 2110604-301B | | | AH412B(2110114-321) | 10 | BO-95(A) |
| 101 | 2110104-301C | 601 | BC-DB1 | 182(2110104-321) | 2 | BO-103(2) |
| | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AH412B(2110114-321) | 10 | BO-95(A) |
| 103 | B-75(284) | 609-1 | BC-DBZ(C) | B74 | 5 | BO-103(Z) |
| 105 | 2110104-301B | 601NBL2 | BC-DB1-NBL2 | 2110104-321 | 2 | BO-103(2) |
| 118 | 6017 | ---- | ---- | 6018 | ---- | ---- |
| 120 | 2120304-301 | 801 | BC-DBM(1) | 2120314-312 | 21-5 | BO-DBM(1)N |
| | | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| 120R | | ---- | ---- | 2120314-312 | 21-5 | BO-DBM(1)N |
| 133 CLASS | B-75(284) | 609-1 | BC-DBZ(C) | 283 | 5 | BO-103(Z) |
| 139 CLASS | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 145 | B-84 | 802 | BC-DBM(Z1) | B-83 | 21-5 | BO-DBM(1)N |
| 146RB | B-84 | 802 | BC-DBM(Z1) | B-83 | 21-5 | BO-DBM(1)N |
| 146RBL | 137A(714) | 802 | BC-DBM(Z1) | 2120314-312 | 21-5 | BO-DBM(1)N |
| 175 | 137A(714) | 802 | BC-DBM(Z1) | 137B(2130104-321) | 22 | BO-DBM(A) |
| 175R | 137A(714) | 802 | BC-DBM(Z1) | 137B(2130104-321) | 22 | BO-DBM(A) |
| 175RB | 2130104-301A | 803NBL5 | BC-DBM(Z2)-NBL5 | 2120304-312 | 21-5 | BO-DBM(1)N |
| 176R | 137A(714) | 802 | BC-DBM(Z1) | 137B(2130104-321) | 22 | BO-DBM(A) |
| 180 | | ---- | ---- | 6015 | ---- | ---- |
| 180J | | ---- | ---- | 6015 | ---- | ---- |
| 181 | | ---- | ---- | 6015 | ---- | ---- |
| 182 | | ---- | ---- | 6015 | ---- | ---- |
| 199 | B-75(284) | 609-1 | BC-DBZ(C) | 283B | 5 | BO-103(Z) |
| 199R | B-75(284) | 609-1 | BC-DBZ(C) | 283B | 5 | BO-103(Z) |
| 199RB | 1144 | 806NBL1 | BC-DBM(2)-NBL1 | 2120314-312 | 21-5 | BO-DBM(1)N |
| 199RBL | 1144 | 806NBL1 | BC-DBM(2)-NBL1 | 2120314-312 | 21-5 | BO-DBM(1)N |
| 204RB | 1144 | 806NBL1 | BC-DBM(2)-NBL1 | 2120314-312 | 21-5 | BO-DBM(1)N |
| 205RB | 1144 | 806NBL1 | BC-DBM(2)-NBL1 | 2120314-312 | 21-5 | BO-DBM(1)N |
| 206RB | 18045 | 806NBL1 | BC-DBM(2)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |
| 207 | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 208RB | 1144 | 806NBL1 | BC-DBM(2)-NBL1 | 2120314-312 | 21-5 | BO-DBM(1)N |
| 210 | 2110104-301B | 601NBL2 | BC-DB1-NBL2 | 2110104-321 | 2 | BO-103(2) |
| 218 | 2110104-301B | 601NBL2 | BC-DB1-NBL2 | 2110104-321 | 2 | BO-103(2) |
| 219 | 2110104-301B | 601NBL2 | BC-DB1-NBL2 | 2110104-321 | 2 | BO-103(2) |
| 223 CLASS | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 224 CLASS | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 225 CLASS | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 226 CLASS | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 227 CLASS | 13086 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 228 CLASS | 12124 | CAP | UNAVAILABLE | 12125 | 19-3 | BO-112(3) |
| 229 CLASS | 12124 | CAP | UNAVAILABLE | 12125 | 19-3 | BO-112(3) |
| 230 | 2110104-301B | 601NBL2 | BC-DB1-NBL2 | 2110104-321 | 2 | BO-103(2) |
| 230B | 2110104-301C | 601 | BC-DB1 | 182(2110104-321) | 2 | BO-103(2) |
| 231R | 2110104-301C | 601 | BC-DB1 | 182(2110104-321) | 2 | BO-103(2) |
| | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AH412B(2110114-321) | 10 | BO-95(A) |
| 231RH | 2110104-301C | 601 | BC-DB1 | 182(2110104-321) | 2 | BO-103(2) |
| 237 CLASS | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 237VM | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 238 CLASS | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 239 CLASS | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 241 | | ---- | ---- | | ---- | ---- |
| 244 CLASS | 15040-2 | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| 245 | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-----------|--------------------|----------|----------------|---------------------|----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 254 CLASS | 15040-2 | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| 255 CLASS | 30507-9 | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| 255RBATC | 15040-2 | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| 256 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 266RI | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 277R | 17034 | 903 | BC-PF9076 | 17035 | 24 | BO-PF130 |
| 277RFS | 17034 | 903 | BC-PF9076 | 17035 | 24 | BO-PF130 |
| 282 | 12124 | CAP | UNAVAILABLE | 12125 | 19-3 | BO-112(3) |
| 282R-1 | 12124 | CAP | UNAVAILABLE | 10656 | 19-3 | BO-112(3) |
| 282RB | 15040-2 | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| 288 | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 289 | 12124 | CAP | UNAVAILABLE | 10656 | 19-3 | BO-112(3) |
| 289R-1 | 12124 | CAP | UNAVAILABLE | 10656 | 19-3 | BO-112(3) |
| 289RB | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| 290 | 2110104-301B | 601NBL2 | BC-DB1-NBL2 | 2110104-321 | 2 | BO-103(2) |
| 290R | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321A | 10 | BO-95(A) |
| | | | | 2110114-321B | | |
| 290RATCW | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AH412B(2110114-321) | 10 | BO-95(A) |
| 290RTC | 2120604-301 | ---- | ---- | 2110114-321 | 10 | BO-95(A) |
| 291R | 2110104-301C | 601 | BC-DB1 | B127(2110104-321) | 2 | BO-103(2) |
| | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AH412B(2110114-321) | 10 | BO-95(A) |
| 291RH | 2110104-301C | 601 | BC-DB1 | B127(2110104-321) | 2 | BO-103(2) |
| 291RATC | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AH412B(2110114-321) | 10 | BO-95(A) |
| 291RATCW | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AH412B(2110114-321) | 10 | BO-95(A) |
| 291RTC | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AH412B(2110114-321) | 10 | BO-95(A) |
| 306RB | 18045 | 806NBL1 | BC-DBM(2)-NBL1 | 2120314-312 | 21-5 | BO-DBM(1)N |
| 310 | 2110104-301B | 601NBL2 | BC-DB1-NBL2 | 2110104-321 | 2 | BO-103(2) |
| 312RATC | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AH412B(2110114-321) | 10 | BO-95(A) |
| 314RATC | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AH412B(2110114-321) | 10 | BO-95(A) |
| 315R | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| 315RATC | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AH415B(2110114-321) | 10 | BO-95(A) |
| 315RTC | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AH415B(2110114-321) | 10 | BO-95(A) |
| 315-1RATC | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AH415B(2110114-321) | 10 | BO-95(A) |
| 318R | 2110104-301C | 601 | BC-DB1 | AD415B(2110114-321) | 2 | BO-103(2) |
| | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AH415B(2110114-321) | 10 | BO-95(A) |
| 318RATC | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AD415B(2110114-431) | 10 | BO-95(A) |
| 318RTC | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AD415B(2110114-431) | 10 | BO-95(A) |
| 318-1RATC | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | AD415B(2110114-431) | 10 | BO-95(A) |
| 327 | 16291-6 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 327R | 16291-6 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 327R-1 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 327RB | 16407-9 | ---- | ---- | 16408 | 26-3 | BO-1215MM-N |
| 327RB-1 | | ---- | ---- | 16408 | 26-3 | BO-1215MM-N |
| 328RB | | ---- | ---- | 16408 | 26-3 | BO-1215MM-N |
| 328RB-1 | | ---- | ---- | 16408 | 26-3 | BO-1215MM-N |
| 328RBATC | | ---- | ---- | 16408 | 26-3 | BO-1215MM-N |
| 332 CLASS | 248460 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 333 CLASS | 15040-2 | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| 339 CLASS | 15040-2 | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| 347 CLASS | 502530 | 705 | BC-457 | B54 | 17 | BO-107(A) |
| 357 CLASS | 12124 | CAP | UNAVAILABLE | 12125 | 19-3 | BO-112(3) |
| 358 CLASS | 12124 | CAP | UNAVAILABLE | 12125 | 19-3 | BO-112(3) |
| 359 CLASS | 12124 | CAP | UNAVAILABLE | 10656 | 19-3 | BO-112(3) |
| 362 | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 375 | B-53(2130704-301A) | 705 | BC-457 | 123(2130504-321) | 17 | BO-107(A) |
| 375R | B-53(2130704-301A) | 705 | BC-457 | 123(2130504-321) | 17 | BO-107(A) |
| 376 | B-53(2130704-301A) | 705 | BC-457 | 123(2130504-321) | 17 | BO-107(A) |
| 376R | B-53(2130704-301A) | 705 | BC-457 | 123(2130504-321) | 17 | BO-107(A) |
| 382 CLASS | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 388 CLASS | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| | | | | 15041 | 31-3 | BO-1215L-N |
| 389 CLASS | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| 389RB | 15040-2 | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| 722 CLASS | B-75(284) | 609-1 | BC-DBZ(C) | B74 | 5 | BO-103(Z) |
| 733R | | ---- | ---- | 35226 | ---- | ---- |
| 744R | | ---- | ---- | | ---- | ---- |
| 745R | | ---- | ---- | | ---- | ---- |
| 751R | | ---- | ---- | 28092 | ---- | ---- |
| 753R | | ---- | ---- | 28092 | ---- | ---- |
| 754R | | ---- | ---- | 28092 | ---- | ---- |
| 756R | | ---- | ---- | 28092 | ---- | ---- |
| 825 CLASS | B-75(284) | 609-1 | BC-DBZ(C) | B74 | 5 | BO-103(Z) |
| CUB | | | | | | |
| CUB-691 | | C-2 | CP-PF151 | | ---- | ---- |
| CUB-692 | | C-2 | CP-PF151 | | ---- | ---- |
| CUB-810 | | ---- | ---- | | 19-3 | BO-112(3) |
| CUB-820 | | ---- | ---- | | 19-3 | BO-112(3) |
| DALIAN | | | | | | |
| GI3 | | 702 | BC-107(2) | | 17-3 | BO-LBH761 |
| GI8 | | 710 | BC-LBH771 | | 17-4 | BO-LBH771 |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|----------------|-------------------|----------|----------------|-----------|----------|-----------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| DIAMOND | | | | | | |
| TB-335 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| TB-471 | | C-2 | CP-PF151 | | ----- | ----- |
| TB-491 | | C-2 | CP-PF151 | | ----- | ----- |
| TB-545 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| TB-546 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| TB-810 | | ---- | ---- | | 19-3 | BO-112(3) |
| TB-820 | | ---- | ---- | | 19-3 | BO-112(3) |
| TB-1245 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| TB-1245L | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| TB-1246 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| TE-6 | | ---- | ---- | | ----- | ----- |
| TF-6 | | ---- | ---- | | ----- | ----- |
| DURKOPP | | | | | | |
| 21 | | ---- | ---- | | ----- | ----- |
| 61 | | ---- | ---- | | 38 | BO-45 |
| 62 | | ---- | ---- | | 38 | BO-45 |
| 203 | 204-335 | 1002 | BC-DU216 | 204-230 | 2 | BO-103(2) |
| 204 | 204-335 | 1002 | BC-DU216 | 204-230 | 2 | BO-103(2) |
| 205 | 204-335 | 1002 | BC-DU216 | 204-230 | 2 | BO-103(2) |
| 206 | 204-335 | 1002 | BC-DU216 | 204-230 | 2 | BO-103(2) |
| 207 | 204-335 | 1002 | BC-DU216 | 204-230 | 2 | BO-103(2) |
| 211 | 211-275 | 1001 | BC-DU211 | 204-230 | 2 | BO-103(2) |
| | 211-275NBL | 1001NBL | BC-DU211-NBL | 204-230A | 6 | BO-103(A) |
| | 211-275M | 1001M | BC-DU211-M | 204-230 | 2 | BO-103(2) |
| | 211-288 | 1001NS | BC-DU211NS | | | |
| | 211-926 | 1001NS-2 | BC-DU211NS-2 | 204-230A | 6 | BO-103(A) |
| | 211-10772 | 1001NS-3 | BC-DU211NS-3 | 204-230 | 2 | BO-103(2) |
| 212 | 211-275 | 1001 | BC-DU211 | 204-230 | 2 | BO-103(2) |
| | 211-275NBL | 1001NBL | BC-DU211-NBL | 204-230A | 6 | BO-103(A) |
| | 211-275M | 1001M | BC-DU211-M | 204-230 | 2 | BO-103(2) |
| | 211-288 | 1001NS | BC-DU211NS | | | |
| | 211-926 | 1001NS-2 | BC-DU211NS-2 | 204-230A | 6 | BO-103(A) |
| | 211-10772 | 1001NS-3 | BC-DU211NS-3 | 204-230 | 2 | BO-103(2) |
| 213 | 211-275 | 1001 | BC-DU211 | 204-230 | 2 | BO-103(2) |
| | 211-275NBL | 1001NBL | BC-DU211-NBL | 204-230A | 6 | BO-103(A) |
| | 211-275M | 1001M | BC-DU211-M | 204-230 | 2 | BO-103(2) |
| | 211-288 | 1001NS | BC-DU211NS | | | |
| | 211-926 | 1001NS-2 | BC-DU211NS-2 | 204-230A | 6 | BO-103(A) |
| | 211-10772 | 1001NS-3 | BC-DU211NS-3 | 204-230 | 2 | BO-103(2) |
| 215 | 211-275 | 1001 | BC-DU211 | 204-230 | 2 | BO-103(2) |
| | 211-275NBL | 1001NBL | BC-DU211-NBL | 204-230A | 6 | BO-103(A) |
| | 211-275M | 1001M | BC-DU211-M | 204-230 | 2 | BO-103(2) |
| | 211-288 | 1001NS | BC-DU211NS | | | |
| | 211-926 | 1001NS-2 | BC-DU211NS-2 | 204-230A | 6 | BO-103(A) |
| | 211-10772 | 1001NS-3 | BC-DU211NS-3 | 204-230 | 2 | BO-103(2) |
| 216 | 204-335 | 1002 | BC-DU216 | 204-230 | 2 | BO-103(2) |
| 218 | 211-275 | 1001 | BC-DU211 | 204-230 | 2 | BO-103(2) |
| | 211-275NBL | 1001NBL | BC-DU211-NBL | 204-230A | 6 | BO-103(A) |
| | 211-275M | 1001M | BC-DU211-M | 204-230 | 2 | BO-103(2) |
| | 211-288 | 1001NS | BC-DU211NS | | | |
| | 211-926 | 1001NS-2 | BC-DU211NS-2 | 204-230A | 6 | BO-103(A) |
| | 211-10772 | 1001NS-3 | BC-DU211NS-3 | 204-230 | 2 | BO-103(2) |
| 221 | 249-369 | CAP | UNAVAILABLE | 245-1660A | 19-2 | BO-112(A) |
| 222 | 249-369 | CAP | UNAVAILABLE | 1660A | 19-2 | BO-112(A) |
| 237 | 249-369 | CAP | UNAVAILABLE | 1660A | 19-2 | BO-112(A) |
| 238 | 249-369 | CAP | UNAVAILABLE | 1660A | 19-2 | BO-112(A) |
| 239 | 249-369 | CAP | UNAVAILABLE | 1660A | 19-2 | BO-112(A) |
| 241 | 249-369 | CAP | UNAVAILABLE | 1660A | 19-2 | BO-112(A) |
| 242 | 249-369 | CAP | UNAVAILABLE | 1660A | 19-2 | BO-112(A) |
| 244 | 249-369 | CAP | UNAVAILABLE | 245-1660A | 19-2 | BO-112(A) |
| 245 | 249-369 | CAP | UNAVAILABLE | 245-1660A | 19-2 | BO-112(A) |
| 246 | 249-369 | CAP | UNAVAILABLE | 245-1660A | 19-2 | BO-112(A) |
| 247 | 249-369 | CAP | UNAVAILABLE | 245-1660A | 19-2 | BO-112(A) |
| 249 | 249-369 | CAP | UNAVAILABLE | 1660A | 19-2 | BO-112(A) |
| 252 | 235-368 | 702 | BC-107(2) | | 17 | BO-107(A) |
| | 235-368NBL | 702NBL | BC-107(2)-NBL | | | |
| 253 | 235-368 | 702 | BC-107(2) | | 17 | BO-107(A) |
| | 235-368NBL | 702NBL | BC-107(2)-NBL | | | |
| 254 | 235-368 | 702 | BC-107(2) | | 17 | BO-107(A) |
| | 235-368NBL | 702NBL | BC-107(2)-NBL | | | |
| 255 | 235-368 | 702 | BC-107(2) | | 17 | BO-107(A) |
| | 235-368NBL | 702NBL | BC-107(2)-NBL | | | |
| 261 | 211-926 | 1001NS-2 | BC-DU211NS-2 | 204-230A | 6 | BO-103(A) |
| | 211-10772 | 1001NS-3 | BC-DU211NS-3 | 204-230 | 2 | BO-103(2) |
| 264 | 235-368 | 702 | BC-107(2) | | 17 | BO-107(A) |
| | 235-368NBL | 702NBL | BC-107(2)-NBL | | | |
| 265 | 265-965 | 1003 | BC-DU265 | 204-230A | 6 | BO-103(A) |
| | 265-979 | 1003NS | BC-DU265NS | | | |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------------|-------------------|----------|---------------------|----------|----------|--------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| | 265-10224 | 1003NS-2 | BC-DU265NS-2 | | | |
| 265-101 | 211-1115 | 1001NS-4 | BC-DU211NS-4 | 204-230 | 2 | BO-103(2) |
| 265-108 | 265-776 | 1006 | BC-DU265BIG | 265-789 | ----- | ----- |
| 265-203 | 265-965 | 1003 | BC-DU265 | 204-230A | 6 | BO-103(A) |
| | 211-275NBL | 1001NBL | BC-DU211-NBL | | | |
| 265-208 | 265-772 | 1006NS | BC-DU265BIG(NS)-NBL | 265-789 | ----- | ----- |
| 265-301 | 265-772 | 1006NS | BC-DU265BIG(NS)-NBL | 265-789 | ----- | ----- |
| 265-305 | 265-772 | 1006NS | BC-DU265BIG(NS)-NBL | 265-789 | ----- | ----- |
| | | ---- | ---- | | ----- | ----- |
| 265-115203 | | | | | | |
| 266 | 265-965 | 1003 | BC-DU265 | 204-230A | 6 | BO-103(A) |
| | 265-979 | 1003NS | BC-DU265NS | | | |
| | 265-10224 | 1003NS-2 | BC-DU265NS-2 | | | |
| 267 | 265-965 | 1003 | BC-DU265 | 204-230A | 6 | BO-103(A) |
| | 265-979 | 1003NS | BC-DU265NS | | | |
| | 265-10224 | 1003NS-2 | BC-DU265NS-2 | | | |
| 268 | 265-965 | 1003 | BC-DU265 | 204-230A | 6 | BO-103(A) |
| | 265-979 | 1003NS | BC-DU265NS | | | |
| | 265-10224 | 1003NS-2 | BC-DU265NS-2 | | | |
| 269 | 265-965 | 1003 | BC-DU265 | 204-230A | 6 | BO-103(A) |
| | 265-979 | 1003NS | BC-DU265NS | | | |
| | 265-10224 | 1003NS-2 | BC-DU265NS-2 | | | |
| 270 | 204-335 | 1002 | BC-DU216 | 204-230 | 2 | BO-103(2) |
| 271 | 211-1115 | 1001NS-4 | BC-DU211NS-4 | 204-230A | 6 | BO-103(A) |
| 272 | 211-1115 | 1001NS-4 | BC-DU211NS-4 | 204-230A | 6 | BO-103(A) |
| 380 | 249-369 | CAP | UNAVAILABLE | 1660A | 19-2 | BO-112(A) |
| | 380-508 | CAP | UNAVAILABLE | | | |
| | 380-3845 | CAP | UNAVAILABLE | | | |
| 380-15305 | 238-6799 | CAP | UNAVAILABLE | | ----- | ----- |
| 380-15535 | 238-6799 | CAP | UNAVAILABLE | | ----- | ----- |
| 460 | | ---- | ---- | | ----- | ----- |
| 541 | 249-369 | CAP | UNAVAILABLE | 249-372 | 19-2 | BO-112(A) |
| 542 | 249-369 | CAP | UNAVAILABLE | 1660A | 19-2 | BO-112(A) |
| 543 | 249-369 | CAP | UNAVAILABLE | 1660A | 19-2 | BO-112(A) |
| 549 | 249-369 | CAP | UNAVAILABLE | 1660A | 19-2 | BO-112(A) |
| | 549-1491 | CAP | UNAVAILABLE | | ----- | ----- |
| 551 | | 1007 | BC-DU551 | 555-919 | ----- | ----- |
| 555 | | 1007 | BC-DU551 | 555-919 | ----- | ----- |
| 556 | 556-5044 | 1008 | BC-DU556 | 1603 | ----- | ----- |
| 557 | 556-5044 | 1008 | BC-DU556 | 1603 | ----- | ----- |
| 558 | 556-5044 | 1008 | BC-DU556 | 1603 | ----- | ----- |
| 570 | 5701243A | ---- | ---- | 1015 | ----- | ----- |
| 697 | 249-369 | CAP | UNAVAILABLE | 1660A | 19-2 | BO-112(A) |
| 746 | | ---- | ---- | | ----- | ----- |
| 15135 | 211-1115 | 1001NS-4 | BC-DU211NS-4 | 204-230 | 2 | BO-103(2) |
| 15305 | 265-772 | 1006NS | BC-DU265BIG(NS)-NBL | 265-789 | ----- | ----- |
| EAGLE | | | | | | |
| EA-106 | | 806NBL1 | BC-DBM(2)-NBL1 | | 22 | BO-DBM(A) |
| EA-156R | | ---- | ---- | | 26-2 | BO-1215MM(A) |
| EA-156RB | | ---- | ---- | | 26-2 | BO-1215MM(A) |
| EA-206D | | 806NBL1 | BC-DBM(2)-NBL1 | | 22 | BO-DBM(A) |
| EA-256RB | | ---- | ---- | | 31-3 | BO-1215L-N |
| EA-2156RB | | ---- | ---- | | 31-3 | BO-1215L-N |
| EA-733 | | ---- | ---- | | ----- | ----- |
| EA-810 | | ---- | ---- | | 19-3 | BO-112(3) |
| EA-820 | | ---- | ---- | | 19-3 | BO-112(3) |
| EA-991 | | C-2 | CP-PF151 | | ----- | ----- |
| EA-992 | | C-2 | CP-PF151 | | ----- | ----- |
| EA-2156C | | ---- | ---- | | 21-5 | BO-DBM(1)N |
| OS-2000 | | 802 | BC-DBM(Z1) | | 22 | BO-DBM(A) |
| ELTAC | | | | | | |
| 750 series | 2-20 | 615NBL9 | BC-DBZ(3)-NBL9 | 2-19 | 14-3 | BO-400(3)N |
| 800 series | H-15 | 802NBL3 | BC-DBM(Z1)-NBL3 | H-16 | 21-6 | BO-DBM(2)N |
| 900 series | H-15 | 802NBL3 | BC-DBM(Z1)-NBL3 | H-16 | 21-6 | BO-DBM(2)N |
| 1000 series | H-15 | 802NBL3 | BC-DBM(Z1)-NBL3 | H-16 | 21-6 | BO-DBM(2)N |
| 1250 series | H-15 | 802NBL3 | BC-DBM(Z1)-NBL3 | H-16 | 21-6 | BO-DBM(2)N |
| 1600 series | H-15 | 802NBL3 | BC-DBM(Z1)-NBL3 | H-16 | 21-6 | BO-DBM(2)N |
| 1800 series | H-15 | 802NBL3 | BC-DBM(Z1)-NBL3 | H-16 | 21-6 | BO-DBM(2)N |
| FEYYUE | | | | | | |
| GC15-1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GC15-3 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| FENG GONG | | | | | | |
| GC1-4 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GC1-6 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| FENG YING | | | | | | |
| FY-810 | | ---- | ---- | | 19-3 | BO-112(3) |
| FY-820 | | ---- | ---- | | 19-3 | BO-112(3) |
| FLYINGMAN | | | | | | |
| GC51-1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GG0802 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-------------------------------|-------------------|----------|----------------|-----------|----------|---------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| FOMAX | | | | | | |
| KDD-5570 | A1837-555-000 | 601 | BC-DB1 | | 2 | BO-103(2) |
| KDD-5570H | A1837-555-000 | 601 | BC-DB1 | | 2 | BO-103(2) |
| KDD-5570HB | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| KDD-5570-7 | K1837-000 | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| KDD-5570H-7 | K1837-000 | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| GELLMAN | | | | | | |
| 68 | | ---- | ---- | | ---- | ---- |
| GOLDEN WHEEL | | | | | | |
| CS-3L7241 | | ---- | ---- | 102-31603 | 26-2 | BO-1215MM(A) |
| CS-3L7243 | | ---- | ---- | 102-31603 | 26-2 | BO-1215MM(A) |
| CS-8B | | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| CS-8BH | | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| CS-8BH | | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| CS-335B | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| CS-335BH | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| CS-335BH | | ---- | ---- | | ---- | ---- |
| CS-350 | | 601 | BC-DB1 | | 8 | BO-95(2) |
| CS-350L | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| CS-350L-T | | 801NBL1 | BC-DBM(1)-NBL1 | | 21-7 | BO-DBM(3)N |
| CS-563 | | ---- | ---- | | 26-2 | BO-1215MM(A) |
| CS-810 | | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| CS-820 | | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| CS-831 | | C-2 | CP-PF151 | | ---- | ---- |
| CS-832 | | C-2 | CP-PF151 | | ---- | ---- |
| CS-861 | | C-2 | CP-PF151 | | ---- | ---- |
| CS-862 | | C-2 | CP-PF151 | | ---- | ---- |
| CS-872-3 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| CS-871 | | ---- | ---- | | ---- | ---- |
| CS-871L | | ---- | ---- | | 26-3 | BO-1215MM-N |
| CS-872-3 | | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| CS-872-5 | | ---- | ---- | | ---- | ---- |
| CS-872L | | ---- | ---- | | 26-3 | BO-1215MM-N |
| CS-875-3 | | CAP | UNAVAILABLE | 203470 | 19-3 | BO-112(3) |
| CS-875-5 | | CAP | UNAVAILABLE | 203470 | 19-3 | BO-112(3) |
| CS-875L | | CAP | UNAVAILABLE | 102-31603 | 26-2 | BO-1215MM(A) |
| CS-1100F | | 601NBL6 | BC-DB1-NBL6 | | 2 | BO-103(2) |
| CS-1100H | | 601NBL6 | BC-DB1-NBL6 | | 2 | BO-103(2) |
| CS-1100S | | 601NBL6 | BC-DB1-NBL6 | | 2 | BO-103(2) |
| CS-3100-3 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| CS-3100-5 | | ---- | ---- | | ---- | ---- |
| CS-3100L | | ---- | ---- | | 26-3 | BO-1215MM-N |
| CS-3150-3 | | CAP | UNAVAILABLE | 203470 | 19-3 | BO-112(3) |
| CS-3150-5 | | CAP | UNAVAILABLE | 203470 | 19-3 | BO-112(3) |
| CS-3150L | | CAP | UNAVAILABLE | | 26-3 | BO-1215MM-N |
| CS-3600 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| CS-3610 | | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| CS-6111B | | CAP | UNAVAILABLE | | ---- | ---- |
| CS-6111BT | | CAP | UNAVAILABLE | | ---- | ---- |
| CS-6111T | | CAP | UNAVAILABLE | | ---- | ---- |
| CS-6112B | | CAP | UNAVAILABLE | | ---- | ---- |
| CS-6112BT | | CAP | UNAVAILABLE | | ---- | ---- |
| CS-6112T | | CAP | UNAVAILABLE | | ---- | ---- |
| CS-8000-20 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| CS-8000-25 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| CS-8000-30 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| CS-8810 | | C-2 | CP-PF151 | | ---- | ---- |
| CS-8820 | | C-2 | CP-PF151 | | ---- | ---- |
| CSU-4100H | | 812NBL3 | BC-NJ280L-NBL3 | | 21-5 | BO-DBM(1)N |
| CSZ-3211 | | 801NBL1 | BC-DBM(1)-NBL1 | | 21-5 | BO-DBM(1)N |
| GROSS & MARCO | | | | | | |
| Multi-head embroidery machine | GBC | ---- | ---- | GBB | ---- | ---- |
| HAPPY | | | | | | |
| HCM | M1058NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | 2 | BO-103(2) |
| HM4 | M1058NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | 2 | BO-103(2) |
| HM4B | ESMPZ01060 | BC | UNAVAILABLE | | ---- | ---- |
| HMF | M1058NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | 2 | BO-103(2) |
| | ESMPZ01060 | BC | UNAVAILABLE | | ---- | ---- |
| HMS | M1058NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | 2 | BO-103(2) |
| | ESMPZ01060 | BC | UNAVAILABLE | | ---- | ---- |
| J-4 | M1058NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | 2 | BO-103(2) |
| J-7 | M1058NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | 2 | BO-103(2) |
| J-8 | M1058NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | 2 | BO-103(2) |
| K-4 | M1058NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | 2 | BO-103(2) |
| K-7 | M1058NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | 2 | BO-103(2) |
| K-8 | M1058NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | 2 | BO-103(2) |
| HUANAN | | | | | | |
| GC48-1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| G16-1 | | 702 | BC-107(2) | | 17-3 | BO-LBH761 |
| GC20505-1 | | CAP | UNAVAILABLE | | 19-10 | BO-B842(A2)-H |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------------|-------------------|----------|-----------------|---------------|----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| GC28-1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| HUSQVARNA | | | | | | |
| 27 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | | 8 | BO-95(2) |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 263 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | | 8 | BO-95(2) |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| HOUSEHOLD | 4011530-OS | 213 | BC-VIK | | ----- | ----- |
| I-SHAN | | | | | | |
| IS-335 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| IS-371 | | C-2 | CP-PF151 | | ----- | ----- |
| IS-372 | | C-2 | CP-PF151 | | ----- | ----- |
| IS-810 | | ----- | ----- | | 19-3 | BO-112(3) |
| IS-820 | | ----- | ----- | | 19-3 | BO-112(3) |
| IDEAL | | | | | | |
| IE35872C | | 803NBL2 | BC-DBM(Z2)-NBL2 | | 22 | BO-DBM(A) |
| IE60000 | | ----- | UNAVAILABLE | | ----- | ----- |
| 1 | | 601 | BC-DB1 | | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| 2 | | 601 | BC-DB1 | | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| 3 | | 803NBL2 | BC-DBM(Z2)-NBL2 | | 22 | BO-DBM(A) |
| IVOMAQ | | | | | | |
| CI-2100-2I | | C-2 | CP-PF151 | | ----- | ----- |
| CI-2100-2DI | | C-2 | CP-PF151 | | ----- | ----- |
| CI-2100-202I | | C-2 | CP-PF151 | | ----- | ----- |
| CI-2100-4I | | CAP | UNAVAILABLE | | ----- | ----- |
| CI-2100-4DI | | CAP | UNAVAILABLE | | ----- | ----- |
| CI-2100-204I | | CAP | UNAVAILABLE | | ----- | ----- |
| CI-2100-204TI | | CAP | UNAVAILABLE | | ----- | ----- |
| CI-2100-2AV | | 903NBL | BC-PF9076-NBL | | 24-2 | BO-PF130(A) |
| CI-3000-1I | | ----- | ----- | | 19-3 | BO-112(3) |
| CI-3000-2RTD1 | | C-2 | CP-PF151 | | ----- | ----- |
| CI-3000-4RTD1 | | C-2 | CP-PF151 | | ----- | ----- |
| CI-3000-201I | | ----- | ----- | | 19-3 | BO-112(3) |
| JANOME | | | | | | |
| DB-J701 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| DB-J702 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| DB-J703 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| DB-J704 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| DB-J705 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| DB-J706 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| DB-J706S | | 801 | BC-DBM(1) | 706-014-006 | 21-5 | BO-DBM(1)N |
| | | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| DB-J707 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| DB-J708 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| DB-J709 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| DB-J756 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| DB-J764 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| DB-J765 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| TA-J761 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| TA-J763 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| TA-J766 | 761-511-009 | 601 | BC-DB1 | 761-094-012 | 8 | BO-95(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| JUKI | | | | | | |
| ACF-161-981 | B1828-980-0A0 | 511-2 | BC-LK(J2) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| ADU-332 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| ADU-992 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| ADU-1852 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| ADU-1853 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| ADU-1854 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-------------|-------------------|----------|----------------|---------------|-----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| AE-6 | GAE06039-0B0 | ---- | ---- | B1809-761-000 | 17-3 | BO-LBH761 |
| AEC-112 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| AMC-206C | B1818-205-0A0 | ---- | ---- | B1805-210-000 | ALUMINIUM | ---- |
| AMS-12A | B1828-980-0AB | 511-3 | BC-LK(J3) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| AMS-205A | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| | | | | B1805-210-000 | ALUMINIUM | ---- |
| AMS-205AH | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-205AS | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-206 | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-206A | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-206AS | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-206AL | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-206AH | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-206AW | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-206CGL | B1828-210-0A0 | ---- | ---- | B1827-280-000 | 27-3 | BO-LKJ(A) |
| AMS-210 | B1828-210-0A0 | ---- | ---- | B1827-280-000 | 27-3 | BO-LKJ(A) |
| AMS-210A | B1828-980-0AB | 511-3 | BC-LK(J3) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| AMS-210AH | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-210B | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-210CGL | B1828-210-0A0 | ---- | ---- | B1827-280-000 | 27-3 | BO-LKJ(A) |
| AMS-212A | B1828-980-0AB | 511-3 | BC-LK(J3) | B1805-210-000 | ALUMINIUM | ---- |
| AMS-212AH | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-212B | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-212CGL | B1828-210-0A0 | ---- | ---- | B1827-280-000 | 27-3 | BO-LKJ(A) |
| AMS-215 | GBK-044010A0 | ---- | ---- | | ---- | ---- |
| AMS-215P | B1828-215-PA0 | 105 | BC-15-88 | | ---- | ---- |
| AMS-220 | B1828-210-0A0 | ---- | ---- | B1827-280-000 | 27-3 | BO-LKJ(A) |
| | B1818-205-000 | ---- | ---- | | | |
| AMS-220A | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-220B | B1828-205-0A0 | ---- | ---- | B1805-205-000 | ALUMINIUM | ---- |
| AMS-220CGL | B1828-210-0A0 | ---- | ---- | B1827-280-000 | 27-3 | BO-LKJ(A) |
| AMS-222BG | B1828-210-0A0 | ---- | ---- | B1827-280-000 | 27-3 | BO-LKJ(A) |
| AMS-224 | B1828-210-0A0 | ---- | ---- | B1827-280-000 | 27-3 | BO-LKJ(A) |
| AMS-224BG | B1828-210-0A0 | ---- | ---- | B1827-280-000 | 27-3 | BO-LKJ(A) |
| AMS-224BG | B1828-210-0A0 | ---- | ---- | B1827-280-000 | 27-3 | BO-LKJ(A) |
| AMS-229BG | B1828-210-0A0 | ---- | ---- | B1827-280-000 | 27-3 | BO-LKJ(A) |
| AMS-341B | | ---- | ---- | | ---- | ---- |
| APW-116 | G1831-116-0A0 | CAP | UNAVAILABLE | B9117-051-000 | 19-3 | BO-112(3) |
| APW-116A | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| APW-117 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| APW-118 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| APW-119 | G1831-116-0A0 | CAP | UNAVAILABLE | B9117-051-000 | 19-3 | BO-112(3) |
| APW-192 | 164-22057 | CAP | UNAVAILABLE | 164-21802 | 22 | BO-DBM(A) |
| APW-193 | 164-22057 | CAP | UNAVAILABLE | 164-21802 | 22 | BO-DBM(A) |
| APW-235H | 164-22057 | CAP | UNAVAILABLE | 164-21802 | 22 | BO-DBM(A) |
| APW-231:244 | 164-22057 | CAP | UNAVAILABLE | 164-21802 | 22 | BO-DBM(A) |
| APW-296 | | ---- | ---- | 164-28153 | ---- | ---- |
| APW-321 | 164-22057 | CAP | UNAVAILABLE | 164-21802 | 22 | BO-DBM(A) |
| APW-870 | | ---- | ---- | | ---- | ---- |
| APW-880 | | ---- | ---- | | ---- | ---- |
| AVP-870 | G1816-870-0A0 | BC | UNAVAILABLE | G1817-870-000 | 6 | BO-103(A) |
| AW-1 | 110-83151 | BC | UNAVAILABLE | 110-83250 | ALUMINIUM | UNAVAILABLE |
| AW-2 | 110-83151 | BC | UNAVAILABLE | 110-83250 | ALUMINIUM | UNAVAILABLE |
| DDL-105 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-115 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-127 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-201 | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SA0 | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| DDL-201H | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SA0 | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| DDL-201S | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SA0 | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| DDL-227 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-227A | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-227F | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-227H | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-227L | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-227M | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-227N | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-227W | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-272 | B1837-027-0A0 | 609 | BC-DBZ(1) | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-412 | B1837-041-0A0 | 606 | BC-DLN | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-436-5 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-500 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-500A | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-501 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-501A | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-505 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-505-100 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-505-200 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-----------------|-------------------|----------|----------------|---------------|-----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| DDL-505-300 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-505A-100 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-505A-200 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-505A-300 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-506 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-506-200 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-506-300 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-506A-200 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-506A-300 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-541 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-541W | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-542 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-543 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-545 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-545W | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-552 | | ---- | ---- | B9117-552-A00 | 10 | BO-95(A) |
| DDL-555 | B1837-041-0A0 | 606 | BC-DLN | B9117-552-A00 | 10 | BO-95(A) |
| DDL-555-2 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-555-2T | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-555-4 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-555A | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-555G | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-555H | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-552-A00 | 10 | BO-95(A) |
| DDL-555H-2 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-555H-4-5 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-555U | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-555U-4 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-555W | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-560 | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DDL-560-5 | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DDL-5530 | 110-38759 | 601NBL17 | BC-DB1-NBL17 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5530A | 110-38759 | 601NBL17 | BC-DB1-NBL17 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5530H | 110-38759 | 601NBL17 | BC-DB1-NBL17 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5550 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5550A | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5550H | 110-38759 | 601NBL17 | BC-DB1-NBL17 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5550-6 | 110-38759 | 601NBL17 | BC-DB1-NBL17 | B9117-552-A00 | 10 | BO-95(A) |
| DDL-5550H-6 | 110-38759 | 601NBL17 | BC-DB1-NBL17 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5550-N-7 | 110-83151 | BC | UNAVAILABLE | 110-83250 | ALUMINIUM | UNAVAILABLE |
| DDL-5550N-7/AWH | 110-83151 | BC | UNAVAILABLE | 110-83250 | ALUMINIUM | UNAVAILABLE |
| DDL-5550U | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5570 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5570A | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5570M | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5570NS | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5571N/AW-1A | 110-83151 | BC | UNAVAILABLE | 110-83250 | ALUMINIUM | UNAVAILABLE |
| DDL-5571NE | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5571NF | 111-05459 | BC | UNAVAILABLE | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5580 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5580A | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5580H | D1837-415-DAL | 606NBL | BC-DLN-NBL | B9117-012-000 | 13-4 | BO-400(4) |
| DDL-5581N/AW-1A | 110-83151 | BC | UNAVAILABLE | 110-83250 | ALUMINIUM | UNAVAILABLE |
| DDL-5600 | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DDL-5600NLL6 | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DDL-5600NLL6 | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DDL-5700N-7 | 228-96252 | ---- | ---- | 110-83250 | ---- | ---- |
| DDL-5700 all | 228-96252 | ---- | ---- | 110-83250 | ---- | ---- |
| DDL-5900 | 228-96252 | ---- | ---- | 110-83250 | ---- | ---- |
| DDW-9 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-9A | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-12 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-92 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-112 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-115 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-122 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-123 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-125 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-125W | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-126 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-126-10 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-126-11 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-126W | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-155 | B1837-155-0A0 | 601-3 | BC-DB1-J | B9117-155-000 | 8-4 | BO-95-HSN |
| DDW-226 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-226A | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-226T | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DDW-226W | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-43 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-43A | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-43B | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-------------------|-------------------|----------|----------------|---------------|-----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| DLD-432 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-432-2 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-432-3 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-432-4 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-432-5 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-432A | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-432A-2 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-432A-3 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-432A-4 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-432B | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-432B-2 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-432B-3 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-432B-4 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-436-5 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-5430 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLD-5430-6 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLM-52 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLM-522 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLM-522A | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLM-523 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLM-5200 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLM-5400-6 | 110-38759 | 601NBL17 | BC-DB1-NBL17 | B9117-012-000 | 13-4 | BO-400(4) |
| DLM-5410-6 | 110-38759 | 601NBL17 | BC-DB1-NBL17 | B9117-012-000 | 13-4 | BO-400(4) |
| DLM-5410N | | ---- | ---- | | ---- | ---- |
| DLM-5410NL | | ---- | ---- | | ---- | ---- |
| DLN-41 | B1837-041-0A0 | 606 | BC-DLN | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-41-2 | B1837-041-0A0 | 606 | BC-DLN | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-41H | B1837-041-0A0 | 606 | BC-DLN | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-412 | B1837-041-0A0 | 606 | BC-DLN | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-412-2 | D1837-415-DAL | 606NBL | BC-DLN-NBL | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-415 | B1837-041-0A0 | 606 | BC-DLN | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-415-2 | D1837-415-DAL | 606NBL | BC-DLN-NBL | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-415-4 | D1837-415-DAL | 606NBL | BC-DLN-NBL | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-415-5 | D1837-415-DAL | 606NBL | BC-DLN-NBL | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-415H | D1837-415-DAL | 606NBL | BC-DLN-NBL | B9117-552-A00 | 10 | BO-95(A) |
| DLN-415H-2 | D1837-415-DAL | 606NBL | BC-DLN-NBL | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-415H-4 | D1837-415-DAL | 606NBL | BC-DLN-NBL | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-415L | D1837-415-DAL | 606NBL | BC-DLN-NBL | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-415L-4-1 | D1837-415-DAL | 606NBL | BC-DLN-NBL | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-415L-4-5 | D1837-415-DAL | 606NBL | BC-DLN-NBL | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-5410H-6-WB | 110-38759 | 601NBL17 | BC-DB1-NBL17 | B9117-012-000 | 13-4 | BO-400(4) |
| DLN-5410N-7/AW-1A | 110-83151 | BC | UNAVAILABLE | 110-83250 | ALUMINIUM | UNAVAILABLE |
| DLU-450 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-450A | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-450B | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-450C | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-450D | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-450E | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-450G | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-450J | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-450-2 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-450-3 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-450-4 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-490-4 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-490-5 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-490BB | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-490L | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-491-5 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-591-5 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-5490 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-5490-6 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DLU-5490N-7 | 110-83151 | BC | UNAVAILABLE | 110-83250 | ALUMINIUM | UNAVAILABLE |
| DLU-5495-6 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DMN-530 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DMN-530-4 | B1837-041-0A0 | 606 | BC-DLN | B9117-012-000 | 13-4 | BO-400(4) |
| DMN-530-5 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DMN-531 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DMN-531-5 | D1837-555-BAA | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DMN-5420-6 | 110-38759 | 601NBL17 | BC-DB1-NBL17 | B9117-012-000 | 13-4 | BO-400(4) |
| DNU-241H | B1837-241-H00 | 806NBL1 | BC-DBM(2)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DSC-246 | | ---- | ---- | | ---- | ---- |
| DSU-142 | 212-10059 | ---- | ---- | | ---- | ---- |
| DSU-144 | D1837-141-EA0 | 810NBL4 | BC-DBM(5)-NBL4 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DSU-145 | B1837-201-SA0 | 801NBL1 | BC-DBM(1)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DSU-145-4 | B1837-201-SA0 | 801NBL1 | BC-DBM(1)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DSU-145-5 | B1837-201-SA0 | 801NBL1 | BC-DBM(1)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DU-141H | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SA0 | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| EB-2 | | ---- | ---- | | ---- | ---- |
| HZL-8800 | | | | A9117-880-000 | 48 | BO-HZL8800 |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-----------|--------------------------------|---------------|----------------------------|---------------|----------|----------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| LBH-761 | B1810-761-0A0 B1810-761-0BA | 702 702NBL | BC-107(2) BC-107(2)-NBL | B1809-761-000 | 17-3 | BO-LBH761 |
| LBH-762 | B1810-761-0A0 B1810-761-0BA | 702 702NBL | BC-107(2) BC-107(2)-NBL | B1809-761-000 | 17-3 | BO-LBH761 |
| LBH-763 | B1810-761-0A0 B1810-761-0BA | 702 702NBL | BC-107(2) BC-107(2)-NBL | B1809-761-000 | 17-3 | BO-LBH761 |
| LBH-771 | B1810-771-0A0 B1810-771-0BA | 710 710NBL | BC-LBH771 BC-LBH771-NBL | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-772 | B1810-771-0A0 B1810-771-0BA | 710 710NBL | BC-LBH771 BC-LBH771-NBL | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-773 | B1810-771-0A0 B1810-771-0BA | 710 710NBL | BC-LBH771 BC-LBH771-NBL | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-774 | B1810-771-0A0 B1810-771-0BA | 710 710NBL | BC-LBH771 BC-LBH771-NBL | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-780 | B1810-771-0A0 | 710 | BC-LBH771 | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-781 | B1810-771-0A0 B1810-771-0BA | 710 710NBL | BC-LBH771 BC-LBH771-NBL | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-782 | B1810-771-0A0 B1810-771-0BA | 710 710NBL | BC-LBH771 BC-LBH771-NBL | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-783 | B1810-771-0A0 B1810-771-0BA | 710 710NBL | BC-LBH771 BC-LBH771-NBL | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-784 | B1810-771-0A0 B1810-771-0BA | 710 710NBL | BC-LBH771 BC-LBH771-NBL | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-790 | 137-29769 | 713 | BC-LBH790 | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-790K | 137-29769 | 713 | BC-LBH790 | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-790S | 137-29769 | 713 | BC-LBH790 | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-791 | 137-29769 | 713 | BC-LBH790 | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-791S | 137-29769 | 713 | BC-LBH790 | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-792 | 137-29769 | 713 | BC-LBH790 | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-793 | 137-29769 | 713 | BC-LBH790 | B1811-771-000 | 17-4 | BO-LBH771 |
| LBH-794 | 137-29769 | 713 | BC-LBH790 | B1811-771-000 | 17-4 | BO-LBH771 |
| LG-57 | | ---- | ---- | B9117-057-000 | 25 | BO-144 |
| LG-57-1 | | ---- | ---- | B9117-057-000 | 25 | BO-144 |
| LG-158 | 040-05742221 | ---- | ---- | B9117-057-000 | 25 | BO-144 |
| LG-158-1 | | ---- | ---- | B9117-057-000 | 25 | BO-144 |
| LGG-777 | | ---- | ---- | B9117-057-000 | 25 | BO-144 |
| LGG-777-2 | | ---- | ---- | B9117-057-000 | 25 | BO-144 |
| LGG-778 | | ---- | ---- | B9117-057-000 | 25 | BO-144 |
| LGS-87 | | ---- | ---- | | 35 | BO-132 |
| LH-51 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LH-51-10 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LH-512 | | ---- | ---- | 101-11300 | 19-8 | BO-112(A)J |
| LH-512-3 | | ---- | ---- | 101-11300 | 19-8 | BO-112(A)J |
| LH-512H | | ---- | ---- | 101-11300 | 19-8 | BO-112(A)J |
| LH-513 | | ---- | ---- | B9117-563-000 | 26-3 | BO-1215MM-N |
| LH-515 | | ---- | ---- | 101-11300 | 19-8 | BO-112(A)J |
| LH-515H | | ---- | ---- | 101-11300 | 19-8 | BO-112(A)J |
| LH-516 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LH-516/8 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LH-517 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LH-518 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LH-525N | G1831-116-0A0 | CAP | UNAVAILABLE | B9117-051-000 | 19-3 | BO-112(3) |
| LH-526A | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LH-527 | B1837-526-0A0 | CAP | UNAVAILABLE | 102-31603 | 26-2 | BO-1215MM(A) |
| LH-528 | B1837-528-0A0 | CAP | UNAVAILABLE | B9117-051-000 | 19-3 | BO-112(3) |
| LH-529 | G1831-116-0A0 | CAP | UNAVAILABLE | B9117-051-000 | 19-3 | BO-112(3) |
| LH-562A | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LH-570 | 164-22057 | CAP | UNAVAILABLE | 164-21802 | 22 | BO-DBM(A) |
| LH-571 | 164-22057 | CAP | UNAVAILABLE | 164-21802 | 22 | BO-DBM(A) |
| LH-1114 | 103-53555 | ---- | ---- | 103-53605 | 31-4 | BO-1215L(A)J-H |
| LH-1150 | 101-10252 | CAP | UNAVAILABLE | B9117-051-000 | 19-3 | BO-112(3) |
| LH-1152 | 101-10252 | CAP | UNAVAILABLE | 101-11300 | 19-8 | BO-112(A)J |
| | | | | B9117-051-000 | 19-3 | BO-112(3) |
| LH-1152-4 | 101-10252 | CAP | UNAVAILABLE | 101-11300 | 19-8 | BO-112(A)J |
| LH-1152-5 | 101-10252 | CAP | UNAVAILABLE | B9117-051-000 | 19-3 | BO-112(3) |
| LH-1160 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LH-1160-4 | 101-10252 | CAP | UNAVAILABLE | 101-11300 | 19-8 | BO-112(A)J |
| LH-1160-5 | 104-42150 | ---- | ---- | 101-11300 | 19-8 | BO-112(A)J |
| LH-1162 | 102-08254 | CAP | UNAVAILABLE | 101-11300 | 19-8 | BO-112(A)J |
| LH-1162-4 | 102-08254 | CAP | UNAVAILABLE | 101-11300 | 19-8 | BO-112(A)J |
| LH-1162-5 | 102-08254 | CAP | UNAVAILABLE | 101-11300 | 19-8 | BO-112(A)J |
| LH-1172 | 103-53555 | ---- | ---- | 103-53605 | 31-4 | BO-1215L(A)J-H |
| LH-1172-5 | 103-53555 | ---- | ---- | 103-54009 | 31-3 | BO-1215L-N |
| LH-1178 | | ---- | ---- | | ---- | ---- |
| LH-1180 | 102-31553 | CAP | UNAVAILABLE | B9117-563-000 | 26-3 | BO-1215MM-N |
| LH-1180-4 | 103-53555 | ---- | ---- | 102-31603 | 26-2 | BO-1215MM(A) |
| LH-1180-5 | 103-53555 | ---- | ---- | 102-31603 | 26-2 | BO-1215MM(A) |
| LH-1182 | 102-31553 | CAP | UNAVAILABLE | 102-31603 | 26-2 | BO-1215MM(A) |
| LH-1182-4 | 102-31553 | CAP | UNAVAILABLE | 102-31603 | 26-2 | BO-1215MM(A) |
| LH-1182-5 | 102-31553 | CAP | UNAVAILABLE | 102-31603 | 26-2 | BO-1215MM(A) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-------------|-------------------|----------|----------------|---------------|-----------|----------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| LH-2152 | 101-10252 | CAP | UNAVAILABLE | 101-11300 | 19-8 | BO-112(A)J |
| LH-2172 | 106-12554 | ---- | ---- | | ---- | ---- |
| LH-2178GF | | ---- | ---- | 228-73350 | ---- | ---- |
| LH-2182 | 106-34657 | ---- | ---- | | ---- | ---- |
| LH-3128 | 226-12600 | CAP | UNAVAILABLE | B9117-051-000 | 19-3 | BO-112(3) |
| | | | | 102-10805 | 19-9 | BO-842(A)-H |
| LH-3128-7 | 226-12600 | CAP | UNAVAILABLE | 102-10805 | 19-9 | BO-842(A)-H |
| | 226-88105 | CAP | UNAVAILABLE | B9117-051-000 | 19-3 | BO-112(3) |
| LH-3168 | 226-88105 | CAP | UNAVAILABLE | B9117-051-000 | 19-3 | BO-112(3) |
| LH-3168-7 | 226-12600 | CAP | UNAVAILABLE | 102-10805 | 19-9 | BO-842(A)-H |
| | 226-88105 | CAP | UNAVAILABLE | B9117-051-000 | 19-3 | BO-112(3) |
| LH-3178 | | CAP | UNAVAILABLE | 102-31603 | 26-2 | BO-1215MM(A) |
| | | | | B9117-563-000 | 26-3 | BO-1215MM-N |
| LH-3178-7 | | CAP | UNAVAILABLE | 102-31603 | 26-2 | BO-1215MM(A) |
| | | | | B9117-563-000 | 26-3 | BO-1215MM-N |
| LH-3188 | | CAP | UNAVAILABLE | 102-31603 | 26-2 | BO-1215MM(A) |
| | | | | B9117-563-000 | 26-3 | BO-1215MM-N |
| LH-3188-7 | | CAP | UNAVAILABLE | 102-31603 | 26-2 | BO-1215MM(A) |
| | | | | B9117-563-000 | 26-3 | BO-1215MM-N |
| LK-232 | B1836-232-0A0 | 511 | BC-LK(J) | A9117-001-000 | 2 | BO-103(2) |
| | | 511NBL | BC-LK(J)-NBL | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-237 | B1836-232-0A0 | 511 | BC-LK(J) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| | | 511NBL | BC-LK(J)-NBL | | | |
| LK-239 | B1836-232-0A0 | 511 | BC-LK(J) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| | | 511NBL | BC-LK(J)-NBL | | | |
| LK-280 | B1828-980-0A0 | 511-2 | BC-LK(J2) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-282 | B1828-980-0A0 | 511-2 | BC-LK(J2) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-283 | B1828-980-0A0 | 511-2 | BC-LK(J2) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-284 | B1828-980-0A0 | 511-2 | BC-LK(J2) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-287 | B1828-980-0A0 | 511-2 | BC-LK(J2) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-289 | B1828-980-0A0 | 511-2 | BC-LK(J2) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-291 | B1828-980-0A0 | 511-2 | BC-LK(J2) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-322 | B1836-232-0A0 | 511 | BC-LK(J) | A9117-001-000 | 2 | BO-103(2) |
| | | 511NBL | BC-LK(J)-NBL | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-980 | B1828-980-0A0 | 511-2 | BC-LK(J2) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-981 | B1828-980-0A0 | 511-2 | BC-LK(J2) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-982 | B1828-980-0A0 | 511-2 | BC-LK(J2) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-987-510 | B1828-980-0A0 | 511-2 | BC-LK(J2) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-992-82 | D1828-MMC-KA0 | 511-5 | BC-LK(J5)-NBL | 138-12102 | | BO-LKJ(A2)H |
| LK-1850 | B1828-980-0AB | 511-3 | BC-LK(J3) | B1827-280-000 | 27-3 | BO-LKJ(A) |
| LK-1851-555 | B1828-980-0BB | 511-4 | BC-LK(J4) | 138-12102 | | BO-LKJ(A2)H |
| LK-1852 | | ---- | ---- | | ---- | ---- |
| LS-130 | | ---- | ---- | B9117-130-000 | 34 | BO-17 |
| LS-246-4 | | ---- | ---- | D1854-246-D00 | 22-5 | BO-DBM(A)J2-H |
| LS-341 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| LT-59 | | ---- | ---- | B9117-057-000 | 25 | BO-144 |
| LT-72 | B1837-012-0A0 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| LT-591 | | ---- | ---- | B9117-057-000 | 25 | BO-144 |
| LU-53 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LU-53-7 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LU-55 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LU-55-2 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LU-55-3 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LU-562 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LU-562A | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LU-562-3 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| LU-563 | 040-56349021H | ---- | ---- | B9117-563-000 | 26-3 | BO-1215MM-N |
| LU-563-3 | 103-53555 | ---- | ---- | B9117-563-000 | 26-3 | BO-1215MM-N |
| LU-1114 | 103-53555 | ---- | ---- | 103-53605 | 31-4 | BO-1215L(A)J-H |
| LU-1114-4 | 103-53555 | ---- | ---- | 103-53605 | 31-4 | BO-1215L(A)J-H |
| LU-1114-5 | 103-53555 | ---- | ---- | 103-53605 | 31-4 | BO-1215L(A)J-H |
| LU-2210 | | ---- | ---- | | ---- | ---- |
| LU-2210-6 | | ---- | ---- | 107-23609 | ALUMINIUM | UNAVAILABLE |
| LU-2260N-7 | | ---- | ---- | 107-76805 | ALUMINIUM | UNAVAILABLE |
| LUH-520 | 103-53555 | ---- | ---- | 102-31603 | 26-2 | BO-1215MM(A) |
| LUH-521 | B1837-526-0A0 | CAP | UNAVAILABLE | 102-31603 | 26-2 | BO-1215MM(A) |
| LUH-526 | B1837-526-0A0 | CAP | UNAVAILABLE | 102-31603 | 26-2 | BO-1215MM(A) |
| LUH-527 | B1837-526-0A0 | CAP | UNAVAILABLE | 102-31603 | 26-2 | BO-1215MM(A) |
| LZ-27 | B1837-027-0A0 | 609 | BC-DBZ(1) | B9117-012-000 | 13-4 | BO-400(4) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| LZ-29 | B1837-027-0A0 | 609 | BC-DBZ(1) | B9117-012-000 | 13-4 | BO-400(4) |
| LZ-39 | B1837-027-0A0 | 609 | BC-DBZ(1) | B9117-039-000 | 5 | BO-103(Z) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| LZ-40 | B1837-027-0A0 | 609 | BC-DBZ(1) | B9117-012-000 | 13-4 | BO-400(4) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| LZ-271 | B1837-027-0A0 | 609 | BC-DBZ(1) | B9117-012-000 | 13-4 | BO-400(4) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------|-------------------|-------------------------------|--|--------------------------------|-----------|------------------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| LZ-271K | B1837-027-0A0 | 609NBL9 609 | BC-DBZ(1)-NBL9 BC-DBZ(1) | B9117-012-000 | 13-4 | BO-400(4) |
| LZ-391 | B1837-027-0A0 | 609NBL6 609NBL9 609 | BC-DBZ(1)-NBL6 BC-DBZ(1)-NBL9 BC-DBZ(1) | B9117-039-000 B9117-012-000 | 5 13-4 | BO-103(Z) BO-400(4) |
| LZ-391N | B1837-027-0A0 | 609NBL9 609NBL6 609NBL9 | BC-DBZ(1)-NBL9 BC-DBZ(1)-NBL6 BC-DBZ(1)-NBL9 | B9117-012-000 | 13-4 | BO-400(4) |
| LZ-402 | B1837-027-0A0 | 609NBL6 609NBL9 609 | BC-DBZ(1)-NBL6 BC-DBZ(1)-NBL9 BC-DBZ(1) | B9117-012-000 | 13-4 | BO-400(4) |
| LZ-403 | B1837-027-0A0 | 609NBL9 609NBL6 609NBL9 | BC-DBZ(1)-NBL9 BC-DBZ(1)-NBL6 BC-DBZ(1)-NBL9 | B9117-012-000 | 13-4 | BO-400(4) |
| LZ-405 | B1837-405-0A0 | 704 704NBL | BC-102 BC-102-NBL | B9117-405-000 | 15-3 | BO-107(3) |
| LZ-405-2 | B1837-405-0A0 | 704 704NBL | BC-102 BC-102-NBL | B9117-405-000 | 15-3 | BO-107(3) |
| LZ-407 | B1837-405-0A0 | 704 704NBL | BC-102 BC-102-NBL | B9117-405-000 | 15-3 | BO-107(3) |
| LZ-581 | B1837-582-0A0 | 617 | BC-DBZ(4) | B9117-155-000 | 8-4 | BO-95-HSN |
| LZ-582 | B1837-582-0A0 | 617 | BC-DBZ(4) | B9117-155-000 | 8-4 | BO-95-HSN |
| LZ-582-2 | B1837-582-0A0 | 617 | BC-DBZ(4) | B9117-155-000 | 8-4 | BO-95-HSN |
| LZ-583 | B1837-582-0A0 | 617 | BC-DBZ(4) | B9117-155-000 | 8-4 | BO-95-HSN |
| LZ-583-8 | B1837-582-0A0 | 617 | BC-DBZ(4) | B9117-155-000 | 8-4 | BO-95-HSN |
| LZ-586 | B1837-586-0A0 | 610 | BC-DBZ(2) | B9117-155-000 | 8-4 | BO-95-HSN |
| LZ-1280 | 100-34056 | 705 705NBL | BC-457 BC-457-NBL | B1809-761-000 | 17-3 | BO-LBH761 |
| LZ-1285 | 100-34056 | 705 | BC-457 | B1809-761-000 | 17-3 | BO-LBH761 |
| LZ-1286 | 100-34056 | 705 705NBL | BC-457 BC-457-NBL | B1809-761-000 | 17-3 | BO-LBH761 |
| LZ-1287 | 100-34056 | 705 705NBL | BC-457 BC-457-NBL | B1809-761-000 | 17-3 | BO-LBH761 |
| LZ-1290 | 100-80059 | ---- | ---- | | 22 | BO-DBM(A) |
| LZ-2280 | 225-24151 | BC | UNAVAILABLE | B1809-761-000 | 17-3 | BO-LBH761 |
| LZ-2285 | 225-24169 | BC | UNAVAILABLE | B1809-761-000 | 17-3 | BO-LBH761 |
| LZ-2286 | 225-24151 | BC | UNAVAILABLE | B1809-761-000 | 17-3 | BO-LBH761 |
| LZH-1290 | 100-80059 | ---- | ---- | 100-80604 | 22 | BO-DBM(A) |
| MB-372 | | ---- | ---- | | ---- | ---- |
| MB-373 | | ---- | ---- | | ---- | ---- |
| MCM-170 | B1837-027-0A0 | 609 609NBL6 609NBL9 | BC-DBZ(1) BC-DBZ(1)-NBL6 BC-DBZ(1)-NBL9 | B9117-012-000 | 13-4 | BO-400(4) |
| MCM-270 | B1837-027-0A0 | 609 609NBL6 609NBL9 | BC-DBZ(1) BC-DBZ(1)-NBL6 BC-DBZ(1)-NBL9 | B9117-012-000 | 13-4 | BO-400(4) |
| ML-111 | | ---- | ---- | | ---- | ---- |
| PLW-1244 | 105-47602 | C-2 | CP-PF151 | | ---- | ---- |
| PLW-1244-6 | 105-45358 | CAP | UNAVAILABLE | | ---- | ---- |
| PLW-1245 | 105-47602 | C-2 | CP-PF151 | | ---- | ---- |
| PLW-1245-6 | 105-45358 | CAP | UNAVAILABLE | | ---- | ---- |
| PLW-1246 | 105-47602 | C-2 | CP-PF151 | | ---- | ---- |
| PLW-1246-6 | 105-45358 | CAP | UNAVAILABLE | | ---- | ---- |
| PLW-1264 | 105-47602 | C-2 | CP-PF151 | | ---- | ---- |
| PLW-1264-6 | | CAP | UNAVAILABLE | | ---- | ---- |
| PLW-1266 | 105-47602 | C-2 | CP-PF151 | | ---- | ---- |
| PLW-1266-6 | | CAP | UNAVAILABLE | | ---- | ---- |
| PLW-4240 | 105-47602 | C-2 | CP-PF151 | | ---- | ---- |
| PLW-4241 | 105-47602 | C-2 | CP-PF151 | | ---- | ---- |
| PLW-4242 | 105-47602 | C-2 | CP-PF151 | | ---- | ---- |
| PLW-4243 | 105-45358 | CAP | UNAVAILABLE | | ---- | ---- |
| PLW-4244 | | CAP | UNAVAILABLE | | ---- | ---- |
| PLW-4245 | 101-10252 | CAP | UNAVAILABLE | 101-11300 | 19-8 | BO-112(A)J |
| TL-72 | B1837-012-0A0 | 601 | BC-DB1 | B9117-007-000 | 2 | BO-103(2) |
| TL-82 | B1837-012-0A0 | 601 | BC-DB1 | B9117-007-000 | 2 | BO-103(2) |
| TL-90 | B1837-012-0A0 | 601 | BC-DB1 | B9117-007-000 | 2 | BO-103(2) |
| TNU-243 | | ---- | ---- | | ---- | ---- |
| TR-7 | B1837-012-0A0 | 601 | BC-DB1 | B9117-007-000 | 2 | BO-103(2) |
| TSC-441 | 210-41850 | ---- | ---- | | ---- | ---- |
| TSH-411 | | ---- | ---- | | ---- | ---- |
| TSN-421 | | ---- | ---- | | ---- | ---- |
| TSU-411 | | ---- | ---- | | ---- | ---- |
| TSU-421 | | ---- | ---- | | ---- | ---- |
| TSU-441 | | ---- | ---- | | ---- | ---- |
| TSU-471 | 210-41850 | ---- | ---- | | ---- | ---- |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------------------|-------------------|----------|-----------------|-------------|----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| TU-273 | | ---- | ---- | | ---- | ---- |
| K-CHANCE | | | | | | |
| KBH-372 | | ---- | ---- | | ---- | ---- |
| KBH-373 | | ---- | ---- | | ---- | ---- |
| KBH-890 | | 710 | BC-LBH771 | | 17-4 | BO-LBH771 |
| KERDER | | | | | | |
| KD-20U | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| KD-810 | | ---- | ---- | | 19-3 | BO-112(3) |
| KD-820 | | ---- | ---- | | 19-3 | BO-112(3) |
| KD-8100-3 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| KD-8100-5 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| KD-8100-7 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| KING'S | | | | | | |
| HC-335 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| HC-471 | | C-2 | CP-PF151 | | ---- | ---- |
| HC-474 | | C-2 | CP-PF151 | | ---- | ---- |
| HC-491 | | C-2 | CP-PF151 | | ---- | ---- |
| HC-616 | | C-2 | CP-PF151 | | ---- | ---- |
| HC-618 | | C-2 | CP-PF151 | | ---- | ---- |
| HC-810 | | ---- | ---- | | 19-3 | BO-112(3) |
| HC-815 | | ---- | ---- | | 19-3 | BO-112(3) |
| HC-820 | | ---- | ---- | | 19-3 | BO-112(3) |
| HC-825 | | ---- | ---- | | 19-3 | BO-112(3) |
| LANDIS | | | | | | |
| K-12 | K25-5B | BC | UNAVAILABLE | | ---- | ---- |
| L | | ---- | ---- | | ---- | ---- |
| LANDIS MCKAY | 36-5-7 | BC | UNAVAILABLE | | ---- | ---- |
| S | AS-6-80 | BC | UNAVAILABLE | | ---- | ---- |
| LEWIS | | | | | | |
| 16 | 1041AL | ---- | ---- | 1047L | ---- | ---- |
| | | | | 1047LA | ---- | ---- |
| 30 | 411-8 | ---- | ---- | 1047L | ---- | ---- |
| | 411-6 | ---- | ---- | 1047LA | ---- | ---- |
| 170 | 411-8 | ---- | ---- | 1047L | ---- | ---- |
| | 411-6 | ---- | ---- | 1047LA | ---- | ---- |
| MAIER UNITAS | | | | | | |
| 1201 | | ---- | ---- | | ---- | ---- |
| 1201Z | | ---- | ---- | | ---- | ---- |
| MAMMUT | | | | | | |
| | | ---- | ---- | | ---- | ---- |
| | | ---- | ---- | | ---- | ---- |
| MARCO | | | | | | |
| Multihead embroidery | 861116 | ---- | ---- | | ---- | ---- |
| MEIJIA | | | | | | |
| G15-2 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| GG70701-3 | | 601 | BC-DB1 | | 13-4 | BO-400(4) |
| MEISTERGRAM | | | | | | |
| M100 | P810005 | 609 | BC-DBZ(1) | P810004 | ---- | ---- |
| M600 | P810005 | 609 | BC-DBZ(1) | P810004 | ---- | ---- |
| M600XL | MBC2 | 803NBL2 | BC-DBM(Z2)-NBL2 | MB2 | 22 | BO-DBM(A) |
| M700 | P810005 | 609 | BC-DBZ(1) | P810004 | ---- | ---- |
| M700XL | MBC2/P413830 | 803NBL2 | BC-DBM(Z2)-NBL2 | MB2/P413670 | 22 | BO-DBM(A) |
| M800 | P810005 | 609 | BC-DBZ(1) | P810004 | ---- | ---- |
| M800XL | 35575/P413830 | 803NBL2 | BC-DBM(Z2)-NBL2 | 35784 | 21-5 | BO-DBM(1)N |
| MERCO | | | | | | |
| | | 615NBL6 | BC-DBZ(3)-NBL6 | | 2 | BO-103(2) |
| | | 615NBL6 | BC-DBZ(3)-NBL6 | | 2 | BO-103(2) |
| MILLION SPECIAL | | | | | | |
| MS-335 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| MS-491 | | C-2 | CP-PF151 | | ---- | ---- |
| MS-474 | | C-2 | CP-PF151 | | ---- | ---- |
| MS-810 | | ---- | ---- | | 19-3 | BO-112(3) |
| MS-820 | | ---- | ---- | | 19-3 | BO-112(3) |
| MS-B872 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| MS-B875 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| MS-B842 | | ---- | ---- | | ---- | ---- |
| MS-B845 | | CAP | UNAVAILABLE | | 19-3 | BO-112(3) |
| MS-1245 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| MITSUBISHI | | | | | | |
| CU-865 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| CU-865-12 | MF10E0125 | 606 | BC-DLN | MF10A0123 | 8 | BO-95(2) |
| CU-865-12FP | MF10E0125 | 606 | BC-DLN | MF10A0123 | 8 | BO-95(2) |
| CU-865-22 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| CU-865-22-FP | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DB-120-1 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DB-120-2 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DB-120-12-7 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-122 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DB-126 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|---------------|-------------------|----------|----------------|-----------|----------|---------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| DB-126-10 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-127 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DB-130 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DB-130-10 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130-10-KY | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130-11 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130-12 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130-13 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130-22 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DB-130E-10 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130E-11 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130E-12 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130E-12-7 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130E-13 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130E-22 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DB-130G-10 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130G-11 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130G-12,13 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130G-22 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DB-130G-127 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130GM-10 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-130GM-127 | MF10E0125 | 601 | BC-DB1 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-132G-10 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DB-132G-12 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DB-132G-22 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DB-170 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DB-170-10 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DB-170-11 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DB-171 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DB-189 | MF40E1125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| DB-189-10 | MF40E1125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| DB-189-11 | MF40E1125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| DB-189-12 | MF40E1125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| DB-189-13 | MF40E1125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| DB-189-22BZ | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MF25B0123 | 21-5 | BO-DBM(1)N |
| DB-189-L | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF36A0123 | 8-3 | BO-95-HSY |
| DB-191 | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF10A0123 | 8 | BO-95(2) |
| DB-199-10 | MF40E1125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| DB-199-10W | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| DB-199-12 | MF40E1125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| DB-199-22 | MG40E0125 | 801NBL1 | BC-DBM(1)-NBL1 | MG44B0123 | 21-7 | BO-DBM(3)N |
| DB-285 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DB-286 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DB-286-10 | MN10A0120-1 | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DB-320-10 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DB-320-11 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DB-320-12 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DB-320-12-8 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DB-321 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DB-325 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DB-325-22 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DB-325-22-D | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DB-327 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DF-200 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DG-519 | MF36E0125 | ---- | ---- | MF41D0123 | 10 | BO-95(A) |
| DN-260 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DN-260-7 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DN-260-10 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DN-260-22 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| DN-260-710 | MN10A0120-1 | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DN-262 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| DN-265 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DN-265-10 | MN10A0120-1 | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DN-265-22 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| DN-267 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| DN-269-10 | MN50E0125 | CAP | UNAVAILABLE | MN50A1123 | 19-7 | BO-112(A)M |
| DN-269-20 | MN52E0125 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| DN-275-10 | MN27A0120 | CAP | UNAVAILABLE | MN10A0123 | 19-3 | BO-112(3) |
| DN-275-10-K | MN27A0120-1 | CAP | UNAVAILABLE | MN10A0123 | 19-3 | BO-112(3) |
| DN-275-20,A | MN26E0120 | CAP | UNAVAILABLE | MN12B0123 | 26-3 | BO-1215MM-N |
| DN-279-10 | | ---- | ---- | | ---- | ---- |
| DN-350 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DN-350-10 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DN-350-12 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DN-352 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DT-330 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DT-330-12 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DU-100 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DU-100-12 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DU-100-22 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|---------------|-------------------|----------|----------------|-----------|----------|---------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| DU-102 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| DU-103 | | ---- | ---- | MP03B0123 | 25 | BO-144 |
| DU-105 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DU-105-12 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DU-105-22 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| DU-107 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| DU-108 | | ---- | ---- | MP03B0123 | 25 | BO-144 |
| DU-120 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DU-120-12 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DU-120-22 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| DU-122 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| DU-123 | | ---- | ---- | MP03B0123 | 25 | BO-144 |
| DU-125 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DU-125-12 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| DU-125-22 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| DU-127 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| DU-128 | | ---- | ---- | MP03B0123 | 25 | BO-144 |
| DU-141NH | | ---- | ---- | | ---- | ---- |
| DU-400 | MN52E0125 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| DX-370 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DX-370-10 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DX-370-20 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DX-370-22 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DX-377 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DX-870 | | CAP | UNAVAILABLE | MN10A0123 | 19-3 | BO-112(3) |
| DX-870-10 | | CAP | UNAVAILABLE | MN10A0123 | 19-3 | BO-112(3) |
| DY-230 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DY-253 | | ---- | ---- | MG23C0123 | 35 | BO-132 |
| DY-253-00 | | ---- | ---- | MG23C0123 | 35 | BO-132 |
| DY-330 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DY-330-12 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DY-330-22 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DY-330-22D | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DY-337 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DY-337-2S | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DY-339 | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MG44B0123 | 21-7 | BO-DBM(3)N |
| DY-339-12 | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF36A0123 | 8-3 | BO-95-HSY |
| DY-339-22 | MG40E0125 | 801NBL1 | BC-DBM(1)-NBL1 | MG44B0123 | 21-7 | BO-DBM(3)N |
| DY-339-22M | MG40E0125 | 801NBL1 | BC-DBM(1)-NBL1 | MG44B0123 | 21-7 | BO-DBM(3)N |
| DY-340-12 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DY-340-22 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DY-340-22BZ | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MG44B0123 | 21-7 | BO-DBM(3)N |
| DY-349-22BZ | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MG44B0123 | 21-7 | BO-DBM(3)N |
| DY-350-12 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| DY-350-22 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| DY-358-22 | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MF25B0123 | 21-5 | BO-DBM(1)N |
| DY-359-22 | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MF25B0123 | 21-5 | BO-DBM(1)N |
| DY-359-22BZ | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MF25B0123 | 21-5 | BO-DBM(1)N |
| KM-T41 | | ---- | ---- | | ---- | ---- |
| LG2-3370-M | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF36A0123 | 8-3 | BO-95-HSY |
| LG2-3370-M1T | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF36A0123 | 8-3 | BO-95-HSY |
| LR5-5520 | | C-2 | CP-PF151 | | ---- | ---- |
| LS2-110-BOB | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| LS2-130-B | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| LS2-130-BOB | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| LS2-130-H | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LS2-130-HOB | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LS2-130-M | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LS2-130-MOB | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LS2-150 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LS2-150-MOB | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF10A0123 | 8 | BO-95(2) |
| LS2-180-B1T | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MF25B0123 | 21-5 | BO-DBM(1)N |
| LS2-180-H | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF36A0123 | 8-3 | BO-95-HSY |
| LS2-180-H1T | MF40E1125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-180-HTW | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-180-M | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-180-M1T | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-180-M1TW | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-180-M1W | MF40E1125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-180-L | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-190-H1T | MF40E1125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-190-H1TZ | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF36A0123 | 8-3 | BO-95-HSY |
| LS2-190-H1TZ2 | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF36A0123 | 8-3 | BO-95-HSY |
| LS2-190-H1W | MF40E1125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-190-M1T | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF36A0123 | 8-3 | BO-95-HSY |
| LS2-190-M1TW | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-190-M1TZ | MF40E1125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-190-M1TZ2 | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF36A0123 | 8-3 | BO-95-HSY |
| LS2-190-N1TZ | MF40E1125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-210M | MN35A0125 | 606NBL | BC-DLN-NBL | MF41D0123 | 10 | BO-95(A) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-----------------|-------------------|----------|-------------|-----------|----------|---------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| LS2-210M1T | MN35A0125 | 606NBL | BC-DLN-NBL | MF41D0123 | 10 | BO-95(A) |
| LS2-210M1TW | MN35A0125 | 606NBL | BC-DLN-NBL | MF41D0123 | 10 | BO-95(A) |
| LS2-680-MOBH | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LS2-690-MOJ | MN10A0120-1 | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| LS2-1130-B | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| LS2-1130-BOB | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| LS2-1130-H | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LS2-1130-HOB | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LS2-1130-M | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LS2-1130-MOB | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LS2-1180-H | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF36A0123 | 8-3 | BO-95-HSY |
| LS2-1180-L | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-1180-L1T | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-1180-M | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-1180-M1T | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-1180-M1TW | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF41D0123 | 10 | BO-95(A) |
| LS2-2210M | MN35A0125 | 606NBL | BC-DLN-NBL | MF41D0123 | 10 | BO-95(A) |
| LS2-2210M1T | MN35A0125 | 606NBL | BC-DLN-NBL | MF41D0123 | 10 | BO-95(A) |
| LS2-2210M1TW | MN35A0125 | 606NBL | BC-DLN-NBL | MF41D0123 | 10 | BO-95(A) |
| LS5-610-HOB | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| LS5-620-HOB | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| LS5-5110 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| LS5-5110-MOB | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| LS5-5120 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| LS5-5120-MOB | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| LT2-220-B | | ---- | ---- | MN50A1123 | 19-7 | BO-112(A)M |
| | | | | MN12B0123 | 26-3 | BO-1215MM-N |
| LT2-220-BO | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| LT2-220-BOB | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| LT2-220-M,MO | MN10A0120-1 | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| | | | | MN72A0123 | 19-15 | BO-112(A2)M |
| LT2-220-MOB | MN10A0120-1 | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| | | | | MN72A0123 | 19-15 | BO-112(A2)M |
| LT2-230-B | | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| | | | | MN74A0123 | 26-5 | BO-B872(A) |
| LT2-230-B1T | MN52E0125 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| | | | | MN74A0123 | 26-5 | BO-B872(A) |
| LT2-230M | | ---- | ---- | MN50A1123 | 19-7 | BO-112(A)M |
| LT2-230-M1T | MN50E0125 | CAP | UNAVAILABLE | MN50A1123 | 19-7 | BO-112(A)M |
| LT2-230-M1TW | MN50E0125 | CAP | UNAVAILABLE | MN50A1123 | 19-7 | BO-112(A)M |
| LT2-230-M1TZ | MN50E0125 | CAP | UNAVAILABLE | MN50A0123 | 19-7 | BO-112(A)M |
| LT2-240-B | MN26B0125 | CAP | UNAVAILABLE | MN12B0123 | 26-3 | BO-1215MM-N |
| LT2-240-BOA,BOB | MN26B0125 | CAP | UNAVAILABLE | MN12B0123 | 26-3 | BO-1215MM-N |
| LT2-240-MOB | MN27A0120-1 | CAP | UNAVAILABLE | MN10A0123 | 19-3 | BO-112(3) |
| LT2-246-BOA | MN28B0125 | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| LT2-246-BOB | MN28B0125 | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| LT2-250-A | MN62A0125 | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LT2-250-A1T | MN62A0125 | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LT2-250-B | MN62A0125 | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LT2-250-B1AT | MN62A0125 | ---- | ---- | MN62A0123 | 40 | BO-1215MM(A)M |
| LT2-250-B1T | MN62A0125 | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LT2-250-M | MN60A0125 | ---- | ---- | MN50A0123 | 19-7 | BO-112(A)M |
| LT2-250-M1AT | MN50E0125 | ---- | ---- | MN50A0123 | 19-7 | BO-112(A)M |
| LT2-250-M1ATW | MN50E0125 | ---- | ---- | MN50A0123 | 19-7 | BO-112(A)M |
| LT2-250-M1T | | ---- | ---- | | ---- | ---- |
| LT2-250-M1TW | MN60A0125 | ---- | ---- | MN50A0123 | 19-7 | BO-112(A)M |
| LT2-260-10 | | ---- | ---- | MN72A0123 | 19-15 | BO-112(A2)M |
| LT2-2220-B | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| | | | | | | |
| LT2-2220-BO | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| LT2-2220-BOB | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| | | | | | | |
| LT2-2220-M | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| | | | | MN72A0123 | 19-15 | BO-112(A2)M |
| LT2-2220-MOB | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| | | | | MN72A0123 | 19-15 | BO-112(A2)M |
| LT2-2220-LOB | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| | | | | MN72A0123 | 19-15 | BO-112(A2)M |
| LT2-2220-L | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| | | | | MN72A0123 | 19-15 | BO-112(A2)M |
| LT2-2230 | | ---- | ---- | MN50A1123 | 19-7 | BO-112(A)M |
| LT2-2230-B | | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| | | | | MN74A0123 | 26-5 | BO-B872(A) |
| LT2-2230-B1T | | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| | | | | MN74A0123 | 26-5 | BO-B872(A) |
| LT2-2230M | | ---- | ---- | MN50A1123 | 19-7 | BO-112(A)M |
| LT2-2230L1T | | ---- | ---- | MN50A1123 | 19-7 | BO-112(A)M |
| LT2-2230M1TW | | ---- | ---- | MN50A1123 | 19-7 | BO-112(A)M |
| LT2-2240-B | MN26E0120 | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| LT2-2240-BOB | MN26E0120 | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|---------------|-------------------|----------|----------------|-----------|----------|---------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| LT2-2240-MOB | MN27A0120 | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| LT2-2250-A | MN62A0125 | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LT2-2250-A1T | MN62A0125 | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LT2-2250-B | MN62A0125 | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LT2-2250-B1T | MN62A0125 | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LT2-2250-M | MN50E0125 | ---- | ---- | MN50A0123 | 19-7 | BO-112(A)M |
| LT2-2250-M1TW | MN60A0125 | ---- | ---- | MN50A0123 | 19-7 | BO-112(A)M |
| LT-350-12 | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LT-350-22 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| LT-359-22 | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MF25B0123 | 21-5 | BO-DBM(1)N |
| LU2-400 | | ---- | ---- | | ---- | ---- |
| LU2-400-B | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| LU2-400-BO | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| LU2-400-BOB | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| LU2-400-HO | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| LU2-400-HOB | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| LU2-402-BOB | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| LU2-410 | MN52E0125 | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LU2-410-B1T | MN52E0125 | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LU2-420-BO | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| LU2-420-BOB | | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LU2-420-HO | | ---- | ---- | | ---- | ---- |
| LU2-420-HOB | MN10A0120-1 | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| LU2-430 | MN52E0125 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| LU2-430-B | MN52E0125 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| LU2-430-B1T | MN52E0125 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| LU2-460-BOB | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| LU2-4410-B | | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LU2-4410-B1T | MN52E0125 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| LU2-4420 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| LU2-4430 | | ---- | ---- | | ---- | ---- |
| LU2-4430-B | | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LU2-4430-B1T | | ---- | ---- | MN52A0123 | 40 | BO-1215MM(A)M |
| LU2-4440 | | ---- | ---- | MN12B0123 | 26-3 | BO-1215MM-N |
| LX2-317 | MF10E0125 | 601 | BC-DB1 | MN10A0123 | 19-3 | BO-112(3) |
| LX2-317-MO | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LX2-371-MO | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LX2-630 | MN50E0125 | CAP | UNAVAILABLE | MQ60A0123 | 19-12 | BO-LX2(A2)-H |
| LX2-630-BO | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| LX2-630-MO | MF10E0125 | 601 | BC-DB1 | MN10A0123 | 19-3 | BO-112(3) |
| LX2-630-M1 | MN50E0125 | CAP | UNAVAILABLE | MQ60A0123 | 19-12 | BO-LX2(A2)-H |
| LX5-871 | | CAP | UNAVAILABLE | MN10A0123 | 19-3 | BO-112(3) |
| LX5-871-MO | | CAP | UNAVAILABLE | MN10A0123 | 19-3 | BO-112(3) |
| LY2-300-COB | | ---- | ---- | MG23C0123 | 35 | BO-132 |
| LY2-340-BOB | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| LY2-340-HOB | MF10E0125 | 601 | BC-DB1 | MN10A0123 | 19-3 | BO-112(3) |
| LY2-380-BIT | MS02E0125 | 801NBL2 | BC-DBM(1)-NBL2 | MG44B0123 | 21-7 | BO-DBM(3)N |
| LZ-207 | MT27E0125 | 704 | BC-102 | MT27A0123 | 15-3 | BO-107(3) |
| LZ-207-10 | MT27E0125 | 704 | BC-102 | MT27A0123 | 15-3 | BO-107(3) |
| LZ-270-10 | MT27E0125 | 704 | BC-102 | MT27A0123 | 15-3 | BO-107(3) |
| LZ-710 | MT70E0125 | 705 | BC-457 | MT40A0123 | 17-1 | BO-271(A) |
| LZ-710-11 | MT70E0125 | 705 | BC-457 | MT40A0123 | 17-1 | BO-271(A) |
| LZ-720 | MT70E0125 | 705 | BC-457 | MT40A0123 | 17-1 | BO-271(A) |
| LZ-720-11 | MT70E0125 | 705 | BC-457 | MT40A0123 | 17-1 | BO-271(A) |
| LZ-750 | MT40A0125 | 702 | BC-107(2) | MT40A0123 | 17-1 | BO-271(A) |
| LZ-760 | MT40A0125 | 702 | BC-107(2) | MT40A0123 | 17-1 | BO-271(A) |
| LZ-760-11 | MT70E0125 | 705 | BC-457 | MT40A0123 | 17-1 | BO-271(A) |
| LZ-760-11-D | MT40A0125 | 702 | BC-107(2) | MT40A0123 | 17-1 | BO-271(A) |
| LZ-780 | MT70E0125 | 705 | BC-457 | MT40A0123 | 17-1 | BO-271(A) |
| LZ-780-11 | MT70E0125 | 705 | BC-457 | MT40A0123 | 17-1 | BO-271(A) |
| LZ-790-11 | MT70E0125 | 705 | BC-457 | MT40A0123 | 17-1 | BO-271(A) |
| LZ2-130-MOB | MF10E0125 | 601 | BC-DB1 | MF10A0123 | 8 | BO-95(2) |
| LZ2-700-MO | MT27E0125 | 704 | BC-102 | MT27A0123 | 15-3 | BO-107(3) |
| LZ2-720-LOB | MT70E0125 | 705 | BC-457 | MT40A0123 | 17-1 | BO-271(A) |
| LZ2-780-LOB | MT70E0125 | 705 | BC-457 | MT40A0123 | 17-1 | BO-271(A) |
| LZ2-790-LOB | MT70E0125 | 705 | BC-457 | MT40A0123 | 17-1 | BO-271(A) |
| PB-810 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| PB-810-10 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| PB-810-10-FP | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| PB-820 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| PB-820-10 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| PB-820-10-FP | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| PB-840 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| PB-840-10 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| PB-840-10-FP | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| PLK-03BTA | MS01A0125 | 510-2 | BC-LK(B2) | MS01A0123 | 27-2 | BO-LKB(A)-2 |
| PLK-03HS | MS01A0125 | 510-2 | BC-LK(B2) | MS01A0123 | 27-2 | BO-LKB(A)-2 |
| PLK-109 | MS01A0125 | 510-2 | BC-LK(B2) | MS01A0123 | 27-2 | BO-LKB(A)-2 |
| PLK-0303 | MS01A0125 | 510-2 | BC-LK(B2) | MS01A0123 | 27-2 | BO-LKB(A)-2 |
| PLK-0604 | MS01A0125 | 510-2 | BC-LK(B2) | MS01A0123 | 27-2 | BO-LKB(A)-2 |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------------|-------------------|----------|----------------|-----------|----------|---------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| PLK-0804 | MS01A0125 | 510-2 | BC-LK(B2) | MS01A0123 | 27-2 | BO-LKB(A)-2 |
| PLK-08HSW | MS01A0125 | 510-2 | BC-LK(B2) | MS01A0123 | 27-2 | BO-LKB(A)-2 |
| PLK-1006 | MS02E0125 | 801NBL2 | BC-DBM(1)-NBL2 | MF25B0123 | 21-5 | BO-DBM(1)N |
| PLK-1210 | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MF25B0123 | 21-5 | BO-DBM(1)N |
| PLK-1212 | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MF25B0123 | 21-5 | BO-DBM(1)N |
| PLK-1410 | MS02E0125 | 801NBL2 | BC-DBM(1)-NBL2 | MF25B0123 | 21-5 | BO-DBM(1)N |
| PLK-1710 | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MF25B0123 | 21-5 | BO-DBM(1)N |
| PLK-2010 | | ---- | ---- | | ---- | ---- |
| PLK-2020 | | ---- | ---- | | ---- | ---- |
| PLK-2020-SB | | ---- | ---- | | ---- | ---- |
| PLK-2520 | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MG44B0123 | 21-7 | BO-DBM(3)N |
| PLK-4510 | MS02E0125 | 801NBL2 | BC-DBM(1)-NBL2 | MF25B0123 | 21-5 | BO-DBM(1)N |
| PLK-A05BT | MS17A0125 | ---- | ---- | MS17A0123 | ---- | ---- |
| PLK-A05PF | MS17A0125 | ---- | ---- | MS17A0123 | ---- | ---- |
| PLK-A0804 | MS17A0125 | ---- | ---- | MS17A0123 | ---- | ---- |
| PLK-A1006 | MS17A0125 | ---- | ---- | MS17A0123 | ---- | ---- |
| PLK-A1710 | MS17A0125 | ---- | ---- | MS17A0123 | ---- | ---- |
| PLK-A2016 | MS17A0125 | ---- | ---- | MS17A0123 | ---- | ---- |
| PLK-A3040 | | ---- | ---- | | ---- | ---- |
| PLK-A3530 | MS17A0125 | ---- | ---- | MS17A0123 | ---- | ---- |
| PLK-A4516 | MS17A0125 | ---- | ---- | MS17A0123 | ---- | ---- |
| PLK-A6019 | MS17A0125 | ---- | ---- | MS17A0123 | ---- | ---- |
| PLK-A6030 | MS17A0125 | ---- | ---- | MS17A0123 | ---- | ---- |
| PLK-B1006 | | ---- | ---- | | ---- | ---- |
| PLK-B2010R | MG44E0125 | 809NBL3 | BC-DBM(4)-NBL3 | MF25B0123 | 21-5 | BO-DBM(1)N |
| PLK-B2516 | MS17A0125 | ---- | ---- | MS17A0123 | ---- | ---- |
| PLX-20JR | MS02E0125 | 801NBL2 | BC-DBM(1)-NBL2 | MF25B0123 | 21-5 | BO-DBM(1)N |
| PLY-501F | MN26E0120 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| PLY-1185 | MN52E0125 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| PLY-7181 | MN52E0125 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| PLY-7182 | MN52E0125 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| PLY-7202 | MN52E0125 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| PLY-7206 | MN52E0125 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| PLY-7206E | MN52E0125 | CAP | UNAVAILABLE | MN52A0123 | 40 | BO-1215MM(A)M |
| PN-840 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| PN-840-10 | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| PN-840-10FP | | ---- | ---- | MN10A0123 | 19-3 | BO-112(3) |
| TA-310 | MF40E0125 | 601NBL6 | BC-DB1-NBL6 | MF10A0123 | 8 | BO-95(2) |
| YU-360-22 | MF25E0125 | 801 | BC-DBM(1) | MF25B0123 | 21-5 | BO-DBM(1)N |
| mitsutomo | | | | | | |
| MT-810 | | ---- | ---- | | 19-3 | BO-112(3) |
| MT-820 | | ---- | ---- | | 19-3 | BO-112(3) |
| NECCHI | | | | | | |
| 400-100 | 971964-4-00 | 908 | BC-PF3114 | | ---- | ---- |
| 411-100 | 9719456-4-00 | 908NBL | BC-PF3114-NBL | | ---- | ---- |
| 418-100 | 387700-3-20 | 702NBL | BC-107(2)-NBL | | 17 | BO-107(A) |
| 419-100 | | 705 | BC-457 | | 17-4-1 | BO-LBH771-H |
| 420 | 1505-4-00 | 706NBL | BC-271-NBL | | 17-1 | BO-271(A) |
| 421 | 1505-4-00 | 706NBL | BC-271-NBL | | 17-1 | BO-271(A) |
| 422 | 1505-4-00 | 706NBL | BC-271-NBL | | 17-1 | BO-271(A) |
| 500 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 510 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 512 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 513 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 514 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 515 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 520 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 522 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 523 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 524 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 525 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 527 | 971861-4-00 | 302 | BC-HR306 | 52400 | 8 | BO-95(2) |
| | 971861-4-00MF | 609NBL6 | BC-DBZ(1)-NBL6 | 52400A | 10 | BO-95(A) |
| | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 529 | 971861-4-00 | 302 | BC-HR306 | 52400 | 8 | BO-95(2) |
| | 971861-4-00MF | 609NBL6 | BC-DBZ(1)-NBL6 | 52400A | 10 | BO-95(A) |
| | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 532 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 533 | 971861-4-00 | 302 | BC-HR306 | 52400 | 8 | BO-95(2) |
| | 971861-4-00MF | 609NBL6 | BC-DBZ(1)-NBL6 | 52400A | 10 | BO-95(A) |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| 534 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 535 | | 609 | BC-DBZ(1) | 52400 | 8 | BO-95(2) |
| | 971861-4-00MF | 609NBL6 | BC-DBZ(1)-NBL6 | 52400A | 10 | BO-95(A) |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| 539 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 554 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 600 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| 601 | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|---------|-------------------|----------|-------------|---------|----------|----------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 602 | 20176-4-05 | 504 | BC-31-15 | | ----- | ----- |
| 603 | 20176-4-05 | 504 | BC-31-15 | | ----- | ----- |
| 630 | | ----- | ----- | | 38 | BO-45 |
| 631 | | ----- | ----- | | 38 | BO-45 |
| 632 | | ----- | ----- | | 38 | BO-45 |
| 633 | | ----- | ----- | | 38 | BO-45 |
| 640 | | ----- | ----- | | 38 | BO-45 |
| 641 | | ----- | ----- | | 38 | BO-45 |
| 642 | | ----- | ----- | | 38 | BO-45 |
| 643 | | ----- | ----- | | 38 | BO-45 |
| 644 | | ----- | ----- | | 38 | BO-45 |
| 720 | 971861-4-00 | 302 | BC-HR306 | 52400 | 8 | BO-95(2) |
| 721 | 971861-4-00 | 302 | BC-HR306 | 52400 | 8 | BO-95(2) |
| 750 | 971861-4-00 | 302 | BC-HR306 | 52400 | 8 | BO-95(2) |
| 752 | 971861-4-00 | 302 | BC-HR306 | 52400 | 8 | BO-95(2) |
| 753 | 971861-4-00 | 302 | BC-HR306 | 52400 | 8 | BO-95(2) |
| 753-102 | | 1006 | BC-DU265BIG | | ----- | ----- |
| 800 | 52340-4 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | 52400 | 8 | BO-95(2) |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 801 | 52340-4 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | 52400 | 8 | BO-95(2) |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 803 | 52340-4 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | | | | 52400A | 10 | BO-95(A) |
| 802 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | 52400 | 8 | BO-95(2) |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 803 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | 52400 | 8 | BO-95(2) |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 810 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | 52400 | 8 | BO-95(2) |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 810RUM | 52340-4 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| 810RVG | 52340-4 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| 812 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | 52400 | 8 | BO-95(2) |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 813 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | 52400 | 8 | BO-95(2) |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 830 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | 52400 | 8 | BO-95(2) |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 831 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | 52400 | 8 | BO-95(2) |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 832 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | 52400 | 8 | BO-95(2) |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 835 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| | | 601M | BC-DB1-M | 52400 | 8 | BO-95(2) |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 840 | 971861-4-00 | 302 | BC-HR306 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| 860 | 554577-4-00 | 606 | BC-DLN | 52400 | 8 | BO-95(2) |
| | 554577-4-00MF | 606 | BC-DLN | | | |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|---------|-------------------|----------|-------------|---------|----------|----------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 881 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| 882 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| 883 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| 884 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| 885 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| 887 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| 890 | | ---- | ---- | | ---- | ---- |
| 895-266 | 227526-4-00MF | ---- | ---- | | ---- | ---- |
| 895-268 | 227526-4-00MF | ---- | ---- | | ---- | ---- |
| 895-566 | 227526-4-00MF | ---- | ---- | | ---- | ---- |
| 895-568 | 227526-4-00MF | ---- | ---- | | ---- | ---- |
| 902-155 | 971727-4-00 | ---- | ---- | | ---- | ---- |
| 910-113 | 971923-4-00 | ---- | ---- | | ---- | ---- |
| 910-114 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| 910-158 | 971923-4-00 | ---- | ---- | | ---- | ---- |
| 910-159 | 971923-4-00 | ---- | ---- | | ---- | ---- |
| 911-113 | 971923-4-00 | ---- | ---- | | ---- | ---- |
| 916-114 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| 917-114 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| 925-101 | 971839-4-00 | ---- | ---- | | ---- | ---- |
| 925-103 | 971928-4-00 | ---- | ---- | | ---- | ---- |
| 925-401 | 971839-4-00 | ---- | ---- | | ---- | ---- |
| 925-403 | 971928-4-00 | ---- | ---- | | ---- | ---- |
| 927-103 | 205528-4-00 | ---- | ---- | | ---- | ---- |
| 927-203 | 205528-4-00 | ---- | ---- | | ---- | ---- |
| 927-263 | 205528-4-00 | ---- | ---- | | ---- | ---- |
| 928 | 971839-4-00 | ---- | ---- | | ---- | ---- |
| 928-101 | 971839-4-00 | ---- | ---- | | ---- | ---- |
| 928-201 | 971839-4-00 | ---- | ---- | | ---- | ---- |
| 928-261 | 971839-4-00 | ---- | ---- | | ---- | ---- |
| 930-113 | 971923-4-00 | ---- | ---- | | ---- | ---- |
| 930-114 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| 930-159 | 971923-4-00 | ---- | ---- | | ---- | ---- |
| 931-100 | 971727-4-00 | ---- | ---- | | ---- | ---- |
| 931-101 | 971727-4-00 | ---- | ---- | | ---- | ---- |
| 932-100 | 971727-4-00 | ---- | ---- | | ---- | ---- |
| 951-260 | 971828-4-00 | ---- | ---- | | ---- | ---- |
| 951-460 | 971828-4-00 | ---- | ---- | | ---- | ---- |
| 953 | 971828-4-10 | CAP | UNAVAILABLE | | ---- | ---- |
| 953-260 | 971828-4-00 | ---- | ---- | | ---- | ---- |
| 953-460 | 971828-4-00 | ---- | ---- | | ---- | ---- |
| 955 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| | | CAP | UNAVAILABLE | | ---- | ---- |
| 956 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| | | CAP | UNAVAILABLE | | ---- | ---- |
| 957 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| | | ---- | ---- | | ---- | ---- |
| 958 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| | | ---- | ---- | | ---- | ---- |
| 960 | 971828-4-10 | CAP | UNAVAILABLE | | ---- | ---- |
| 960-260 | 971924-4-00 | ---- | ---- | | ---- | ---- |
| 960-261 | 971924-4-00 | ---- | ---- | | ---- | ---- |
| 961 | 971828-4-10 | CAP | UNAVAILABLE | | ---- | ---- |
| 961-260 | 871924-4-00 | ---- | ---- | | ---- | ---- |
| 961-261 | 871924-4-00 | ---- | ---- | | ---- | ---- |
| 965 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| 966 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| 971 | 971828-4-10 | CAP | UNAVAILABLE | | ---- | ---- |
| | | CAP | UNAVAILABLE | | ---- | ---- |
| 971-260 | 971828-4-00 | ---- | ---- | | ---- | ---- |
| 971-261 | 971828-4-00 | ---- | ---- | | ---- | ---- |
| 971-460 | 971828-4-00 | ---- | ---- | | ---- | ---- |
| 971-461 | 971828-4-00 | ---- | ---- | | ---- | ---- |
| 974 | 205528-4-10 | ---- | ---- | | ---- | ---- |
| 975 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| | | CAP | UNAVAILABLE | | ---- | ---- |
| 976 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| | | CAP | UNAVAILABLE | | ---- | ---- |
| 977 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| 978 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| 980 | 971828-4-10 | CAP | UNAVAILABLE | | ---- | ---- |
| 980-103 | 205528-4-00 | ---- | ---- | | ---- | ---- |
| 980-203 | 205528-4-00 | ---- | ---- | | ---- | ---- |
| 980-260 | 971924-4-00 | ---- | ---- | | ---- | ---- |

| MACHINE | BOBBIN CASE (CAP) | | | REF.NO. | BOBBIN | |
|----------------------------|-------------------|----------|---------------|----------|----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | | ITEM NO. | ARTICLE |
| 980-261 | 871924-4-00 | ---- | ---- | | ---- | ---- |
| 985 | 971723-4-00 | CAP | UNAVAILABLE | | ---- | ---- |
| 1895 | 227526-4-00 | ---- | ---- | | ---- | ---- |
| BD | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| BDA | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| BE | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| BF | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| BI | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| BIA | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| BPR | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| BTR | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| BU | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| BV | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| IA | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| LELIA | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| NORA | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| OP | | ---- | ---- | | 38 | BO-45 |
| RM | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| RVG | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| RVM | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| RZI | 110528-4-00 | 302 | BC-HR306 | 52400 | 8 | BO-95(2) |
| SA | 20176-4-05 | 504 | BC-31-15 | | ---- | ---- |
| SG | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| SM | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| UAN-800 | 225912-4-00 | ---- | ---- | | ---- | ---- |
| UAN-1501 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| UAN-1531 | 971878-4-00 | 601 | BC-DB1 | 52400 | 8 | BO-95(2) |
| | 222528-4 | 601NBL6 | BC-DB1-NBL6 | 52400A | 10 | BO-95(A) |
| UAN-2500 | 971912-4-00 | ---- | ---- | | ---- | ---- |
| UAN-2641 | 227526-4-00MF | ---- | ---- | | ---- | ---- |
| POCKET SETTER IDEAL IE-600 | IE35870 | ---- | ---- | IE18358 | ---- | ---- |
| | | | | IE18358A | ---- | ---- |
| NEW LONG | | | | | | |
| DD-3 | | ---- | ---- | | 38 | BO-45 |
| DD-5 | | ---- | ---- | | 35 | BO-132 |
| DD-6 | | ---- | ---- | | 38 | BO-45 |
| NITAKA | | | | | | |
| DY-350L | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| DY-350S | | 601 | BC-DB1 | | 13-4 | BO-400(4) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| DY-370L | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| DY-370S | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| LK-850E | | ---- | ---- | | ---- | ---- |
| LK-850T | | ---- | ---- | | ---- | ---- |
| LT2-B922-3 | | ---- | ---- | | ---- | ---- |
| LT2-B932 | | ---- | ---- | | 19-3 | BO-112(3) |
| LT2-B932-5 | | ---- | ---- | | ---- | ---- |
| TC-810 | | ---- | ---- | | 19-3 | BO-112(3) |
| TC-810S | | ---- | ---- | | 19-3 | BO-112(3) |
| TC-820 | | ---- | ---- | | 19-3 | BO-112(3) |
| TC-820S | | ---- | ---- | | 19-3 | BO-112(3) |
| TC-1553-3-5 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| TC-1555-3-5 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| TC2-B842 | | ---- | ---- | | 19-3 | BO-112(3) |
| TC2-B845 | | CAP | UNAVAILABLE | | 19-3 | BO-112(3) |
| TC2-B872 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| TC2-B872-3 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| TC2-B872-5 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| TC2-B875 | | CAP | UNAVAILABLE | | 26-3 | BO-1215MM-N |
| TC2-B842-3 | | ---- | ---- | | ---- | ---- |
| TC2-B842-5 | | ---- | ---- | | ---- | ---- |
| TC2-B935 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| TC2-B1685 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| TC2-B1883 | | CAP | UNAVAILABLE | | 19-3 | BO-112(3) |
| TC2-B1885 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| TCW-8B | | ---- | ---- | | 19-3 | BO-112(3) |
| TTC-1530 | | 601NBL6 | BC-DB1-NBL6 | | 2 | BO-103(2) |
| TTC-1550 | | 601NBL6 | BC-DB1-NBL6 | | 2 | BO-103(2) |
| OMAC | | | | | | |
| EOC | | 616NBL6 | BC-AD396-NBL6 | | 10 | BO-95(A) |
| PANDA | | | | | | |
| JU-20U | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| PEGASUS | | | | | | |
| DH-10 | | ---- | ---- | | ---- | ---- |

| MACHINE | BOBBIN CASE (CAP) | | | REF.NO. | BOBBIN | |
|----------------|-------------------|----------|---------------|---------|-----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | | ITEM NO. | ARTICLE |
| DH-20 | | ---- | ---- | | ---- | ---- |
| DH-30 | | ---- | ---- | | ---- | ---- |
| DPS-2 | 178081 | 702 | BC-107(2) | | 17 | BO-107(A) |
| | | 702NBL | BC-107(2)-NBL | | | |
| DPS-3 | 178081 | 702 | BC-107(2) | | 17 | BO-107(A) |
| | | 702NBL | BC-107(2)-NBL | | | |
| DPS-4 | 178081 | 702 | BC-107(2) | | 17 | BO-107(A) |
| | | 702NBL | BC-107(2)-NBL | | | |
| DPS-150 | 178081 | 702 | BC-107(2) | | 17 | BO-107(A) |
| | | 702NBL | BC-107(2)-NBL | | | |
| PENGUIN | | | | | | |
| PEG-810 | | ---- | ---- | | 19-3 | BO-112(3) |
| PEG-820 | | ---- | ---- | | 19-3 | BO-112(3) |
| PFAFF | | | | | | |
| 11 | | ---- | ---- | | ---- | ---- |
| 27-55/11 | | ---- | ---- | | ---- | ---- |
| 28 | | ---- | ---- | | ---- | ---- |
| 29 | | ---- | ---- | | ---- | ---- |
| 30 | 2247 | ---- | ---- | | ---- | ---- |
| 31 | 2247 | ---- | ---- | | ---- | ---- |
| 34 Series | 6843 | 909 | BC-PF6843 | 2030 | ---- | ---- |
| 38 | | ---- | ---- | 2030 | ---- | ---- |
| 41 | 168628 | 910 | BC-PF418 | 168178 | ALUMINIUM | ---- |
| 65 | 6843 | 909 | BC-PF6843 | 2030 | ---- | ---- |
| 70 | | ---- | ---- | | ---- | ---- |
| 114 | 8243 | 908 | BC-PF3114 | 20240 | ---- | ---- |
| | 8243NBL | 908NBL | BC-PF3114-NBL | | | |
| 115 | 8243 | 908 | BC-PF3114 | 20240 | ---- | ---- |
| | 8243NBL | 908NBL | BC-PF3114-NBL | | | |
| 116 | 8243 | 908 | BC-PF3114 | 20240 | ---- | ---- |
| | 8243NBL | 908NBL | BC-PF3114-NBL | | | |
| 117 | 8243 | 908 | BC-PF3114 | 20240 | ---- | ---- |
| | 8243NBL | 908NBL | BC-PF3114-NBL | | | |
| 120 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 122 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 130 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | | 905 | BC-PF9076(14) | | | |
| 133 | 9266 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | | 902 | BC-PF9266 | | | |
| 134 | 9266 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | | 902 | BC-PF9266 | | | |
| 138 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 140 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 141(-155) | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 142(-900) | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 142-720 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 142-720(-900) | 140650 | CAP | UNAVAILABLE | 10079 | ---- | ---- |
| 142-721 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 142-721(-900) | 140650 | CAP | UNAVAILABLE | 10079 | ---- | ---- |
| 143 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 144 | 113192 | CAP | UNAVAILABLE | 10079 | ---- | ---- |
| 144-720 | 10159 | C-2 | CP-PF151 | 118308 | ALUMINIUM | ---- |
| 145 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 146 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 151 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 155 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 175-196 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 190 | | CAP | UNAVAILABLE | 10079 | ---- | ---- |
| 191 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 192 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 192-720 | 19923 | ---- | ---- | | ---- | ---- |
| 193 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 194 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 194-720 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 195 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 196 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 230 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 232 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 234 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 238 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 242 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 244 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 260 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 292 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-----------|-------------------|----------|---------------|---------|-----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 293 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 294 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 300 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 331 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 332 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 333 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 335 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 335-H2 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 337-734 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 341 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 341-347 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 343 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 345H3 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 346 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 346H3 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 353 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 353-354 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 354 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 360 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 390 | | CAP | UNAVAILABLE | 10079 | ----- | ----- |
| 417(-900) | 168628 | 910 | BC-PF418 | 168178 | ALUMINIUM | ----- |
| 418(-900) | 168628 | 910 | BC-PF418 | 168178 | ALUMINIUM | ----- |
| 419(-900) | 168628 | 910 | BC-PF418 | 168178 | ALUMINIUM | ----- |
| 430 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 432 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 433 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 434 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 437 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| 438 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| 439 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| 441 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 441-900 | 118414 | CAP | UNAVAILABLE | 10079 | ----- | ----- |
| 441R-705 | | CAP | ----- | | ----- | ----- |
| 441R-755 | | CAP | ----- | | ----- | ----- |
| 442 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 442-900 | 118414 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ----- |
| 443 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 443-900 | 118414 | CAP | UNAVAILABLE | 10079 | ----- | ----- |
| 444 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 444-900 | 118414 | CAP | UNAVAILABLE | 10079 | ----- | ----- |
| 445 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 445-900 | 118414 | CAP | UNAVAILABLE | 10079 | ----- | ----- |
| 446 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 446-900 | 118414 | CAP | UNAVAILABLE | 10079 | ----- | ----- |
| 447 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 447-900 | 118414 | CAP | UNAVAILABLE | 10079 | ----- | ----- |
| 448 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 448-900 | 118414 | CAP | UNAVAILABLE | 10079 | ----- | ----- |
| 451 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 452 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 453 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 454 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 455 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 456 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 457 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------------|-------------------|----------|---------------|---------|-----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 460 | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| 461(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 462(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 463(-900) | 69672 | 906 | BC-PF69672 | 9033 | 24 | BO-PF130 |
| | 69672NBL | 906NBL | BC-PF696-NBL | 168144 | 24-2 | BO-PF130(A) |
| 464(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 465(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 466(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 467(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 468(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 469(-900) | 69672 | 906 | BC-PF69672 | 9033 | 24 | BO-PF130 |
| | 69672NBL | 906NBL | BC-PF696-NBL | 168144 | 24-2 | BO-PF130(A) |
| 470 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ----- |
| 470PLAIN MACHINE | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 471 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 471-493A,B(L) | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ----- |
| 471-493C(L) | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ----- |
| 471-900 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ----- |
| 472 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 472-900 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ----- |
| 473 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 473-900 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ----- |
| 474 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 474-900 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ----- |
| 475 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 475-900 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ----- |
| 476 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 476-900 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ----- |
| 477 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 477-900 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ----- |
| 478 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 478-900 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ----- |
| 479 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 479-900 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ----- |
| 480 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 69672NBL | 906NBL | BC-PF696-NBL | 168144 | 24-2 | BO-PF130(A) |
| 481(-900) | 69672 | 906 | BC-PF69672 | 9033 | 24 | BO-PF130 |
| | 69672NBL | 906NBL | BC-PF696-NBL | 168144 | 24-2 | BO-PF130(A) |
| 482(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 483(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 484(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 485(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 486(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 487(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 487NL | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 488(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 489(-900) | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 489NL | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|----------------|-------------------|----------|---------------|--------------|-----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 490 | | ---- | ---- | | 19-6 | BO-112(6) |
| 490 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 490-900 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ---- |
| 491 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 491-900 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ---- |
| 492 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 492-900 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ---- |
| 493 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 493-900 | 119458 | CAP | UNAVAILABLE | 118308 | ALUMINIUM | ---- |
| 541(-546) | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 542 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 543 | 18348 | CAP | UNAVAILABLE | 14356 | 41 | BO-PF541 |
| 544 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 544-720 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 545 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 546 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 551(-555) | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 552 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 553 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 554 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 555 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 560 | 167597 | ---- | ---- | 168144 | 24-2 | BO-PF130(A) |
| 563NL | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 591(-596) | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 592 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 593 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 594 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 595 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 596 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 720 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 734 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 748 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 837 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 838 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| | 9076NBL | 903NBL | BC-PF9076-NBL | 168144 | 24-2 | BO-PF130(A) |
| | 9076M | 903M | BC-PF9076-M | 9033 | 24 | BO-PF130 |
| 871-893 | 10159 | C-2 | CP-PF151 | 10079 | ---- | ---- |
| 1240 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| | 140287 | CAP | UNAVAILABLE | 18480 | | |
| 1241(-1246) | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 1242 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 1242-720 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 1242-748 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 1242-720(-900) | 140287 | CAP | UNAVAILABLE | 18480 | 41 | BO-PF541 |
| 1243 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 1244(-720) | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 1244-748 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 1244-720(-900) | 140287 | CAP | UNAVAILABLE | 18480 | 41 | BO-PF541 |
| 1245 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 1245-900 | 18348 | CAP | UNAVAILABLE | 18480 | 41 | BO-PF541 |
| 1246 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 1246-720 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 1246-748 | 18348 | CAP | UNAVAILABLE | 18339 | 41 | BO-PF541 |
| 1246-900 | 140287 | CAP | UNAVAILABLE | 18480 | 41 | BO-PF541 |
| 3114 | 8243 | 908 | BC-PF3114 | 20240 | ---- | ---- |
| | 8243NBL | 908NBL | BC-PF3114-NBL | | | |
| 3115 | 8243 | 908 | BC-PF3114 | 20240 | ---- | ---- |
| | 8243NBL | 908NBL | BC-PF3114-NBL | | | |
| 3116 | 8243 | 908 | BC-PF3114 | 120054 | ---- | ---- |
| | 8243NBL | 908NBL | BC-PF3114-NBL | 20240 | ---- | ---- |
| 3118 | 8243 | 908 | BC-PF3114 | 20240 | ---- | ---- |
| | 8243NBL | 908NBL | BC-PF3114-NBL | | | |
| 3125 | 24423 | 901 | BC-PF24423 | 91-002030-05 | ---- | ---- |
| | 24423NBL | 901NBL | BC-PF244-NBL | 168178 | ALUMINIUM | ---- |
| 3135 | 24423 | 901 | BC-PF24423 | 2030 | ---- | ---- |
| | 24423NBL | 901NBL | BC-PF244-NBL | 168178 | ALUMINIUM | ---- |
| 3136 | 24423 | 901 | BC-PF24423 | 2030 | ---- | ---- |
| | 24423NBL | 901NBL | BC-PF244-NBL | 168178 | ALUMINIUM | ---- |
| 3325 | | ---- | ---- | 2030 | ---- | ---- |
| 3331 | 24423 | 901 | BC-PF24423 | 2030 | ---- | ---- |
| | 24423NBL | 901NBL | BC-PF244-NBL | 168178 | ALUMINIUM | ---- |
| 3334 | 24423 | 901 | BC-PF24423 | 2030 | ---- | ---- |
| | 24423NBL | 901NBL | BC-PF244-NBL | 168178 | ALUMINIUM | ---- |
| 3335 | 24423 | 901 | BC-PF24423 | 2030A | ---- | ---- |
| | 24423NBL | 901NBL | BC-PF244-NBL | 168178 | ALUMINIUM | ---- |
| 3336 | 24423 | 901 | BC-PF24423 | 2030 | ---- | ---- |
| 3337 | 24423 | 901 | BC-PF24423 | 2030 | ---- | ---- |
| 3516 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|----------------|-------------------|----------|----------------|---------|-----------|------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 3518 | 168628 | 910 | BC-PF418 | 168178 | ALUMINIUM | ----- |
| | 168628 | 910 | BC-PF418 | 168634 | STEEL | ----- |
| 3518-418-900 | 168628 | 910 | BC-PF418 | 168178 | ALUMINIUM | ----- |
| 3518-481-900 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 3518-483-900 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 3527 | 8243 | 908 | BC-PF3114 | 20240 | ----- | ----- |
| 3541 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 3548 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| 3553 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 3557 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 3563 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 3564 | 8243 | 908 | BC-PF3114 | 20240 | ----- | ----- |
| 3565 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 3568 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 3571-483-900 | 9076 | 903 | BC-PF9076 | 9033 | 24 | BO-PF130 |
| 3830 | 10159 | C-2 | CP-PF151 | 10079 | ----- | ----- |
| KSM-200 | 135659 | 802 | BC-DBM(Z1) | | 21-5 | BO-DBM(1)N |
| | 135672 | 802NBL3 | BC-DBM(Z1)-NBL | | | |
| PHOENIX | | | | | | |
| 29 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| | | 601M | BC-DB1-M | | | |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 49 | | 305 | BC-HR2 | | 2 | BO-103(2) |
| 429 | | 305 | BC-HR2 | | 2 | BO-103(2) |
| 499 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| | | 601M | BC-DB1-M | | | |
| | | 601M2 | BC-DB1-M2 | | | |
| | | 601-2 | BC-DB1-WH | | | |
| 549 | | 305 | BC-HR2 | | 2 | BO-103(2) |
| PRINCE | | | | | | |
| LX-2000 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| LPZ-5000CNC | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| LPZ-6000NCN | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| MOZ-40N | | 702 | BC-107(2) | | 17 | BO-107(A) |
| MOZ-40S | | 702 | BC-107(2) | | 17 | BO-107(A) |
| MOZ-40SP | | 704 | BC-102 | | 15 | BO-107(1) |
| PLM-100 | | ----- | ----- | | 31-3 | BO-1215L-N |
| SPL-100 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| SPX-200CNC | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| SPZ-500 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| SPZ-600 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| RANDAL | | | | | | |
| 168 | | ----- | ----- | | ----- | ----- |
| S7 | | ----- | ----- | | ----- | ----- |
| S89 | | ----- | ----- | | ----- | ----- |
| REFREY | | | | | | |
| 901 | 901 12 60 | C-2 | CP-PF151 | | ----- | ----- |
| 901/41 | 901 12 60/41 | ----- | ----- | | ----- | ----- |
| 902 | 901 12 60 | C-2 | CP-PF151 | | ----- | ----- |
| 902/41 | 901 12 60/41 | ----- | ----- | | ----- | ----- |
| 905 | 1920 12 60 | 801NBL1 | BC-DBM(1)-NBL1 | | 22 | BO-DBM(A) |
| 906 | 90 12 60 | 601NBL6 | BC-DB1-NBL6 | | 8 | BO-95(2) |
| 910 | 90 12 60 | 601NBL6 | BC-DB1-NBL6 | | 8 | BO-95(2) |
| 918 | 90 12 60 | 601NBL6 | BC-DB1-NBL6 | | 8 | BO-95(2) |
| 920 | 91 12 60 | 606 | BC-DLN | | 13-4 | BO-400(4) |
| 920/3 | 91 12 60 | 606 | BC-DLN | | 13-4 | BO-400(4) |
| 921 | 91 12 60 | 606 | BC-DLN | | 13-4 | BO-400(4) |
| 921/3 | 91 12 60 | 606 | BC-DLN | | 13-4 | BO-400(4) |
| 925 | 91 12 60 | 606 | BC-DLN | | 13-4 | BO-400(4) |
| 925/3 | 91 12 60 | 606 | BC-DLN | | 13-4 | BO-400(4) |
| 927/3 | 91 12 60 | 606 | BC-DLN | | 13-4 | BO-400(4) |
| 1901 | 1901 12 60 | C-2 | CP-PF151 | | ----- | ----- |
| 1901/41 | 1901 12 60/41 | 702NBL | BC-107(2)-NBL | | 17 | BO-107(A) |
| 1902 | 1901 12 60 | C-2 | CP-PF151 | | ----- | ----- |
| 1902/41 | 1901 12 60/41 | 702NBL | BC-107(2)-NBL | | 17 | BO-107(A) |
| 1920 | 1920 12 60 | 801NBL1 | BC-DBM(1)-NBL1 | | 22 | BO-DBM(A) |
| 1922 | 1920 12 60 | 801NBL1 | BC-DBM(1)-NBL1 | | 22 | BO-DBM(A) |
| 1923 | 1920 12 60 | 801NBL1 | BC-DBM(1)-NBL1 | | 22 | BO-DBM(A) |
| 1925 | 1920 12 60 | 801NBL1 | BC-DBM(1)-NBL1 | | 22 | BO-DBM(A) |
| 1927 | 1920 12 60 | 801NBL1 | BC-DBM(1)-NBL1 | | 22 | BO-DBM(A) |
| 1930-51/52 | 1930 12 60 | 702 | BC-107(2) | | 17 | BO-107(A) |
| 1930-81/82 | 1930 12 60 | 702 | BC-107(2) | | 17 | BO-107(A) |
| 1931 | 1930 12 60 | 702 | BC-107(2) | | 17 | BO-107(A) |
| RESTA | | | | | | |
| H220 G1 | | 801NBL1 | BC-DBM(1)-NBL1 | | 22 | BO-DBM(A) |
| H220 G2 | | 801NBL1 | BC-DBM(1)-NBL1 | | 22 | BO-DBM(A) |
| H220 G3 | | 801NBL1 | BC-DBM(1)-NBL1 | | 22 | BO-DBM(A) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|----------------|-------------------|----------|----------------|---------|----------|--------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| H220 G4 | | 801NBL1 | BC-DBM(1)-NBL1 | | 22 | BO-DBM(A) |
| RICCAR | | | | | | |
| RD-101 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| RD-102 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| RT-5 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| | | 601NBL6 | BC-DB1-NBL6 | | | |
| HOUSEHOLD | | 304 | BC-HR1 | | 1 | BO-103(1) |
| | | 304AL | BC-HR1-AL | | | |
| | | 306 | BC-HR3 | | | |
| SANHWA | | | | | | |
| LT2-B961 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| SANSHIN | | | | | | |
| SCZ11 | | 804 | BC-DBL(1)-B | | 23-2 | BO-DBL(1)N |
| SCZ14 | | 804 | BC-DBL(1)-B | | | |
| SCZ23 | | 804 | BC-DBL(1)-B | | | |
| SANTONI | | | | | | |
| MFA-84 | CT 000789/0 | ---- | ---- | | ---- | ---- |
| SEIKO | | | | | | |
| BSW Series | | ---- | ---- | | ---- | ---- |
| CH-2B | | ---- | ---- | 29092 | ---- | ---- |
| CH-2RF | | ---- | ---- | 29092 | ---- | ---- |
| CH-6B | | ---- | ---- | 29092 | ---- | ---- |
| CH-7B | | ---- | ---- | 29092 | ---- | ---- |
| CH-8B | | ---- | ---- | 29092 | ---- | ---- |
| CH-8BV | | ---- | ---- | 29092 | ---- | ---- |
| CK-1 | | ---- | ---- | | ---- | ---- |
| CW-1 | 13086 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| CW-6 | 13086 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| CW-6B | 13086 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| CW-7 | 13086 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| CW-7B | 13086 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| CW-8 | 13086 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| CW-8B | 13086 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| CW-8BV | 13086 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| CW-8V | 13086 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| CW-8VB | 13086 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| DE-6 | | 503 | BC-269 | 6018 | ---- | ---- |
| | | 503NBL | BC-269-NBL | | | |
| DE-8 | | 503 | BC-269 | 6018 | ---- | ---- |
| DE-6 | | 503NBL | BC-269-NBL | 6018 | ---- | ---- |
| DI-4 | | ---- | ---- | 46083 | ---- | ---- |
| GPB-8W | 37255-07 | C-2 | CP-PF151 | 37257 | ---- | ---- |
| H-2B | 18550 | 801 | BC-DBM(1) | 18034 | 21-5 | BO-DBM(1)N |
| H-2BL | 18550 | 801NBL1 | BC-DBM(1)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |
| H-8B | | ---- | ---- | 18710 | 1 | BO-103(1) |
| H-8BD | 0287112 | 606 | BC-DLN | | 8 | BO-95(2) |
| HC-2B | | 903NBL | BC-PF9076-NBL | | 24-2 | BO-PF130(A) |
| HC-2BL | 18550 | 801NBL1 | BC-DBM(1)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |
| HC-2BLA | 18550 | 801 | BC-DBM(1) | 18034 | 21-5 | BO-DBM(1)N |
| HCL-2BL | 18850 | 801NBL1 | BC-DBM(1)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |
| JW-8BL | | ---- | ---- | 70141 | 25 | BO-144 |
| JW-8BLC | | ---- | ---- | 70769 | ---- | ---- |
| LAH-1LC | 321783 | ---- | ---- | 18034 | 21-5 | BO-DBM(1)N |
| LAH-1LC/N | 18850 | 801NBL1 | BC-DBM(1)-NBL1 | 35784 | 21-5 | BO-DBM(1)N |
| LCW Series | | ---- | ---- | 18034 | 21-5 | BO-DBM(1)N |
| LD-27R | | ---- | ---- | | ---- | ---- |
| LLPW-1L | 15850-9C | CAP | ---- | | 26-3 | BO-1215MM-N |
| LLW-7B | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LLW-7BL(-TA) | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LLW-7L(-TA) | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LLW-8BL(-TA) | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LLW-8L(-TA) | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LLW-27BL(-TA) | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LLW-27L(-TA) | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LLW-28 | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LLW-28BL | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LLW-28BL-TA | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LLW-28L | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LLW-28L-TA | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LPW-2G Series | | C-1F | CP-51F | | ---- | ---- |
| LPW-6 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-6B | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-6BL | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LPW-6BLC | 36145-09 | CAP | ---- | 36216 | 26-2 | BO-1215MM(A) |
| LPW-6L | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LPW-7 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-7B | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|----------------|-------------------|----------|------------------|---------|----------|--------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| LPW-7BL | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LPW-7L | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LPW-8 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-8B | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-8BL | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LPW-8L | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LPW-26 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-26B | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-26BL | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LPW-26BLC | 36145-09 | CAP | ---- | 36216 | 26-2 | BO-1215MM(A) |
| LPW-26L | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LPW-27 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-27B | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-27BK | 12856-9C | CAP | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-27BL | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LPW-27BLK | 14706-09 | CAP | ---- | | ---- | ---- |
| LPW-27BM | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-27L | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LPW-28 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-28B | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-28BK | 12856-9C | CAP | ---- | 10656 | 19-3 | BO-112(3) |
| LPW-28BL | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LPW-28BLK | 14706-09 | CAP | ---- | | ---- | ---- |
| LPW-28L | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSC-8B | 17034 | 903 | BC-PF9076 | 17035 | 24 | BO-PF130 |
| | | 903NBL | BC-PF9076-NBL | | | |
| | | 903M | BC-PF9076-M | | | |
| LSC-8BHC | 17318 | 905NBL | BC-PF9076(14)NBL | 17035 | 24 | BO-PF130 |
| LSC-8BL | 18550 | 801 | BC-DBM(1) | 18034 | 21-5 | BO-DBM(1)N |
| LSC-8BLV | 18550 | 801 | BC-DBM(1) | 18034 | 21-5 | BO-DBM(1)N |
| LSC-8BV | 17034 | 903 | BC-PF9076 | 17035 | 24 | BO-PF130 |
| | | 903NBL | BC-PF9076-NBL | | | |
| | | 903M | BC-PF9076-M | | | |
| LSC-8BVC | 17318 | 905NBL | BC-PF9076(14)NBL | 17035 | 24 | BO-PF130 |
| LSW-6L | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-6L-G | 15850-09 | CAP | UNAVAILABLE | 16408 | 26-3 | BO-1215MM-N |
| LSW-7BL(-T) | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-7BLC | 30502-9C | CAP | ---- | 34315 | 31-2 | BO-1215L(A) |
| LSW-7BLC-BT | 30502-9C | CAP | ---- | 34315 | 31-2 | BO-1215L(A) |
| LSW-7BLC-BTFL | 30502-9C | CAP | ---- | 34315 | 31-2 | BO-1215L(A) |
| LSW-7L(-T) | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-7L-G | 15850-09 | CAP | UNAVAILABLE | 16408 | 26-3 | BO-1215MM-N |
| LSW-7LC | 30502-9C | CAP | ---- | 34315 | 31-2 | BO-1215L(A) |
| LSW-7LC-BTFL | 30502-9C | CAP | ---- | 34315 | 31-2 | BO-1215L(A) |
| LSW-8 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LSW-8B | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LSW-8BL(-T) | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8BLC | 30502-9C | CAP | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8BLC-BT | 30502-9C | CAP | ---- | 34315 | 31-2 | BO-1215L(A) |
| LSW-8BLC-BTFL | 30502-9C | CAP | ---- | 34315 | 31-2 | BO-1215L(A) |
| LSW-8BLC/CS | 30502-9C | CAP | ---- | 34315 | 31-2 | BO-1215L(A) |
| LSW-8BL/CS | 30502-9C | CAP | ---- | 34315 | 31-2 | BO-1215L(A) |
| LSW-8BL/CS/TA | 30502-9C | CAP | ---- | 34315 | 31-2 | BO-1215L(A) |
| LSW-8BLM | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8BLMC | 30502-9C | CAP | ---- | 34315 | 31-2 | BO-1215L(A) |
| LSW-8BLV | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8BLVMF | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8BLVP | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8BLVPM | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8C | | CAP | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8L(-T) | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8LC-BTFL | 30502-9C | CAP | ---- | 34315 | 31-2 | BO-1215L(A) |
| LSW-8LC | 30502-9C | CAP | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8LC(N) | | CAP | ---- | | 31-2 | BO-1215L(A) |
| LSW-8LG | | ---- | ---- | | 31-3 | BO-1215L-N |
| LSW-8LM | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8LV | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8LVMF | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8LVP | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-8LVPM | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-26BL | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-26BL-R | 15850-09 | CAP | UNAVAILABLE | 16408 | 26-3 | BO-1215MM-N |
| LSW-26L | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-26L-R | 15850-09 | CAP | UNAVAILABLE | 16408 | 26-3 | BO-1215MM-N |
| LSW-26L-TA | 15853-13 | ---- | ---- | | ---- | ---- |
| LSW-26LH | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-27BL | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-27BLC | 31303-9C | CAP | ---- | 16408 | 26-3 | BO-1215MM-N |
| LSW-27BLC-BT | 31303-9C | CAP | ---- | 16408 | 26-3 | BO-1215MM-N |
| LSW-27BLC-BTFL | 31303-9C | CAP | ---- | 16408 | 26-3 | BO-1215MM-N |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-----------------|-------------------|----------|-----------------|---------|----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| LSW-27BLC(N) | | ---- | ---- | | ---- | ---- |
| LSW-27BLK | 15850-09 | CAP | UNAVAILABLE | 16408 | 26-3 | BO-1215MM-N |
| LSW-27BLKC | 31303-9C | CAP | ---- | 16408 | 26-3 | BO-1215MM-N |
| LSW-27BLKC-BT | 31303-9C | CAP | ---- | 16408 | 26-3 | BO-1215MM-N |
| LSW-27BLKC-BTFL | 31303-9C | CAP | ---- | 16408 | 26-3 | BO-1215MM-N |
| LSW-27BLM | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-27L | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-28BL | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-28BLC | 31303-9C | CAP | ---- | 16408 | 26-3 | BO-1215MM-N |
| LSW-28BLC-BT | 31303-9C | CAP | ---- | 16408 | 26-3 | BO-1215MM-N |
| LSW-28BLC-BTFL | 31303-9C | CAP | ---- | 16408 | 26-3 | BO-1215MM-N |
| LSW-28BL-TA | | ---- | ---- | | ---- | ---- |
| LSW-28BLK | 15850-09 | CAP | UNAVAILABLE | 16408 | 26-3 | BO-1215MM-N |
| LSW-28BLKC | 31303-9C | CAP | ---- | 16408 | 26-3 | BO-1215MM-N |
| LSW-28BLKC-BT | 31303-9C | CAP | ---- | 16408 | 26-3 | BO-1215MM-N |
| LSW-28BLKC-BTFL | 31303-9C | CAP | ---- | 16408 | 26-3 | BO-1215MM-N |
| LSW-28L | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LSW-28L-TA | | ---- | ---- | | ---- | ---- |
| LTW-26 | 248460 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LTW-26R | 15875-09 | CAP | ---- | 10656 | 19-3 | BO-112(3) |
| LTW-27 | 248460 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LTW-27B | 248460 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LTW-27BK | 16291-06 | CAP | UNAVAILABLE | 10656 | 19-3 | BO-112(3) |
| LTW-27BLM | | ---- | ---- | 15041 | 31-3 | BO-1215L-N |
| LTW-27BM | 248460 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| LTW-27BL | 18550 | 801 | BC-DBM(1) | 18034 | 21-5 | BO-DBM(1)N |
| LZH-EVL | | 802NBL3 | BC-DBM(Z1)-NBL3 | 18034 | 21-5 | BO-DBM(1)N |
| LZH-EVLC | | 802NBL3 | BC-DBM(Z1)-NBL3 | 18034 | 21-5 | BO-DBM(1)N |
| NCL-2BL | 18550 | 801 | BC-DBM(1) | 18034 | 21-5 | BO-DBM(1)N |
| PW-6 | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-6-1 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-6-3 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-6B | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-6B-1 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-6B-3 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-7 | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-7B | 233765 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-8 | 12124 | CAP | UNAVAILABLE | 12125 | 19-3 | BO-112(3) |
| PW-8B | 12124 | CAP | UNAVAILABLE | 12125 | 19-3 | BO-112(3) |
| PW-8BM | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-8M | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-26 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-26B | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-27 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-27B | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-28 | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PW-28B | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| PWB-8GW | 37255-07 | C-2 | CP-PF151 | 37257 | ---- | ---- |
| PWB-8GW-LP | 37255-07 | C-2 | CP-PF151 | 37257 | ---- | ---- |
| PWB-8GWC | 37735-7C | C-2 | CP-PF151 | 37257 | ---- | ---- |
| PWB-8GWC-FL | 37735-7C | C-2 | CP-PF151 | 37257 | ---- | ---- |
| PWB-8GWC-LC | 37735-7C | C-2 | CP-PF151 | 37257 | ---- | ---- |
| PWB-8GWC-LP | 37735-7C | C-2 | CP-PF151 | 37257 | ---- | ---- |
| PWB-8W | 37255-07 | C-2 | CP-PF151 | 37257 | ---- | ---- |
| PWB-22GW | 37255-07 | C-2 | CP-PF151 | 37257 | ---- | ---- |
| PWB-22WC-FL | 37735-7C | C-2 | CP-PF151 | 37257 | ---- | ---- |
| PWB-22WGC | 37255-07 | C-2 | CP-PF151 | 37257 | ---- | ---- |
| PWG-7 | | C-1F | CP-51F | | ---- | ---- |
| PWG-7M | | C-1F | CP-51F | | ---- | ---- |
| SE-2 | | 507 | BC-78 | | ---- | ---- |
| SE-8 | | 507 | BC-78 | | ---- | ---- |
| SK-2B | | ---- | ---- | CS1441 | 35 | BO-132 |
| SK-6 | | ---- | ---- | CS1441 | 35 | BO-132 |
| SK-6F | | ---- | ---- | CS1441 | 35 | BO-132 |
| SK-6F-1 | | ---- | ---- | CS1441 | 35 | BO-132 |
| SK-6F-20 | | ---- | ---- | CS1441 | 35 | BO-132 |
| SK-7 | | ---- | ---- | CS1441 | 35 | BO-132 |
| SK-8 | | ---- | ---- | CS1441 | 35 | BO-132 |
| SKM-26 | | ---- | ---- | CS1441 | 35 | BO-132 |
| SKM-36 | | ---- | ---- | CS1441 | 35 | BO-132 |
| SKZ Series | | ---- | ---- | | ---- | ---- |
| SLH-2B | | ---- | ---- | 35226 | ---- | ---- |
| SLH-2BHF | | ---- | ---- | 35226 | ---- | ---- |
| SPW-6 | | C-1 | CP-51 | | ---- | ---- |
| SPW-26 | | C-1 | CP-51 | | ---- | ---- |
| STH-3BL | 18045 | 806NBL1 | BC-DBM(2)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |
| STH-6BL | 18045 | 806NBL1 | BC-DBM(2)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |
| STH-7BL | 18045 | 806NBL1 | BC-DBM(2)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |
| STH-7BL-25 | 18045 | 806NBL1 | BC-DBM(2)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |
| STH-7BLC-BT | | 806NBL1 | BC-DBM(2)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|--------------------|-------------------|----------|----------------|---------|----------|--------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| STH-8BD | 18096 | 806NBL1 | BC-DBM(2)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |
| STH-8BL | 18045 | 806NBL1 | BC-DBM(2)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |
| STH-8BL-25 | 18045 | 806NBL1 | BC-DBM(2)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |
| STH-8BLC | | ---- | ---- | 18358 | 22 | BO-DBM(A) |
| STH-8BLC-BT | 18045 | 806NBL1 | BC-DBM(2)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |
| STH-8BLC-BTFC | 18045 | 806NBL1 | BC-DBM(2)-NBL1 | 18034 | 21-5 | BO-DBM(1)N |
| STW-6 | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-7 | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-7B | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-8 | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-8B | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-8B | 18096 | ---- | ---- | | ---- | ---- |
| STW-8BM | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-8BV | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-8BVP | | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-8BVPM | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-8M | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-8V | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-8VM | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-8VP | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-8VPM | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-26 | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-26B | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-27 | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-27B | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-28 | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| STW-28B | 10655 | ---- | ---- | 10656 | 19-3 | BO-112(3) |
| TD-2 | | 503NBL | BC-269-NBL | 6018 | ---- | ---- |
| TD-2S | | 503 | BC-269 | | | |
| | | 503NBL | BC-269-NBL | 6018 | ---- | ---- |
| TD-5 | | 503NBL | BC-269-NBL | | | |
| TD-6 | | 503 | BC-269 | 6018 | ---- | ---- |
| | | 503NBL | BC-269-NBL | | | |
| TDW-2B | | 503 | BC-269 | 6018 | ---- | ---- |
| | | 503NBL | BC-269-NBL | | | |
| TDW-6B | | 503 | BC-269 | 6018 | ---- | ---- |
| | | 503NBL | BC-269-NBL | | | |
| TE-2 | | ---- | ---- | 8096 | 34 | BO-17 |
| TE-2S | | ---- | ---- | | 34 | BO-17 |
| TE-5 | | ---- | ---- | 8096 | 34 | BO-17 |
| TE-5B | | ---- | ---- | 8096 | 34 | BO-17 |
| TE-6 | | ---- | ---- | 8096 | 34 | BO-17 |
| TE-6B | | ---- | ---- | 8096 | 34 | BO-17 |
| TF-5 | | ---- | ---- | 8096 | 34 | BO-17 |
| TF-5B | | ---- | ---- | 8096 | 34 | BO-17 |
| TF-6 | | ---- | ---- | 8096 | 34 | BO-17 |
| TF-6B | | ---- | ---- | 8096 | 34 | BO-17 |
| TH-2B | | ---- | ---- | | ---- | ---- |
| TH-6B | | ---- | ---- | | ---- | ---- |
| TH-7B | | ---- | ---- | | ---- | ---- |
| TH-8B | | ---- | ---- | | ---- | ---- |
| TH-813 | | ---- | ---- | | ---- | ---- |
| WB-8GW | 37255-9C | CAP | ---- | | ---- | ---- |
| WB-8GWC(-FL) | 37735-7C | C-2 | CP-PF151 | 38033 | ---- | ---- |
| SHANG GONG | | | | | | |
| GC30-4-5D | | 601NBL6 | BC-DB1-NBL6 | | 2 | BO-103(2) |
| GD8-7 | | CAP | UNAVAILABLE | | 26-2 | BO-1215MM(A) |
| GC30-1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GC30-2 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| GC30-3 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| GC15-1 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| GC15-2 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| GC15-3 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GC15-5-4D | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| GD8-1 | | 601NBL6 | BC-DB1-NBL6 | | 2 | BO-103(2) |
| G15 | | 702 | BC-107(2) | | 17-3 | BO-LBH761 |
| SHIANG WANG | | | | | | |
| WR-335 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| WR-810 | | ---- | ---- | | 19-3 | BO-112(3) |
| WR-820 | | ---- | ---- | | 19-3 | BO-112(3) |
| WR-991 | | C-2 | CP-PF151 | | ---- | ---- |
| WR-992 | | C-2 | CP-PF151 | | ---- | ---- |
| SICAMA | | | | | | |
| LT2-B842 | | ---- | ---- | | 19-3 | BO-112(3) |
| LT2-B845 | | CAP | UNAVAILABLE | | 19-3 | BO-112(3) |
| LT2-B872 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| LT2-B875 | | CAP | UNAVAILABLE | | 26-3 | BO-1215MM-N |
| SC-1162-5 | | CAP | UNAVAILABLE | | 19-8 | BO-112(A)J |
| SC-1162-6 | | CAP | UNAVAILABLE | | 19-8 | BO-112(A)J |
| SC-1182-5 | | CAP | UNAVAILABLE | | 26-2 | BO-1215MM(A) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|----------------------|-------------------|----------|----------------|---------|----------|--------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| SC-1182-6 | | CAP | UNAVAILABLE | | 26-2 | BO-1215MM(A) |
| SINGER | | | | | | |
| 7-9,27 | | ---- | ---- | 11910 | ---- | ---- |
| 7-31,33,41,56 | | ---- | ---- | 16901 | ---- | ---- |
| 7-34,48 | | ---- | ---- | 11910 | ---- | ---- |
| 7CL | | ---- | ---- | 16901 | ---- | ---- |
| 11K | | ---- | ---- | 202053 | ---- | ---- |
| 11-11 | | ---- | ---- | | ---- | ---- |
| 12K,W | 208383 | 509 | BC-12 | 206076 | ---- | ---- |
| 15-30 | 15277 | 101 | BC-HA1 | 2996 | ---- | ---- |
| 15K30,83 | 15277 | 101 | BC-HA1 | 2996 | ---- | ---- |
| 15K88,90,91 | 125291 | 105 | BC-15-88 | | ---- | ---- |
| | 33486 | | | | | |
| 16,-188 | 125115 | 506 | BC-69 | 2996 | ---- | ---- |
| 16U,-288 | 125115 | 506 | BC-69 | 2996 | ---- | ---- |
| 17 | | ---- | ---- | 2073 | 34 | BO-17 |
| 17-22,23,25,27 | 125115 | 506 | BC-69 | 2996 | ---- | ---- |
| 17-30,41,42 | | ---- | ---- | 2073 | 34 | BO-17 |
| 17-241,242 | | ---- | ---- | 2073 | 34 | BO-17 |
| 17U123 | 505086 | 101 | BC-HA1 | 2996 | ---- | ---- |
| 17U130 | | ---- | ---- | 2073 | 34 | BO-17 |
| 17U133 | 125115 | 506 | BC-69 | 2996 | ---- | ---- |
| 17U141,241,242 | | ---- | ---- | 2073 | 34 | BO-17 |
| 18 | | ---- | ---- | 2073 | 34 | BO-17 |
| 18U | | ---- | ---- | 2073 | 34 | BO-17 |
| 18U122,222,322 | | ---- | ---- | 2073 | 34 | BO-17 |
| 19-9,10,17 | 17324 | 107 | BC-19-9 | | ---- | ---- |
| 20U | 541678NBL6 | 615NBL6 | BC-DBZ(3)-NBL6 | 55623 | 2 | BO-103(2) |
| 20U11,13,23 | 541678 | 615 | BC-DBZ(3) | 55623 | 2 | BO-103(2) |
| 20U31,33,34,35 | 410025 | 615 | BC-DBZ(3) | 55623 | 2 | BO-103(2) |
| 20U42,43 | 541678 | 615 | BC-DBZ(3) | 55623 | 2 | BO-103(2) |
| 20UX-142,143 | 410025 | 615 | BC-DBZ(3) | 55623 | 2 | BO-103(2) |
| | | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| | | 615NBL9 | BC-DBZ(3)-NBL9 | | | |
| 21W | 236853 | CAP | UNAVAILABLE | 203470 | 19-3 | BO-112(3) |
| 21W4,5,6,100,101,102 | 203209 | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| 21W-(30:35) | 203209 | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| 21W162 | 233765 | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| | 203209 | ---- | ---- | | | |
| 21W180,182 | | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| 22W-all class | 203209 | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| 27,28 | 8327 | 401 | LS-27 | | ---- | ---- |
| | 83505 | 403 | LS-COMBI | | | |
| 29-1 | | ---- | ---- | 8604 | ---- | ---- |
| 29-30 | 81952 | S-2 | S-29L | 82552 | 39 | BO-29L |
| 29K71,73,171 | 8603 | S-1A | S-29A | 8604 | ---- | ---- |
| | 81964 | S-1B | S-29B | | | |
| | 82177 | CA-1 | CA-29 | | ---- | ---- |
| 29K72 | 81952 | S-2 | S-29L | 82552 | 39 | BO-29L |
| | 82205 | CA-2 | CA-29L | | ---- | ---- |
| 29U171 | HA46082 | S-2 | S-29L | HA46083 | 39 | BO-29L |
| | 82205 | CA-2 | CA-29L | | ---- | ---- |
| 29U171A,173A | 8654 | S-1A | S-29A | 8604 | ---- | ---- |
| | 81964 | S-1B | S-29B | | | |
| | 82177 | CA-1 | CA-29 | | ---- | ---- |
| 29U172,A | 81952 | S-2 | S-29L | 82552 | 39 | BO-29L |
| | 82205 | CA-2 | CA-29L | | ---- | ---- |
| 31-15,18 | 62740 | 504 | BC-31-15 | 2996 | ---- | ---- |
| 31-19,20 | 20756 | 508 | BC-31-20 | 19131 | ---- | ---- |
| 32 | 33942 | 505 | BC-68 | 2996 | ---- | ---- |
| 44 | 20756 | 508 | BC-31-20 | 19131 | ---- | ---- |
| 44-10,12 | 62740 | 504 | BC-31-15 | 2996 | ---- | ---- |
| 44-13 | 20756 | 508 | BC-31-20 | 19131 | ---- | ---- |
| 45K | | ---- | ---- | 95093 | 38 | BO-45 |
| 46W | 233765 | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| 46W61,62 | | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| 47W,62,63 | 233765 | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| 47W70 | 233765 | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| 51W | 241676 | C-1F | CP-51F | 233939 | ---- | ---- |
| 51W51,52 | 237168 | ---- | ---- | 233939 | 19-3 | BO-112(3) |
| 51W53:59 | 241676 | C-1F | CP-51F | 233939 | ---- | ---- |
| 52K | 241676 | C-1F | CP-51F | 233939 | ---- | ---- |
| 52W21,22 | 241676 | C-1F | CP-51F | 233939 | ---- | ---- |
| 52W30,31 | 233765 | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| 55-20 | | ---- | ---- | | ---- | ---- |
| 61W | 202533 | ---- | ---- | 202265 | ---- | ---- |
| 66 | 32590 | S-101 | SBC-66 | 32522 | 32 | BO-66 |
| | | | | 172222 | | |
| 68 | 5784 | ---- | ---- | 5810 | 32 | BO-66 |
| 68-1 to 38 | | ---- | ---- | 2073 | 34 | BO-17 |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-----------------|-------------------|----------|----------------|---------|----------|-----------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 68-39 | 33942 | 505 | BC-68 | 2996 | ----- | ----- |
| | 33942H | 505-2 | BC-68-2 | | | |
| 69 | 125115 | 506 | BC-69 | 2996 | ----- | ----- |
| 69-16 | | ----- | ----- | 2073 | 34 | BO-17 |
| 71-5,6 | 39624 | 501 | BC-71(1) | 23500 | ----- | ----- |
| | 23502NBL | 501NBL | BC-71(1)-NBL | 23500A | ----- | ----- |
| 71-12,13 | 249598 | 501 | BC-71(1) | 23500 | ----- | ----- |
| | 23502NBL | 501NBL | BC-71(1)-NBL | 23500A | ----- | ----- |
| 71-30,31,32 | 39624 | 502 | BC-71(2) | 23500 | ----- | ----- |
| | 249599NBL | 502NBL | BC-71(2)-NBL | 23500A | ----- | ----- |
| 71-47,52 | 249598 | 501 | BC-71(1) | 23500 | ----- | ----- |
| | 23502NBL | 501NBL | BC-71(1)-NBL | 23500A | ----- | ----- |
| 71-48,112 | | ----- | ----- | | ----- | ----- |
| 71-101,107,141 | 249921 | 502-2 | BC-71-101 | 23500 | ----- | ----- |
| 72W | 203209 | ----- | ----- | 213710 | ----- | ----- |
| 72W12 | 236853 | CAP | UNAVAILABLE | 203470 | 19-3 | BO-112(3) |
| 78(CL) | 224841 | 507 | BC-78 | 2996 | ----- | ----- |
| 95 | 52237 | 601 | BC-DB1 | 40264 | 8 | BO-95(2) |
| | 52237NBL1 | 601NBL1 | BC-DB1-NBL1 | | | |
| | 52237M | 601M | BC-DB1-M | | | |
| | 52237M2 | 601M2 | BC-DB1-M2 | | | |
| | 52237WH | 601-2 | BC-DB1-WH | | | |
| | | ----- | ----- | | 9 | BO-95NS |
| 95-1-10 | 149063 | 604 | BC-251 | 272152 | 10 | BO-95(A) |
| 95-10 | 52237 | 601 | BC-DB1 | 40264 | 8 | BO-95(2) |
| | 52237NBL1 | 601NBL1 | BC-DB1-NBL1 | 40264 | 8 | BO-95(2) |
| 95-40 TO 100 | 52237 | 601 | BC-DB1 | 40264 | 8 | BO-95(2) |
| | 52237NBL1 | 601NBL1 | BC-DB1-NBL1 | 40264 | 8 | BO-95(2) |
| 96,-10 | 149063 | 604 | BC-251 | 40264 | 8 | BO-95(2) |
| | 52237NBL1 | 601NBL1 | BC-DB1-NBL1 | | | |
| | 52237M | 601M | BC-DB1-M | | | |
| | 52237M2 | 601M2 | BC-DB1-M2 | | | |
| | 52237WH | 601-2 | BC-DB1-WH | | | |
| | | ----- | ----- | | 9 | BO-95NS |
| 96-40,60 TO 100 | 52237 | 601 | BC-DB1 | 40264 | 8 | BO-95(2) |
| | 52237NBL1 | 601NBL1 | BC-DB1-NBL1 | 40264 | 8 | BO-95(2) |
| 97-2 | | ----- | ----- | | ----- | ----- |
| 97CL | | ----- | ----- | | ----- | ----- |
| 99 | 32590 | S-101 | SBC-66 | 32522 | 32 | BO-66 |
| | | | | 172222 | | |
| 101 & 102 | 32590 | S-101 | SBC-66 | 32522 | 32 | BO-66 |
| | | | | 172222 | | |
| 103,D-10,K | 52237 | 601 | BC-DB1 | 55623 | 2 | BO-103(2) |
| | 52237NBL1 | 601NBL1 | BC-DB1-NBL1 | | 3 | BO-103(3) |
| 107G | 241404 | 702 | BC-107(2) | 210530 | 15 | BO-107(1) |
| | 224441NBL | 702NBL | BC-107(2)-NBL | 263099 | | |
| | 224441M | 702M | BC-107(2)-M | | | |
| 107W1,5,13 | 210915 | 701 | BC-107(1) | 210530 | 15 | BO-107(1) |
| | 210915NBL | 701NBL | BC-107(1)-NBL | 263099 | | |
| 107W3,14,15,50 | 224441 | 702 | BC-107(2) | 210530 | 15 | BO-107(1) |
| | 224441NBL | 702NBL | BC-107(2)-NBL | 263099 | | |
| | 224441M | 702M | BC-107(2)-M | | | |
| 107W17,18,19,52 | 210915 | 701 | BC-107(1) | 210530 | 15 | BO-107(1) |
| | 210915NBL | 701NBL | BC-107(1)-NBL | 263099 | | |
| 107W100:103 | 224418 | 704 | BC-102 | 210530 | 15 | BO-107(1) |
| | 224418NBL | 704NBL | BC-102-NBL | 263099 | | |
| 108 | | ----- | ----- | 202265 | ----- | ----- |
| 108K,20 | 202533 | ----- | ----- | 202265 | ----- | ----- |
| 108U(20,30) | 202533 | ----- | ----- | 202265 | ----- | ----- |
| 108W(1,20,21) | 202533 | ----- | ----- | 202265 | ----- | ----- |
| 110K,W | 233765 | ----- | ----- | 203470 | 19-3 | BO-112(3) |
| 110W-2 | 241676 | C-1F | CP-51F | 233939 | ----- | ----- |
| 110W124,128 | | ----- | ----- | 203470 | 19-3 | BO-112(3) |
| 111G | | ----- | ----- | 203470 | 19-3 | BO-112(3) |
| 111W,100:113 | 233765 | ----- | ----- | 203470 | 19-3 | BO-112(3) |
| 111W150,151 | 233765 | ----- | ----- | 203470 | 19-3 | BO-112(3) |
| 111W153:156 | 233765 | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 112G127,139 | | ----- | ----- | 203470 | 19-3 | BO-112(3) |
| 112W110:139 | 248460 | ----- | ----- | 203470 | 19-3 | BO-112(3) |
| 112W115:139 | 237168 | ----- | ----- | 203470 | 19-3 | BO-112(3) |
| 112W140,145,146 | 237168 | ----- | ----- | 233939 | 19-3 | BO-112(3) |
| 112W140,145,146 | 248460 | ----- | ----- | 203470 | 19-3 | BO-112(3) |
| 118W,1,4 | 241676 | C-1F | CP-51F | 233939 | ----- | ----- |
| 119W,1 | 241676 | C-1F | CP-51F | 233939 | ----- | ----- |
| 121C200A,300A | 149063 | 604 | BC-251 | 272152 | 10 | BO-95(A) |
| | 149063NBL | 604NBL | BC-251-NBL | | | |
| | 115388M | 604M | BC-251-M | 270010 | 13-4 | BO-400(4) |
| 121C | 513169 | ----- | ----- | 272152 | 10 | BO-95(A) |
| 121C200B,300B | 522533 | 611-1 | BC-770-NBL1 | 272152 | 10 | BO-95(A) |
| 121C300 | 522456 | 807NBL2 | BC-DBM(3)-NBL2 | 239729 | 22 | BO-DBM(A) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------------|-------------------|----------|----------------|---------|----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 121C330AA | 530198 | 801 | BC-DBM(1) | 239729 | 22 | BO-DBM(A) |
| | 530198NBL | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| 121D | 513169 | ---- | ---- | 272152 | 10 | BO-95(A) |
| 121D200A,300A | 149063 | 604 | BC-251 | 272152 | 10 | BO-95(A) |
| | 149063NBL | 604NBL | BC-251-NBL | | | |
| | 115388M | 604M | BC-251-M | 270010 | 13-4 | BO-400(4) |
| 121D200B,300B | 522533 | 611-1 | BC-770-NBL1 | 272152 | 10 | BO-95(A) |
| 121D300 | 522456 | 807NBL2 | BC-DBM(3)-NBL2 | 239729 | 22 | BO-DBM(A) |
| 121D330AA | 530198 | 801 | BC-DBM(1) | 239729 | 22 | BO-DBM(A) |
| | 530198NBL | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| 127,W1:W3 | 54505 | 402 | LS-28 | | ---- | ---- |
| | 83505 | 403 | LS-COMBI | | | |
| 128 | 54505 | 402 | LS-28 | | ---- | ---- |
| | 83505 | 403 | LS-COMBI | | | |
| 131W,103:113 | 233765 | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| 132B | 103109 | ---- | ---- | CS1441 | 35 | BO-132 |
| 132K,R | 103109 | ---- | ---- | 97949 | 35 | BO-132 |
| 133K,12:15 | 103109 | ---- | ---- | 97949 | 35 | BO-132 |
| 133K17,18 | 103121 | ---- | ---- | 97949 | 35 | BO-132 |
| 133W(103) | 224418 | 704 | BC-102 | | 15-3 | BO-107(3) |
| 134W | | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| 136W | 241676 | C-1F | CP-51F | 233939 | ---- | ---- |
| 138G101,102 | 237168 | ---- | ---- | 233939 | 19-3 | BO-112(3) |
| 138G103 | 264204 | CAP | UNAVAILABLE | 233939 | 19-3 | BO-112(3) |
| 138W(101) | 237168 | ---- | ---- | 233939 | 19-3 | BO-112(3) |
| 138W102 | 241676 | C-1F | CP-51F | 233939 | ---- | ---- |
| 138W103 | 264204 | CAP | UNAVAILABLE | 233939 | 19-3 | BO-112(3) |
| 140W1,2,3,12 | 224418 | 704 | BC-102 | 210530 | 15 | BO-107(1) |
| | 224418NBL | 704NBL | BC-102-NBL | 263099 | | |
| 143W1:W3,W18 | 241404 | 702 | BC-107(2) | 210530 | 15 | BO-107(1) |
| | 224441NBL | 702NBL | BC-107(2)-NBL | 263099 | | |
| 144W | 265090 | ---- | ---- | 264645 | 25 | BO-144 |
| 145W | 265090 | ---- | ---- | 264645 | 25 | BO-144 |
| 150W3,103 | 224441 | 702 | BC-107(2) | 210530 | 15 | BO-107(1) |
| 151K,W | 241404 | 702 | BC-107(2) | 233028 | 17-1 | BO-271(A) |
| | 224441NBL | 702NBL | BC-107(2)-NBL | 502526 | | |
| | 224441M | 702M | BC-107(2)-M | 263099 | 15 | BO-107(1) |
| 153K,W | 233765 | ---- | ---- | 203470 | 19-3 | BO-112(3) |
| 167G,W | 241676 | C-1F | CP-51F | 233939 | ---- | ---- |
| 168G,W | 237168 | ---- | ---- | 233939 | 19-3 | BO-112(3) |
| 180W201,202 | 264256 | ---- | ---- | 233939 | 19-3 | BO-112(3) |
| 188K,U | 149063 | 604 | BC-251 | 55623 | 2 | BO-103(2) |
| | 143390 | 608 | BC-281(SS) | | | |
| | 544745 | 601 | BC-DB1 | | | |
| 188U31,33,35 | 52237 | 601 | BC-DB1 | 55623 | 2 | BO-103(2) |
| 191D | 149063 | 604 | BC-251 | 55623 | 2 | BO-103(2) |
| | 143390 | 608 | BC-281(SS) | | | |
| | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 191D200(A,AA,BA) | 544745 | 601 | BC-DB1 | 55623 | 2 | BO-103(2) |
| | 540735 | 601NBL1 | BC-DB1-NBL1 | | | |
| 191D240AA | 544745 | 601 | BC-DB1 | 55623 | 2 | BO-103(2) |
| | 540735 | 601NBL1 | BC-DB1-NBL1 | | | |
| 191D300(A,AA,BA) | 544745 | 601 | BC-DB1 | 55623 | 2 | BO-103(2) |
| | 540735 | 601NBL1 | BC-DB1-NBL1 | | | |
| 191DX250A | 544745 | 601 | BC-DB1 | 55623 | 2 | BO-103(2) |
| | 540735 | 601NBL1 | BC-DB1-NBL1 | | | |
| 191DX258A | 544745 | 601 | BC-DB1 | 55623 | 2 | BO-103(2) |
| | 540735 | 601NBL1 | BC-DB1-NBL1 | | | |
| 191DX558A | | BC | UNAVAILABLE | 55623 | 2 | BO-103(2) |
| 191U | 544745 | 601 | BC-DB1 | 55623 | 2 | BO-103(2) |
| | 540735 | 601NBL1 | BC-DB1-NBL1 | | | |
| 195K:196K | 149063 | 604 | BC-251 | 272152 | 10 | BO-95(A) |
| | 52237NBL1 | 601NBL1 | BC-DB1-NBL1 | | | |
| | 149063 | 604 | BC-251 | | | |
| | 115388NBL | 604NBL | BC-251-NBL | | | |
| 201K | | ---- | ---- | | ---- | ---- |
| HOUSEHOLD | 105032 | 301 | BC-HR206 | 55623 | 2 | BO-103(2) |
| 211A | | ---- | ---- | | 31-2 | BO-1215L(A) |
| 211A157JA | | ---- | ---- | 233939 | 19-3 | BO-112(3) |
| 211A165JA | | ---- | ---- | 233939 | 19-3 | BO-112(3) |
| 211A166JA | | ---- | ---- | 233939 | 19-3 | BO-112(3) |
| 211A166KA | | ---- | ---- | 233939 | 19-3 | BO-112(3) |
| 211G140,141 | | ---- | ---- | 244750 | 19-2 | BO-112(A) |
| 211G145,146,151 | | ---- | ---- | 244750 | 19-2 | BO-112(A) |
| 211G155:157 | 233765 | ---- | ---- | 244750 | 19-2 | BO-112(A) |
| 211G157A | | ---- | ---- | 244750 | 19-2 | BO-112(A) |
| 211G158,165,166 | | ---- | ---- | 244750 | 19-2 | BO-112(A) |
| 211G265,266 | | ---- | ---- | 244750 | 19-2 | BO-112(A) |
| 211G351,357,358 | 514241 | C-4 | CP-212BIG | 514201 | ---- | ---- |
| 211G440 | | ---- | ---- | 244750 | 19-2 | BO-112(A) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------------|-------------------|----------|-------------|---------|----------|----------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 211G441,451 | 512551 | C-3 | CP-212 | 233939 | ----- | ----- |
| 211G456 | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 211G457 | 512551 | C-3 | CP-212 | 233939 | ----- | ----- |
| 211G465,466 | 514241 | C-4 | CP-212BIG | 514201 | ----- | ----- |
| 211G539,541 | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 211G557,558 | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 211G566,A | | ----- | ----- | 510007 | 26-3 | BO-1215MM-N |
| 211G641 | 514241 | C-4 | CP-212BIG | 514201 | ----- | ----- |
| 211G665,666 | 512551 | C-3 | CP-212 | 233939 | ----- | ----- |
| 211G765,766,776 | 514241 | C-4 | CP-212BIG | 514201 | ----- | ----- |
| 211G866A,867A | | ----- | ----- | 510007 | 26-3 | BO-1215MM-N |
| 211GX101,103,112 | 512551 | C-3 | CP-212 | 233939 | ----- | ----- |
| 211GX102,108 | 514241 | C-4 | CP-212BIG | 514201 | ----- | ----- |
| 211GX104,106,109 | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 211GX110,115 | | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 211GX114,117 | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 211U157(A) | | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 211U165(A)166(A) | 233765 | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 211U257,341 | | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 211U365,366 | | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 211U539A | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 211U566,A | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 211U566JA | | ----- | ----- | 417268 | 26-2 | BO-1215MM(A) |
| 211U566KA | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 211U567 | | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 211U567A,B | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 211U567JB | | ----- | ----- | 417268 | 26-2 | BO-1215MM(A) |
| 211U866,867 | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 211UX157,165,166 | | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 211UX566 | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 211UX567,B | 412317 | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 211W151,155 | 233765 | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 212A141BA,GA | | ----- | ----- | 233939 | 19-3 | BO-112(3) |
| 212A939(JA,JB) | | ----- | ----- | | ----- | ----- |
| 212G | | ----- | ----- | 514201 | ----- | ----- |
| 212G8 | 514241 | C-4 | CP-212BIG | 514201 | ----- | ----- |
| 212G140,141,145 | | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 212G146 | | ----- | ----- | | 19-8 | BO-112(A)J |
| 212G340,341 | 514241 | C-4 | CP-212BIG | 514201 | ----- | ----- |
| 212G440,441 | 512551 | C-3 | CP-212 | 233939 | ----- | ----- |
| 212G539,541 | 510009 | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 212G641 | 514241 | C-4 | CP-212BIG | 514201 | ----- | ----- |
| 212GX2 | 510009 | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 212GX4:X6 | | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 212GX8,102,104 | 514241 | C-4 | CP-212BIG | 514201 | ----- | ----- |
| 212GX45,101,103 | 512551 | C-3 | CP-212 | 233939 | ----- | ----- |
| 212GX106,114 | 510009 | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 212GX107 | 512551 | C-3 | CP-212 | 233939 | ----- | ----- |
| 212GX108,110 | 514241 | C-4 | CP-212BIG | 514201 | ----- | ----- |
| 212LX670 | | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 212U41 | | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 212U141,A | 412317 | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 212U143 | 412317 | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 212U143,A,GA | 412440 | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 212U144,A | 412440 | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 212U440 | | ----- | ----- | | ----- | ----- |
| 212U441 | 512551 | C-3 | CP-212 | 233939 | ----- | ----- |
| 212U442 | 412317 | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 212U443,A | 412317 | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 212U444 | 412440 | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 212U539A | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 212U541,A | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 212U543,A,AG | 416523 | CAP | UNAVAILABLE | 510007 | 26-4 | BO-1215MM-N-SN |
| 212U544 | 416523 | CAP | UNAVAILABLE | 510007 | 26-4 | BO-1215MM-N-SN |
| 212U566 | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 212U839,841,843 | 412317 | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 212U839A | | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 212U841A | | ----- | ----- | 510007 | 26-4 | BO-1215MM-N-SN |
| 212U843A | 416523 | CAP | UNAVAILABLE | 510007 | 26-4 | BO-1215MM-N-SN |
| 212W140,141 | | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 212W145,146 | | ----- | ----- | 244750 | 19-2 | BO-112(A) |
| 220U | 544745 | 601 | BC-DB1 | 55623 | 2 | BO-103(2) |
| 220U2,U3 | 541678 | 615 | BC-DBZ(3) | 55623 | 2 | BO-103(2) |
| 220U12,13,22,23 | 52237 | 601 | BC-DB1 | 40264 | 8 | BO-95(2) |
| 221 | 45751 | 303 | BC-HR221 | 45785 | ----- | ----- |
| | 45926 | B-1 | B-221 | | ----- | ----- |
| | 45829 | H-1 | H-221 | | ----- | ----- |
| 236G,U,W | 241676 | C-1F | CP-51F | 233939 | ----- | ----- |
| 238G | 241676 | C-1F | CP-51F | 233939 | ----- | ----- |
| 241,245(CL),251 | 544745 | 601 | BC-DB1 | 40264 | 8 | BO-95(2) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|---------------------|-------------------|----------|----------------|-------------|----------|-----------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| | 52237NBL1 | 601NBL1 | BC-DB1-NBL1 | | | |
| | 52237M | 601M | BC-DB1-M | | | |
| | 52237M2 | 601M2 | BC-DB1-M2 | | | |
| | 52237WH | 601-2 | BC-DB1-WH | | | |
| | 149063 | 604 | BC-251 | 272152 | 10 | BO-95(A) |
| | 115388NBL | 604NBL | BC-251-NBL | | | |
| | 147149 | 612 | BC-241 | 270010 | 13-4 | BO-400(4) |
| | 147149NBL | 612NBL | BC-241-NBL | | | |
| | 147149M | 612M | BC-241-M | | | |
| 269W | 43725 | 503 | BC-269 | 23500A | ----- | ----- |
| 271K1,2,3 | 271785 | 706 | BC-271 | 502526 | 17 | BO-107(A) |
| | 107118NBL | 706NBL | BC-271-NBL | 233028 | 17-1 | BO-271(A) |
| 271K4,14 | 107119 | 706-2 | BC-271-2 | 502526 | 17 | BO-107(A) |
| | 271864 | 706-2 | BC-271-2 | 233028 | 17-1 | BO-271(A) |
| 271K11,12,13 | 271785 | 706 | BC-271 | 233028 | 17-1 | BO-271(A) |
| | 107118NBL | 706NBL | BC-271-NBL | | | |
| 271K24,201,211 | 271785 | 706 | BC-271 | 233028 | 17-1 | BO-271(A) |
| | 107118NBL | 706NBL | BC-271-NBL | | | |
| 281,-1,3,5 | 149063 | 604 | BC-251 | 272152 | 10 | BO-95(A) |
| | 115388NBL | 604NBL | BC-251-NBL | | | |
| | 115388M | 604M | BC-251-M | 270010 | 13-4 | BO-400(4) |
| 281-20:24,30 | 149063 | 604 | BC-251 | 272152 | 10 | BO-95(A) |
| | 115388NBL | 604NBL | BC-251-NBL | | | |
| | 115388M | 604M | BC-251-M | 270010 | 13-4 | BO-400(4) |
| 281-41,43,61 | 143390 | 608 | BC-281(SS) | 272152 | 10 | BO-95(A) |
| 281-81,83 | 149063 | 604 | BC-251 | 272152 | 10 | BO-95(A) |
| | 115388NBL | 604NBL | BC-251-NBL | | | |
| | 115388M | 604M | BC-251-M | 270010 | 13-4 | BO-400(4) |
| 281-141,143 | 143390 | 608 | BC-281(SS) | 272152 | 10 | BO-95(A) |
| 281-161,162,164 | 143390 | 608 | BC-281(SS) | 272152 | 10 | BO-95(A) |
| 281-181,183 | 143390 | 608 | BC-281(SS) | 272152 | 10 | BO-95(A) |
| 281UTT | 544745 | 601 | BC-DB1 | 55623 | 2 | BO-103(2) |
| 291D | 149063 | 604 | BC-251 | 270010 | 13-4 | BO-400(4) |
| 291U | 544745 | 601 | BC-DB1 | 55623 | 2 | BO-103(2) |
| | 505358 | | | | | |
| | 540735 | 601NBL1 | BC-DB1-NBL1 | | | |
| 301 | 45751 | 303 | BC-HR221 | 45785 | ----- | ----- |
| | 170166 | B-2 | B-301 | | ----- | ----- |
| | 170167 | H-2 | H-301 | | ----- | ----- |
| 306 | 173058 | 302 | BC-HR306 | 55623 | 2 | BO-103(2) |
| 306M | 541678 | 615 | BC-DBZ(3) | 55623 | 2 | BO-103(2) |
| | 173058 | 302 | BC-HR306 | | | |
| 307G(2) | 224441 | 702 | BC-107(2) | 263099 | 15 | BO-107(1) |
| 307G2 | 224441NBL | 702NBL | BC-107(2)-NBL | 263099 | 15 | BO-107(1) |
| | 224441M | 702M | BC-107(2)-M | | | |
| 312T141 | | ----- | ----- | CH455964H01 | 19-3 | BO-112(3) |
| 312U,U171 | | ----- | ----- | CH455964H01 | 19-3 | BO-112(3) |
| 319 | 173058 | 302 | BC-HR306 | 55623 | 2 | BO-103(2) |
| 320 | 541678 | 615 | BC-DBZ(3) | 55623 | 2 | BO-103(2) |
| | 173058 | 302 | BC-HR306 | | | |
| 331K | 62740 | 504 | BC-31-15 | 2996 | ----- | ----- |
| 366K177,145,146,225 | 149063 | 604 | BC-251 | 270010 | 13-4 | BO-400(4) |
| | 143390 | 608 | BC-281(SS) | 272152 | 10 | BO-95(A) |
| | 115388NBL | 604NBL | BC-251-NBL | 270010 | 13-4 | BO-400(4) |
| | 115388M | 604M | BC-251-M | | | |
| 369,W | 239728 | 807NBL2 | BC-DBM(3)-NBL2 | 239729 | 22 | BO-DBM(A) |
| 371U | 210915NBL | 701NBL | BC-107(1)-NBL | 263099 | 15 | BO-107(1) |
| 391D | 149063 | 604 | BC-251 | 270010 | 13-4 | BO-400(4) |
| 391U | 544745 | 601 | BC-DB1 | 40264 | 8 | BO-95(2) |
| 400W | 149063 | 604 | BC-251 | 272152 | 10 | BO-95(A) |
| | 115388NBL | 604NBL | BC-251-NBL | | | |
| | 115388M | 604M | BC-251-M | 270010 | 13-4 | BO-400(4) |
| | 52237 | 601 | BC-DB1 | 55623 | 2 | BO-103(2) |
| 401 | 153758 | S-102 | SBC-400 | | ----- | ----- |
| 402W | 275091 | 605 | BC-402 | 272152 | 10 | BO-95(A) |
| | 275091NBL | 605NBL | BC-402-NBL | 270010 | 13-4 | BO-400(4) |
| | 52237 | 601 | BC-DB1 | 55623 | 2 | BO-103(2) |
| 404,413,416,418 | 153758 | S-102 | SBC-400 | | ----- | ----- |
| 431D,F,T,U | 410564 | 504-2 | BC-431 | 2996 | ----- | ----- |
| | 62740 | 504 | BC-31-15 | 2996A | ----- | ----- |
| 451K | 149063 | 604 | BC-251 | 272152 | 10 | BO-95(A) |
| | 115388NBL | 604NBL | BC-251-NBL | | | |
| 457A,G,GX | 502530 | 705 | BC-457 | 502526 | 17 | BO-107(A) |
| | 502530NBL | 705NBL | BC-457-NBL | 233028 | 17-1 | BO-271(A) |
| | 502530M | 705M | BC-457-M | 263099 | 15 | BO-107(1) |
| 457U,105,125 | 502530 | 705 | BC-457 | 502526 | 17 | BO-107(A) |
| | 502530NBL | 705NBL | BC-457-NBL | 233028 | 17-1 | BO-271(A) |
| | 502530M | 705M | BC-457-M | 263099 | 15 | BO-107(1) |
| 457U,134,135,140 | 502530 | 705 | BC-457 | 502526 | 17 | BO-107(A) |
| | 502530NBL | 705NBL | BC-457-NBL | 233028 | 17-1 | BO-271(A) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|----------------------|-------------------|----------|----------------|---------|----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| | 502530M | 705M | BC-457-M | 263099 | 15 | BO-107(1) |
| 457U405,425,435 | 502530 | 705 | BC-457 | 233028 | 17-1 | BO-271(A) |
| 457UX | 502530 | 705 | BC-457 | 233028 | 17-1 | BO-271(A) |
| 469U ALL CLASS | 418047 | 511-2 | BC-LK(J2) | 418046 | 27-3 | BO-LKJ(A) |
| 471U | | ---- | ---- | | 17-4-1 | BO-LBH771-H |
| 491D,100GA:308GA | 544745 | 601 | BC-DB1 | 272152 | 10 | BO-95(A) |
| | 505358 | | | | | |
| | 540735 | 601NBL1 | BC-DB1-NBL1 | | | |
| | 149063 | 604 | BC-251 | 270010 | 13-4 | BO-400(4) |
| 491DX201GA | 544745 | 601 | BC-DB1 | 272152 | 10 | BO-95(A) |
| 491U | 544745 | 601 | BC-DB1 | 272152 | 10 | BO-95(A) |
| | 505358 | | | | | |
| | 540735 | 601NBL1 | BC-DB1-NBL1 | | | |
| 491UX100B,G,H | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 491UX110B,G,H | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 491UX200B,G,H | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 491UX201GA | 544745 | 601 | BC-DB1 | 272152 | 10 | BO-95(A) |
| 491UX210B,G,H | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 491UX300B,G,H | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 491UX310B,G,H | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 550U13 | 52237 | 601 | BC-DB1 | 40264 | 8 | BO-95(2) |
| 569U | 418047 | 511-2 | BC-LK(J2) | 418046 | 27-3 | BO-LKJ(A) |
| | 281777 | ---- | ---- | | ---- | ---- |
| 569U1141 | | ---- | ---- | | ---- | ---- |
| 591C200A,AA,BD | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591C210BD,BF,GD,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591C240AD,AF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591C300A,AA,AD,AF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591C300BD,BF,GD,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591C305A,AA | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591C308A,AA,AD,AF | 414021 | 606NBL | BC-DLN-NBL | 55623 | 2 | BO-103(2) |
| 591C318BD,BF,GD,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D200A,AA,AD,AF,BD | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D203 | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D,205A,AA,AF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D210BD,BF,GD,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D210GAC | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D215BD,BF,GD,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D240AD,AF,BD,BF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D240GD,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D300A,AA,BD,BF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D300GD,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D301 | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D302AF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D303,A | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D305A,AA,AD,AF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D308A,AA,AD,AF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D310BD,BF,GD,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D310GA,GAC | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D315BD,BF,GD,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D318BD,BF,GD,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591D/C | 149063 | 604 | BC-251 | 270010 | 13-4 | BO-400(4) |
| | 143390 | 608 | BC-281(SS) | 55623 | 2 | BO-103(2) |
| 591DUX100 | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591DX ALL CLASS | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591DX100 | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591E ALL CLASS | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591U ALL CLASS | 544745 | 601 | BC-DB1 | 272152 | 10 | BO-95(A) |
| | 540735 | 601NBL1 | BC-DB1-NBL1 | | | |
| 591UTT | 540735 | 601NBL1 | BC-DB1-NBL1 | 376265 | 10 | BO-95(A) |
| 591UX100AF,BF,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591UX220,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591UX301 | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591UX302,AF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591UX312,BF,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591UX313,BF,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591UX320GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 591V ALL CLASS | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 600W | 149063 | 604 | BC-251 | 272152 | 10 | BO-95(A) |
| | 115388NBL | 604NBL | BC-251-NBL | | | |
| | 115388M | 604M | BC-251-M | 270010 | 13-4 | BO-400(4) |
| 601D100AA | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 601D100AD,AF,BD,BF | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 601D100GA,GD,GF | 540735 | 601NBL1 | BC-DB1-NBL1 | 40264 | 8 | BO-95(2) |
| 650E | 239728 | 807NBL2 | BC-DBM(3)-NBL2 | 239729 | 22 | BO-DBM(A) |
| 660 | 544745 | 601 | BC-DB1 | 40264 | 8 | BO-95(2) |
| 660A1,2,3 | 149063 | 604 | BC-251 | 270010 | 13-4 | BO-400(4) |
| | 115388NBL | 604NBL | BC-251-NBL | | | |
| | 115388M | 604M | BC-251-M | 270010 | 13-4 | BO-400(4) |
| 660W | 149063NBL | 604NBL | BC-251-NBL | 270010 | 13-4 | BO-400(4) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|---------------------------|-------------------|----------|-----------------|---------|----------|------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 675U | 502530 | 705 | BC-457 | 233028 | 17-1 | BO-271(A) |
| 691D(200,300) | 540735 | 601NBL1 | BC-DB1-NBL1 | 40264 | 8 | BO-95(2) |
| 770 | 522312 | 611 | BC-770 | 272152 | 10 | BO-95(A) |
| 770D1,3 | 149063 | 604 | BC-251 | 272152 | 10 | BO-95(A) |
| | 115388NBL | 604NBL | BC-251-NBL | | | |
| 770D41,43 | 522533 | 611-1 | BC-770-NBL1 | 272152 | 10 | BO-95(A) |
| 771D1,3 | 149063 | 604 | BC-251 | 272152 | 10 | BO-95(A) |
| | 115388NBL | 604NBL | BC-251-NBL | | | |
| 771D41,43 | 522533 | 611-1 | BC-770-NBL1 | 272152 | 10 | BO-95(A) |
| 771G | 522312 | 611 | BC-770 | 272152 | 10 | BO-95(A) |
| 1300 | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 1591 | 540735 | 601NBL1 | BC-DB1-NBL1 | 272152 | 10 | BO-95(A) |
| 1650E | 239728 | 807NBL2 | BC-DBM(3)-NBL2 | 239729 | 22 | BO-DBM(A) |
| 1669U101UBT | 281777 | ---- | ---- | | ---- | ---- |
| SIROKUMA | | | | | | |
| LM-600 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| SOTEXI | | | | | | |
| PIK-PIK L2000 | | 803NBL2 | BC-DBM(Z2)-NBL2 | | 22 | BO-DBM(A) |
| SPEEDBINDER CARPET | | | | | | |
| SPEEDBINDER CARPET | 241404 | 702 | BC-107(2) | 210530 | 15 | BO-107(1) |
| | 224441 | | | 263099 | | |
| STAGER | | | | | | |
| DZ-S31 ALL CLASS | 539 | 705 | BC-457 | | 15-3 | BO-107(3) |
| | | 705NBL | BC-457-NBL | | | |
| DZ-S310 ALL CLASS | 539 | 705 | BC-457 | | 15-3 | BO-107(3) |
| | | 705NBL | BC-457-NBL | | | |
| DZ-S722 | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| DZ-S821 ALL CLASS | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| DZ-S823 ALL CLASS | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| DZ-S825 | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| SE-12 ALL CLASS | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| SZ-21 | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| SZ-21-1B(N) | 714 | 802 | BC-DBM(Z1) | | 21-5 | BO-DBM(1)N |
| | | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| SZ-21-1B(NL) | 714 | 802 | BC-DBM(Z1) | | 21-5 | BO-DBM(1)N |
| | | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| SZ-21-1(N) | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| SZ-21-2(N) | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| SZ-21-3(N) | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| SZ-21-3B(NL) | 714 | 802 | BC-DBM(Z1) | | 21-5 | BO-DBM(1)N |
| | | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| SZ-21-4(N) | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| SZ-21-4B(NL) | 714 | 802 | BC-DBM(Z1) | | 21-5 | BO-DBM(1)N |
| | | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| SZ-21-5(N) | 714 | 802 | BC-DBM(Z1) | | 21-5 | BO-DBM(1)N |
| | | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| SZ-21-5(NL) | 714 | 802 | BC-DBM(Z1) | | 21-5 | BO-DBM(1)N |
| | | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| SZ-21-6(N) | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| SZ-21-7(N) | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| SZ-21-8(N) | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| SZ-25 ALL CLASS | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------------|-------------------|----------|----------------|------------|----------|----------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| SZ-72 ALL CLASS | 284 | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| | | 609NBL9 | BC-DBZ(1)-NBL9 | | | |
| SZ-310 ALL CLASS | 539 | 705 | BC-457 | | 15-3 | BO-107(3) |
| | | 705NBL | BC-457-NBL | | | |
| | | 609-1 | BC-DBZ(C) | | 5 | BO-103(Z) |
| Z/Z | | | | | | |
| SUNGOOD | | | | | | |
| GC40-1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GC0501 | | CAP | UNAVAILABLE | | 19-3 | BO-112(3) |
| GC34 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| GF11001 | | 702 | BC-107(2) | | 17-3 | BO-LBH761 |
| SUNNUN | | | | | | |
| EB-883 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| DB-620 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| DB-622 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| DB-625 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| DB-627 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| DY-637 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| YU-740 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| SUNSTAR | | | | | | |
| AD-331 | | ---- | ---- | | ---- | ---- |
| AD-3310 | | ---- | ---- | | ---- | ---- |
| D-146BL | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| DPK-2 | | 702 | BC-107(2) | | 15 | BO-107(1) |
| KLZ-371 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| KM-18 | | ---- | ---- | | 34 | BO-17 |
| KM-18K | | ---- | ---- | | ---- | ---- |
| KM-123A | | 601 | BC-DB1 | | 2 | BO-103(2) |
| KM-123B | | 601 | BC-DB1 | | 2 | BO-103(2) |
| KM-235A | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| KM-235B | | 606NBL | BC-DLN-NBL | | 10 | BO-95(A) |
| KM-340BL | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| KM-380 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| KM-380-B | | ---- | ---- | | ---- | ---- |
| KM-390 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| KM-560 | | CAP | UNAVAILABLE | | 26-3 | BO-1215MM-N |
| KM-560-7 | | CAP | UNAVAILABLE | | ---- | ---- |
| KM-590BL | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| KM-740 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| KM-750 | | ---- | ---- | | 19-3 | BO-112(3) |
| KM-750-BL | | ---- | ---- | | ---- | ---- |
| KM-750-7 | | ---- | ---- | | ---- | ---- |
| KM-750-7BL | | CAP | UNAVAILABLE | | 26-5 | BO-B872(A) |
| KM-790 | | CAP | UNAVAILABLE | | 19-3 | BO-112(3) |
| KM-790-BL | | CAP | UNAVAILABLE | | 26-5 | BO-B872(A) |
| KM-790-7 | | CAP | UNAVAILABLE | | 19-10 | BO-B842(A2)-H |
| KM-790-7BL | | CAP | UNAVAILABLE | | 26-2-1 | BO-1215MM(A)-H |
| KM-813-817 | | CAP | UNAVAILABLE | | 26-2-1 | BO-1215MM(A)-H |
| KM-823-827 | | ---- | ---- | | 19-3 | BO-112(3) |
| KM-857-867 | | ---- | ---- | | 19-3 | BO-112(3) |
| KM-867 | | ---- | ---- | | 19-3 | BO-112(3) |
| KM-867-7 | | CAP | UNAVAILABLE | | ---- | ---- |
| KM-5877 | | CAP | UNAVAILABLE | | ---- | ---- |
| KM-7507 | | ---- | ---- | | ---- | ---- |
| KM-7907 | | ---- | ---- | | ---- | ---- |
| KM-8677 | | CAP | UNAVAILABLE | | ---- | ---- |
| KM2-740 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| KM2-740B | | ---- | ---- | | 19-3 | BO-112(3) |
| KM2-740BL | | ---- | ---- | | 26-3 | BO-1215MM-N |
| KPW-827B | | ---- | ---- | | 19-3 | BO-112(3) |
| TAILOR | | | | | | |
| TG-360NR | | ---- | ---- | | ---- | ---- |
| TN-310S | | 705 | BC-457 | | 15-3 | BO-107(3) |
| TAJIMA | | | | | | |
| TM | ME0503000000 | 615 | BC-DBZ(3) | ME50040000 | 2 | BO-103(2) |
| | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| | | 615NBL9 | BC-DBZ(3)-NBL9 | | | |
| TMB | ME0503000000 | 615 | BC-DBZ(3) | ME50040000 | 2 | BO-103(2) |
| | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| | | 615NBL9 | BC-DBZ(3)-NBL9 | | | |
| TMBE | ME0503000000 | 615 | BC-DBZ(3) | ME50040000 | 2 | BO-103(2) |
| | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| | | 615NBL9 | BC-DBZ(3)-NBL9 | | | |
| TMBW | M1058B | 615 | BC-DBZ(3) | M1057B | 2 | BO-103(2) |
| | M1058NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| TME | ME0503000000 | 615 | BC-DBZ(3) | ME50040000 | 2 | BO-103(2) |
| | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| | | 615NBL9 | BC-DBZ(3)-NBL9 | | | |
| TME-D | ME0503000000 | 615 | BC-DBZ(3) | ME50040000 | 2 | BO-103(2) |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|---------------|-------------------|----------|-----------------|--------------|----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| | | 615NBL9 | BC-DBZ(3)-NBL9 | | | |
| TME-DC | ME0503000000 | 615 | BC-DBZ(3) | ME50040000 | 2 | BO-103(2) |
| | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| | | 615NBL9 | BC-DBZ(3)-NBL9 | | | |
| TME-H | ME0503000000 | 615 | BC-DBZ(3) | ME50040000 | 2 | BO-103(2) |
| | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| | | 615NBL9 | BC-DBZ(3)-NBL9 | | | |
| TME-HC | ME0503000000 | 615 | BC-DBZ(3) | ME50040000 | 2 | BO-103(2) |
| | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| | | 615NBL9 | BC-DBZ(3)-NBL9 | | | |
| TMEF | ME0503000000 | 615 | BC-DBZ(3) | ME50040000 | 2 | BO-103(2) |
| | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| | | 615NBL9 | BC-DBZ(3)-NBL9 | | | |
| TMEF-H | ME0503000000 | 615 | BC-DBZ(3) | ME50040000 | 2 | BO-103(2) |
| | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| | | 615NBL9 | BC-DBZ(3)-NBL9 | | | |
| TMEF-H615 | MEC503000DBM | 803NBL5 | BC-DBM(Z2)-NBL5 | M1057BA | 22 | BO-DBM(A) |
| TMEF-HC | MEC503000DBM | 803NBL5 | BC-DBM(Z2)-NBL5 | MEC504000DBM | 22 | BO-DBM(A) |
| TMEG | ME0503000000 | 615 | BC-DBZ(3) | ME50040000 | 2 | BO-103(2) |
| | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| | | 615NBL9 | BC-DBZ(3)-NBL9 | | | |
| TMEG-G910 | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | ME50040000 | 2 | BO-103(2) |
| TMEG-G914 | MEC503000DBM | 803NBL5 | BC-DBM(Z2)-NBL5 | MEC504000DBM | 22 | BO-DBM(A) |
| TMEG-M1212 | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | ME50040000 | 2 | BO-103(2) |
| TMEG-X | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | ME50040000 | 2 | BO-103(2) |
| TMEG-XC | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | ME50040000 | 2 | BO-103(2) |
| TMEG-XG920 | MEC503000DBM | 803NBL5 | BC-DBM(Z2)-NBL5 | MEC504000DBM | 22 | BO-DBM(A) |
| TMF | ME0503000000 | 615 | BC-DBZ(3) | ME50040000 | 2 | BO-103(2) |
| | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | | | |
| | | 615NBL9 | BC-DBZ(3)-NBL9 | | | |
| TMFD-C | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | ME50040000 | 2 | BO-103(2) |
| TMFX-C | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | ME50040000 | 2 | BO-103(2) |
| TMFX-C901 | MEC503000DBM | 803NBL5 | BC-DBM(Z2)-NBL5 | MEC504000DBM | 22 | BO-DBM(A) |
| TMFX-C902 | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | ME50040000 | 2 | BO-103(2) |
| TMLE | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | ME50040000 | 2 | BO-103(2) |
| TMLG | MEC503000DBM | 803NBL5 | BC-DBM(Z2)-NBL5 | MEC504000DBM | 22 | BO-DBM(A) |
| TMEX-C901 | ME0503000NBL | 615NBL6 | BC-DBZ(3)-NBL6 | ME50040000 | 2 | BO-103(2) |
| TMP-20 | TMP033000000 | CAP | UNAVAILABLE | | 19-3 | BO-112(3) |
| TSM-30 | MEC503000DBM | 803NBL5 | BC-DBM(Z2)-NBL5 | MEC504000DBM | 22 | BO-DBM(A) |
| LARGE TYPE | MEC503000DBM | 803NBL5 | BC-DBM(Z2)-NBL5 | MEC504000DBM | 22 | BO-DBM(A) |
| TAKING | | | | | | |
| TK-8BL | | 806NBL1 | BC-DBM(2)-NBL1 | | 22 | BO-DBM(A) |
| TK-88 | | 601NBL6 | BC-DB1-NBL6 | | 2 | BO-103(2) |
| TK-335 | | 903 | BC-PF9076 | | 24-2 | BO-PF130(A) |
| | | | | | 24 | BO-PF130 |
| TK-335N | | 903NBL | BC-PF9076-NBL | | 24-2 | BO-PF130(A) |
| TK-372 | | ---- | ---- | | ---- | ---- |
| TK-373 | | ---- | ---- | | ---- | ---- |
| TK-545 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| TK-546 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| TK-591 | | C-2 | CP-PF151 | | ---- | ---- |
| TK-592 | | C-2 | CP-PF151 | | ---- | ---- |
| TK-652 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| TK-810 | | ---- | ---- | | 19-3 | BO-112(3) |
| TK-820 | | ---- | ---- | | 19-3 | BO-112(3) |
| TK-842-5 | | ---- | ---- | | ---- | ---- |
| TK-842-32 | | ---- | ---- | | ---- | ---- |
| TK-872-3 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| TK-872-5 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| TK-875-3 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| TK-875-5 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| TK-845-3 | | CAP | UNAVAILABLE | | 19-3 | BO-112(3) |
| TK-845-5 | | CAP | UNAVAILABLE | | 19-3 | BO-112(3) |
| TK-888 | | 710 | BC-LBH771 | | 17-4 | BO-LBH771 |
| TK-991 | | C-2 | CP-PF151 | | ---- | ---- |
| TK-992 | | C-2 | CP-PF151 | | ---- | ---- |
| TK-1245 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| TK-1246 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| TK-1828 | | ---- | ---- | | ---- | ---- |
| TK-1828E/HE | | ---- | ---- | | ---- | ---- |
| TK-1828H | | ---- | ---- | | ---- | ---- |
| TK-1836 | | ---- | ---- | | ---- | ---- |
| TK-1836E/HE | | ---- | ---- | | ---- | ---- |
| TK-1836H | | ---- | ---- | | ---- | ---- |
| TK-1842 | | ---- | ---- | | ---- | ---- |
| TK-1842E/HE | | ---- | ---- | | ---- | ---- |
| TK-1842H | | ---- | ---- | | ---- | ---- |
| TOYOTA | | | | | | |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------|-------------------|----------|----------------|--------------|----------|--------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 146 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| 146A | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| 146B | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| 146G | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| 146M | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| 147 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| 147A | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AC-1007 | | | | 2130904-320 | 45-1 | BO-TSS124(A) |
| AC-1009 | | | | 2130904-320 | 45-1 | BO-TSS124(A) |
| AC-1011 | | | | 2130904-320 | 45-1 | BO-TSS124(A) |
| AC-1041 | | | | 2130904-320 | 45-1 | BO-TSS124(A) |
| AD140 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD140B | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD140M | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD146G | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD148 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD148B | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD148M | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD150 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD150G | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD156 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD156G | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD156M | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD157-500 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-501 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-502 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-503 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-603 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-604 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-610 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-620 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-622 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-623 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-625 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-626 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-660 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-662 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-663 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-665 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-666 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-710 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-713 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157-716 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157A-622 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157A-625 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157A-663 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157A-666 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157A-713 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157A-716 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157B-622 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157G-500 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157G-502 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157G-602 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157G-622 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157G-625 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157G-662 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD157G-665 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158-2 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158-3 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158-21 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158-22 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158-31 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158-32 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158A-2 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158A-31 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158A-32 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158B-2 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158B-21 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158B-22 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158G-2 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158G-21 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD158G-22 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD302 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD320 | | BC | UNAVAILABLE | 2130104-321 | 22 | BO-DBM(A) |
| AD320-22 | 2122304-301B | 806NBL1 | BC-DBM(2)-NBL1 | 2122804-320A | 45-4 | BO-TSS134(A) |
| AD320-662 | 2122304-301B | 806NBL1 | BC-DBM(2)-NBL1 | 2122804-320A | 45-4 | BO-TSS134(A) |
| AD324 | 2120304-301 | 801 | BC-DBM(1) | 2120314-321 | 21-5 | BO-DBM(1)N |
| | 2110804-301 | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| AD331 | | ---- | ---- | 2140104-321 | 19-6 | BO-112(6) |
| AD331L | | ---- | ---- | 2121404-321 | 31-3 | BO-1215L-N |

| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|---------------|-------------------|----------|----------------|--------------|-----------|--------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| AD331LP(-12) | | ---- | ---- | 2121404-321 | 31-3 | BO-1215L-N |
| AD332 | | ---- | ---- | 2140104-321 | 19-6 | BO-112(6) |
| AD332L | | ---- | ---- | 2121404-321 | 31-3 | BO-1215L-N |
| AD332LP(-1,2) | | ---- | ---- | 2121404-321 | 31-3 | BO-1215L-N |
| AD338 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD340 | 2121604-301B | 606NBL | BC-DLN-NBL | 2110104-321 | 2 | BO-103(2) |
| AD340-620 | 2121604-301B | 606NBL | BC-DLN-NBL | 2110104-321 | 2 | BO-103(2) |
| AD340-622 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD340-625 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD340-B | 2121604-301B | 606NBL | BC-DLN-NBL | 2110104-321 | 2 | BO-103(2) |
| AD340B-622 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD340B-625 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD341 | 2121604-301B | 606NBL | BC-DLN-NBL | 2110104-321 | 2 | BO-103(2) |
| AD345 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| AD345-620 | 2121604-301B | 606NBL | BC-DLN-NBL | 2110104-321 | 2 | BO-103(2) |
| AD345-622 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD345-625 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD352 | 2121604-301B | 606NBL | BC-DLN-NBL | 2110104-321 | 2 | BO-103(2) |
| AD352-700 | 2121604-301B | 606NBL | BC-DLN-NBL | 2110104-321 | 2 | BO-103(2) |
| AD352-702 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD352-705 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD417A | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2110114-321B | 10 | BO-95(A) |
| AD470 | | ---- | ---- | | ---- | ---- |
| AD500 | 1230003-560C | 307 | BC-HR4 | 2110104-321 | 2 | BO-103(2) |
| AD550 | 2130704-301A | 705 | BC-457 | 2130504-321 | 17 | BO-107(A) |
| | 2130714-301A | 705NBL | BC-457-NBL | | | |
| AD551 | 2130704-301A | 705 | BC-457 | 2130504-321 | 17 | BO-107(A) |
| | 2130714-301A | 705NBL | BC-457-NBL | | | |
| AD552 | 2130704-301A | 705 | BC-457 | 2130504-321 | 17 | BO-107(A) |
| AD553 | 2130704-301A | 705 | BC-457 | 2130504-321 | 17 | BO-107(A) |
| AD700 | 2121604-301B | 606NBL | BC-DLN-NBL | 2110104-321 | 2 | BO-103(2) |
| AD740 | | ---- | ---- | 2140104-321 | 19-6 | BO-112(6) |
| AD740B | | ---- | ---- | 2140104-321 | 19-6 | BO-112(6) |
| AD740X2 | | ---- | ---- | 2140104-321 | 19-6 | BO-112(6) |
| AD820 | 1230003-560C | 307 | BC-HR4 | 2110104-321 | 2 | BO-103(2) |
| AD1000 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2111604-320A | 45-2 | BO-TSS125(A) |
| AD1010 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2111604-320A | 45-2 | BO-TSS125(A) |
| AD1012G | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2111604-320A | 45-2 | BO-TSS125(A) |
| AD1020 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2111604-320A | 45-2 | BO-TSS125(A) |
| AD1112G | 2114004-301 | BC | UNAVAILABLE | 2114004-321 | ALUMINIUM | UNAVAILABLE |
| AD1200 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2111604-320A | 45-2 | BO-TSS125(A) |
| AD1202K | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2111604-320A | 45-2 | BO-TSS125(A) |
| AD1202V | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2111604-320A | 45-2 | BO-TSS125(A) |
| AD1203V | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2111604-320A | 45-2 | BO-TSS125(A) |
| AD1212G | 2114004-301 | BC | UNAVAILABLE | 2114004-321 | ALUMINIUM | UNAVAILABLE |
| AD1213G | 2114004-301 | BC | UNAVAILABLE | 2114004-321 | ALUMINIUM | UNAVAILABLE |
| AD2000 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2111604-320A | 45-2 | BO-TSS125(A) |
| AD3000 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2111604-320A | 45-2 | BO-TSS125(A) |
| AD3050 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2111604-320A | 45-2 | BO-TSS125(A) |
| AD3110 | | ---- | ---- | | ---- | ---- |
| AD3110P | | ---- | ---- | | ---- | ---- |
| AD3200 | 2122304-301B | 806NBL1 | BC-DBM(2)-NBL1 | 2122804-320A | 45-4 | BO-TSS134(A) |
| AD3300 | | ---- | ---- | 2122704-320A | 45-5 | BO-TSS196(A) |
| AD3310 | | ---- | ---- | | ---- | ---- |
| AD3310P | | ---- | ---- | | ---- | ---- |
| AD3320 | | ---- | ---- | | ---- | ---- |
| AD3320P | | ---- | ---- | | ---- | ---- |
| AD4000 | 2110604-301B | 601NBL2 | BC-DB1-NBL2 | 2111604-320A | 45-2 | BO-TSS125(A) |
| AL-410 | | ---- | ---- | | ---- | ---- |
| AL-432 | | ---- | ---- | | ---- | ---- |
| AT101XH71 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D134 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D134-41 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D134B | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D134H | 2120304-301 | 801 | BC-DBM(1) | 2120314-321 | 21-5 | BO-DBM(1)N |
| | 2110804-301 | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| D146 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D146-41 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D146A | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D146B | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D146G | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D146M | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D147 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D147A | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D149 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| | 2120304-301 | 801 | BC-DBM(1) | 2120314-321 | 21-5 | BO-DBM(1)N |
| | 2110804-301 | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| D330 | | ---- | ---- | 2121404-321A | 31-3 | BO-1215L-N |
| D347 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D348 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |



























| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-----------------|-------------------|----------|-----------------|-------------|----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| D351 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D530 | 2130104-301A | 802 | BC-DBM(Z1) | 2130104-321 | 22 | BO-DBM(A) |
| | 2130104-310A | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| D530-E | 2130104-301A | 802 | BC-DBM(Z1) | 2130104-321 | 22 | BO-DBM(A) |
| | 2130104-310A | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| D530-18E | 2130104-310A | 802NBL3 | BC-DBM(Z1)-NBL3 | 2130104-321 | 22 | BO-DBM(A) |
| D530-30P | 2130104-310A | 802NBL3 | BC-DBM(Z1)-NBL3 | 2130104-321 | 22 | BO-DBM(A) |
| D530-101 | 2130104-301A | 802 | BC-DBM(Z1) | 2130104-321 | 22 | BO-DBM(A) |
| | 2130104-310A | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| D530-110 | 2130104-301A | 802 | BC-DBM(Z1) | 2130104-321 | 22 | BO-DBM(A) |
| | 2130104-310A | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| D530-120 | 2130104-301A | 802 | BC-DBM(Z1) | 2130104-321 | 22 | BO-DBM(A) |
| | 2130104-310A | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| D530-130 | 2120304-301 | 801 | BC-DBM(1) | 2120314-321 | 21-5 | BO-DBM(1)N |
| | 2110804-301 | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| D530-140 | 2120304-301 | 801 | BC-DBM(1) | 2120314-321 | 21-5 | BO-DBM(1)N |
| | 2110804-301 | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| D530-18E | 2130104-301A | 802 | BC-DBM(Z1) | 2130104-321 | 22 | BO-DBM(A) |
| | 2130104-310A | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| D530-30P | 2130104-301A | 802 | BC-DBM(Z1) | 2130104-321 | 22 | BO-DBM(A) |
| | 2130104-310A | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| D532 | 2130104-301A | 802 | BC-DBM(Z1) | 2130104-321 | 22 | BO-DBM(A) |
| | 2130104-310A | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| D533 | 2130104-301A | 802 | BC-DBM(Z1) | 2130104-321 | 22 | BO-DBM(A) |
| | 2130104-310A | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| D534 | 2130104-301A | 802 | BC-DBM(Z1) | 2130104-321 | 22 | BO-DBM(A) |
| | 2130104-310A | 802NBL3 | BC-DBM(Z1)-NBL3 | | | |
| D1332-11 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D1332-41 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D1412-41 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D1412-61 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D1413-42 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D1422 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D1422-42 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D1512-41 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D1513-43 | 2110104-301C | 601 | BC-DB1 | 2110104-321 | 2 | BO-103(2) |
| D2432 | 2121604-301B | 606NBL | BC-DLN-NBL | 2110104-321 | 2 | BO-103(2) |
| DX936 | | ---- | ---- | | ---- | ---- |
| JB-500 | 123003-560C | 615 | BC-DBZ(3) | 2110104-321 | 2 | BO-103(2) |
| TREASURE | | | | | | |
| BM-550 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| | | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| BS-170 | | ---- | ---- | | ---- | ---- |
| BS-170J | | ---- | ---- | | ---- | ---- |
| BS-170LA | | ---- | ---- | | ---- | ---- |
| BS-170PB | | ---- | ---- | | ---- | ---- |
| BS-170SF | | ---- | ---- | | ---- | ---- |
| BS-170SP | | ---- | ---- | | ---- | ---- |
| BS-171 | | ---- | ---- | | ---- | ---- |
| BS-172 | | ---- | ---- | | ---- | ---- |
| BS-200 | | ---- | ---- | | ---- | ---- |
| BS-300 | | ---- | ---- | | ---- | ---- |
| BS-320 | | ---- | ---- | | ---- | ---- |
| BS-1107 | | 704 | BC-102 | | 15 | BO-107(1) |
| BS-1108 | | 704NBL | BC-102-NBL | | 15 | BO-107(1) |
| TYPICAL | | | | | | |
| GC6-1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GC6-1-D3 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| GC6-8 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GC6-28 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GC38-1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GC40-1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GC40-2 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GC40-4 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GYD20-6 | | 615NBL6 | BC-DBZ(3)-NBL6 | | 22 | BO-DBM(A) |
| UNICORN | | | | | | |
| DB2-H310 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| DB2-H311 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| DB2-H312 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| DB2-H360KM-10 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| DB2-H360KM-12 | | 601NBL6 | BC-DB1-NBL6 | | 10 | BO-95(A) |
| DB2-H510 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| DY-H340 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| LS2-H540 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| LT2-H240-MOB | | CAP | UNAVAILABLE | | 19-3 | BO-112(3) |
| LT2-H240-BOB | | CAP | UNAVAILABLE | | 26-3 | BO-1215MM-N |
| LT2-H320 | | ---- | ---- | | 19-3 | BO-112(3) |
| LT2-H321 | | ---- | ---- | | 19-3 | BO-112(3) |
| LT2-H322 | | ---- | ---- | | 26-3 | BO-1215MM-N |
| LT2-H323 | | ---- | ---- | | 26-3 | BO-1215MM-N |

























| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|----------------------------|-------------------|----------|------------------|---------------|----------|------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| LT2-H620 | | ---- | ---- | | ---- | ---- |
| LT2-H620H | | ---- | ---- | | ---- | ---- |
| LT5-HP331 | | ---- | ---- | | 19-3 | BO-112(3) |
| LT5-HP331AT | | CAP | UNAVAILABLE | | ---- | ---- |
| LT5-HP333 | | ---- | ---- | | 19-3 | BO-112(3) |
| LT5-HP333AT | | CAP | UNAVAILABLE | | ---- | ---- |
| LZ2-H272 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| PLN-7 | | ---- | ---- | | 19-3 | BO-112(3) |
| PLN-7B | | ---- | ---- | | 19-3 | BO-112(3) |
| PLN-27 | | ---- | ---- | | 19-3 | BO-112(3) |
| PLN-27B | | ---- | ---- | | 19-3 | BO-112(3) |
| UNION SPECIAL | | | | | | |
| 16 | | ---- | ---- | 1047L | ---- | ---- |
| 16(LEWIS) | | ---- | ---- | 1047L | ---- | ---- |
| | | | | 1047LA | ---- | ---- |
| 30 | | ---- | ---- | | ---- | ---- |
| 170-2 | | ---- | ---- | | ---- | ---- |
| 170x2 | | ---- | ---- | | ---- | ---- |
| 200-1 | | ---- | ---- | | ---- | ---- |
| 200x1 | | ---- | ---- | | ---- | ---- |
| 61200 | 61413E | 2002 | BC-UN614E | 61212 | 8 | BO-95(2) |
| | 61413E-NBL | 2002NBL | BC-UN614E-NBL | 61212A | 10 | BO-95(A) |
| 61300 | 61413E | 2002 | BC-UN614E | 61212 | 8 | BO-95(2) |
| | 61413E-NBL | 2002NBL | BC-UN614E-NBL | 61212A | 10 | BO-95(A) |
| 61400 | 61413E | 2002 | BC-UN614E | 61212 | 8 | BO-95(2) |
| | 61413E-NBL | 2002NBL | BC-UN614E-NBL | 61212A | 10 | BO-95(A) |
| | 61413E-M | 2002M | BC-UN614E-M | 61212 | 8 | BO-95(2) |
| 61800 | 61413E-NBL | 2002NBL | BC-UN614E-NBL | 62212 | 19-3 | BO-112(3) |
| | | ---- | ---- | 62212A | 19-2 | BO-112(A) |
| 61900 | 61413E | 2002 | BC-UN614E | 61212 | 8 | BO-95(2) |
| | 61413E-NBL | 2002NBL | BC-UN614E-NBL | 61212A | 10 | BO-95(A) |
| | 61413E-M | 2002M | BC-UN614E-M | 61212 | 8 | BO-95(2) |
| 62200 | 61413E-NBL | 2002NBL | BC-UN614E-NBL | 62212 | 19-3 | BO-112(3) |
| | | ---- | ---- | 62212A | 19-2 | BO-112(A) |
| 63400 | 61413 | 2001 | BC-UN614 | 61212A | 10 | BO-95(A) |
| | 61413E | 2002 | BC-UN614E | 61212 | 8 | BO-95(2) |
| | 61413E-NBL | 2002NBL | BC-UN614E-NBL | 61212A | 10 | BO-95(A) |
| | 61413E-M | 2002M | BC-UN614E-M | 61212 | 8 | BO-95(2) |
| 63900 | 61413 | 2001 | BC-UN614 | 61212 | 8 | BO-95(2) |
| | 63913B | 2005 | BC-UN639B | | | |
| | 63913A | 2005-1 | BC-UN639A | 61212 | 8 | BO-95(2) |
| | 63913NBL | 2003 | BC-UN639(SS) | 61212A | 10 | BO-95(A) |
| UNITED SHOE MACHINE | | | | | | |
| | | BC | UNAVAILABLE | | ---- | ---- |
| | | BC | UNAVAILABLE | | ---- | ---- |
| VI.BE.MAC | | | | | | |
| 650/E | | 807NBL2 | BC-DBM(3)-NBL2 | | 22 | BO-DBM(A) |
| 1650/E | | 807NBL2 | BC-DBM(3)-NBL2 | | 22 | BO-DBM(A) |
| VIGORELLI | | | | | | |
| | 307 5762 | ---- | ---- | | ---- | ---- |
| VIKING | | | | | | |
| | | ---- | ---- | S-11770 | ---- | ---- |
| WILLCOX & GIBS | | | | | | |
| 5 | | ---- | ---- | | ---- | ---- |
| 10A | 6-11/311-816-003 | ---- | ---- | 5/311-815-005 | ---- | ---- |
| 24B | | ---- | ---- | | ---- | ---- |
| | | ---- | ---- | | ---- | ---- |
| WEI RONG | | | | | | |
| WR-335 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| | | 609NBL6 | BC-DBZ(1)-NBL6 | | | |
| WR-810 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| WR-820 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| WR-991 | | C-2 | CP-PF151 | | ---- | ---- |
| WR-992 | | C-2 | CP-PF151 | | ---- | ---- |
| WR-5705 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| WUGONG | | | | | | |
| GG0805-1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| GG0805-2 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| XINGONG | | | | | | |
| GC37-1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| YAKUMO/NAKAJIMA | | | | | | |
| 171L | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 178L | B1837-201-OAO | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 178Y-2 | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| 178Y-3 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| 180L | B1837-201-OAO | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 180LY | B1837-201-OAO | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| 180LY-2 | 115490-005 | 811NBL3 | BC-DBM(6)NJ-NBL3 | B9117-201-000 | 21-5 | BO-DBM(1)N |






























| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------|-------------------|----------|------------------|---------------|----------|---------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| 181LY | 115490-005 | 811NBL3 | BC-DBM(6)NJ-NBL3 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 241L | | ---- | ---- | | 26-3 | BO-1215MM-N |
| 242L | B1837-526-0A0 | CAP | UNAVAILABLE | | 26-2 | BO-1215MM(A) |
| 243 | | ---- | ---- | | ---- | ---- |
| 246 | | CAP | UNAVAILABLE | | ---- | ---- |
| 280L | 110018-000 | 812NBL3 | BC-NJ280L-NBL3 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 280LB | 15201/15470LB | ---- | ---- | | ---- | ---- |
| 280LBY | 15201/15470LB | ---- | ---- | | ---- | ---- |
| 280LY | D1837-141-EA0 | 810NBL4 | BC-DBM(5)-NBL4 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 280LY-B | 110018-000 | 812NBL3 | BC-NJ280L-NBL3 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 281L | | ---- | ---- | 115120-000 | 22-1 | BO-DBM(A)BR-H |
| 281LY | D1837-141-EA0 | 810NBL4 | BC-DBM(5)-NBL4 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 281LY-B | D1837-141-EA0 | 810NBL4 | BC-DBM(5)-NBL4 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 321L | 115470-005 | CAP | UNAVAILABLE | 201143000 | 21-5 | BO-DBM(1)N |
| 341 | | ---- | ---- | | ---- | ---- |
| 341L | 115470-005 | CAP | UNAVAILABLE | 201143000 | 21-5 | BO-DBM(1)N |
| 340 | | ---- | ---- | | ---- | ---- |
| 380 | 109471-005 | 619NBL6 | BC-NJ380-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| 380B | 109070-001 | 619 | BC-NJ380 | B9117-012-000 | 13-4 | BO-400(4) |
| 380Y | 109471-005 | 619NBL6 | BC-NJ380-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| 381L | 110018-000 | 812NBL3 | BC-NJ280L-NBL3 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 381LY | 115490-005 | 811NBL3 | BC-DBM(6)NJ-NBL3 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 381Y | 109471-005 | 619NBL6 | BC-NJ380-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| 411 | | ---- | ---- | | ---- | ---- |
| 421 | | ---- | ---- | | ---- | ---- |
| 441 | | ---- | ---- | | ---- | ---- |
| 471 | | ---- | ---- | | ---- | ---- |
| 480 | | ---- | ---- | | ---- | ---- |
| 480L | | ---- | ---- | | 26-3 | BO-1215MM-N |
| 481 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| 481-2 | | ---- | ---- | | ---- | ---- |
| 481-3 | | ---- | ---- | | ---- | ---- |
| 481L | | ---- | ---- | 11200L | 26-3 | BO-1215MM-N |
| 482 | | ---- | ---- | B9117-051-000 | 19-3 | BO-112(3) |
| 482-2 | | ---- | ---- | | ---- | ---- |
| 482-3 | | ---- | ---- | | ---- | ---- |
| 482L | | ---- | ---- | 11200L | 26-3 | BO-1215MM-N |
| 561 | | C-2 | CP-PF151 | | ---- | ---- |
| 562 | | C-2 | CP-PF151 | | ---- | ---- |
| 563 | | C-2 | CP-PF151 | | ---- | ---- |
| 564 | | C-2 | CP-PF151 | | ---- | ---- |
| 580L | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| 680L | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| 680LY | 115490-005 | 811NBL3 | BC-DBM(6)NJ-NBL3 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 681 | B1837-245-0A0 | ---- | ---- | | ---- | ---- |
| 681LY-B | 115490-005 | 811NBL3 | BC-DBM(6)NJ-NBL3 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 880L | 110018-000 | 812NBL3 | BC-NJ280L-NBL3 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| 880LM | | 806NBL1 | BC-DBM(2)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | 110018-000 | 812NBL3 | BC-NJ280L-NBL3 | | | |
| 981 | | ---- | ---- | | ---- | ---- |
| 982 | | ---- | ---- | | ---- | ---- |
| 983 | | ---- | ---- | | ---- | ---- |
| 986 | | ---- | ---- | | ---- | ---- |
| DBE-780 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| DBE-N63 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| DBU-70L | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| DBU-175 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| DBU-175-1 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| DBU-175-2 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| DBU-175-3 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| DBU-175L | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| DBU-175L-1 | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| DBU-175L-2 | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| DBU-180 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| DBU-180-2 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| DBU-180L | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |






























| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|------------|-------------------|----------|------------------|---------------|----------|------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| DBU-180L-2 | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| DBU-181LY | 115490-005 | 811NBL3 | BC-DBM(6)NJ-NBL3 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| DBU-681LY | 115490-005 | 811NBL3 | BC-DBM(6)NJ-NBL3 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | | | |
| DBU-N65 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| DD-N73 | | ---- | ---- | 102062-000 | 38 | BO-45 |
| DDN-738 | | ---- | ---- | 102062-000 | 38 | BO-45 |
| DDU-380 | | ---- | ---- | B9117-012-000 | 13-4 | BO-400(4) |
| DDU-411 | | ---- | ---- | 102259-000 | ---- | ---- |
| DDU-N73 | | ---- | ---- | 102062-000 | 38 | BO-45 |
| DEN-750 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| DEN-780 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| DEN-N70 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| DEU-750 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DEU-750 | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DEU-780 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DEU-780 | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DEU-N70 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DNU-241H-4 | D1837-141-EA0 | 810NBL4 | BC-DBM(5)-NBL4 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DNU-241H-5 | D1837-141-EA0 | 810NBL4 | BC-DBM(5)-NBL4 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DNU-241H-6 | D1837-141-EA0 | 810NBL4 | BC-DBM(5)-NBL4 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DSC-245 | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-58 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-58 | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-78 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-78 | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-80-2 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| | 112035-000 | 601NBL6 | BC-DB1-NBL6 | | | |
| DSN-80-3 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-80-3 | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-80L | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DSN-80L | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DSN-165 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-165 | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-170 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-170 | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-178-1 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-178-1 | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-178-2 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-178-2 | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-178-3 | 203072-000 | 601 | BC-DB1 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-178-3 | 112035-000 | 601NBL6 | BC-DB1-NBL6 | B9117-012-000 | 13-4 | BO-400(4) |
| DSN-178L | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DSN-178L | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DSN-178L-2 | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DSN-178L-2 | D1837-141-EA0 | 810NBL4 | BC-DBM(5)-NBL4 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DSN-178L-3 | B1837-201-0A0 | 801 | BC-DBM(1) | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DSN-178L-3 | B1837-201-SAO | 801NBL1 | BC-DBM(1)-NBL1 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| DU-141H | 115490-005 | 811NBL3 | BC-DBM(6)NJ-NBL3 | B9117-201-000 | 21-5 | BO-DBM(1)N |
| KG-360M | | ---- | ---- | | | |
| T-215 | | 503 | BC-269 | 105215-000 | ---- | ---- |
| TDU-781 | | 503 | BC-269 | 105215-000 | ---- | ---- |
| TDU-781 | | 503NBL | BC-269-NBL | 105215-000 | ---- | ---- |
| TDU-N62 | | 503 | BC-269 | 105215-000 | ---- | ---- |
| TDU-N62 | | 503NBL | BC-269-NBL | 105215-000 | ---- | ---- |
| TG-360N | | ---- | ---- | 108084-000 | ---- | ---- |
| YAMAICHI | | | | | | |
| Y&Y-800CNC | | 802 | BC-DBM(Z1) | | 22 | BO-DBM(A) |
| YAMATO | | | | | | |
| CB-501 | | ---- | ---- | | ---- | ---- |
| CB-503 | | ---- | ---- | | ---- | ---- |
| CB-511 | | ---- | ---- | | ---- | ---- |
| DP | | 704 | BC-102 | | 17 | BO-107(A) |
| DP | | 704NBL | BC-102-NBL | | 17 | BO-107(A) |
| DP2 | 75128 | 702 | BC-107(2) | 75129 | 17 | BO-107(A) |
| DP2 | | 702NBL | BC-107(2)-NBL | | 17 | BO-107(A) |
| DP3 | 75128 | 702 | BC-107(2) | 75129 | 17 | BO-107(A) |
| DP3 | | 702NBL | BC-107(2)-NBL | | 17 | BO-107(A) |
| DP6 | | ---- | ---- | | ---- | ---- |
| DP-1101 | 77309 | 1003 | BC-DU265 | | 10 | BO-95(A) |
| DP-1102 | 77309 | 1003 | BC-DU265 | | 10 | BO-95(A) |
| DP-1111 | 77309 | 1003 | BC-DU265 | | 10 | BO-95(A) |





























| MACHINE | BOBBIN CASE (CAP) | | | BOBBIN | | |
|-----------------|-------------------|----------|-----------------|---------|----------|-------------|
| | REF.NO. | ITEM NO. | ARTICLE | REF.NO. | ITEM NO. | ARTICLE |
| DP-1112 | 77309 | 1003 | BC-DU265 | | 10 | BO-95(A) |
| NB-2000 | | ---- | ---- | | ---- | ---- |
| NB-2050 | | ---- | ---- | | ---- | ---- |
| YASHIMA | | | | | | |
| LF12 | | C-2 | CP-PF151 | | ---- | ---- |
| LF103 | | C-2 | CP-PF151 | | ---- | ---- |
| LF224 | | C-2 | CP-PF151 | | ---- | ---- |
| LF225 | | C-2 | CP-PF151 | | ---- | ---- |
| LF226 | | C-2 | CP-PF151 | | ---- | ---- |
| LT2-YX | | C-2 | CP-PF151 | | ---- | ---- |
| LX2-Y1 | | 601 | BC-DB1 | | 2 | BO-103(2) |
| LX2-Y1 | | 601NBL6 | BC-DB1-NBL6 | | 2 | BO-103(2) |
| MW-90B | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| MW-90B | | 801NBL1 | BC-DBM(1)-NBL1 | | 21-5 | BO-DBM(1)N |
| YASUDA | | | | | | |
| DI-4 | | ---- | ---- | | ---- | ---- |
| YING LUN | | | | | | |
| GY101-1 | | 615NBL6 | BC-DBZ(3)-NBL6 | | 22 | BO-DBM(A) |
| YULUN | | | | | | |
| 547U205 | | 705 | BC-457 | | 17 | BO-107(A) |
| 547U225 | | 705 | BC-457 | | 17 | BO-107(A) |
| 547U435L | | 705 | BC-457 | | 17 | BO-107(A) |
| TKN-671-W | | C-2 | CP-PF151 | | ---- | ---- |
| YLM-335 | | 609 | BC-DBZ(1) | | 2 | BO-103(2) |
| YLM-335 | | 609NBL6 | BC-DBZ(1)-NBL6 | | 2 | BO-103(2) |
| YLM-340 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| YLM-350-22 | | 801 | BC-DBM(1) | | 21-5 | BO-DBM(1)N |
| YLM-457U | | ---- | ---- | | ---- | ---- |
| YLM-545 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| YLM-546 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| YLM-572-W | | C-2 | CP-PF151 | | ---- | ---- |
| YLM-671-W | | C-2 | CP-PF151 | | ---- | ---- |
| YLM-810-G | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| YLM-820-G | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| YLM-1245 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| YLM-1246 | | CAP | UNAVAILABLE | | 41 | BO-PF541 |
| ZSK | | | | | | |
| | 574057 | 912NBL6 | BC-PF9076TG-NBL | 168144 | 24-2 | BO-PF130(A) |
| 166 | | ---- | ---- | | ---- | ---- |
| 166E | | ---- | ---- | | ---- | ---- |
| 166M | 574057 | 912NBL6 | BC-PF9076TG-NBL | 168144 | 24-2 | BO-PF130(A) |
| 167E | 574057 | 912NBL6 | BC-PF9076TG-NBL | 168144 | 24-2 | BO-PF130(A) |
| 168M | 574057 | 912NBL6 | BC-PF9076TG-NBL | 168144 | 24-2 | BO-PF130(A) |
| 168/6E-8E | 574057 | 912NBL6 | BC-PF9076TG-NBL | 168144 | 24-2 | BO-PF130(A) |
| 169E | 574057 | 912NBL6 | BC-PF9076TG-NBL | 168144 | 24-2 | BO-PF130(A) |
| 170E | 574057 | 912NBL6 | BC-PF9076TG-NBL | 168144 | 24-2 | BO-PF130(A) |
| 171E | 574057 | 912NBL6 | BC-PF9076TG-NBL | 168144 | 24-2 | BO-PF130(A) |
| 172 | 574057 | 912NBL6 | BC-PF9076TG-NBL | 168144 | 24-2 | BO-PF130(A) |
| 174 | 574057 | 912NBL6 | BC-PF9076TG-NBL | 168144 | 24-2 | BO-PF130(A) |
| 7000 | | ---- | ---- | | ---- | ---- |
| 8000 | | ---- | ---- | | ---- | ---- |






























| | | | | | |
|--|--|--|--|---|--|
| <p>Bobbincase Cap Base Shuttle Carrier Hook</p> | <p>(1) Household -CB- Type</p> | <p>101 BC-HA1 with NS Tension Spring.</p>  | <p>102 BC-HA1(NS) with Bend in Tread slot.</p>  | <p>103 BC-HA1(G)</p>  | <p>105 BC-15-88</p>  |
| <p>106 BC-HA1(JNS)</p>  | <p>107 BC-19-91</p>  | <p>(2) Household -ZIGZAG- Type</p> | <p>203 BC-HZ3(NS) 12.3mm slot with NS Tension Spring.</p>  | <p>203NBL BC-HZ3(NS)-NBL with NBL-101 Spring</p>  | <p>203AL BC-HZ3(NS)-AL with Auto-Latch</p>  |
| <p>203-1 BC-HZ3(NS)-B 12.3mm slot</p>  | <p>204 BC-HZ4(NS) 12.3mm slot with NS Tension Spring. with Tread Guide Hole.</p>  | <p>205 BC-HZ5 12.3mm slot</p>  | <p>206 BC-HZ6 12.3mm slot with Tread Guide Hole.</p>  | <p>207 BC-HZ7 11.0mm slot with Short Tension Spring</p>  | <p>208 BC-HZ8 11.0mm slot with Short Tension Spring with Tread Guide Hole.</p>  |
| <p>208NBL BC-HZ8-NBL with NBL-101 Spring</p>  | <p>210 BC-HZ10 11.0mm slot with Short Tension Spring</p>  | <p>211 BC-NE</p>  | <p>213 BC-VIK</p>  | <p>214 BC-HZ11</p>  | <p>215 BC-HZ4(NS)-J</p>  |
| <p>(3) Household -Rotating- Type</p> | <p>301 BC-HR206</p>  | <p>302 BC-HR306</p>  | <p>303 BC-HR221</p>  | <p>304 BC-HR1 12mm Opening</p>  | <p>304AL BC-HR1-AL with Auto-Latch</p>  |




























| | | | | | |
|---|---|---|--|---|--|
| <p>305 BC-HR2 12mm Opening</p>  | <p>306 BC-HR3 12mm Opening</p>  | <p>307 BC-HR4 12mm Opening</p>  | <p>307NBL BC-HR4-NBL6 with NBL-406 Spring.</p>  | <p>308NBL9 BC-HR5-NBL9 with NBL-409 Spring.</p>  | |
| <p>(4) Household -Special- Type</p> | <p>401 LS-27</p>  | <p>402 LS-28</p>  | <p>403 LS-COMBI Combination Type</p>  | <p>B-1 B-221</p>  | <p>H-1 H-221</p>  |
| | <p>B-2 B-301</p>  | <p>H-2 H-301</p>  | <p>S-101 SBC-66</p>  | <p>S-102 SBC-400</p>  | |
| <p>(5) Industrial Use -CB- Type</p> | <p>501 BC-71(1)</p>  | <p>501NBL BC-71(1)-NBL with NBL-101 Spring.</p>  | <p>502 BC-71(2)</p>  | <p>502NBL BC-71(2)-NBL with NBL-101 Spring.</p>  | <p>502-1 BC-71(2)-1</p>  |
| | <p>502-2 BC-71-101</p>  | <p>502-3 BC-71-(3)</p>  | <p>503 BC-269</p>  | <p>503NBL BC-269-NBL with NBL-101 Spring.</p>  | <p>503M2 BC-269-M2 with Adjustable Magnet</p>  |




























| | | | | | | |
|--|---|---|---|---|---|--|
| 504-2 BC-431  | 505 BC-68  | 505-2 BC-68-2 with Tread Guide Hole  | 506 BC-69  | 507 BC-78  | 508 BC-31-20  | |
| 509 BC-12  | 510 BC-LK(B)  | 510NBL BC-LK(B)-NBL with NBL-101 Spring.  | 510-2 BC-LK(B2) with NBL-101 Spring.  | 510-3 BC-LK(B3) with NBL-101 Spring.  | 511 BC-LK(J)  | |
| 511NBL BC-LK(J)-NBL with NBL-101 Spring.  | 511-2 BC-LK(J2)  | 511-3 BC-LK(J3)  | 511-4 BC-LK(J4) with NBL-101 Spring.  | 511-5 BC-LK(J5)-NBL with NBL-101 Spring.  | 512 LK-SENSOR with mechanism to sensor  | |
| <p>(6) Industrial Use -Rotating- Type</p> | 601 BC-DB1  | 601NBL1 BC-DB1-NBL1 with NBL-401 Spring.  | 601NBL2 BC-DB1-NBL2 with NBL-402 Spring.  | 601NBL6 BC-DB1-NBL6 with NBL-406 Spring.  | 601NBL17 BC-DB1-NBL17 with NBL-417 Spring.  | |
| | 601M BC-DB1-M with Magnet  | 601M-1 BC-DB1-ML with Large Magnet  | 601M-2 BC-DB1-M2 with Adjustable Magnet  | 601-2 BC-DB1-WH with Tread Guide Hole  | 601-3 BC-DB1-J  | 604 BC-251 Wide Opening.  |


















| | | | | | |
|--|---|---|---|--|--|
| <p>604NBL BC-251-NBL with NBL-404 Spring</p>  | <p>604M BC-251-M with Magnet</p>  | <p>605 BC-402 Wide Opening.</p>  | <p>605NBL BC-402-NBL with NBL-404 Spring</p>  | <p>606 BC-DLN 10mm Opening</p>  | <p>606NBL BC-DLN-NBL with NBL-404 Spring</p>  |
| <p>608 BC-281(SS)</p>  | <p>609 BC-DBZ(1) 18mm Opening</p>  | <p>609NBL6 BC-DBZ(1)-NBL6 with NBL-406 Spring</p>  | <p>609NBL9 BC-DBZ(1)-NBL9 with NBL-409 Spring</p>  | <p>609-1 BC-DBZ(C) 18mm Opening</p>  | <p>610 BC-DBZ(2) 18mm Opening</p>  |
| <p>611 BC-770</p>  | <p>611-1 BC-770-NBL1 with NBL-401 Spring</p>  | <p>612 BC-241</p>  | <p>612NBL BC-241-NBL with NBL-406 Spring</p>  | <p>612M BC-241-M with Magnet</p>  | <p>613 BC-MT with Oil Tank.</p>  |
| <p>614 DB-SENSOR with mechanism to censor</p>  | <p>615 BC-DBZ(3) 12mm Opening</p>  | <p>615NBL6 BC-DBZ(3)-NBL6 with NBL-406 Spring</p>  | <p>615NBL9 BC-DBZ(3)-NBL9 with NBL-409 Spring</p>  | <p>616 BC-AD396</p>  | <p>616NBL6 BC-AD396-NBL6 with NBL-406 Spring</p>  |
| <p>617 BC-DBZ(4)</p>  | <p>618 BC-ALFA109</p>  | <p>619 BC-NJ380</p>  | <p>619NBL6 BC-NJ380-NBL6 with NBL-406 Spring</p>  | <p>620 BC-DBZ(5)</p>  | |

| | | | | | |
|--|---|---|---|--|---|
| <p>(7) Industrial Use -Special- Type</p> | <p>701 BC-107(1) with Flat Tension Spring.</p>  | <p>701NBL BC-107(1)-NBL with NBL-603 Spring</p>  | <p>702 BC-107(2) with Split Tension Spring</p>  | <p>702NBL BC-107(2)-NBL with NBL-603 Spring</p>  | <p>702M BC-107(2)-M with Magnet</p>  |
| <p>704 BC-102</p>  | <p>704NBL BC-102-NBL with NBL-603 Spring</p>  | <p>705 BC-457</p>  | <p>705-1 BC-457(NS)</p>  | <p>705NBL BC-457-NBL with NBL-603 Spring</p>  | <p>705M BC-457-M with Magnet</p>  |
| <p>706 BC-271</p>  | <p>706NBL BC-271-NBL with NBL-603 Spring</p>  | <p>706-2 BC-271-2</p>  | <p>710 BC-LBH771</p>  | <p>710NBL BC-LBH771-NBL with NBL-603 Spring</p>  | <p>713 BC-LBH790 with NBL-604 Spring</p>  |
| <p>C-1 CP-51 without Oiling Felt.</p>  | <p>C-1F CP-51F</p>  | <p>C-3 CP-212</p>  | <p>C-4 CP-212 BIG Large Hook</p>  | <p>S-1A S-29A without Bobbin</p>  | <p>S-1B S-29B without Bobbin with Thick Tension Spring</p>  |
| <p>CA-1 CA-29</p>  | <p>S-2 S-29L without Bobbin</p>  | <p>CA-2 CA-29L</p>  | <p>(8) Industrial Use -Large- Type</p> | <p>801 BC-DBM(1) Large Capacity.</p>  | <p>801NBL1 BC-DBM(1)-NBL1 Large Capacity with NBL-1301 Spring</p>  |

| | | | | | |
|---|--|--|---|--|---|
| <p>801NBL2 BC-DBM(1)-NBL2 Large Capacity. with NBL-1302 Spring</p>  | <p>801NBL3 BC-DBM(1)-NBL3 Large Capacity with NBL-1303 Spring</p>  | <p>801NBL3-1 BC-DBM(1)-NBL3-HV Large Capacity with NBL-1303 Spring for Heavy Tread work.</p>  | <p>802 BC-DBM(Z1) Large Capacity.</p>  | <p>802NBL3 BC-DBM(Z1)-NBL3 Large Capacity. with NBL-1303 Spring</p>  | <p>803 BC-DBM(Z2) Large Capacity.</p>  |
| <p>803NBL2 BC-DBM(Z2)-NBL2 Large Capacity with NBL-1302 Spring</p>  | <p>804 BC-DBL(1)-B 31.5mm pai</p>  | <p>805 BC-GELLMAN</p>  | <p>806NBL1 BC-DBM(2)-NBL1 Large Capacity. with NBL-1301 Spring</p>  | <p>807 BC-DBM(3) Large Capacity.</p>  | <p>807NBL2 BC-DBM(3)-NBL2 Large Capacity with NBL-1302 Spring</p>  |
| <p>809NBL3 BC-DBM(4)-NBL3 Large Capacity. with NBL-1303 Spring</p>  | <p>810NBL4 BC-DBM(5)-NBL4 Large Capacity with NBL-1304 Spring</p>  | <p>811NBL3 BC-DBM(6)NJ-NBL3 Large Capacity with NBL-1303 Spring</p>  | <p>812NBL3 BC-NJ280L-NBL3 Large Capacity. with NBL-1303 Spring</p>  | <p>813NBL3 BC-DBM(AD)-NBL3 Large Capacity. with NBL-1303 Spring</p>  | <p>(9) PFAFF Type</p> |
| <p>901 BC-PF24423</p>  | <p>901NBL BC-PF244-NBL with NBL-101 Spring</p>  | <p>902 BC-PF9266 6.4mm Opening</p>  | <p>903 BC-PF9076 9mm Opening</p>  | <p>903NBL BC-PF9076-NBL with NBL-806 Spring</p>  | <p>903M BC-PF9076-M with Magnet</p>  |
| <p>905 BC-PF9076(14) 14mm Opening</p>  | <p>905NBL BC-PF9076(14)NBL with NBL-806 Spring</p>  | <p>906 BC-PF69672 9mm Opening with Tread Guide Hole</p>  | <p>906NBL BC-PF696-NBL with NBL-806 Spring</p>  | <p>908 BC-PF3114</p>  | <p>908NBL BC-PF3114-NBL with NBL-603 Spring</p>  |

| | | | | | |
|---|--|---|--|--|---|
| <p>909 BC-PF6843</p>  | <p>910 BC-PF418 with NBL-1310 Spring</p>  | <p>911NBL4 BC-PF9076(TA)-NBL4 with NBL-404 Spring</p>  | <p>912NBL6 BC-PF9076TG-NBL with NBL-806 Spring</p>  | <p>C-2 CP-PF151</p>  | <p>(10) Durkopp Type</p> |
| <p>1001 BC-DU211</p>  | <p>1001NBL BC-DU211-NBL with NBL-406 Spring</p>  | <p>1001M BC-DU211-M with Magnet</p>  | <p>1001NS BC-DU211NS</p>  | <p>1001NS-2 BC-DU211NS-2</p>  | <p>1001NS-3 BC-DU211NS-3 with NBL-406 Spring</p>  |
| <p>1001NS-4 BC-DU211NS-4 with NBL-406 Spring</p>  | <p>1002 BC-DU216</p>  | <p>1003 BC-DU265</p>  | <p>1003NS BC-DU265NS</p>  | <p>1003NS-2 BC-DU265NS-2</p>  | <p>1006 BC-DU265BIG Big Size</p>  |
| <p>1006NS BC-DU265BIG(NS)-NBL with NBL-1310 Spring.</p>  | <p>1008 BC-DU556</p>  | <p>(11) Union Special Type</p> | <p>2001 BC-UN614</p>  | <p>2002 BC-UN614E</p>  | <p>2002NBL BC-UN614E-NBL with NBL-402 Spring.</p>  |
| <p>2002M BC-UN614E-M with Magnet</p>  | <p>2003 BC-UN639(SS) 18mm Opening with NBL-406 Spring.</p>  | <p>2005 BC-UN639B</p>  | <p>2005-1 BC-UN639A</p>  | <p>Attachment</p> | <p>A-1 ST-1 Bobbin Case Straightener</p>  |

| <p>Quilting & Embroidery Lace Shuttle</p> | <p><u>3001</u> TQ-6</p>  | <p><u>3002</u> TQ-7</p>  | <p><u>3003</u> TQ-10(BIG)</p>  | <p><u>3004</u> TE-5</p>  | |
|--|---|---|---|---|---|
| <p>Bobbins</p> | <p>1 BO-103(1) 21.2 pai, 6 pai, 9.2mm Nickel Plating. Soft</p>  | <p>2 BO-103(2) 21.2 pai, 6 pai, 9.2mm Nickel Plating. Hard</p>  | <p>3 BO-103(3) 21.2 pai, 6 pai, 9.2mm Black Finish. Hard</p>  | <p>5 BO-103(Z) 21.2 pai, 6 pai, 9.2mm Nickel Plating. Hard</p>  | <p>5-2 BO-103(Z)-2 21.2 pai, 6 pai, 9.2mm Nickel Plating. Soft</p>  |
| <p>6 BO-103(A) 21.2 pai, 6 pai, 9.2mm Aluminum. with Cut</p>  | <p>8 BO-95(2) 21.2 pai, 6 pai, 9.2mm Nickel Plating. Hard</p>  | <p>8-3 BO-95-HSY 21.2 pai, 6 pai, 9.2mm Yellow Finish. Hard</p>  | <p>8-4 BO-95-HSN 21.2 pai, 6 pai, 9.2mm Nickel Plating. Soft</p>  | <p>9 BO-95NS 21.2 pai, 6 pai, 9.2mm Nickel Plating. Soft</p>  | <p>9-1 BO-95NS(1) 21.2 pai, 6 pai, 9.2mm Nickel Plating. Hard</p>  |
| <p>10 BO-95(A) 21.2 pai, 6 pai, 9.2mm Aluminum</p>  | <p>10-1 BO-95(A)-H 21.2 pai, 6 pai, 9.2mm Aluminum Hard Finish</p>  | <p>13 BO-400(2) 21.2 pai, 6 pai, 9.2mm Black Finish. Hard</p>  | <p>13-4 BO-400(4) 21.2 pai, 6 pai, 9.2mm Nickel Plating. Hard</p>  | <p>14-3 BO-400(3)N 21.2 pai, 6 pai, 9.2mm Nickel Plating. Hard</p>  | <p>15 BO-107(1) 25 pai, 6 pai, 7.7mm Black Finish. Hard</p>  |
| <p>15-3 BO-107(3) 25 pai, 6 pai, 7.7mm Nickel Plating. Hard</p>  | <p>17 BO-107(A) 25.1 pai, 6 pai, 7.7mm Aluminum</p>  | <p>17-1 BO-271(A) 25.1 pai, 6 pai, 7.7mm Aluminum</p>  | <p>17-1-1 BO-271(A)-B 25.1 pai, 6 pai, 7.7mm Aluminum Black Finish</p>  | <p>17-2 BO-B814(A) 25.1 pai, 5.9 pai, 7.7mm Aluminum</p>  | <p>17-3 BO-LBH761 25.1 pai, 5.9 pai, 7.7mm Aluminum</p>  |

| | | | | | |
|--|--|--|---|--|---|
| <p>17-3-1 BO-LBH761 25.1 pai, 5.9 pai, 7.7mm Aluminum Hard Finish</p>  | <p>17-4 BO-LBH771 25.1 pai, 5.9 pai, 7.8mm Aluminum</p>  | <p>17-4-1 BO-LBH771-H 25.1 pai, 5.9 pai, 7.8mm Aluminum Hard Finish</p>  | <p>17-5 BO-107(A2) 25.1 pai, 5.95 pai, 7.6mm Aluminum</p>  | <p>19 BO-112(2) 22 pai, 6 pai, 10.3mm Black Finish. Hard</p>  | <p>19-2 BO-112(A) 21.9 pai, 6 pai, 10.0mm Aluminum</p>  |
| <p>19-3 BO-112(3) 22 pai, 6 pai, 10.3mm Nickel Plating. Hard</p>  | <p>19-6 BO-112(6) 22 pai, 6 pai, 10.3mm Nickel Plating. Hard with Cut</p>  | <p>19-7 BO-112(A)M 22 pai, 6 pai, 9.6mm Aluminum</p>  | <p>19-8 BO-112(A)J 22 pai, 6 pai, 10mm Aluminum</p>  | <p>19-9 BO-842(A)-H 22 pai, 6 pai, 10mm Aluminum Hard Finish</p>  | <p>19-10 BO-B842(A2)-H 22 pai, 6 pai, 10mm Aluminum Hard Finish</p>  |
| <p>19-11 BO-LX2(A)-H 22 pai, 5.9 pai, 9.6mm Aluminum Hard Finish</p>  | <p>19-12 BO-LX2(A2)-H 22 pai, 5.9 pai, 9.6mm Aluminum Hard Finish</p>  | <p>19-13 BO-112(A)MT-H 28 pai, 6 pai, 11.3mm Aluminum Hard Finish</p>  | <p>19-14 BO-112(7) 22 pai, 6 pai, 10.3mm Nickel Plating. Hard</p>  | <p>21-5 BO-DBM(1)N 25.8 pai, 6 pai, 11mm Nickel Finish. Hard Large Capacity.</p>  | <p>21-6 BO-DBM(2)N 25.8 pai, 6 pai, 11mm Nickel Finish. Hard with Cut. Large Capacity</p>  |
| <p>21-7 BO-DBM(3)N 25.7 pai, 6 pai, 11mm Nickel Finish. Hard Large Capacity.</p>  | <p>21-8 BO-DBM(4)N 25.8 pai, 6 pai, 5.5mm Nickel Finish. Hard Large Capacity.</p>  | <p>22 BO-DBM(A) 25.5 pai, 6 pai, 11mm Aluminum Large Capacity.</p>  | <p>22-1 BO-DBM(A)BR-H 25.8 pai, 6 pai, 11mm Aluminum Hard Finish Large Capacity.</p>  | <p>22-2 BO-DBM(A)SN 25.5 pai, 6.02 pai, 11mm Aluminum Large Capacity.</p>  | <p>22-4 BO-DBM(A)J 25.8 pai, 6 pai, 11.1mm Aluminum Large Capacity.</p>  |
| <p>22-5 BO-DBM(A)J2-H 25.8 pai, 6 pai, 10.55mm Aluminum Hard Finish Large Capacity.</p>  | <p>23-2 BO-DBL(1)N 29.8 pai, 7.24 pai, 11.5mm Nickel Finish. Hard</p>  | <p>24 BO-PF130 22 pai, 6 pai, 8.9mm Nickel Plating. Hard</p>  | <p>24-2 BO-PF130(A) 22.1 pai, 5.9 pai, 8.9mm Aluminum</p>  | <p>25 BO-144 37 pai, 6 pai, 13mm Nickel Plating. Hard</p>  | <p>26-2 BO-1215MM(A) 28 pai, 6 pai, 11.4mm Aluminum Large Capacity.</p>  |

| | | | | | |
|--|---|--|--|---|---|
| <p>26-2-1 BO-1215MM(A)-H 28 pai, 6 pai, 11.4mm Aluminum Hard Finish Large Capacity.</p>  | <p>26-3 BO-1215MM-N 28 pai, 6 pai, 11.8mm Nickel Plating. Hard Large Capacity.</p>  | <p>26-4 BO-1215MM-N-SN 28 pai, 6 pai, 11.8mm Nickel Plating. Hard Large Capacity.</p>  | <p>26-5 BO-B872(A) 28 pai, 6 pai, 11.4mm Aluminum Large Capacity.</p>  | <p>27 BO-LKB(A) 20.7 pai, 6.2 pai, 11.8mm Aluminum</p>  | <p>27-2 BO-LKB(A)-2 20.7 pai, 6.2 pai, 11.8mm Aluminum with Cut (Both Side) for Heavy Thread work.</p>  |
| <p>27-3 BO-LKJ(A) 20.7 pai, 6.2 pai, 11.8mm Aluminum</p>  | <p>27-4 BO-LKB(A)-H 20.7 pai, 6.2 pai, 12.1mm Aluminum Hard Finish</p>  | <p>28 DB-MTB 21.2 pai, 6 pai, 9.2mm Black Finish. Hard</p>  | <p>29 BO-DB200 21.2 pai, 6 pai, 8.8mm Black Finish. Hard</p>  | <p>30 BO-LK210 20.65 pai, 6 pai, 11.8mm Black Finish. Hard</p>  | <p>31-2 BO-1215L(A) 29 pai, 6 pai, 11.8mm Aluminum Large Capacity.</p>  |
| <p>31-3 BO-1215L-N 29 pai, 6 pai, 12.4mm Nickel Plating. Hard Large Capacity.</p>  | <p>31-4 BO-1215L(A)J-H 29 pai, 6 pai, 11.8mm Aluminum Hard Finish Large Capacity.</p>  | <p>32 BO-66 20.65 pai, 6.2 pai, 10.8mm Nickel Plating. Hard</p>  | <p>34 BO-17 20.25 pai, 5.75 pai, 9mm Nickel Plating. Hard</p>  | <p>35 BO-132 34.6 pai, 7.05 pai, 15.25mm Nickel Plating. Hard</p>  | <p>38 BO-45 20.2 pai, 6 pai, 31.2mm Nickel Plating. Hard</p>  |
| <p>39 BO-29L 20 pai, 5.8 pai, 7.8mm Nickel Plating. Hard</p>  | <p>40 BO-1215MM(A)M 28 pai, 6 pai, 11mm Aluminum</p>  | <p>41 BO-PF541 28 pai, 6 pai, 11.3mm Nickel Plating. Hard</p>  | <p>44 BO-HUSQ 21.2 pai, 6 pai, 9.2mm Nickel Plating. Hard</p>  | <p>45-1 BO-TSS124(A) 20.67 pai, 6.16 pai, 11.8mm Aluminum</p>  | <p>45-2 BO-TSS125(A) 21.2 pai, 6 pai, 9.2mm Aluminum</p>  |
| <p>45-3 BO-TSS126(A) 21.2 pai, 6 pai, 9.2mm Aluminum</p>  | <p>45-4 BO-TSS134(A) 25.5 pai, 6 pai, 11mm Aluminum</p>  | <p>45-5 BO-TSS196(A) 29 pai, 6 pai, 12.4mm Aluminum</p>  | <p>47 BO-B484(A)-H 30.2 pai, 7.5 pai, 11.7mm Aluminum Hard Finish Large Capacity.</p>  | <p>47-1 BO-B484 30 pai, 7.5 pai, 11.7mm Nickel Plating. Hard</p>  | <p>48 BO-HZL880 21 pai, 6 pai, 9.2mm Nickel Plating. Soft</p>  |

| | | | | | |
|---|---|---|---|---|--|
| <p>TM-1 for Household - Rotating- Type BC-HR etc. for Industrial -Use Rotating- Type BC-DB1, BC-DBZ Type etc.</p> | <p>TM-2 for Household -CB- Type BC-HA1, BC-HZ Type etc.</p> | <p>TM-3 for Industrial Use Large Type BC-DBM etc.</p> | <p>TM-4 for PFAFF Type BC-PF9076 ect.</p> | <p>TM-5 for Industrial Use -CB- Type BC-269, BC-LK(B), BC- LK(J) etc.</p> | <p>TM-6 for Industrial Use Special Type BC-107, BC-457, BC- LBH Type</p> |
|---|---|---|---|---|--|



| BOBBIN CASE, CAP, BASE, SHUTTLE, CARRIER & HOOK | | | |
|---|--|-------------------------------|---|
| 1. BOBBIN CASE, CAP, BASE, SHUTTLE, CARRIER & HOOK | | | |
| (1) HOUSEHOLD-CB-TYPE | | | |
| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
| 101 | BC-HA1 | 15277,505086 | SINGER 15-30,15K30,83,17U123 |
| 102 | BC-HA1(NS) with NS Tension Spring. | 15277NS | Straight Stitch Sewing Machine |
| 103 | BC-HA1(G) with Bend in Tread slot. | 15277G | Straight Stitch Sewing Machine |
| 105 | BC-15-88 | B1828-215-PA0 125291,33486 | JUKI AMS-215P SINGER 15K88,90,91 |
| 106 | BC-HA1(JNS) | | |
| 107 | BC-19-9 | 17324 | SINGER 19-9,10,17 |
| (2) HOUSEHOLD-ZIGZAG-TYPE | | | |
| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
| 203 | BC-HZ3(NS) 12.3mm slot*with NS Tension Spring. | JO1313Z | Zigzag Sewing Machine |
| 203NBL | BC-HZ3(NS)-NBL with NBL-101 Spring | | Zigzag Sewing Machine |
| 203AL | BC-HZ3(NS)-AL with Auto-Latch | | Zigzag Sewing Machine |
| 203-1 | BC-HZ3(NS)-B 12.3mm slot*Black Finish. | | Zigzag Sewing Machine |
| 204 | BC-HZ4(NS) 12.3mm slot*with NS Tension Spring.*with Tread Guide Hole. | | Zigzag Sewing Machine |
| 205 | BC-HZ5 12.3mm slot | | Zigzag Sewing Machine |
| 206 | BC-HZ6 12.3mm slot*with Tread Guide Hole. | | Zigzag Sewing Machine |
| 207 | BC-HZ7 11.0mm slot*with Short Tension Spring | | Zigzag Sewing Machine |
| | | 128582-003 | BROTHER HOUSEHOLD |
| 208 | BC-HZ8 11.0mm slot*with Short Tension Spring*with Tread Guide Hole. | | Zigzag Sewing Machine |
| 208NBL | BC-HZ8-NBL with NBL-101 Spring | | Zigzag Sewing Machine |
| 210 | BC-HZ10 11.0mm slot*with Short Tension Spring | | Zigzag Sewing Machine |
| | | 128582-002 | BROTHER HOUSEHOLD |
| 211 | BC-NE | 201764 | NECCHI B.F. & B.U. MIRA.NOVA.NORA.MIRANDA. ESPERIA510,512,513,514,515, ADLER153,153-A, ANKER RZ BELL 402, JULIA 534,523,525, SUPERNOVA B.F. & A. |
| 213 | BC-VIK | 4011530-OS | VIKING (HUSQVARNA) 19A,19E,21,21A,21E,51,2000,6000 |
| 214 | BC-HZ11 | 66141(MZ) | JAGUAR |
| 215 | BC-HZ4(NS)-J | 120903-005(NJ) | Zigzag Sewing Machine |
| 216 | BC-HZ12 | 0015346303 | BERNINA |
| (3) HOUSEHOLD-ROTATING-TYPE | | | |
| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
| 301 | BC-HR206 | 105032 | SINGER 206 |
| 302 | BC-HR306 | 211297 | ALFA 102,109 |
| | | 971861,110528 | NECCHI 527,529,533,720,721,750,752,753,840,RZI |
| | | 173058 | SINGER 306,306M,319,320 |
| 303 | BC-HR221 | 45751 | SINGER 221,301 |
| 304 | BC-HR1 12mm Opening | | ALFA HOUSEHOLD |
| | | 116638-001 | BROTHER HOUSEHOLD |
| | | | RICCAR HOUSEHOLD |
| 304AL | BC-HR1-AL with Auto-Latch | | RICCAR HOUSEHOLD |
| 305 | BC-HR2 12mm Opening | | ADLER 026,126,199,419,420,489 |
| | | | MEISTER |
| | | | PHOENIX 49,429,549 |
| | | | VIGORELLI |
| 306 | BC-HR3 12mm Opening | | RICCAR HOUSEHOLD |
| 307 | BC-HR4 12mm Opening | 121447-001 | BROTHER HOUSEHOLD |
| | | 1230003-560C | TOYOTA AD500,AD820 |
| | | JO1313Z-2 | |
| 307NBL | BC-HR4-NBL6 with NBL-406 Spring. | JO1313Z-2NBL | BROTHER HOUSEHOLD |
| 308NBL9 | BC-HR5-NBL9 with NBL-409 Spring. | S09706-001 | BROTHER HOUSEHOLD |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---|---------------------------------------|--------------------|---|
| (4) HOUSEHOLD-SPECIAL-TYPE | | | |
| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
| 401 | LS-27 | 8327 | SINGER 27,28, |
| 402 | LS-28 | 54505 | SINGER 127,W1,W2,W3,128 |
| 403 | LS-COMBI Combination Type | 83505 | SINGER 27,28,127,128,128W1:W3 |
| B-1 | B-221 | 45926 | SINGER 221 |
| H-1 | H-221 | 45829 | SINGER 221 |
| B-2 | B-301 | 170166 | SINGER 301 |
| H-2 | H-301 | 170167 | SINGER 301 |
| S-101 | SBC-66 | 32590 | SINGER 66,99,101,102 |
| S-102 | SBC-400 | 153758 | SINGER 401,404,413,416,418 |
| (5) INDUSTRIAL USE-CB-TYPE | | | |
| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
| 501 | BC-71(1) | 23502,249598 | SINGER 71-5,6,12,13,47,52 |
| 501NBL | BC-71(1)-NBL with NBL-101 Spring. | 23502NBL | SINGER 71-5,6,12,13,47,52 |
| 502 | BC-71(2) | 39624,249599 | SINGER 71-30,31,32 |
| 502NBL | BC-71(2)-NBL with NBL-101 Spring. | 39624NBL,249599NBL | SINGER 71-30,31,32 |
| 502-1 | BC-71(2)-1 | 249599 | SINGER 71-30,31,32 |
| 502-2 | BC-71-101 | 249921 | SINGER 71-101,107,141 |
| 502-3 | BC-71-(3) | | CONSEW |
| 503 | BC-269 | | SEIKO DE-6,8,TD-2S,6,TDW-2B,6B |
| | | 43725 | SINGER 269W all |
| | | | YAKUMO, NAKAJIMA T-215,TDU-781,N62 |
| 503NBL | BC-269-NBL with NBL-101 Spring. | | SEIKO DE-6,TD-2,2S,5,6,TDW-2B,6B |
| | | | YAKUMO, NAKAJIMA TDU-781,N62 |
| 503M2 | BC-269-M2 with Adjustable Magnet | 43725M2 | SINGER 269W all |
| 504 | BC-31-15 | 037-00-151-4 | ADLER 37 |
| | | 112439 | ALFA 157 |
| | | 20176-4-05 | NECCHI 500,510,512,513,514,515,520,522,522.523,524,525,527,529,532,534,539,554, 600,601,602,603, BD,BDA,BE,BF,BI,BIA,BPR,BTR,BU,BV,IA,LELIA,NORA,SA |
| | | 62740 | SINGER 31-15,18,44-10,12,331K,431D,F,T,U |
| 504-2 | BC-431 | 410564 | SINGER 431D,F,T,U |
| 505 | BC-68 | 33942 | SINGER 32,68-39 |
| 505-2 | BC-68-2 with Tread Guide Hole | 33942H | SINGER 68-39 |
| 506 | BC-69 | 125115 | SINGER 16,-188,16U,-288,17-22,23,25,27,17U133,69 |
| 507 | BC-78 | | SEIKO SE-2,8 |
| | | 224841 | SINGER 78(CL) |
| 508 | BC-31-20 | 20756 | SINGER 31-19,20,44,-13 |
| 509 | BC-12 | 208383 | SINGER 12K,W |
| 510 | BC-LK(B) | 116828-001 | BROTHER LK3-B220,B221,B222,B223,B826,B827,B828 |
| 510NBL | BC-LK(B)-NBL with NBL-101 Spring. | 116828NBL | BROTHER LK3-B220,B221,B222,B223,B826,B827,B828 |
| 510-2 | BC-LK(B2) with NBL-101 Spring. | 159610-101 | BROTHER BAS-303,310,311,320,321,322,325,326,330,555 LK3-B430-1,-2,-3,-4,-5,-6,-7,-8,-9, LK3-B431,B432,B433,B434,B435,B436,B438,-2,-4,B441 |
| | | MS01A0125 | MITSUBISHI PLK-03BTA,HS,109,0303,0604,0804,08HSW |
| 510-3 | BC-LK(B3) with NBL-101 Spring. | 152690-201 | BROTHER LK3-B434 |
| 511 | BC-LK(J) | B1836-232-0A0 | JUKI LK-232,237,239,322 |
| 511NBL | BC-LK(J)-NBL with NBL-101 Spring. | | JUKI LK-232,237,239,322 |
| 511-2 | BC-LK(J2) | B1828-980-0A0 | JUKI ACF-161-981,LK-280,282,283,284,287,289,291,980,982,987-510 |
| | | 418047 | SINGER 469U ALL,569U |
| 511-3 | BC-LK(J3) | B1828-980-0AB | JUKI AMS-12A,210A,212A,LK-1850 |
| 511-4 | BC-LK(J4) with NBL-101 Spring. | B1828-980-0BB | JUKI LK-1851-555 |
| 511-5 | BC-LK(J5)-NBL with NBL-101 Spring. | D1828-MMC-KA0 | JUKI LK-992-82 |
| 512 | LK-SENSOR with mechanism to censor | | Tacking, Pattern Tacking Machine |
| (6) INDUSTRIAL USE-ROTATING-TYPE | | | |
| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
| 601 | BC-DB1 | | ABLE HB-100,150,480,500,HBS-5000 |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|--|------------------|---|
| | BC-DB1 | | AD148,B,M,150,G,156,G,M,338,345,AT101XH71, D134,-41,B,46,-41,A,B,G,MD147,A,D149,D347,D348,D351,D1332-11,-41, D1412-41,-61,D1413-42,D1422,-42,D1512-41,D1513-43, TYPICAL GC6-1,-8,-28,38-1,40-1,-2,-4, UNICORN DB2-H310,H311,H510 WUGONG GG0805-1 |
| | BC-DB1 | | XINGONG GC37-1 |
| | | 203072-000 | YAKUMO, NAKAJIMA DBE-780,-N63,DBU-175,-1,-2,-3,180,-2,N65,DEN-750,780,N70, DEU-750,780,N70,DSN-58,78,80-2,-3,165,170,178-1,-2,-3,178Y-3, YASHIMA LX2-Y1 |
| 601NBL1 | BC-DB1-NBL1 with NBL-401 Spring. | 540735,52237NBL1 | SINGER 95,95-10,95-40 TO 100,96,-10,96-40,60 TO 100 103,D-10,K,191D,191D200(A,AA,BA),191D240AA, 191D300(A,AA,BA),191DX250A,191DX258A,191U, 195K:196K,241,245,251,291U,491D,100GA:308GA, 491U,491UX100B,G,H,491UX110B,G,H,491UX200B,G,H, 491UX210B,G,H,491UX300B,G,H,491UX310B,G,H 591C200A,AA,BD,591C210BD,BF,GD,GF,591C240AD,AF, 591C300A,AA,AD,AF,591C300BD,BF,GD,GF,591C305A,AA, 591C318BD,BF,GD,GF,591D200A,AA,AD,AF,BD,591D203, 591D,205A,AA,AF,591D210BD,BF,GD,GF,GAC, |
| | BC-DB1-NBL1 with NBL-401 Spring. | 540735,52237NBL1 | SINGER 591D215BD,BF,GD,GF,591D240AD,AF,BD,BF,591D240GD,GF, 591D300A,AA,BD,BF,591D300GD,GF,591D301,591D302AF, 591D303,A,591D305A,AA,AD,AF,591D308A,AA,AD,AF, 591D310BD,BF,GD,GF,591D310GA,GAC, 591D315BD,BF,GD,GF,591D318BD,BF,GD,GF, 591DUX100,591DX ALL,591DX100,591E ALL,591U ALL, 591UTT,591UX100AF,BF,GF,591UX220,GF,591UX301, 591UX302,AF,591UX312,BF,GF,591UX313,BF,GF, 591UX320GF,591V ALL,601D100AA,601D100AD,AF,BD,BF, 601D100GA,GD,GF,691D(200,300),1300,1591 |
| 601NBL2 | BC-DB1-NBL2 with NBL-402 Spring. | 2110104-301B | CONSEW 100,101,105,210,218,219,230,231R,290,290R,RATCW,291R,291RATC, 291RATCW,291RTC,310,312RATC,314RATC,315RATC,315RTC,315-1RATC, 318R,318RATC,318RTC,318-1RATC |
| | | 2110604-301B | TOYOTA AD157-500,-501,-502,-503,-603,-604,-610,620,-622,-623,-625,626,660,-662,-663, AD157-665,-666,-710,-713,-716,-622,157A-625,-663,-666,-713,-716,157B-622, AD157G-500,-502,-602,-622,625,-662,-665,158,-2,-3,-21,-22,-31,-32, AD158A-2,-31,-32,158B-2,-21,-22,158G-2,-21,-22,302,340-622,-625, AD340B-622,-625,345-622,-625,352-702,-705,417A, AD1000,1010,1012G,1020,1200,1202K,1202V,1203V,2000,3000,3050,4000, |
| 601NBL6 | BC-DB1-NBL6 with NBL-406 Spring. | | ABLE HB-300,HBS-2700 ADLER 196, 148350-101,S03245-0 |
| | | | BROTHER BAS-23,47,301,302,700,752,753,754,755, DB2-B705-1,-3,-5,B706-1,-3,B707-3,-5 DB2-B715-1,-3,-5,-103,-105,-107,-203,-205,403,-405,-503,-505,B716-1,-3,-5, DB2-B730NBN,B735-1,-3,-5,-7,B736-1,-3,-5,B737-1,-1-3,-3,-5,-905, DB2-B738-1,-3,-5,B757-3,-3-0,-5,-103,-105,-203,-205,403,-405,-503,-505, DB2-B772,B774,B777,B778,-3,-4,-103,-104,-203,-204,-803,-804 DB2-B790-3,-3-0,-5-0,-103,-105,-203,-205,303,-403,-503,-505,-603,-605, DB2-B791-1,-3-0,-5-0,-70-3,-70-5,-90-3,-90-5,-333, DB2-B792-3-0,-400,-503,-613,B793,-303,-305,B795,-313 DP2-B791-003,-10-3,-10-5,-40-3,-40-5,DD7000, |
| | BC-DB1-NBL6 with NBL-406 Spring. | | CHUAN NENG CN-991-3,-5,-7,992-3,-5,-7 COLUMBIA N430,-2 |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|----------------------------------|-----------------------------------|------------------|--------------|
| | | K1837-000 | FOMAX |
| | | | GOLDEN WHEEL |
| | | | HUSQVARNA |
| | | | IDEAL |
| | | | JANOME |
| | BC-DB1-NBL6 with NBL-406 Spring. | D1837-555-BAA | JUKI |
| | | | |
| | | | |
| | | | |
| | | | |
| | BC-DB1-NBL6 with NBL-406 Spring. | MF40E1125 | mitsubishi |
| | | | |
| | | | |
| | | | |
| | | | |
| BC-DB1-NBL6 with NBL-406 Spring. | 222528-4 | NECCHI | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| BC-DB1-NBL6 with NBL-406 Spring. | 112035-000 | YAKUMO, NAKAJIMA | |
| | | | |
| | | | |
| | | | |
| | | | |
| 601NBL1 | BC-DB1-NBL17 with NBL-417 Spring. | 110-38759 | JUKI |
| 601M | BC-DB1-M with Magnet | 52237M | ADLER |
| | | | HUSQVARNA |
| 601M-1 | BC-DB1-ML with Large Magnet | 52237ML | NECCHI |
| | | | PHOENIX |
| 601M-2 | BC-DB1-M2 with Adjustable Magnet | 52237M2 | SINGER |
| | | | ADLER |
| 601-2 | BC-DB1-WH with Tread Guide Hole | 52237WH | HUSQVARNA |
| | | | NECCHI |
| 601-3 | BC-DB1-J | B1837-155-OA0 | PHOENIX |
| | | | SINGER |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|--------------------------------|--|--|
| 604 | BC-251 Wide Opening. | 8402 0266 149063 | 8332,8334 95-1-10,96,-10,121C200A,300A,188K,U,191D,195K:196K, 281,-1,3,5,20:24,30,81,83,291D,366K177,145,146,225, 391D,400W,451K,591D/C,600W,660A1,2,3,770D1,3 |
| 604NBL | BC-251-NBL with NBL-404 Spring | 149063NBL,115388NBL | SINGER 121C200A,300A,121D200A,300A,195K:196K,241,245,251, 281,-1,3,5,20:24,30,81,83,366K177,145,146,225,400W, 451K,600W,660A1,2,3,660W,770D1,3,771D1,3, |
| 604M | BC-251-M with Magnet | 115388M,149063M | SINGER 121C200A,300A,281,-1,-3,-5,-20:-24,-30,-81,-83 366K177,145,146,225,400W,600W,660A1,2,3 |
| 605 | BC-402 Wide Opening. | 275091 | SINGER 402W |
| 605NBL | BC-402-NBL with NBL-404 Spring | 275091NBL | SINGER 402W |
| 606 | BC-DLN 10mm Opening | 112327 B1837-041-0A0 MF10E0125 554577-4-00 91 12 60 0287112 | ALFA 127,157,201:209,214:217 JUKI DDL-412,555,DLN-41,-2,41H,412,415,DMN-530-4 MITSUBISHI CU-865-12,FP NECCHI 860 REFREY 920,/3,921,/3,925,/3,927/3 SEIKO H-8BD |
| 606NBL | BC-DLN-NBL with NBL-404 Spring | S20553-001 D1837-415-DAL MN35A0125 414021 2121604-301B | BROTHER DP2-B771,B772,B791,DDL-5580H, JUKI DLN-412-2,415-2,-4,-5,H,H-2,H-4,L,L-4-1,L-4-5 MITSUBISHI LS2-210M,M1T,M1TW,2210M,M1T,M1TW SINGER 591C308A,AA,AD,AF SUNSTAR KM-235B TOYOTA AD340,-620,-B,345-620,AD-352,AD-700,D2432 |
| 608 | BC-281(SS) | 143390 | SINGER 188K,U,191D,281-41,43,61,141,143,161,162,164 281-181,183,366K177,145,146,225,591D/C |
| 609 | BC-DBZ(1) 18mm Opening | 89-178C KF220370 117596-001 | ADLER 199,289,419,489 ANKER PHOENIX 29,39,49,429,499,549,C-49 BARUDAN BEAM,BEAT,BEH,BEJ,BEJM-UF,BEL,BELL,BEM BEMR,BEMS,BEMX,BESR,BEU,BEUF,BEX BROTHER BAS-400,LE2-B861,-1,-7,TZ1-B651,-B652,TZ1 CHIYODA LZ-201 DIAMOND TB-335 FLYINGMAN GG0802 GOLDEN WHEEL CS-335B,BH I-SHAN IS-335 |
| 609 | BC-DBZ(1) 18mm Opening | B1837-027-0A0 P810005 | JUKI DDL-272,LZ-27,29,39,40,271,271K,391,391N,DDL-402,403,MCM-170,270 KERDER KD-20U KING'S HC-335 MEIJIA G15-2 MEISTERGRAMM M100,M600,M700,M800 MILLION SPECIAL MS-335 NECCHI 535 PANDA JU-20U SANHWA LT2-B961 SHIANG WANG WR-335 |
| 609 | BC-DBZ(1) 18mm Opening | 284 | SIROKUMA LM-600 STAGER DZ-S722,S821 ALL,S823 ALL,S825,SE-12 ALL, SZ-21,21-1(N),21-2(N),21-3(N),21-4(N),21-6(N),21-7(N),21-8(N),25 ALL,72 ALL SUNNUN EB-883 SUNSTAR KLZ-371 TAKING TK-652 UNICORN LZ2-H272 WOEI RONG WR-335 WUGONG GG0805-2 |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|--|-----------------------------------|--------------------|--|
| 609NBL6 | BC-DBZ(1)-NBL6with NBL-406 Spring | | YULUN YLM-335 |
| | | | ADLER 199,289,419,489 |
| | | KF220440,BBC1,B-01 | BARUDAN BEAM,BEAT,BEH,BEJ,BEJM-UF,BEL,BELL,BEM,BEMR |
| | | B-0170NBL | BEMS,BEMX,BESR,BEU,BEUF,BEX |
| | | S17096-001 | BROTHER BAS-411,415,LE2-B861-1,-7,TZ1-B651,B652 |
| | | | DIAMOND TB-335 |
| | | | JUKI LZ-27,39,40,271,271K,391,391N,402,403,MCM-170,270 |
| | | | KING'S HC-335 |
| | | 971861-4-00MF | NECCHI 527,529,533,535 |
| | | | SANHWA LT2-B961 |
| | | | STAGER DZ-S722,S821 ALL,S823 ALL,S825,SE-12 ALL, SZ-21,-1N,-2N,-3N,-4N,-6N,-7N,-8N,25 ALL,72 ALL |
| | | | SUNNUN EB-883 |
| | | | TAKING TK-652 |
| | | | WOEI RONG WR-335 |
| 609NBL9 | BC-DBZ(1)-NBL9with NBL-409 Spring | | YULUN YLM-335 |
| | | | ADLER 199,289,419,489 |
| | | 117596NBL9 | BROTHER LE2-B861-1,-7,TZ1-B651,B652 |
| | | | JUKI LZ-27,39,40,271,271K,391,391N,402,403,MCM-170,270 |
| | | | NECCHI 533,535 |
| 609-1 | BC-DBZ(C)18mm Opening | B-75(284) | STAGER DZ-S722,S821 ALL,S823 ALL,S825,SE-12 ALL, SZ-21,-1N,-2N,-3N,-4N,-6N,-7N,-8N,25 ALL,72 ALL |
| | | | CONSEW 99,103,133 CLASS,199,199R,722 CLASS,825 CLASS ZIZ |
| 610 | BC-DBZ(2)18mm Opening | B1837-586-0A0 | JUKI LZ-586 |
| 611 | BC-770 | 522312 | SINGER 770,771G |
| 611-1 | BC-770-NBL1with NBL-401 Spring | 522533 | SINGER 121C200B,300B,121D200B,300B,770D41,43,771D41,43 |
| 612 | BC-241 | 147149 | SINGER 241,245,251 |
| 612NBL | BC-241-NBLwith NBL-406 Spring | 147149NBL | SINGER 241,245,251 |
| 612M | BC-241-Mwith Magnet | 147149M | SINGER 241,245,251 |
| 613 | BC-MTwith Oil Tank. | | single-needle lock stitch sewing machine |
| 614 | DB-SENSORwith mechanism to censor | | single-needle lock stitch sewing machine |
| 615 | BC-DBZ(3)12mm Opening | 541678 | SINGER 20U11,13,23,31,33,34,35,42,43,20UX-142,143,220U2,U3,306M,320 |
| 615NBL6 | BC-DBZ(3)-NBL6with NBL-406 Spring | ME0503000000,M105 | TAJIMA TM,TMB,TMBE,TMBW,TME,-D,-DC,-H,-HC,TMEF,-H,TMEG,TMF |
| | | | BUTTERFLY GY4-1 |
| | | M1058NBL | HAPPY HCM,HM4,HMF,HMS,J-4,7,8,,K-4,7,8 |
| | | | MERCO |
| | | 541678NBL6 | SINGER 20U,20UX-142,143 |
| | | ME0503000NBL,M105 | TAJIMA TM,TMB,TMBE,TMBW,TME,TME-D,-DC,-H,-HC,TMEF,-H, TMEG,-G910,-M1212,-X,-XC,TMF,TMFD-C,TMFX-C,TMFX-C902,TMLE, TMEX-C901 |
| | | | TYPICAL GYD20-6, |
| | | | YING LUN GY101-1 |
| 615NBL9 | BC-DBZ(3)-NBL9with NBL-409 Spring | 2-20 | ELTAC 750 series |
| | | | SINGER 20UX-142,143 |
| | | | TAJIMA TM,TMB,TMBE,TME,-D,-DC,-H,-HC,TMEF-HC,TMEG-H,TMF |
| 616 | BC-AD396 | 396-15-078-4 | ADLER 296,381,396 |
| 616NBL6 | BC-AD396-NBL6with NBL-406 Spring | 396-15-082-4 | ADLER 296,381,396 |
| | | | OMAC EOC |
| 617 | BC-DBZ(4) | B1837-582-0A0 | JUKI LZ-581,582,582-2,583,583-8 |
| 618 | BC-ALFA109 | | ALFA 102,109 |
| 619 | BC-NJ380 | 109070-001 | YAKUMO, NAKAJIMA 380B |
| 619NBL6 | BC-NJ380-NBL6with NBL-406 Spring | 109471-005 | YAKUMO, NAKAJIMA 380,Y,381Y |
| 620 | BC-DBZ(5) | 163-61750 | JUKI |
| (7) INDUSTRIAL USE-SPECIAL-TYPE | | | |
| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|--|---------------------|--|
| 701 | BC-107(1) with Flat Tension Spring. | 210915 | SINGER 107W1,5,13,17,18,19,52 |
| 701NBL | BC-107(1)-NBL with NBL-603 Spring | 210915NBL | SINGER 107W1,5,13,17,18,19,52,371U |
| 702 | BC-107(2) with Split Tension Spring | 098-00-178-4 | ADLER 91,98 |
| | | | DALIAN G13 |
| | | 235-368 | DURKOPP 252,253,254,255,264 |
| | | | HUANAN G16-1 |
| | | B1810-761-0A0 | JUKI LBH-761,762,763 |
| | | MT40A0125 | MITSUBISHI LZ-750,760,-11-D |
| | | 178081 | PEGASUS DPS-2,3,4,150 |
| | | | PRINCE MOZ-40N,S |
| | | 1930 12 60 | REFREY 1930-51/52,1930-81/82,1931 |
| | | | SHANG GONG G15 |
| | | 241404,224441 | SINGER 107G,107W3,14,15,50,143W1:W3,W18,150W3,103,151K,W,307G(2) |
| | | 241404 | SPEEDBINDER CARPET |
| | | | SUNGOOD GF11001, |
| | | | SUNSTAR DPK-2 |
| | | 75128 | YAMATO DP2,3 |
| 702NBL | BC-107(2)-NBL with NBL-603 Spring | 098-15-005-4 | ADLER 91,98 |
| | | 143986-101 | BROTHER LH4-B812,B813 |
| | | 235-368NBL | DURKOPP 252,253,254,255,264 |
| | | B1810-761-0BA | JUKI LBH-761,762,763 |
| | | 387700-3-20 | NECCHI 418-100 |
| | | | PEGASUS DPS-2,3,4,150 |
| | | 1901 12 60/41 | REFREY 1901/41,1902/41 |
| | | 224441NBL,241404NBL | SINGER 107G,107W3,14,15,50,143W1:W3,W18,151K,W,307G2 |
| | | | YAMATO DP2,3 |
| 702M | BC-107(2)-M with Magnet | 224441M | SINGER 107G,107W3,14,15,50,151K,W,307G2 |
| 704 | BC-102 | B1837-405-0A0 | JUKI LZ-405,-2,407, |
| | | MT27E0125 | MITSUBISHI LZ-207,207-10,LZ2-700-MO |
| | | | PRINCE MOZ-40SP |
| | | 224418 | SINGER 107W100:103,133W(103),140W1,2,3,12, |
| | | | TREASURE BS-1107 |
| | | | YAMATO DP |
| 704NBL | BC-102-NBL with NBL-603 Spring | 224418NBL | JUKI LZ-405,-2,407 |
| | | | SINGER 107W100:103,140W1,2,3,12 |
| | | | TREASURE BS-1108 |
| | | | YAMATO DP |
| 705 | BC-457 | 159157-001,158471-0 | BROTHER BAS-500,510,LH4-B815,B816,LZ2-B852,B853,B854,TZ1-B852, |
| | | 502530,B-53 | CONSEW 347 ALL,375,375R,376,376R |
| | | 100-34056 | JUKI LZ-1280,1285,1286,1287 |
| | | MT70E0125 | MITSUBISHI LZ-710,710-11,720,720-11,760-11,780,780-11,790-11, |
| | | | LZ2-720-LOB,780-LOB,790-LOB |
| | | | NECCHI 419-100 |
| | | 502530,539 | SINGER 457A,G,GX,457U,105,125,134,135,140,405,425,435 |
| | | | 457UX,675U,DZ-S31 ALL,DZ-S310 ALL,SZ-310 ALL |
| | | | TAILOR TN-310S |
| | | 2130704-301A | TOYOTA AD550,551,552,553 |
| | | | YULUN 547U205,435L |
| 705-1 | BC-457(NS) | 502530NS | SINGER 457G,U, |
| 705NBL | BC-457-NBL with NBL-603 Spring | | JUKI LZ-1280,1286,1287 |
| | | 502530NBL | SINGER 457A,G,GX,U,105,125,134,135,140 |
| | | | STAGER DZ-S31 ALL,S310 ALL,SZ-310 ALL, |
| | | 2130714-301A | TOYOTA AD550,551 |
| 705M | BC-457-M with Magnet | 502530M | SINGER 457A,G,GX,U,105,125,134,135,140 |
| 706 | BC-271 | 271785 | SINGER 271K1,2,3,11,12,13,24,201,211 |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|--------------------------------------|--|------------------------------------|---|
| 706NBL | BC-271-NBLwith NBL-603 Spring | 1505-4-00 107118NBL | NECCHI 420,421,422 SINGER 271K1,2,3,11,12,13,24,201,211 |
| 706-2 | BC-271-2 | 107119,271864 | SINGER 271K4,14 |
| 710 | BC-LBH771 | B1810-771-0A0 | DALIAN GI8 JUKI LBH-771,772,773,774,780,781,782,783,784 K-CHANCE KBH-890 TAKING TK-888 |
| 710NBL | BC-LBH771-NBLwith NBL-603 Spring | B1810-771-0BA | JUKI LBH-771,771,772,773,774,781,782,783,784 |
| 713 | BC-LBH790with NBL-604 Spring | 137-29769 | JUKI LBH-790,K,S,791,S,792,793,794 |
| C-1 | CP-51without Oiling Felt. | | SEIKO SPW-6,SPW-26 |
| C-1F | CP-51F | 241676 | SEIKO LPW-2G Series,PWG-7,M SINGER 51W,53,59,52K,52W21,22,110W-2,118W,1,4, 119W,1,136W,138W102,167G,W,236G,U,W,238G |
| C-3 | CP-212 | 512551 | SINGER 211G441,451,457,665,666,211GX101,103,112 212G440,441,212GX45,101,103,107,212U441 |
| C-4 | CP-212BIGLarge Hook | 514241 | SINGER 211G351,357,358,465,466,641,765,766,776 211GX102,108,212G8,340,341,641,212GX8,102,104,108,110 |
| S-1A | S-29Awithout Bobbin | 8603,8654 | SINGER 29K71,73,171,29U171A,173A |
| S-1B | S-29Bwithout Bobbin*with Thick Tension Spring | 81964 | SINGER 29K71,73,171,29U171A,173A |
| CA-1 | CA-29 | 82177 | SINGER 29K71,73,171,29U171A,173A |
| S-2 | S-29Lwithout Bobbin | 81952,HA46082 | SINGER 29-30,29K72,29U171,172,A |
| CA-2 | CA-29L | 82205 | SINGER 29K72,29U171,172,A |
| (8) INDUSTRIAL USE-LARGE-TYPE | | | |
| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
| 801 | BC-DBM(1)Large Capacity. | 147790-001 R1144 2120304-301 | ABLE HB-380 BROTHER DB2-B740,B741,B741-3,B741-3,B745-5,B745-7,B797,B797-5 CHANDLER DY-337 CONSEW 120 FOMAX KDD-5570HB GOLDEN WHEEL CS-350L JANOME DB-J706S B1837-201-0A0 JUKI DDL-201,H,S,DU-141H MF25E0125 MITSUBISHI CU-865-22,865-22-FP,DB-120-1,-2,127,130,-22,130E-22,130G-22 DB-132G-22,325-22,-22-D,327,DX-370-20,-22,377, DY-330-22,-22D,337,-2S,340-22,350-22, LS2-110-BOB,130-B,BOB,1130-B,BOB LT-350-22,LU2-460-BOB,LX2-630-BO,LY2-340-BOB,YU-360-22 |
| | BC-DBM(1)Large Capacity. | | NITAKA DY-350L,370L,370S PRINCE LX-2000,LPZ-5000CNC,6000NCN,SPX-200CNC,SPZ-500,600 18550 SEIKO H-2B,HC-2BLA,LSC-8BL,LSC-8BLV,LTW-27BL,NCL-2BL 530198 SINGER 121C330AA,121D330AA SUNNUN DY-637,YU-740 SUNSTAR D-146BL,KM-340BL,380,390,590BL 2120304-301 TOYOTA AD324,D134H,D324,D530-130,D530-140 |
| | BC-DBM(1)Large Capacity. | | TREASURE BM-550 UNICORN DB2-H312,DY-H340,LS2-H540 WOEI RONG WR-5705 B1837-201-0A0 YAKUMO, NAKAJIMA 178L,180L,180LY,580L,680L,DBU-70L,175L,-1,-2,180L,-2,DSN-80L,178L,-2,-3, YASHIMA MW-90B YULUN YLM-340,350-22 |
| 801NBL | BC-DBM(1)-NBL1Large Capacity,*with NBL-1301 Spring | 151845-001 | ATTILIO FORTE AF6LGE BROTHER BAS-26,36,350,361,370,375,412,416,423 DB2-B740,B741,-3,B745-5,-7,B746,-5,-7,-8,B747-5,-5-0,-7,-7-0, DB2-B748-305,-307,B748,B797,-5,B798,-300 CHUAN NENG CN-915-3 |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|--|--------------------|---|
| | | | CONSEW 120 |
| | | | GOLDEN WHEEL CS-350L-T,CSZ-3211 |
| | | | JANOME DB-J706S, |
| | | B1837-201-SAO | JUKI DDL-201,H,S,560,-5,5600,NL6,NLL6,DSU-145,-4,-5,DU-141H, |
| | | MG40E0125 | MITSUBISHI DB-199-22,DY-339-22,-22M |
| | BC-DBM(1)-NBL1 Large Capacity.*with NBL-1301 Spring | 1920 12 60 | REFREY 905,1920,1922,1923,1925,1927, |
| | | | RESTA H220 G1,G2,G3,G4 |
| | | 18550 | SEIKO H-2BL,HC-2BL,HCL-2BL,LAH-1LC/N |
| | | 530198NBL | SINGER 121C330AA,121D330AA |
| | | 2110804-301 | TOYOTA AD324,D134H,D324,D530-130,-140 |
| | | | TREASURE BM-550 |
| | | B1837-201-SAO | YAKUMO, NAKAJIMA 171L,180LY,580L,680L,DBU-70L,175L,-1,-2,180L,-2,181LY,DSN-80L,178L,-3 |
| | | | YASHIMA MW-90B |
| 801NBL2 | BC-DBM(1)-NBL2 Large Capacity.*with NBL-1302 Spring | MS02E0125 | MITSUBISHI LY2-380-BIT,PLK-1006,1410,4510,PLX-20JR |
| 801NBL3 | BC-DBM(1)-NBL3 Large Capacity.*with NBL-1303 Spring | | MITSUBISHI LY2-380-BIT,PLK-1006,1410,4510,PLX-20JR |
| 801NBL3 | BC-DBM(1)-NBL3-HV Large Capacity.*with NBL-1303 Spring*for Heavy Tread work. | | MITSUBISHI LY2-380-BIT,PLK-1006,1410,4510,PLX-20JR |
| 802 | BC-DBM(Z1) Large Capacity. | | CHIYODA LZ-301 |
| | | B-84,137A(714) | CONSEW 145,146RB,146RBL,175,175R,176R |
| | | | EAGLE OS-2000 |
| | | 135659 | PFAFF KSM-200 |
| | | 714 | STAGER SZ-21-1B(N),-1BNL,-3BNL,-4BNL,-5(N),-5NL |
| | | 2130104-301A | TOYOTA D530,-E,-18E,-30P,-101,-110,-120,D532,D533,D534 |
| | | | YAMAICHI Y&Y-800CNC |
| 802NBL3 | BC-DBM(Z1)-NBL3 Large Capacity.*with NBL-1303 Spring | H-15 | ELTAC 800,900,1000,1250,1600,1800 series |
| | | 135672 | PFAFF KSM-200 |
| | | | SEIKO LZH-EVL,LZH-EVLC |
| | | | STAGER SZ-21-1B(N),(NL),-3B(NL),-4B(NL),-5(N),-5(NL) |
| | | 2130104-310A | TOYOTA D530,-E,-18E,-30P,-101,-110,-120,-18E,-30P,D532,D533,D534 |
| 803 | BC-DBM(Z2) Large Capacity. | | TAJIMA |
| 803NBL2 | BC-DBM(Z2)-NBL2 Large Capacity.*with NBL-1302 Spring | | IDEAL IE35872C,3 |
| | | MBC2,P413830,35575 | MEISTERGRAMM M600XL,M700XL,M800XL, |
| | | | SOTEXI PIK L2000 |
| 803NBL5 | BC-DBM(Z2)-NBL5 Large Capacity.*with NBL-1305 Spring | KF220302 | BARUDAN BEMR,BEMS,BEMX |
| | | | CHUAN NENG CN-915-5 |
| | | 2130104-301A | CONSEW 175RB |
| | | MEC503000DBM | TAJIMA TMEF-H615,-HC,TMEG-G914,-XG920,TMFX-C901,TSM-30,LARGE TYPE |
| 804 | BC-DBL(1)-B31.5mm pai | | SANSHIN SCZ11,14,23 |
| 805 | BC-GELLMAN | 5784 | GELLMAN |
| 806NBL1 | BC-DBM(2)-NBL1 Large Capacity.*with NBL-1301 Spring | | CHIKON CK-8BL-1,STH-8BL |
| | | 1144,18045 | CONSEW 199RB,199RBL,204RB,205RB,206RB,208RB,306RB |
| | | | EAGLE EA-106,EA-206D |
| | | B1837-241-H00 | JUKI DNU-241H |
| | | 18045 | SEIKO STH-3BL,6BL,7BL,7BL-25,7BLC-BT,8BD,8BL,8BL-25,STH-8BLC-BT,-BTFC |
| | | | TAKING TK-8BL |
| | | 2122304-301B | TOYOTA AD320-22,-662,AD3200 |
| | | | YAKUMO, NAKAJIMA 880LM |
| 807 | BC-DBM(3) Large Capacity. | | SINGER 121C300,121D300,369,W,650E,1650E |
| 807NBL2 | BC-DBM(3)-NBL2 Large Capacity.*with NBL-1302 Spring | 522456,239728 | SINGER 121C300,121D300,369,W,650E,1650E |
| | | | VI.BE.MAC 650/E,1650/E |
| 809NBL3 | BC-DBM(4)-NBL3 Large Capacity.*with NBL-1303 Spring | MG44E0125 | MITSUBISHI DB-189-22BZ,DY-339,340-22BZ,349-22BZ,358-22, DY-359-22,-22BZ,LS2-180-B1T,LT-359-22,PLK-1210,1212,1710,2520,B2010R |
| 810NBL4 | BC-DBM(5)-NBL4 Large Capacity.*with NBL-1304 Spring | D1837-141-EA0 | JUKI DSU-144 |
| | | D1837-141-EA0 | YAKUMO, NAKAJIMA 280LY,281LY,LY-B,DNU-241H-4,-5,-6,DSN-178L-2 |
| 811NBL3 | BC-DBM(6)NJ-NBL3 Large Capacity.*with NBL-1303 Spring | 115490-005 | YAKUMO, NAKAJIMA 180LY-2,181LY,381LY,680LY,681LY-B,DBU-181LY,681LY,DU-141H |
| 812NBL3 | BC-NJ280L-NBL3 Large Capacity.*with NBL-1303 Spring | | GOLDEN WHEEL CSU-4100H |
| | | 110018-000 | YAKUMO, NAKAJIMA 280L,LY-B,381L,880L,LM |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|-----------------------|--|---------------|--|
| 813NBL3 | BC-DBM(AD)-NBL3 Large Capacity.*with NBL-1303 Spring | | ADLER |
| (9) PFAFF TYPE | | | |
| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
| 901 | BC-PF24423 | 24423 | PFAFF 3125,3135,3136,3331,3334,3335,3336,3337 |
| 901NBL | BC-PF244-NBL with NBL-101 Spring | 24423NBL | PFAFF 3125,3135,3136,3331,3334,3335 |
| 902 | BC-PF92666.4mm Opening | 9266 | PFAFF 133,134 |
| 903 | BC-PF90769mm Opening | 069-00-578-4 | ADLER 69,69-373,69-FA-373,1296 |
| | | | ATTILIO FORTE AF6 |
| | | 17034 | CONSEW 277R,277RFS |
| | | 9076 | PFAFF 130,133,134,138,230,232,234,238,260,300,331,332,333,335,-H2,337-734,341,343,360,430,432,433,434,437,438,439,461,-900,462,-900,464,-900,465,-900,466,-900,467,-900,468,-900,480,482,-900,483,-900,484,-900,485,-900,486,-900,487,-900,487NL,488,-900,489,-900,489NL,563NL,734,837,838,3516,3518-481-900,3518-483-900,3541,3553,3557,3563,3565,3568,3571-483-900 |
| | | 17034 | SEIKO LSC-8B,8BV |
| | | | TAKING TK-335, |
| 903NBL | BC-PF9076-NBL with NBL-806 Spring | 069-15-028-4 | ADLER 69,-FA-373,1296 |
| | | | ATTILIO FORTE AF6 |
| | | | IVOMAQ CI-2100-2AV |
| | | 9076NBL | PFAFF 232,234,260,300,331,332,333,341,343,360,430,432,433,434,461,-900,462,-900,464,-900, |
| | | | SEIKO HC-2B,LSC-8B,8BV |
| | | | TAKING TK-335N |
| 903M | BC-PF9076-M with Magnet | | ADLER 69 |
| | | 9076M | PFAFF 232,234,260,300,331,332,333,341,343,360,430,432,433,434,461,-900,462,-900,464,-900,465,-900,466,-900,467,-900,468,-900,482,-900,483,-900,484,-900,485,-900,486,-900,487,-900,488,-900,489,-900,837,838 |
| | | | SEIKO LSC-8B,8BV |
| 905 | BC-PF9076(14)14mm Opening | | PFAFF 130 |
| 905NBL | BC-PF9076(14)NBL with NBL-806 Spring | 17318 | SEIKO LSC-8BHC,8BVC |
| 906 | BC-PF696729mm Opening*with Tread Guide Hole | 69672 | PFAFF 463(-900),469(-900),481(-900) |
| 906NBL | BC-PF696-NBL with NBL-806 Spring | 69672NBL | PFAFF 463(-900),469(-900),480,481(-900) |
| 908 | BC-PF3114 | 971964-4-00 | NECCHI 400-100 |
| | | 8243 | PFAFF 114,115,116,117,3114,3115,3116,3118,3527,3564 |
| 908NBL | BC-PF3114-NBL with NBL-603 Spring | 9719456-4-00 | NECCHI 411-100 |
| | | 8243NBL | PFAFF 114,115,116,117,3114,3115,3116,3118 |
| 909 | BC-PF6843 | 6843 | PFAFF 34 Series,65 |
| 910 | BC-PF418 with NBL-1310 Spring | 168628 | PFAFF 41,417,-900,418,-900,419,-900,3518,3518-418-900 |
| 911NBL4 | BC-PF9076(TA)-NBL4 with NBL-404 Spring | | PFAFF |
| 912NBL6 | BC-PF9076TG-NBL with NBL-806 Spring | 574057 | ZSK 166M,167E,168M,168/6E-8E,169E,170E,171E,172,174 |
| C-2 | CP-PF151 | 145507 | ALFA 184-303,185-303,-503 |
| | | | ATTILIO FORTE AF7,7LGE,7R,8,8CE,8R,10LGE,72,82,82CE,87,102LGE,872,879 |
| | | | CUB CUB-691,692 |
| | | | DIAMOND TB-471,491 |
| | | | EAGLE EA-991,992 |
| | | | GOLDEN WHEEL CS-831,832,861,862,8810,8820 |
| | | | I-SHAN IS-371,372 |
| | | | IVOMAQ CI-2100-2I,-2DI,-202I,3000-2RTD1,-4RTD1 |
| | | | JUKI PLW-1244,1245,1246,1264,1266,4240,4241,4242, |
| | | | KING'S HC-471,474,491,616,618 |
| | | | MILLION SPECIAL MS-474,491, |
| | | | MITSUBISHI LR5-5520 |
| | | | REFREY 901,902,1901,1902 |
| | | | 10159 |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|----------|-------------------|--|
| | | | 346H3,353,-354,354,441,442,443,444,445,446,447,448,451,452,453,454,455,456,457,470,PLAIN MACHINE,471,-493A,B(L),-493C(L),472,473,474,475,476,478,479,490,491,492,493,545,871-893,3548,3830 |
| | | 37255-07,37735-7C | SEIKO GPB-8W,PWB-8GW,8GW-LP,8GWC,-FL,-LC,-LP,8W PWB-22GW,22WC-FL,22WGC,8GWC(-FL) |
| | CP-PF151 | | SHIANG WANG WR-991,992 |
| | | | TAKING TK-591,592,991,992, |
| | | | WOEI RONG WR-991,992 |
| | | | YAKUMO, NAKAJIMA 561,562,563,564 |
| | | | YASHIMA LF12,103,224,225,226,LT2-YX |
| | | | YULUN TKN-671-W,YLM-572-W,671-W |

(10) DURKOPP TYPE

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|--|---------------|--|
| 1001 | BC-DU211 | 211-275 | DURKOPP 211,212,213,215,218 |
| 1001NBL | BC-DU211-NBLwith NBL-406 Spring | 211-275NBL | DURKOPP 211,212,213,215,218,265-203 |
| 1001M | BC-DU211-Mwith Magnet | 211-275M | DURKOPP 211,212,213,215,218 |
| 1001NS | BC-DU211NS | 211-288 | DURKOPP 211,212,213,215,218 |
| 1001NS- | BC-DU211NS-2 | 211-926 | DURKOPP 211,212,213,215,218,261 |
| 1001NS- | BC-DU211NS-3with NBL-406 Spring | 211-10772 | DURKOPP 211,212,213,215,218,261 |
| 1001NS- | BC-DU211NS-4with NBL-406 Spring | 211-1115 | DURKOPP 265-101,271,272,15135 |
| 1002 | BC-DU216 | 204-335 | DURKOPP 203,204,205,206,207,216,270 |
| 1003 | BC-DU265 | 265-965 | DURKOPP 265,266,267,268,269 YAMATO DP-1101,1102,1111,1112 |
| 1003NS | BC-DU265NS | 265-979 | DURKOPP 265,266,267,268,269 |
| 1003NS- | BC-DU265NS-2 | 265-10224 | DURKOPP 265,266,267,268,269 |
| 1006 | BC-DU265BIGBig Size | 265-776 | DURKOPP 265-108 NECCHI 753-102 |
| 1006NS | BC-DU265BIG(NS)-NBLwith NBL-1310 Spring. | 265-772 | DURKOPP 265-208,265-301,265-305,15305 |
| 1008 | BC-DU556 | 556-5044 | DURKOPP 556,557,558 |

(11) UNION SPECIAL TYPE

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|---|---------------|--|
| 2001 | BC-UN614 | 61413 | UNION SPECIAL 63400,63900, |
| 2002 | BC-UN614E | 61413E | UNION SPECIAL 61200,61300,61400,61900,63400 |
| 2002NBL | BC-UN614E-NBLwith NBL-402 Spring. | 61413E-NBL | UNION SPECIAL 61200,61300,61400,61800,61900,62200,63400 |
| 2002M | BC-UN614E-Mwith Magnet | 61413E-M | UNION SPECIAL 61400,61900,63400 |
| 2003 | BC-UN639(SS)18mm Opening*with NBL-406 Spring. | 63913NBL | UNION SPECIAL 63900 |
| 2005 | BC-UN639B | 63913B | UNION SPECIAL 63900 |
| 2005-1 | BC-UN639A | 63913A | UNION SPECIAL 63900 |

2.ATTACHMENT

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|------------------------------|---------------|---|
| A-1 | ST-1Bobbin Case Straightener | | Bobbin Case Straightener for 21.4mmφ Bobbin Cases |

3.QUILTING & EMBROIDERY LACE SHUTTLE

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|------------|---------------|---------|
| 3001 | TQ-6 | | |
| 3002 | TQ-7 | | |
| 3003 | TQ-10(BIG) | | |
| 3004 | TE-5 | | |

BOBBINS

| ITEM NO | ARTICLE | REFERNCENO. | SUMMARY |
|---------|--|-------------|-------------------|
| 1 | BO-103(1)21.2 pai, 6 pai, 9.2mm*Nickel Plating. Soft | | ALFA HOUSEHOLD |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|--|---|---|
| | | | HOUSEHOLD |
| | | 18710 | RICCAR SEIKO H-8B |
| 2 | BO-103(2)21.2 pai, 6 pai, 9.2mm*Nickel Plating. Hard | | ABLE HB-480 |
| | | | ALFA 102,109, |
| | | | BARATTO HBA-1 |
| | | KF220410,B-0171,BA | BARUDAN BEAM,BEAT,BEH,BEJ,BEJM-UF,BEL,BELL,BEM,BEMR, BEMS,BEMX,BESR,BEU,BEUF,BEX, |
| | | 100376-001 | BROTHER DB2-B715-105,-107,-205,-405,-505,B737-905,B790-105,-205,605, DB2-B791-10-5,-40-5,B791-70-5,-90-5,LE2-B861-7,TA1-B621, TA2-B621,B622,B623,TZ1-B651,B652, |
| | | | BUTTERFLY GC25-1,-2, |
| | | | CHIYODA LZ-201 |
| | BO-103(2)21.2 pai, 6 pai, 9.2mm*Nickel Plating. Hard | | CHUAN NENG CN-990-3,-5,-7, |
| | | | COLUMBIA N430,-2 |
| | | 182,B127,AD415B, 2110104-321,2110114-321 | CONSEW 100,101,105,210,218,219,230,B,231R,RH, 290,R,RH,310,315R,318R, |
| | | | DIAMOND TB-335 |
| | | 204-230 | DURKOPP 203,204,205,206,207,211,212,213,215,216,218,261,265-101,270,15135, |
| | | | FEIYUE GC15-1,-3, |
| | | | FENG GONG GC1-4,-6, |
| | | | FLYINGMAN GC51-1,GG0802 |
| | | | FOMAX KDD-5570,H |
| | BO-103(2)21.2 pai, 6 pai, 9.2mm*Nickel Plating. Hard | | GOLDEN WHEEL CS-335B,BH,1100F,H,S,3600,8000-20,-25,-30, |
| | | | HAPPY HCM,HM4,HMF,HMS,J-4,-7,-8,K-4,-7,-8, |
| | | | HUANAN GC28-1,GC48-1, |
| | | | HUSQVARNA 27,263 |
| | | | I-SHAN IS-335 |
| | | A9117-001-000,B9117 | JUKI LK-232,322,TL-72,82,90,TR-7, |
| | | | KERDER KD-20U,8100-3,-5,-7 |
| | | | KING'S HC-335 |
| | | | MEIJIA G15-2 |
| | | | MERCO ? |
| | BO-103(2)21.2 pai, 6 pai, 9.2mm*Nickel Plating. Hard | | MILLION SPECIAL MS-335 |
| | | | NITAKA TC-1553-3-5,1555-3-5,TTC-1530,1550 |
| | | | PANDA JU-20U |
| | | | PHOENIX 29,49,429,499,549, |
| | | | RICCAR RD-101,102,RT-5 |
| | | | SANHWA LT2-B961 |
| | | | SHANG GONG GC15-3,30-1,-4-5D,GD8-1 |
| | | | SHIANG WANG WR-335 |
| | | 55623 | SINGER 20U,11,13,23,31,33,34,35,42,43,20UX-142,143,103,D-10,K,188K,188U,31,33,35, 191D,200(A,AA,BA),240AA,300(A,AA,BA),191DX250A,258A,558A,191U,206, 220U,2,3,281UTT,291U,306,M,319,320,402W,591C308A,AA,AD,AF,D/C |
| | BO-103(2)21.2 pai, 6 pai, 9.2mm*Nickel Plating. Hard | | SIROKUMA LM-600 |
| | | | STAGER DZ-S722,S821 ALL,S823 ALL,S825,SE-12 ALL SZ-21,-1(N),-2(N),-4(N),-6(N),-7(N),-8(N),SZ-25 ALL,72 ALL |
| | | | SUNGOOD GC40-1 |
| | | | SUNNUN DB-620,622,625,627,EB-883, |
| | | | SUNSTAR KLZ-371,KM-123A,B, |
| | | ME50040000,M1057B | TAJIMA TM,TMB,TMBE,TMBW,TME,-D,-DC,TMEF,-H, TMEG,-G910,-M1212,-X,-XC,TME-H,HC,TMEX-C901 TMF,TMFD-C,TMFX-C,-C902,TMLE |
| | BO-103(2)21.2 pai, 6 pai, 9.2mm*Nickel Plating. Hard | | TAKING TK-88,652 |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|---|---|--|
| | | 2110104-321 | TOYOTA 146,A,B,G,M,147,A,AD140,B,M,146G,148,B,M, AD150,G,156,G,M,338,340,-620,-B,341,345,-620,352,-700,500,700,820, AT101XH71,D134,-41,B,D146,-41,A,B,G,M,D147,A,D149,D347,D348, D351,D1332-11,-41,D1412-41,-61,D1413-42,D1422,-42,D1512-41,-43,D2432, TYPICAL GC6-1,-8,-28,38-1,40-1,-2,-4, UNICORN DB2-H310,H311,H510,LZ2-H272 WOEI RONG WR-335, WUGONG GG0805-1,-2 XINGONG GC37-1 YASHIMA LX2-Y1 YULUN YLM-335 |
| 3 | BO-103(3) 21.2 pai, 6 pai, 9.2mm*Black Finish. Hard | | SINGER 103.D-10,K |
| 5 | BO-103(Z) 21.2 pai, 6 pai, 9.2mm*Nickel Plating. Hard | 283,283B,B74 B9117-039-000 | CONSEW 99,103,133 CLASS,199,R,722 CLASS,825 CLASS, JUKI LZ-39,391, STAGER ZIZ |
| 5-2 | BO-103(Z) 21.2 pai, 6 pai, 9.2mm*Nickel Plating. Soft | 129714-001 | BROTHER HOUSEHOLD |
| 6 | BO-103(A) 21.2 pai, 6 pai, 9.2mm*Aluminum. with Cut | KF220410A,B-0171A, 204-230A G1817-870-000 | BARUDAN BEAM,BEAT,BEH,BEJ,BEJM-UF,BEL,BELL,BEM,BEMR, BEMS,BEMX,BESR,BEU,BEUF,BEX, DURKOPP 211,212,213,215,218,261,265,-203,266,267,268,269,271,272, JUKI AVP-870 |
| 8 | BO-95(2) 21.2 pai, 6 pai, 9.2mm*Nickel Plating. Hard | 061-00-056-0 761-094-012 MF10A0123 | ABLE HB-150,500,HBS-5000, ADLER 026,61,96,196,199,289,296,381,396,419,420,489 ANKER PHOENIX 29,39,49,429,499,549,C-49, GOLDEN WHEEL CS-350 HUSQVARNA 27,263 IDEAL 1,2, JANOME DB-J701,J702,J703,J704,J705,J706,J707,J708, DB-J709,J756,J764,J765,TA-J761,J763,J766, MITSUBISHI CU-865-12,-12FP,DB-122,132G-10,-12,170,-10,-11,171,191,320-10,-11,-12,-12-8, DB-321,325,DN-350,-10,-12,352,DT-330,-12,DX-370,-10, DY-230,330,-12,340-12,350-12, LS2-130-H,HOB,M,MOB,150-MOB,680-MOBH,1130-H,HOB,M,MOB, LT-350-12,LX2-317-MO,371-MO,LZ2-130-MOB,TA-310 |
| | BO-95(2) 21.2 pai, 6 pai, 9.2mm*Nickel Plating. Hard | 52400 | NECCHI 527,529,533,535,720,721,750,752,753,800,801,802,803,810,RUM,RVG, 812,813,830,831,832,835,840,860,881,882,883,884,885, 887,RM,RVG,RVM,RZI,SG,SM,UAN-1501,1531, REFREY 906,910,918, SEIKO H-8BD |
| | | 40264 | SINGER 95,-10,-40 TO -100,96,-10,-40,-60 TO -100,220U12,13,22,23,241, 245(CL),251,391U,550U13, 601D100GA,GD,GF,660,691D(200,300), |
| | | 61212 | UNION SPECIAL 61200,61300,61400,61900,63400,63900, |
| 8-3 | BO-95-HSY 21.2 pai, 6 pai, 9.2mm*Yellow Finish. Hard | MF36A0123 | MITSUBISHI CU-865,DB-120-12-7,126,-10,130,-10,-10-KY,-11, DB-130-12,-13,130E-10,-11,-12,-12-7,-13,130G-10,-11,-12,-13,-127, DB-130,GM-10,-127,189-L,DY-339-12,LG2-3370-M,M1T, LS2-180-H,190-H1TZ,H1TZ2,M1T,M1TZ2,1180-H |
| 8-4 | BO-95-HSN 21.2 pai, 6 pai, 9.2mm*Nickel Plating. Soft | B9117-155-000 | JUKI DDW-155,LZ-581,582,-2,583,-8,586, |
| 9 | BO-95NS 21.2 pai, 6 pai, 9.2mm*Nickel Plating. Soft | | SINGER 95,96,-10, |
| 9-1 | BO-95NS(1) 21.2 pai, 6 pai, 9.2mm*Nickel Plating. Hard | | |
| 10 | BO-95(A) 21.2 pai, 6 pai, 9.2mm*Aluminum | 296-15-282-0 146290-001 | ABLE HB-300,HBS-2700 ADLER 196,199,289,296,381,396,419,489, ALTIN 8332,8334, BROTHER BAS-23,400,411,415,700,752,753,754,755,DB2-B705-1,-3,-5, DB2-B706-1,-3,B707-3,B715-1,-3,-5,-103,-203,-403,-503, DB2-B716-1,-3,-5,B735-5,B736-1,-3,-5,B737,-1,-1-3,-3,-5, |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|---|--|--|
| | | | DB2-B738-1,-3,-5,B757-3,-3-0,-5,-103,-105,-203,-205,-403, DB2-B757-405,-503,-505,B771,B772,B774,B777,B778, DB2-B781-3,-4,-103,-104,-203,-204,-803,-804, DB2-B790-3,-3-0,-5-0,-103,-203,-303,-403,-503,-505,-603, DB2-B791-1,-3-0,-5,-5-0,-70-3,-90-3,333,B792-3-0,-400,-503,-613, DB2-B793,-303,-305,B795,-313, DD7000,DP2-B791,-003,-10-3,-40-3,LE2-B861-1,-7 |
| | BO-95(A) 21.2 pai, 6 pai, 9.2mm*Aluminum | | CHUAN NENG CN-991-3,-5,-7,992-3,-5,-7, COLUMBIA N430,-2 CONSEW 100,101,231R,290R,290RATCW,290RTC,291R,291RATC,291RATCW, 291RTC,312RATC,314RATC,315RATC,315RTC,315-1RATC FOMAX KDD-5570-7,5570H-7 HUSQVARNA 27,263 IDEAL 1,2 |
| | BO-95(A) 21.2 pai, 6 pai, 9.2mm*Aluminum | B9117-552-A00 MF41D0123 52400A | JUKI DDL-552,555,555H,DDL-5550-6,415H, MITSUBISHI DB-189,-10,-11,-12,-13,199-10,-10W,199,199-12 DG-519,LS2-180-H1T,HTW,M,M1T,M1TW,M1W,L, LS2-190-H1T,H1W,M1TW,M1TZ,N1TZ,210M,M1T,M1TW, LS2-1180-L,L1T,M,M1T,M1TW,2210M,M1T,M1TW, NECCHI 527,529,533,535,800,801,802,803,810,812,813,830,831,832,835, 840,881,882,883,884,885,887, RM,RVG,RVM,SG,SM,UAN-1501,UAN-1531 OMAC EOC PRINCE SPL-100 |
| | BO-95(A) 21.2 pai, 6 pai, 9.2mm*Aluminum | 272152,376265 | SHANG GONG GC15-1,-2,-5-4D,30-2,-3 SINGER 95-1-10,1591,121C,121C200A,300A,300B, 121D,121D200A,300A,300B,1300,191D,195K:196K,241,245,251, 281,-1,3,5,20:24,30,41,43,61,81,83,141,143,161,162,164,181,183, 366K177,145,146,225,400W,402W,451K,491D,100GA:308GA, 491DX201GA,491U,491UX100B,G,H,200B,G,H,201GA, 491UX210B,G,H,300B,G,H,310B,G,H, 591C200A,AA,BD,240AD,AF,300A,AA,AD,AF, 591C300BD,BF,GD,GF,305A,AA,318BD,BF,GD,GF 591D,200A,AA,AD,AF,BD,203,205A,AA,AF, 591D210BD,BF,GAC,GD,GF,215BD,BF,GD,GF, 591D240AD,AF,BD,BF,GD,GF,300A,AA,BD,BF,GD,GF 591D300,301,302AF,303,A,305A,AA,AD,AF,308A,AA,AD,AF, 591D310BD,BF,GA,GAC,GD,GF,315BD,BF,GD,GF, 591D318BD,BF,GD,GF,591DUX100,591DX ALL,591E ALL, 591U ALL,591UTT ALL,591UX100AF,BF,GF,220,GF,301,302,AF,312,BF,GF 591UX313,BF,GF,320GF,591V ALL 600W,601D100AA,AD,AF,BD,BF,770,770D1,3,41,43,771D1,3,41,43,771G, |
| | BO-95(A) 21.2 pai, 6 pai, 9.2mm*Aluminum | 2110114-321B 61212A | SUNGOOD GC34 SUNSTAR KM-235A,B TOYOTA AD157-500,501,502,503,603,604,610,620,622,623, AD157-625,626,660,662,663,665,666,710,713,716, AD157A-622,625,663,666,713,716,157B-622,157G-500,502,602,622,625,662,665, AD158-2,-3,-21,-22,-31,-32,158A-2,-31,-32,158B-2,-21,-22,AD158G-2,-21,-22, AD302,340-622,-625,340B-622,-625,345-622,-625,352-702,-705,417A TYPICAL GC6-1-D3 UNICORN DB2-H360KM-10,-12, UNION SPECIAL 61200,61300,61400,61900,63400,36900, YAMATO DP-1101,1102,1111,1112, |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|---|---------------------|---|
| 10-1 | BO-95(A) -H21.2 pai, 6 pai, 9.2mm*Aluminum Hard Finish | | |
| 13-4 | BO-400(4) 21.2 pai, 6 pai, 9.2mm*Nickel Plating. Hard | | ABLE HB-100 |
| | | | ALFA 127,157,201:209,214:217 |
| | | 117132-001 | BROTHER BAS-47,301,302,DB1-B760-3,-5,DB2-B706-5,B707-5,B714-1,-3,-5, DB2-B730NBN,B735-1,-3,-5,-7,B755-1,-3,-5,B756,B758, DB2-B763-1,-3,-5,B765-01,-03,-05,B767,-5,-B771,B733,B777,-3, DB2B781,-1,-2,-3-0,B790,-5,-103,-203,-403,-503,-603, DB2-B791-3,-5,-70-3,-90-3,B792-003,-013,-015,-017,3,B793-3, DB2-B795-013,B791-005,-10-3,-40-3,TA1-B75-013 |
| | | B9117-012-000 | JUKI ADU-332,992,1852,1853,1854,AEC-112, DDL-105,115,127,227,227A,F,H,L,M,N,W,272,412, DDL-436-5,500,A,501,A,505,-100,-200,-300, DDL-505A-100,-200,-300,506,-200,-300,506A-200,-300,541,W, DDL-542,543,545,W,555-2,T,-4,A,G,H-2,H-4-5,U,U-4,W, DDL-5530,A,H,5550,A,H,H-6,U,5570,A,M,NE,NE,NF DDL-5580,A,H,DDW-9,A,12,92,112,115,122,123, DDW-125,W,126,-10,-11,W,226,A,T,W, DLD-43,43A,B,432,-2,-3,-4,-5,A,A-2,A-3,A-4,432B,B-2,B-3,B-4, DLD-436-5,5430,-6B,DLM-52,522,A,523,5200,5400-6,5410-6, DLN-41,-2,H,412,-2,415,-2,-4,-5,H-2,H-4,415L,-4-1,-4-5, DLN-5410H-6-WB,DLU-450,-2,-3,-4,A,B,C,D,E,G,J, DLU-490-4,-5,BB,L,491-5,591-5,5490,-6,5495-6 DMN-530,-4,-5,531,-5,5420-6,LT-72 LZ-27,29,40,271,K,391,N,402,403,MCM-170,270, |
| | BO-400(4) 21.2 pai, 6 pai, 9.2mm*Nickel Plating. Hard | | MEJIA GG70701-3 |
| | | | NITAKA DY-350S |
| | | | REFREY 920,920/3,921,921/3,925,925/3,927/3 |
| | | 270010 | SINGER 121C200A,300A,D200A,300A,241,245,251,281,-1,3,5,20:24,30,81,83,291D, 366K177,145,146,225,391D,400W,402W 491D,100GA:308GA,591D/C,600W,660A1,2,3,660W, 178Y-2,-3,380,B,Y,381Y,DBE-780,N63,DBU-175,-1,-2,-3,180,-2,N65,DDU-380, DEN-750,780,N70,DEU-750,780,N70,DSC-245, DSN-58,78,80-2,-3,165,170,178-1,-2,-3 |
| | | B9117-012-000 | YAKUMO, NAKAJIMA 178Y-2,-3,380,B,Y,381Y,DBE-780,N63,DBU-175,-1,-2,-3,180,-2,N65,DDU-380, DEN-750,780,N70,DEU-750,780,N70,DSC-245, DSN-58,78,80-2,-3,165,170,178-1,-2,-3 |
| 14-3 | BO-400(3) N21.2 pai, 6 pai, 9.2mm*Nickel Plating. Hard | 2-19 | ELTAC 750 series |
| 15 | BO-107(1) 25 pai, 6 pai, 7.7mm*Black Finish. Hard | 098-00-180-0 | ADLER 91,98 |
| | | | PRINCE MOZ-40SP |
| | | 210530,263099 | SINGER 107W1,2,3,5,12,13,14,15,17,18,19,50,52,100:103,107G, 140W1,2,3,12,143W1:W3,W18,150W3,103,151K,W,307G(2), 307G2,371U,457A,G,GX,U,105,125,134,135,140, |
| | | 210530,263099 | SPEEDBINDER CARPET |
| | | | SUNSTAR DPK-2 |
| | | | TREASURE BS-1107,BS-1108 |
| 15-3 | BO-107(3) 25 pai, 6 pai, 7.7mm*Nickel Plating. Hard | B9117-405-000 | JUKI LZ-405,-2,407, |
| | | MT27A0123 | MITSUBISHI LZ-207,-10,270-10,LZ2-700-MO |
| | | | SINGER 133W(103) |
| | | | STAGER DZ-S31 ALL,DZ-S310 ALL,SZ-310 ALL |
| | | | TAILOR TN-310S |
| 17 | BO-107(A) 25.1 pai, 6 pai, 7.7mm*Aluminum | | ADLER 91,98, |
| | | B54,123,2130504-321 | CONSEW 347 CLASS,375,375R,376,376R, |
| | | | DURKOPP 252,253,254,255,264, |
| | | | NECCHI 418-100 |
| | | | PEGASUS DPS-2,3,4,150, |
| | | | PRINCE MOZ-40N,40S, |
| | | | REFREY 1901/41,1902/41,1930-51/52,-81/82,1931 |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|--|---------------------|---|
| | | 502526 | SINGER 271K1,2,3,4,14,457A,G,GX,457U,105,125,134,135,140, |
| | | 2130504-321 | TOYOTA AD550,551,552,553 |
| | | 75129 | YAMATO DP,DP2,DP3 |
| | | | YULUN 547U205,225,435L |
| 17-1 | BO-271(A)25.1 pai, 6 pai, 7.7mm*Aluminum | MT40A0123 | mitsubishi LZ2-720-LOB,780-LOB,790-LOB,LZ-710,-11, LZ-720,-11,750,760,-11,-11-D,780,-11,790-11 |
| | | | NECCHI 420,421,422 |
| | | 233028 | SINGER 151K,W,271K1,2,3,4,11,12,13,14,24,201,211,457A,G,GX, 457U,105,125,134,135,140,405,425,435,457UX,675U |
| 17-1-1 | BO-271(A)-B25.1 pai, 6 pai, 7.7mm*Aluminum Black Finish | P976001X01 | for machine same with BO-271(A) (Black Finish) |
| 17-2 | BO-B814(A)25.1 pai, 5.9 pai, 7.7mm*Aluminum | 146025-001,117480-0 | BROTHER DL1-B812,B813,DL4-B812,B813, LH4-B812,B813,B814,-1,-2,-3,-4,-5,-102,B817,LZ1-B851 |
| 17-3 | BO-LBH76125.1 pai, 5.9 pai, 7.7mm*Aluminum | | DALIAN GI3 |
| | | | HUANAN G16-1 |
| | | B1809-761-000 | JUKI AE-6,LBH-761,762,763,LZ-1280,1285,1286,1287,2280,2285,2286, |
| | | | SHANG GONG G15 |
| | | | SUNGOOD GF11001 |
| 17-3-1 | BO-LBH76125.1 pai, 5.9 pai, 7.7mm*Aluminum Hard Finish | 158205-001 | BROTHER LZ2-B852,853,854,TZ1-B852 |
| 17-4 | BO-LBH77125.1 pai, 5.9 pai, 7.8mm*Aluminum | | DALIAN GI8 |
| | | B1811-771-000 | JUKI LBH-771,772,773,774,780,781,782,783,784,790,K,S,791,S,792,793,794, |
| | | | K-CHANCE KBH-890 |
| | | | TAKING TK-888 |
| 17-4-1 | BO-LBH771-H25.1 pai, 5.9 pai, 7.8mm*Aluminum Hard Finish | 159158-001 | BROTHER BAS-500,510,LH4-B815,-5,B816 |
| | | | NECCHI 419-100 |
| | | | SINGER 471U |
| 17-5 | BO-107(A2)25.1 pai, 5.95 pai, 7.6mm*Aluminum | 2130504-321 | TOYOTA AD550,551,552,553 |
| 19-2 | BO-112(A)21.9 pai, 6 pai, 10.mm*Aluminum | 148603-001 | BROTHER BAS-600,LT2-B832,-1,-3,-3-0,-3-0(A),-5,-5-0, LT2-B832-400,-401,-403,-405,-503,-505,-B833,-3-0, LT2-B835-3,-3-0,-3-0(A),-5-0,-5-0(A), LT2-B835-400,-403,-405,-500,-503,-505,-800,-900,-903,-905, |
| | | 245-1660A,249-372 | DURKOPP 221,222,237,238,239,241,242,244,245,246,247,249,380,541,542,543,549,697, |
| | | 244750 | SINGER 111W153:156,211G140,141,145,146,151,155:157, 211G157A,158,165,166,265,266,440,211GX110,115, 211U157(A),165(A)166(A),257,341,365,366,567, 211UX157,165,166,567,B,211W151,155,212G140,141,145, 212GX4:X6,212LX670,212U41,141,A,143,A,GA,144,A,442,443,A, 212U444,839A,212W140,141,145,146, |
| | | 62212A | UNION SPECIAL 61800,62200 |
| 19-3 | BO-112(3)22 pai, 6 pai, 10.3mm*Nickel Plating. Hard | | ABLE HB-630,LTS-220ML, |
| | | 112781-001 | BROTHER B800,LT2-B831-1,-3,-5,B835-403,-405,-503,-505,-900,-903,-905, |
| | | 10656,12125 | CONSEW 139 CLASS,207,223 CLASS,224 CLASS,225 CLASS, 226 CLASS,227 CLASS,228 CLASS,229 CLASS, 237 CLASS,237VM,238 CLASS,239 CLASS,245,256,266RI, 282,R-1,288,289,R-1,327,R,R-1,332 CLASS,357 CLASS, 358 CLASS,359 CLASS,362,382 CLASS,388 CLASS,389 CLASS |
| | | | CUB CUB-810,820, |
| | | | DIAMOND TB-810,820, |
| | | | EAGLE EA-810,820, |
| | | | FENG YING FY-810,820, |
| | | 203470 | GOLDEN WHEEL CS-8B,BH,810,820,872-3,875,-3,-5,CS-3150-3,-5,3610, |
| | | | I-SHAN IS-810,820, |
| | | | IVOMAQ CI-3000-11,-2011, |
| | | B9117-051-000 | JUKI APW-116,A,117,118,119,LH-51,-10,516,/8,517,518,525N,526A,528 |
| | | | LH-529,562A,1150,1152,-5,1160,3128,-7,3168,-7,LU-53,-7,55,-2,-3,562,-3,A, |
| | | | KERDER KD-810,820, |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|--|---------------|---|
| | | | KING'S HC-810,815,820,825, |
| | | | MILLION SPECIAL MS-810,820,B845, |
| | | MN10A0123 | mitsubishi DB-285,286,-10,DF-200,DN-260,-7,-10,-710,265,-10,275-10,-10K, DU-100,-12,105,-12,120,-12,125,-12,DX-870,-10,LS2-690-MOJ LS5-610-HOB,620-HOB,5110,MOB,5120,MOB, LT2-220-M,MO,MOB,240-MOB,2220-L,LOB,M,MOB,2240-MOB, LU2-400-HO,HOB,420-HOB,LX2-317,630-MO,LX5-871,MO, LY2-340-HOB,PB-810,-10,-10-FP,820,-10,-10-FP,840,-10,-10-FP, PN-840,-10,-10FP |
| | BO-112(3) 22 pai, 6 pai, 10.3mm*Nickel Plating. Hard | | MITSUTOMO MT-810,820 |
| | | | NITAKA LT2-B932,TC2-B842,B845,B1883,TC-810,S,820,S,TCW-8B |
| | | | PENGUIN PEG-810,820, |
| | | 10656,12125 | SEIKO CW-1,6,B,7,B,8,B,BV,V,VB, LPW-6,B,7,B,8,B,26,B,27,B,BK,BM,28,B,BK, LSW-8,B,LTW-26,R,27,B,BK,BM, PW-6,-1,-3,B,B-1,B-3,7,B,8,B,BM,M,26,B,27,B,28,B, STW-6,7,B,8,B,BM,BV,BVP,BVPM,M,V,VM,VP,VPM,26,B,27,B,28,B, WR-810,820 |
| | | | SHIANG WANG WR-810,820 |
| | | | SICAMA LT2-B842,B845 |
| | | 203470,233939 | SINGER 21W,4,5,6,30:35,100,101,102,162,180,182,22W-all,312T141,U,U171, 46W,61,62,47W,62,63,70,51W51,52,52W30,31,72W12, 110K,110W,124,128,111G,111W,100:113,150,151, 112G127,139,112W110:139,140,145,146,131W,103:113,134W, 138G101,102,103,138W(101),103,153K,W,168G,W,180W201,202, 211A157JA,165JA,166JA,166KA,212A141BA,GA, |
| | | CH455964H01 | SUNGOOD GC0501 |
| | | | SUNSTAR KM2-740B,750,790,823-827,857-867,KPW-827B |
| | | | TAJIMA TMP-20 |
| | | | TAKING TK-810,820,845-3,-5, |
| | | | UNICORN LT2-H240-MOB,H320,H321,LT5-HP331,HP333,PLN-7,B,27,B, |
| | | 62212 | UNION SPECIAL 61800,62200 |
| | | B9117-051-000 | YAKUMO, NAKAJIMA 481,482, |
| 19-6 | BO-112(6) 22 pai, 6 pai, 10.3mm*Nickel Plating. Hard*with Cut | | PFAFF 490 |
| | | 2140104-321 | TOYOTA AD331,332,740,B,X2, |
| 19-7 | BO-112(A)M 22 pai, 6 pai, 9.6mm*Aluminum | MN50A1123 | MITSUBISHI DN-269-10,LT2-220-B,230-M,M1T,M1TW,M1TZ, LT2-250-M,M1AT,M1ATW,M1TW,2230.L1T,M,M1TW,2250-M,M1TW, |
| 19-8 | BO-112(A)J 22 pai, 6 pai, 10mm*Aluminum | 101-11300 | JUKI LH-512,-3,H,515,H,1152,-4,1160-4,-5,1162,-4,-5,2152,PLW-4245 SICAMA SC-1162-5,-6, SINGER 212G146 |
| 19-9 | BO-842(A)-H 22 pai, 6 pai, 10mm*Aluminum Hard Finish | | BROTHER LH4-B815 |
| | | 102-10805 | JUKI LH-3128,-7,3168-7, |
| 19-10 | BO-B842(A2)-H 22 pai, 6 pai, 10mm*Aluminum Hard Finish | S01928-101 | BROTHER LT2-B841,-1,B842,-903,-905,B845,-3,-5,-7,403,-405,-407,-903,-905,-907, LT2-B847,-1,-401,-901,LT2-B848,-1,-401,LZ2-B842 |
| | | S01928-101 | HUANAN GC20505-1 |
| | | | SUNSTAR KM-790-7 |
| 19-11 | BO-LX2(A)-H 22 pai, 5.9 pai, 9.6mm*Aluminum Hard Finish | A142D500H02 | MITSUBISHI LX2-630,-M1 |
| 19-12 | BO-LX2(A2)-H 22 pai, 5.9 pai, 9.6mm*Aluminum Hard Finish | MQ60A0123 | MITSUBISHI LX2-630,-M1 |
| 19-13 | BO-112(A)MT-H 28 pai, 6 pai, 11.3mm*Aluminum Hard Finish | MN62A0123 | MITSUBISHI LT2-250B |
| 19-14 | BO-112(7) 22 pai, 6 pai, 10.3mm*Nickel Plating. Hard | 112781-101 | BROTHER LZ2-B831 |
| 19-15 | BO-112(A2)M 25.8 pai, 6 pai, 11mm*Nickel Finish. Hard*Large Capacity. | MN72A0123 | MITSUBISHI LT2-220-M,MO,MOB,260-10,LT2-2220-LOB,M,MOB, |
| 21-5 | BO-DBM(1)N 25.8 pai, 6 pai, 11mm*Nickel Finish. Hard*Large Capacity. | | ABLE HB-380 |
| | | 117061-001 | BROTHER BAS-26,360,361,370,375,412,416,423, DB2-B740,B741,-3,B745-5,-7,B746,-5,-7,-8,B747-5,-5-0,-7,-7-0, DB2-B748-305,-307,B748,B797,-5 |
| | | R1143 | CHANDLER DY-337 |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|---|---|---|
| | | 2120314-312,B-83 18034 | CONSEW 120,R,145,146,RB,RBL,175RB,199RB,RBL,204RB, 205RB,206RB,208RB,306RB EAGLE EA-2156C FOMAX KDD-5570HB GOLDEN WHEEL CS-350L,CSU-4100H,CSZ-3211 |
| | BO-DBM(1)N 25.8 pai, 6 pai, 11mm*Nickel Finish. Hard*Large Capacity. | 706-014-006 B9117-201-000 35784 MF25B0123 | JANOME DB-J706S JUKI DDL-201,H,S,560,-5,5600,NL6,NLL6,DNU-241H,DSU-144,145,-4,-5,DU-141H, MEISTERGRAMM M800XL MITSUBISHI CU-865-22,-22-FP DB-120-1,-2,127,130,-22,E-22,G-22,132G-22,189-22BZ,325-22,-22-D,327 DX-370-20,-22,377,DY-330-22,-22D,337,-2S, DY-340-22,350-22,358-22,359-22,-22BZ LS2-110-BOB,130-B,BOB,180-B1T,1130-B,BOB LT-350-22,359-22,LU2-460-BOB,LX2-630-BO, LY2-340-BOB,PLK-1006,1210,1212,1410, PLK-1710,4510,B2010R,PLX-20JR,YU-360-22, |
| | BO-DBM(1)N 25.8 pai, 6 pai, 11mm*Nickel Finish. Hard*Large Capacity. | 18034,35784 | NITAKA DY-350L,370L,S, PFAFF KSM-200 PRINCE LPZ-5000CNC,6000NCN,LX-2000,SPX-200CNC,SPZ-500,600 SEIKO H-2B,BL,HC-2BL,BLA,HCL-2BL,LAH-1LC,1LC/N LCW Series,LSC-8BL,8BLV,LTW-27BL,LZH-EVL,EVLC, NCL-2BL,STH-3BL,6BL,7BL,-25,7BLC-BT,STH-8BD,8BL,-25,8BLC-BT,-BTFC, STAGER SZ-21-1B(N),(NL),-3B(NL),-4B(NL),-5(N),(NL) SUNNUN DY-637,YU-740, SUNSTAR D-146BL,KM-340BL,380,390,590BL, |
| | BO-DBM(1)N 25.8 pai, 6 pai, 11mm*Nickel Finish. Hard*Large Capacity. | 2120314-321 B9117-201-000,20114 | TOYOTA AD324,D134H,324,530-130,-140, TREASURE BM-550 UNICORN DB2-H312,DY-H340,LS2-H540, WOEI RONG WR-5705 YAKUMO, NAKAJIMA 171L,178L,180L,LY,LY-2,181LY,280L,LY,LY-B,281LY,LY-B,321L,341L,381L,LY, 580L,680L,LY,LY-B,681,880L,LM,DBU-70L,175L,-1,-2,180L,-2,181LY, DBU-681LY,DNU-241H-4,-5,-6,DSN-80L,178L,-2,-3,DU-141H YASHIMA MW-90B YULUN YLM-340,350-22 |
| 21-6 | BO-DBM(2)N 25.8 pai, 6 pai, 11mm#Nickel Finish. Hard#with Cut. Large Capacity. | H-16 | ELTAC 800,900,1000,1250,1600,1800 series |
| 21-7 | BO-DBM(3)N 25.7 pai, 6 pai, 11mm#Nickel Finish. Hard#Large Capacity. | S01587-001 MG44B0123 | BROTHER DB2-B798,-300,TZ1-B798 GOLDEN WHEEL CS-350L-T MITSUBISHI DB-199-22,DY-339,-22,-22M,340-22BZ,349-22BZ,LY2-380-BIT,PLK-2520 |
| 21-8 | BO-DBM(4)N 25.8 pai, 6 pai, 5.5mm#Nickel Finish. Hard#Large Capacity. | W467883H01 | MITSUBISHI DB-325-22-D,327,DY-330-22-D,-337-2S |
| 22 | BO-DBM(A) 25.5 pai, 6 pai, 11mm#Aluminum#Large Capacity. | 137B,2130104-321 164-21802,100-80604 MB2,P413670 18358 | ATTILIO FORTE AF6LGE BARUDAN BEMR,BEMS,BEMX BUTTERFLY GY4-1 CHIKON CK-8BL-1,STH-8BL, CHIYODA LZ-301 CHUAN NENG CN-915-3,-5, CONSEW 175,R,176R EAGLE EA-106,206D,OS-2000 IDEAL 3,IE35872C, JUKI APW-192,193,231:244,235H,321,LH-570,571,LZ-1290,LZH-1290, MEISTERGRAMM M600XL,M700XL REFREY 905,1920,1922,1923,1925,1927, RESTA H220 G1,G2,G3,G4 SEIKO STH-8BLC |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|--|-----------------------|--|
| | | 239729 | SINGER 121C300,121C330AA,121D300,121D330AA,369,W,650E,1650E, |
| | | | SOTEXI PIK-PIK L2000 |
| | | MEC504000DBM,M10 | TAJIMA TMEF-H615,HC,TMEG-G914,XG920,TMFX-C901,TMLG TSM-30,LARGE TYPE, |
| | | | TAKING TK-8BL |
| | | 2130104-321 | TOYOTA AD320,D530,-E,-18E,-30P,-101,-110,-120,D532,D533,D534, |
| | | | TYPICAL GYD20-6 |
| | | | VI.BE.MAC 650/E,1650/E |
| | | | YAMAICHI Y&Y-800CNC |
| | | | YING LUN GY101-1 |
| 22-1 | BO-DBM(A)BR-H25.8 pai, 6 pai, 11mm#Aluminum Hard Finish#Large Capacity. | 159794-001 | BROTHER BAS-36,350 |
| | | 115120-000 | YAKUMO, NAKAJIMA 281L |
| 22-2 | BO-DBM(A)SN25.5 pai, 6.02 pai, 11mm#Aluminum#Large Capacity. | 239729 | SINGER 369W |
| 22-4 | BO-DBM(A)J25.8 pai, 6 pai, 11.1mm#Aluminum#Large Capacity. | D9117-141-E00 | JUKI DSU-145-4,-5 |
| 22-5 | BO-DBM(A)J2-H25.8 pai, 6 pai, 10.55mm#Aluminum Hard Finish#Large Capacity. | D1854-246-D00 | JUKI LS-246-4 |
| 23-2 | BO-DBL(1)N29.8 pai, 7.24 pai, 11.5mm#Nickel Finish. Hard | | SANSHIN SCZ11,14,23, |
| 24 | BO-PF13022 pai, 6 pai, 8.9mm#Nickel Plating. Hard | 069-00-580-0 | ADLER 69,-373,-FA-373,1296, |
| | | | ATTILIO FORTE AF6 |
| | | 17035 | CONSEW 277R,RFS, |
| | | 9033 | PFAFF 130,133,134,138,230,232,234,238,260,300,331,332,333,335,-H2, 337-734,341,343,360,430,432,433,434,437,438,439,461,-900, 462,-900,463,-900,464,-900,465,-900,466,-900,467,-900,468,-900, 469,-900,480,481,-900,482,-900,483,-900,484,-900,485,-900,486,-900, 487,-900,487NL,488,-900,489,-900,489NL,563NL,734,837,838,3516, 3518-481-900,-483-900,3541,3553,3557,3563,3565,3568,3571-483-900 |
| | | 17035 | SEIKO LSC-8B,BHC,BV,BVC, |
| | | | TAKING TK-335 |
| 24-2 | BO-PF130(A)22.1 pai, 5.9 pai, 8.9mm#Aluminum | 068-00-180-0,069-15-0 | ADLER 67,68,69,-FA-373,76,1296, |
| | | | ATTILIO FORTE AF6 |
| | | | IVOMAQ CI-2100-2AV |
| | | 168144 | PFAFF 232,234,260,300,331,332,333,341,343,360,430,432,433,434,437,438, 439,460,461,-900,462,-900,463,-900,464,-900,465,-900,466,-900, 467,-900,468,-900,469,-900,480,481,-900,482,-900,483,-900,484,-900, 485,-900,486,-900,487,-900,488,-900,489,-900,560,837,838, |
| | | | SEIKO HC-2B |
| | | | TAKING TK-335,N, |
| | | 168144 | ZSK 166M,167E,168/6E-8E,168M,169E,170E,171E,172,174 |
| 25 | BO-14437 pai, 6 pai, 13mm#Nickel Plating. Hard | B9117-057-000 | JUKI LG-57,-1,158,-1,LGG-777,-2,778,LT-59,591, |
| | | MP03B0123 | MITSUBISHI DU-103,108,123,128, |
| | | 70141 | SEIKO JW-8BL |
| | | 264645 | SINGER 144W,145W, |
| 26-2 | BO-1215MM(A)28 pai, 6 pai, 11.4mm#Aluminum#Large Capacity. | 155484-001 | BROTHER LS2-B872,LT2-B836,B882, CHIKON CK-563 |
| | | | EAGLE EA-156R,RB, |
| | | 102-31603 | GOLDEN WHEEL CS-3L7241,3L7243,563,875L, |
| | | 102-31603 | JUKI LH-527,1180-4,-5,1182,-4,-5,3178,-7,3188,-7,LUH-520,521,526,527, |
| | | 36216 | SEIKO LPW-6BLC,26BLC, |
| | | | SHANG GONG GD8-7 |
| | | | SICAMA SC-1182-5,-6, |
| | | 417268 | SINGER 211U566JA,211U567JB |
| | | | YAKUMO, NAKAJIMA 242L |
| 26-2-1 | BO-1215MM(A)-H28 pai, 6 pai, 11.4mm#Aluminum Hard Finish#Large Capacity. | S09285-001 | BROTHER BAS-610,611,LS2-B872-400,B875,-403,-405,-407,-903,-905, SUNSTAR KM-790-7BL,813-817 |
| 26-3 | BO-1215MM-N28 pai, 6 pai, 11.8mm#Nickel Plating. Hard#Large Capacity. | 16408 | ABLE LT2-220BF CONSEW 327RB,-1,328RB,-1,RBATC |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|---|-------------------------|---|
| | | B9117-563-000 | GOLDEN WHEEL CS-871L,872-3,872L,3100-3,L,3150L, JUKI LH-513,1180,3178,-7,3188,-7,LU-563,-3, |
| | | MN12B0123 | MILLION SPECIAL MS-B872,B875, mitsubishi DN-260-22,262,265-22,267,275-20,A, DU-100-22,102,105-22,107,120-22,122,125-22,127 LT2-220-B,BO,BOB,240-B,BOA,BOB,246-BOA,BOB, LT2-2220-B,BO,BOB,2240-B,BOB, LU2-400-B,BO,BOB,402-BOB,420-BO,4420,4440, |
| | BO-1215MM-N 28 pai, 6 pai, 11.8mm#Nickel Plating. Hard#Large Capacity. | 16408 | NITAKA TC2-B872,-3,-5,B875,B935,B1685,B1885 SEIKO LLPW-1L,LPW-27BLK,28BLK, LSW-26BL-R,L-R,6L-G,7L-G,27BLC,-BT,-BTFL,27BLK,BLKC,-BT,-BTFL, LSW-28BLC,-BT,-BTFL,28BLK,BLKC,-BT,-BTFL, |
| | | 510007 | SICAMA LT2-B872,B875, SINGER 211G566,A,G866A,867A SUNSTAR KM-560,740,KM2-740,BL, TAKING TK-872-3,-5,875-3,-5, UNICORN LT2-H240-BOB,H322,H323, 11200L YAKUMO, NAKAJIMA 241L,480L,481L,482L, |
| 26-4 | BO-1215MM-N-SN 28 pai, 6 pai, 11.8mm#Nickel Plating. Hard#Large Capacity. | 510007 | SINGER 211G456,539,541,539,541,557,558,211GX104,106,109,114,117, 211U539A,566,A,KA,211U567A,B,866,867,211UX566,212G539,541, 212GX2,106,114,212U143,539A,541,A,543,A,AG, 212U544,566,839,841,843,A,841A, |
| 26-5 | BO-B872(A) 28 pai, 6 pai, 11.4mm#Aluminum#Large Capacity. | 155484-101 MN74A0123 | BROTHER LT2-B836,-3,B872,-3,-5,-403,-405,-903,-905,B875,-3,-5,-7,BAS-612 MITSUBISHI LT2-230-B,B1T,2230-B1T, SUNSTAR KM-750-7BL,790-BL, |
| 27 | BO-LKB(A) 20.7 pai, 6.2 pai, 11.8mm#Aluminum | 145265-001 | BROTHER BAS-330,LK3-B220,B221,B222,B223,B431,B432,B433,B434,B826,B827,B828, LK3-B434 |
| 27-2 | BO-LKB(A) -220.7 pai, 6.2 pai, 11.8mm#Aluminum#with Cut (Both Side)#for Heavy Thread w | 154663-001 MS01A0123 | BROTHER PLK-0303,03BTA,HS,0604,0804,08HSW,109, MITSUBISHI |
| 27-3 | BO-LKJ(A) 20.7 pai, 6.2 pai, 11.8mm#Aluminum | B1827-280-000 | JUKI ACF-161-981,AMS-12A,206CGL,210,A,CGL,212CGL, AMS-220,CGL,222BG,224,BG,229BG, LK-232,237,239,280,282,283,284,287,289,291,322,980,981,982,987-510,1850, 418046 SINGER 469U ALL,569U, |
| | BO-LKJ(A)2)H | 138-12102 | JUKI AMC-206C,LK-992-82,1851-555, |
| 27-4 | BO-LKB(A) -H20.7 pai, 6.2 pai, 12.1mm#Aluminum Hard Finish | 159613-001 | BROTHER BAS-303,310,311,320,321,322,325,326,555, LK3-B430-1,-2,-3,-4,-5,-6,-7,-8,-9,B435,B436,B438,-2,-4,B441,B826,B828, |
| 28 | DB-MTB 21.2 pai, 6 pai, 9.2mm#Black Finish. Hard | | for 613 DB-MT Bobbin Case with Oil Tank |
| 29 | BO-DB2002 21.2 pai, 6 pai, 8.8mm#Black Finish. Hard | | for 614 DB-SENSOR Bobbin Case |
| 30 | BO-LK2102 0.65 pai, 6 pai, 11.8mm#Black Finish. Hard | | for 512 LK-SENSOR Bobbin Case |
| 31-2 | BO-1215L(A) 29 pai, 6 pai, 11.8mm#Aluminum#Large Capacity. | 156380-001 34315 | BROTHER LS2-B837,-5, SEIKO LSW- 7 BLC,-BT,-BTFL,8BL/CS,BL/CS/TA,8BLC/CS, LSW-8BLC-BT,-BTFL,8BLMC,8LC(N)-BTFL SINGER 211A |
| 31-3 | BO-1215L-N 29 pai, 6 pai, 12.4mm#Nickel Plating. Hard#Large Capacity. | 150971-001 15041 | BROTHER LS2-B837,-5,LT2-B837,-300,B838,-5, CONSEW 244 CLASS,254 CLASS,255 CLASS,255RBATC,282RB, 289RB,333 CLASS,339 CLASS,388 CLASS,389RB, EAGLE EA-256RB,2156RB 103-54009 JUKI LH-1172-5 PRINCE PLM-100 15041 SEIKO LLW-7B,BL(-TA),L(-TA),8BL(-TA),L(-TA),27BL(-TA),L(-TA),28,BL,-TA,L,-TA, LPW-6BL,L,7BL,L,8BL,L,26BL,L,27BL,L,28BL,L, LSW-6L,7BL(-T),L(-T),LSW-8BL(-T),BLC,BLM,BLV LSW-8BLVMF,BLVP,BLVPM,C,L(-T),L,C,L,G,L,M,LV,LVMF LSW-8LVP,LVPM,26BL,L,LH,27BL,BLM,L,28BL,L,LTW-27BLM, 2121404-321A TOYOTA AD331L,LP(-12),332L,LP(-1,2),D330, |
| 31-4 | BO-1215L(A)J-H 29 pai, 6 pai, 11.8mm#Aluminum Hard Finish#Large Capacity. | 103-53605 | JUKI LH-1114,1172,LU-1114,-4,-5, |

| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
|---------|--|-------------------|--|
| 32 | BO-6620.65 pai, 6.2 pai, 10.8mm#Nickel Plating. Hard | 32522,5810,172222 | SINGER 66,68,99,101 & 102, |
| 34 | BO-1720.25 pai, 5.75 pai, 9mm#Nickel Plating. Hard | | ADLER 48 |
| | | B9117-130-000 | JUKI LS-130 |
| | | 8096 | SEIKO TE-2,S,5,B,6,B,TF-5,B,6,B, |
| | | 2073 | SINGER 17,-30,-41,-42,-241,-242,17U130,141,241,242, 18,18U,122,222,322,68-1 to 38,69-16 |
| | | | SUNSTAR KM-18 |
| 35 | BO-13234.6 pai, 7.05 pai, 15.25mm#Nickel Plating. Hard | | ADLER 265 |
| | | | JUKI LGS-87 |
| | | MG23C0123 | mitsubishi DY-253,-00,LY2-300-COB, |
| | | | NEW LONG DD-5 |
| | | CS1441 | SEIKO SK-2B,6,F,F-1,F-20,7,8,SKM-26,36, |
| | | 97949 | SINGER 132B,K,R,133K,12:15,17,18, |
| 38 | BO-4520.2 pai, 6 pai, 31.2mm#Nickel Plating. Hard | 005-00-242-0 | ADLER 4,5,104,105,165,166, |
| | | | DURKOPP 61,62,630,631,632,633,640,641,642,643,644,OP, |
| | | | NEW LONG DD-3,6 |
| | | 95093 | SINGER 45K |
| | | 102062-000 | YAKUMO, NAKAJIMA DD-N73,DDN-738,DDU-N73, |
| 39 | BO-29L20 pai, 5.8 pai, 7.8mm#Nickel Plating. Hard | 82552,HA46083 | SINGER 29-30,29K72,29U171,172,A, |
| 40 | BO-1215MM(A)M28 pai, 6 pai, 11mm#Aluminum | MN52A0123 | MITSUBISHI DN-269-20,DU-400,LT2-230-B,B1T,250-A,A1T,B,B1T LT2-250-B1AT,2230-B,B1T,2250-A,A1T,B,B1T, LU2-410,B1T,420-BOB,430,B,B1T,4410-B,B1T, LU2-4430-B,B1T,PLY-501F,1185,7181,7182,PLY-7202,7206,E |
| 41 | BO-PF54128 pai, 6 pai, 11.3mm#Nickel Plating. Hard | | DIAMOND TB-545,546,1245,L,1246, |
| | | | JUKI LS-341 |
| | | | MILLION SPECIAL MS-1245 |
| | | 14356,18339,18480 | PFAFF 541,542,543,544,-720,546,551,552,553,554,555,591,592,593,594,595, 596,720,748,1240,1241,1242,-720,-720(-900),-748,1243, 1244,-720,-748,-900,1245,1246,-720,748,-900, |
| | | | TAKING TK-545,546,1245,1246, |
| | | | WOEI RONG WR-810,820, |
| | | | YULUN YLM-545,546,810-G,820-G,1245,1246, |
| 44 | BO-HUSQ21.2 pai, 6 pai, 9.2mm#Nickel Plating. Hard | HUSQVERNER | HUSQVERNER 27,263 |
| 45-1 | BO-TSS124(A)20.67 pai, 6.16 pai, 11.8mm#Aluminum | 2130904-320 | TOYOTA AC-1007,1009,1011,1041, |
| 45-2 | BO-TSS125(A)21.2 pai, 6 pai, 9.2mm#Aluminum | 2111604-320A | TOYOTA AD1000,1010,1012G,1020,1200,1202K,V,1203V,2000,3000,3050,4000, |
| 45-3 | BO-TSS126(A)21.2 pai, 6 pai, 9.2mm#Aluminum | 2111614-320 | TOYOTA AD1000,1012,1013, |
| 45-4 | BO-TSS134(A)25.5 pai, 6 pai, 11mm#Aluminum | 2122804-320A | TOYOTA AD320-22,-662,3200, |
| 45-5 | BO-TSS196(A)29 pai, 6 pai, 12.4mm#Aluminum | 2122704-320A | TOYOTA AD3300 |
| 47 | BO-B484(A)-H30.2 pai, 7.5 pai, 11.7mm#Aluminum Hard Finish#Large Capacity. | S00693-001 | BROTHER DS112T-2,LK3-B484,B485,B486, |
| 47-1 | BO-B48430 pai, 7.5 pai, 11.7mm#Nickel Plating. Hard | S00871-001 | BROTHER LK3-B484,B485,B486, |
| 48 | BO-HZL88021 pai, 6 pai, 9.2mm#Nickel Plating. Soft | A9117-880-000 | JUKI HZL-8800 |

| (5) TENSION GAUGE | | | |
|-------------------|--|---------------|---------------------------------|
| ITEM NO | ARTICLE | REFERENCE NO. | SUMMARY |
| | TM-1for Household -Rotating- Type#for Industrial -Use Rotating- Type | | BC-HR etc. |
| | | | BC-DB1, BC-DBZ Type etc. |
| | TM-2for Household -CB- Type | | BC-HA1, BC-HZ Type etc. |
| | TM-3for Industrial Use Large Type | | BC-DBM etc. |
| | TM-4for PFAFF Type | | BC-PF9076 ect. |
| | TM-5for Industrial Use -CB- Type | | BC-269, BC-LK(B), BC-LK(J) etc. |
| | TM-6for Industrial Use Special Type | | BC-107, BC-457, BC-LBH Type |

Weight List

| ID | ITEM NO | | 1 pcs | 50 pcs | TENSION SPRING | NBL SPRING | LATCH SPRING | LATCH COMPLETE | TENSION SPRING REGULATING SCREW | TENSION SPRING SCREW | LATCH STOP SCREW | EXTRA PART | |
|----|---------|----------------|-------|--------|----------------|------------|--------------|----------------|---------------------------------|----------------------|------------------|------------|--|
| 1 | 101 | BC-HA1 | 12.3 | 675 | 15278 | | 2975 | 15141T | 591 | | | | |
| 2 | 102 | BC-HA1(NS) | 12.3 | 675 | TSP-102 | | 2975 | 15141T | 591 | | | | |
| 3 | 103 | BC-HA1(G) | 12.3 | 675 | 15278 | | 2975 | 15141T | 591 | | | | |
| 4 | 105 | BC-15-88 | 12.3 | 675 | 125293 | | 2975 | 15141T | 591 | | | | |
| 5 | 106 | BC-HA1(JNS) | 12.3 | 675 | TSP-108 | | 2975 | 125288T | 591 | | | | |
| 6 | 107 | BC-19-9 | 12.7 | 695 | TSP-111 | | LSP-5 | LC-110-A | 591 | | | | |
| 7 | 203 | BC-HZ3(NS) | 12.3 | 675 | TSP-102 | | 2975 | 15141T | 591 | | | | |
| 8 | 203NBL | BC-HZ3(NS)-NBL | 12.3 | 675 | TSP-102 | NBL-101 | 2975 | 15141T | 591 | | | | |
| 9 | 203AL | BC-HZ3(NS)-AL | 12.3 | 675 | TSP-102 | | 2975 | 15141AL | 591 | | 592 | | |
| 10 | 203-1 | BC-HZ3(NS)-B | 12.3 | 675 | TSP-102B | | 2975 | LC-104C | | | | | |
| 11 | 204 | BC-HZ4(NS) | 12.3 | 675 | TSP-102 | | 2975 | 15141T | 591 | | | | |
| 12 | 205 | BC-HZ5 | 12.3 | 675 | 15278 | | 2975 | 15141T | 591 | | | | |
| 13 | 206 | BC-HZ6 | 12.3 | 675 | 15278 | | 2975 | 15141T | 591 | | | | |
| 14 | 207 | BC-HZ7 | 12.3 | 675 | TSP-104 | | 2975 | 15141T | 591 | | | | |
| 15 | 208 | BC-HZ8 | 12.3 | 675 | TSP-104 | | 2975 | 15141T | 591 | | | | |
| 16 | 208NBL | BC-HZ8-NBL | 12.3 | 675 | TSP-104 | NBL-101 | 2975 | 15141T | 591 | | | | |
| 17 | 210 | BC-HZ10 | 12 | 660 | TSP-104 | | 2975 | 15141T | 591 | | | | |
| 18 | 211 | BC-NE | 12.3 | 675 | 20178 | | 2975 | 15141T | 591 | | | | |
| 19 | 213 | BC-VIK | 10.7 | 595 | TSP-901-B | | 2975 | LC-901 | 591 | SMS-105 | 592 | | |
| 20 | 214 | BC-HZ11 | 12 | 660 | TSP-104 | | 2975 | 15141T | 591 | | | | |
| 21 | 215 | BC-HZ4(NS)-J | 12.3 | 675 | TSP-102 | | 2975 | 15141T | 591 | | | | |
| 22 | 301 | BC-HR206 | 9.8 | 541 | 105035 | | 2975 | 40393T | 591 | 1380 | 592 | | |
| 23 | 302 | BC-HR306 | 10 | 551 | 105035 | | 2975 | 40393T | 591 | 1380 | 592 | | |
| 24 | 303 | BC-HR221 | 9 | 622 | 45789 | | LSP-3 | 40393T | 201016 | 200592 | 200964 | | |
| 25 | 304 | BC-HR1 | 8.6 | 481 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | |
| 26 | 304AL | BC-HR1-AL | 8.6 | 481 | 40394NS | | 2975 | 40393AL | 591 | 1380 | 592 | | |
| 27 | 305 | BC-HR2 | 9.9 | 546 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | |
| 28 | 306 | BC-HR3 | 8.8 | 491 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | |
| 29 | 307 | BC-HR4 | 8.8 | 491 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | |
| 30 | 307NBL6 | BC-HR4-NBL6 | 8.8 | 491 | 40394NS | NBL-406 | 2975 | 40393T | 591 | 1380 | | | |
| 31 | 308NBL9 | BC-HR4-NBL9 | 9 | 622 | 40394NS | NBL-409 | 2975 | 40393T | 591 | 1380 | | | |
| 32 | 401 | LC-27 | 13.6 | 731 | 8326 | | | | 215 | | | | |
| 33 | 402 | LS-28 | 13.6 | 731 | 8326 | | | | 215 | | | | |
| 34 | 403 | LS-COMBI | 13.6 | 731 | 8326 | | | | 215 | | | | |
| | B-1 | B-221 | | | | | | | | | | | |
| | H-1 | H-221 | | | | | | | | | | | |
| | B-2 | B-301 | | | | | | | | | | | |
| | H-2 | H-301 | | | | | | | | | | | |
| 39 | S-101 | SBC-66 | 13.3 | 837 | 32567 | | | | 1172 | 1173 | | | |
| 40 | S-102 | SBC-400 | 13 | 822 | 172202 | | | | 1172 | 1173 | | | |
| 41 | 501 | BC-71(1) | 12.3 | 675 | 15278 | | 2975 | 15141T | 591 | | | | |
| 42 | 501NBL | BC-71(1)-NBL | 12.3 | 675 | 15278 | NBL-101 | 2975 | 15141T | 591 | | | | |
| 43 | 502 | BC-71(2) | 12.3 | 675 | 15278 | | 2975 | 15141T | 591 | | | | |
| 44 | 502NBL | BC-71(2)-NBL | 12.3 | 675 | 15278 | NBL-101 | 2975 | 15141T | 591 | | | | |
| 45 | 502-1 | BC-71(2)-1 | 12.3 | 675 | 15278 | | 2975 | 15141T | 591 | | | | |

Weight List

| ID | ITEM NO | | 1 pcs | 50 pcs | TENSION SPRING | NBL SPRING | LATCH SPRING | LATCH COMPLETE | TENSION SPRING REGULATING SCREW | TENSION SPRING SCREW | LATCH STOP SCREW | EXTRA PART | |
|----|----------|----------------|-------|--------|----------------|------------|--------------|----------------|---------------------------------|----------------------|------------------|-----------------------------|----------------------|
| 46 | 502-2 | BC-71-101 | 12.5 | 661 | 15278 | | 2975 | LC-111 | 591 | | | | |
| 47 | 502-3 | BC-71(3) | 12.3 | 675 | TSP-108 | | 2975 | 15141T | 591 | | | | |
| 48 | 503 | BC-269 | 12.3 | 675 | 15278 | | 2975 | 15141T | 591 | | | | |
| 49 | 503NBL | BC-269-NBL | 12.3 | 675 | 15278 | NBL-101 | 2975 | 15141T | 591 | | | | |
| 50 | 503M2 | BC-269-M2 | 12.3 | 675 | 15278 | | 2975 | 15141T | 591 | | | | |
| 51 | 504 | BC-31-15 | 12.2 | 670 | 15278 | | 2975 | 15141T | 591 | | | | |
| 52 | 504-2 | BC-431 | 12.2 | 670 | TSP-102 | | 2975 | 15141T | 591 | | | | |
| 53 | 505 | BC-68 | 12.2 | 670 | 15278 | | 2975 | 15141T | 591 | | | | |
| 54 | 505-2 | BC-68-2 | 12.2 | 670 | 15278 | | 2975 | 15141T | 591 | | | | |
| 55 | 506 | BC-69 | 12.3 | 675 | 15278 | | 2975 | 15141T | 591 | | | | |
| 56 | 507 | BC-78 | 12.2 | 670 | 15278 | | 2975 | 15141T | 591 | | | | |
| 57 | 508 | BC-31-20 | 12.7 | 695 | 20654 | | 2975 | 20650 | 591 | | 592 | | |
| 58 | 509 | BC-12 | 12 | 660 | 204531 | | | | 200598 | 200592 | | | |
| 59 | 510 | BC-LK(B) | 12.3 | 675 | TSP-104 | | 2975 | 15141T | 591 | | | | |
| 60 | 510NBL | BC-LK(B)-NBL | 12.3 | 675 | TSP-104 | NBL-101 | 2975 | 15141T | 591 | | | | |
| 61 | 510-2 | BC-LK(B2) | 12.3 | 675 | TSP-102 | NBL-101 | 2975 | 15141T | 591 | | | | |
| 62 | 510-3 | BC-LK(B3) | 12.3 | 675 | TSP-102 | NBL-101 | 2975 | 15141T | 591 | | 592 | | |
| 63 | 511 | BC-LK(J) | 12.3 | 675 | 15278 | | 2975 | 15141T | 591 | | | | |
| 64 | 511NBL | BC-LK(J)-NBL | 12.3 | 675 | 15278 | NBL-101 | 2975 | 15141T | 591 | | | | |
| 65 | 511-2 | BC-LK(J2) | 12.3 | 675 | 15278 | | 2975 | 15141T | 591 | | | | |
| 66 | 511-3 | BC-LK(J3) | 12.3 | 675 | 15278 | | 2975 | 15141T | 591 | | | | |
| 67 | 511-4 | BC-LK(J4) | 12.3 | 675 | 15278 | NBL-101 | 2975 | 15141T | 591 | | | | |
| 68 | 511-5 | BC-LK(J5) | 12.3 | 675 | 15278 | NBL-101 | 2975 | 15141T | 591 | | | | |
| 69 | 512 | LK-CENSOR | 12.7 | 695 | TSP-102 | | 2975 | LC-109 | 591 | | 592 | | |
| 70 | 601 | BC-DB1 | 9.7 | 536 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | |
| 71 | 601NBL1 | BC-DB1-NBL1 | 9.7 | 536 | 40394NS | NBL-401 | 2975 | 40393T | 591 | 1380 | | | |
| 72 | 601NBL2 | BC-DB1-NBL2 | 9.7 | 536 | 40394NS | NBL-402 | 2975 | 40393T | 591 | 1380 | | | |
| 73 | 601NBL6 | BC-DB1-NBL6 | 9.7 | 536 | 40394NS | NBL-406 | 2975 | 40393T | 591 | 1380 | | | |
| 74 | 601NBL17 | BC-DB1-NBL17 | 9.7 | 536 | 40394NS | NBL-417 | 2975 | 40393T | 591 | 1380 | | | |
| 75 | 601M | BC-DB1-M | 9.7 | 536 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | |
| 76 | 601M-1 | BC-DB1-ML | 9.7 | 536 | 40394NS | | 2975 | | | | | | |
| 77 | 601M-2 | BC-DB1-M2 | 9.7 | 536 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | |
| 78 | 601-2 | BC-DB1-WH | 9.7 | 536 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | |
| 79 | 601-3 | BC-DB1-J | 9.7 | 536 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | |
| 80 | 604 | BC-251 | 9.5 | 526 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | |
| 81 | 604NBL | BC-251-NBL | 9.5 | 526 | 40394NS | NBL-404 | 2975 | 40393T | 591 | 1380 | | | |
| 82 | 604M | BC-251-M | 9.5 | 526 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | |
| 83 | 605 | BC-402 | 9.5 | 526 | 40394NS | | 2975 | 40393 | 591 | 1380 | 592 | | |
| 84 | 605NBL | BC-402-NBL | 9.5 | 526 | 40394NS | NBL-404 | 2975 | 40393 | 591 | 1380 | 592 | | |
| 85 | 606 | BC-DLN | 9.5 | 526 | 40394NS | | 2975 | 40393T | 591 | 1380 | | NBL SPRING REGULATING SCREW | NBL SPRING SET SCREW |
| 86 | 606NBL | BC-DLN-NBL | 9.5 | 526 | 40394NS | NBL-404 | 2975 | 40393T | 591 | 1380 | | | |
| 87 | 608 | BC-281(SS) | 9.7 | 536 | 40394NS | 143391 | 2975 | 40393T | 591 | 1380 | | 350963 | 350964 |
| 88 | 609 | BC-DBZ(1) | 8.8 | 491 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | |
| 89 | 609NBL6 | BC-DBZ(1)-NBL6 | 8.8 | 491 | 40394NS | NBL-406 | 2975 | 40393T | 591 | 1380 | | | |
| 90 | 609NBL9 | BC-DBZ(1)-NBL9 | 8.8 | 491 | 40394NS | NBL-409 | 2975 | 40393T | 591 | 1380 | | | |

| ID | ITEM NO | | 1 pcs | 50 pcs | TENSION SPRING | NBL SPRING | LATCH SPRING | LATCH COMPLETE | TENSION SPRING REGULATING SCREW | TENSION SPRING SCREW | LATCH STOP SCREW | EXTRA PART | | |
|-----|---------|----------------|-------|--------|----------------|------------|--------------|----------------|---------------------------------|----------------------|-------------------------|-------------------------------|-----------------------------|---------------------------|
| | | | | | | | | | | | | NBL SPRING SET SCREW | THREAD GUIDE EYELET | THREAD GUIDE EYELET SCREW |
| 91 | 609-1 | BC-DBZ(C) | 8.8 | 491 | 40394NS | | 2975 | 40393T | 591 | 1380 | | NBL SPRING SET SCREW | | |
| 92 | 610 | BC-DBZ(2) | 9.5 | 526 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | | |
| 93 | 611 | BC-770 | 9.3 | 516 | 40394OS | 143391 | 2975 | 40393 | 591 | 1380 | | 350964 | | |
| 94 | 611-1 | BC-770-NBL | 9.3 | 516 | 40394OS | NBL-401 | 2975 | 40393 | 591 | 1380 | | | | |
| 95 | 612 | BC-241 | 9.7 | 536 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | | |
| 96 | 612NBL | BC-241-NBL | 9.7 | 536 | 40394NS | NBL-406 | 2975 | 40393T | 591 | 1380 | | | | |
| 97 | 612M | BC-241-M | 9.7 | 536 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | | |
| 98 | 613 | DB-MT | 9.8 | 541 | 40394NS | NBL-403 | 2975 | 40393 | 591 | 1380 | 592 | | | |
| 99 | 614 | DB-CENSOR | 10.2 | 570 | 40394NS | | 2975 | LC-406-B | 591 | 1380 | 592 | | | |
| 100 | 615 | BC-DBZ(3) | 8.8 | 491 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | | |
| 101 | 615NBL6 | BC-DBZ(3)-NBL6 | 8.8 | 491 | 40394NS | NBL-406 | 2975 | 40393T | 591 | 1380 | | THREAD GUIDE EYELET | THREAD GUIDE EYELET SCREW | |
| 102 | 615NBL9 | BC-DBZ(3)-NBL9 | 8.8 | 491 | 40394NS | NBL-409 | 2975 | 40393T | 591 | 1380 | | | | |
| 103 | 616 | BC-AD396 | 9.5 | 526 | 40394NS | | 2975 | 40393T | 591 | 1380 | | STL-407 | SMS-202 | |
| 104 | 616NBL6 | BC-AD396-NBL6 | 9.5 | 526 | 40394NS | NBL-406 | 2975 | 40393T | 591 | 1380 | | STL-407 | SMS-202 | |
| 105 | 617 | BC-DBZ(4) | 8.8 | 491 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | | |
| 106 | 618 | BC-ALFA109 | 9.5 | 526 | TSP-405 | | 2975 | 40393 | 591 | 1380 | | | | |
| 107 | 619 | BC-NJ380 | 9.5 | 526 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | | |
| 108 | 619NBL6 | BC-NJ380-NBL6 | 9.7 | 536 | 40394NS | NBL-406 | 2975 | 40393T | 591 | 1380 | | | | |
| 109 | 620 | BC-DBZ(5) | 9.3 | 516 | 40394NS | | 2975 | 40393T | 591 | 1380 | | | | |
| 110 | 701 | BC-107(1) | 12 | 772 | 210845 | | 210736 | 210914 | 201016 | 200592 | 200964 | | | |
| 111 | 701NBL | BC-107(1)-NBL | 12 | 772 | 210845 | NBL-603 | 210736 | 210914 | 201016 | 200592 | 200964 | | | |
| 112 | 702 | BC-107(2) | 12 | 772 | 263110 | | 210736 | 210914 | 201016 | 200592 | 200964 | | | |
| 113 | 702NBL | BC-107(2)-NBL | 12 | 772 | 263110 | NBL-603 | 210736 | 210914 | 201016 | 200592 | 200964 | | | |
| 114 | 702M | BC-107(2)-M | 13.9 | 745 | 263110 | | 210736 | 210914 | 201016 | 200592 | 200964 | | | |
| 115 | 704 | BC-102 | 13.1 | 827 | 224421 | | 210736 | 210914 | 201016 | 200592 | 200964 | | | |
| 116 | 704NBL | BC-102-NBL | 13.1 | 827 | 224421 | NBL-603 | 210736 | 210914 | 201016 | 200592 | 200964 | | | |
| 117 | 705 | BC-457 | 11.8 | 762 | 271964 | | 210736 | 502529 | 201016 | 200592 | 200964 | | | |
| 118 | 705-1 | BC-457(NS) | 11.8 | 762 | 271964 | | 210736 | 502529 | 201016 | 200592 | 200964 | | | |
| 119 | 705NBL | BC-457-NBL | 11.8 | 762 | 271964 | NBL-603 | 210736 | 502529 | 201016 | 200592 | 200964 | | | |
| 120 | 705M | BC-457-M | 13.9 | 745 | 106426 | | 210736 | 502529 | 201016 | 200592 | 200964 | | | |
| 121 | 706 | BC-271 | 12 | 772 | 106426 | | 210736 | 271787 | 201016 | 200592 | 200964 | | | |
| 122 | 706NBL | BC-271-NBL | 12 | 772 | 106426 | NBL-603 | 210736 | 271787 | 201016 | 200592 | 200964 | | | |
| 123 | 706-2 | BC-271-2 | 12 | 772 | 106426 | | 210736 | 271787 | 201016 | 200592 | 200964 | | | |
| 124 | 710 | BC-LBH771 | 12 | 772 | 263110 | | 210736 | 210914 | 201016 | 200592 | 200964 | | | |
| 125 | 710NBL | BC-LBH771-NBL | 12 | 772 | 263110 | NBL-603 | 210736 | 210914 | 201016 | 200592 | 200964 | | | |
| 126 | 713 | BC-LBH790 | 14.5 | 897 | 271964 | NBL-604 | 210736 | 502529 | SMS-608 | SMS-609 | 200964 | OILLING FELT RETAINER | OILLING FELT RETAINER SCREW | OILLING FELT |
| 127 | C-1 | CP-51 | 8 | 572 | 235771 | | | | 200984 | 200594 | | | | |
| 128 | C-1F | CP-51F | 8.2 | 582 | 235771 | | | | 200984 | 200594 | | 241675 | 350405 | 241674 |
| 129 | C-3 | CP-212 | 8.6 | 602 | 512600 | | | | 200984 | 200594 | | | | |
| 130 | C-4 | CP-212BIG | 11.7 | 757 | 512600 | | | | 200984 | 200594 | | | | |
| 131 | S-1A | S-29A | 5.2 | 320 | 8611 | | | | 662F | | | CARRIER SPRING | CARRIER SPRING SCREW | |
| 132 | S-1B | S-29B | 5.2 | 320 | 81876 | | | | 662F | | | | | |
| 133 | CA-1 | CA-29 | 5.3 | 325 | | | | | 662F | | | 8610 | 241D | |
| | | | | | | | | | | | BOBBIN RETAINING SPRING | BOBBIN RETAINING SPRING SCREW | THREAD PULL-OFF | PULL-OFF SCREW |

| ID | ITEM NO | | 1 pcs | 50 pcs | TENSION SPRING | NBL SPRING | LATCH SPRING | LATCH COMPLETE | TENSION SPRING REGULATING SCREW | TENSION SPRING SCREW | LATCH STOP SCREW | EXTRA PART | | |
|-----|-----------|--------------------|-------|--------|----------------|------------|--------------|----------------|---------------------------------|----------------------|------------------|----------------------|-------|------|
| 134 | S-2 | S-29L | 10.8 | 600 | 81994 | | | | 132D | | 7868 | 133D | 81951 | 404D |
| 135 | CA-2 | CA-29L | 9 | 510 | | | | | | | | | | |
| 136 | 801 | BC-DBM(1) | 15.5 | 688 | TSP-1305 | | 210736 | LC-1305 | 591L | 1380L | LATCH STOP SCREW | | | |
| 137 | 801NBL1 | BC-DBM(1)-NBL1 | 15.5 | 688 | TSP-1305 | NBL-1301 | 210736 | LC-1305 | 591L | 1380L | | | | |
| 138 | 801NBL2 | BC-DBM(1)-NBL2 | 15.5 | 688 | TSP-1305 | NBL-1302 | 210736 | LC-1305 | 591L | 1380L | 592 | | | |
| 139 | 801NBL3 | BC-DBM(1)-NBL3 | 15.5 | 688 | TSP-1305 | NBL-1303 | 210736 | LC-1305 | 591L | 1380L | | | | |
| 140 | 801NBL3-1 | BC-DBM(1)-NBL3-HV | 15.5 | 688 | TSP-1310 | NBL-1303 | 210736 | LC-1305 | 591L | 1380L | | | | |
| 141 | 802 | BC-DBM(Z1) | 15 | 670 | TSP-1305 | | 210736 | LC-1305 | 591L | 1380L | | | | |
| 142 | 802NBL3 | BC-DBM(Z1)-NBL3 | 15 | 670 | TSP-1305 | NBL-1303 | 210736 | LC-1305 | 591L | 1380L | | | | |
| 143 | 803 | BC-DBM(Z2) | 14 | 635 | TSP-1305 | | 210736 | LC-1305 | 591L | 1380L | | | | |
| 144 | 803NBL2 | BC-DBM(Z2)-NBL2 | 14 | 635 | TSP-1305 | NBL-1302 | 210736 | LC-1305 | 591L | 1380L | | | | |
| 145 | 804 | BC-DBL(1) | 19.3 | 820 | TSP-1303 | | 210736 | LC-1305 | 591L | 1380L | | | | |
| 146 | 805 | BC-GELLMAN | 37.5 | 1485 | 5935 | | LSP-6 | LC-1201 | 591L | | | | | |
| 147 | 806NBL1 | BC-DBM(2)-NBL1 | 15.5 | 688 | TSP-1301 | NBL-1301 | 210736 | LC-1305 | 591L | 1380L | | | | |
| 148 | 807 | BC-DBM(3) | 15.5 | 688 | TSP-1305 | | 210736 | LC-1305 | 591L | 1380L | | | | |
| 149 | 807NBL2 | BC-DBM(3)-NBL2 | 15.5 | 688 | TSP-1305 | NBL-1302 | 210736 | LC-1305 | 591L | 1380L | | | | |
| 150 | 809NBL3 | BC-DBM(4)-NBL3 | 15.5 | 688 | TSP-1309 | NBL-1303 | 210736 | LC-1305 | 591L | 1380L | | | | |
| 151 | 810NBL4 | BC-DBM(5)-NBL4 | 15.5 | 688 | TSP-1301 | NBL-1304 | 210736 | LC-1305 | 591L | 1380L | | | | |
| 152 | 811NBL3 | BC-NJ280-NBL3 | 15.5 | 688 | TSP-1305 | NBL-1303 | 210736 | LC-1305 | 591L | 1380L | | | | |
| 153 | 812NBL3 | BC-NJ280L-NBL3 | 15.5 | 688 | TSP-1305 | NBL-1303 | 210736 | LC-1305 | 591L | 1380L | | | | |
| 154 | 813NBL3 | BC-DBM(AD)-NBL3 | 15.5 | 688 | TSP-1305 | NBL-1303 | 210736 | LC-1305 | 591L | 1380L | | | | |
| 155 | 901 | BC-PF24423 | 12.3 | 675 | 6892 | | 2134 | 6847T | 250 | | | | | |
| 156 | 901NBL | BC-PF244-NBL | 12.3 | 675 | 6892 | NBL-101 | 2134 | 6847T | 250 | | | | | |
| 157 | 902 | BC-PF9266 | 9.5 | 525 | 9026 | | 2134 | 9048 | 250 | 390 | | | | |
| 158 | 903 | BC-PF9076 | 9.3 | 516 | 9026 | | 2134 | 9048 | 250 | 390 | | | | |
| 159 | 903NBL | BC-PF9076-NBL | 9.3 | 516 | 9026 | NBL-806 | 2134 | 9048 | 250 | 390 | | | | |
| 160 | 903M | BC-PF9076-M | 9.3 | 516 | 9026 | | 2134 | 9048 | 250 | 390 | | | | |
| 161 | 905 | BC-PF9076(14) | 8.8 | 491 | 9026 | | 2134 | 9048 | 250 | 390 | | | | |
| 162 | 905NBL6 | BC-PF9076(14)-NBL | 8.9 | 492 | 9026 | NBL-806 | 2134 | LC-804 | 250 | 390 | | | | |
| 163 | 906 | BC-PF69672 | 9.3 | 516 | 9026 | | 2134 | 9048 | 250 | 390 | | | | |
| 164 | 906NBL | BC-PF696-NBL | 9.3 | 516 | 9026 | NBL-806 | 2134 | 9048 | 250 | 390 | | | | |
| 165 | 908 | BC-PF3114 | 11.5 | 747 | 8086 | | 2134 | 8163 | 998 | 390 | | | | |
| 166 | 908NBL | BC-PF3114-NBL | 11.5 | 747 | 8086 | NBL-603 | 2134 | 8163 | 998 | 390 | | | | |
| 171 | C-2 | CP-PF151 | 6.9 | 517 | 10166 | | | | 928 | 390 | | | | |
| 167 | 909 | BC-PF6843 | 12.2 | 670 | 6892 | | 2134 | 68471 | 250 | | | | | |
| 168 | 910 | BC-PF418 | 13.3 | 701 | 9026 | NBL-1310 | 2134 | 168630 | 250 | 390 | | | | |
| 169 | 911NBL4 | BC-PF9076(TA)-NBL4 | 11.2 | 607 | 9026 | NBL-404 | 2134 | LC-804 | 250 | 390 | | | | |
| 170 | 912NBL6 | BC-PF9076TG-NBL6 | 8.9 | 492 | 9026 | NBL-806 | 2134 | 9048 | 250 | 390 | | | | |
| 172 | 1001 | BC-DU211 | 9.8 | 541 | 40394NS | | 204339 | 40393T | 591 | 1380 | | | | |
| 173 | 1001NBL | BC-DU211-NBL | 9.8 | 541 | 40394NS | NBL-406 | 204339 | 40393T | 591 | 1380 | | | | |
| 174 | 1001M | BC-DU211-M | 9.8 | 541 | 40394NS | | 204339 | 40393T | 591 | 1380 | | NBL SPRING SET SCREW | | |
| 175 | 1001NS | BC-DU211NS | 10 | 551 | 40394NS | | 204339 | 40393T | 591 | 1380 | | | | |
| 176 | 1001NS-2 | BC-DU211NS-2 | 10.4 | 571 | TSP-408 | NBL-408 | 204339 | 40393T | 591 | 1380 | | SMS-606 | | |
| 177 | 1001NS-3 | BC-DU211NS-3 | 10.2 | 561 | TSP-408 | | 204339 | 40393T | 591 | 1380 | | | | |

| ID | ITEM NO | | 1 pcs | 50 pcs | TENSION SPRING | NBL SPRING | LATCH SPRING | LATCH COMPLETE | TENSION SPRING REGULATING SCREW | TENSION SPRING SCREW | LATCH STOP SCREW | EXTRA PART | | |
|-----|----------|---------------------|-------|--------|----------------|------------|--------------|----------------|---------------------------------|----------------------|------------------|----------------------|---------------------------|--|
| 178 | 1001NS-4 | BC-DU211NS-4 | 10.4 | 572 | 40394NS | NBL-406 | 204339 | 40393 | 591 | 1380 | | | | |
| 179 | 1002 | BC-DU216 | 9.7 | 536 | 40394NS | | 204339 | 40393T | 591 | 1380 | | | | |
| 180 | 1003 | BC-DU265 | 10.2 | 561 | 40394NS | | 204339 | 40393T | 591 | 1380 | | NBL SPRING SET SCREW | | |
| 181 | 1003NS | BC-DU265NS | 10.4 | 571 | 40394NS | | 204339 | 40393T | 591 | 1380 | | | | |
| 182 | 1003NS-2 | BC-DU265NS-2 | 10.2 | 561 | TSP-408 | NBL-408 | 204339 | 40393T | 591 | 1380 | | SMS-606 | | |
| 183 | 1006 | BC-DU265BIG | 13.5 | 725 | 211935 | | 204339 | 265779 | 591L | 1380L | | | | |
| 184 | 1006NS | BC-DU265BIG(NS)-NBL | 13.5 | 725 | TSP-1302 | NBL-1310 | LSP-6 | LC-1303 | 591L | 1380L | 592 | | | |
| 185 | 1008 | BC-DU556 | 12 | 772 | TSP-601 | | 210736 | LC-614 | SMS-608 | SMS-609 | | THREAD GUIDE EYELET | THREAD GUIDE EYELET SCREW | |
| 186 | 2001 | BC-UN614 | 9.7 | 536 | 40394NS | | 61216N | 40393T | 591 | 1380 | SMS-801 | | | |
| 187 | 2002 | BC-UN614E | 9.5 | 526 | 40394NS | | 61216N | 40393T | 591 | 1380 | | STL-407 | SMS-202 | |
| 188 | 2002NBL | BC-UN614E-NBL | 9.5 | 526 | 40394NS | NBL-402 | 61216N | 40393T | 591 | 1380 | | STL-407 | SMS-202 | |
| 189 | 2002M | BC-UN614E-M | 9.5 | 526 | 40394NS | | 61216N | 40393T | 591 | 1380 | | STL-407 | SMS-202 | |
| 190 | 2003 | BC-UN639(SS) | 9.5 | 526 | 40394NS | NBL-406 | 61216N | 40393T | 591 | 1380 | | | | |
| 191 | 2005 | BC-UN639B | 9.7 | 536 | 40394NS | | 61216N | 40393T | 591 | 1380 | | | | |
| 192 | 2005-1 | BC-UN639A | 9.7 | 536 | 40394NS | | 61216N | 40393T | 591 | 1380 | | | | |
| 193 | A-1 | ST-1 | 80 | 212 | | | | | | | | | | |
| 194 | 3001 | TQ-6 | | | | | | | | | | | | |
| 195 | 3002 | TQ-7 | | | | | | | | | | | | |
| 196 | 3003 | TQ-10 | | | | | | | | | | | | |
| 197 | 3004 | TE-5 | | | | | | | | | | | | |
| 198 | 1 | BO-103(1) | 4.5 | 480 | | | | | | | | | | |
| 199 | 2 | BO-103(2) | 4.5 | 480 | | | | | | | | | | |
| 200 | 3 | BO-103(3) | 4.5 | 480 | | | | | | | | | | |
| 201 | 5 | BO-103(Z) | 4.5 | 480 | | | | | | | | | | |
| 202 | 5-2 | BO-103(Z)-2 | 4.5 | 480 | | | | | | | | | | |
| 203 | 6 | BO-103(A) | 1.6 | 190 | | | | | | | | | | |
| 204 | 8 | BO-95(2) | 4.9 | 520 | | | | | | | | | | |
| 205 | 8-3 | BO-95-HSY | 4.9 | 520 | | | | | | | | | | |
| 206 | 8-4 | BO-95-HSN | 4.9 | 520 | | | | | | | | | | |
| 207 | 9 | BO-95NS | 4.6 | 490 | | | | | | | | | | |
| 208 | 9-1 | BO-95NS(1) | 4.6 | 490 | | | | | | | | | | |
| 209 | 10 | BO-95(A) | 1.6 | 190 | | | | | | | | | | |
| 210 | 10-1 | BO-95(A)-H | 1.6 | 190 | | | | | | | | | | |
| 211 | 13 | BO-400(2) | 3.8 | 410 | | | | | | | | | | |
| 212 | 13-4 | BO-400(4) | 3.8 | 410 | | | | | | | | | | |
| 213 | 14-3 | BO-400(3)N | 3.7 | 400 | | | | | | | | | | |
| 214 | 15 | BO-107(1) | 5.8 | 612 | | | | | | | | | | |
| 215 | 15-3 | BO-107(3) | 5.8 | 612 | | | | | | | | | | |
| 216 | 17 | BO-107(A) | 2.3 | 262 | | | | | | | | | | |
| 217 | 17-1 | BO-271(A) | 2.5 | 282 | | | | | | | | | | |
| 218 | 17-1-1 | BO-271(A)-B | | | | | | | | | | | | |
| 219 | 17-2 | BO-B814(A) | 2.5 | 282 | | | | | | | | | | |
| 220 | 17-3 | BO-LBH761 | 2.3 | 262 | | | | | | | | | | |
| 221 | 17-3-1 | BO-LBH761H | 2.3 | 262 | | | | | | | | | | |
| 222 | 17-4 | BO-LBH771 | 2.3 | 262 | | | | | | | | | | |

| ID | ITEM NO | | 1 pcs | 50 pcs | TENSION SPRING | NBL SPRING | LATCH SPRING | LATCH COMPLETE | TENSION SPRING REGULATING SCREW | TENSION SPRING SCREW | LATCH STOP SCREW | EXTRA PART | | |
|-----|---------|----------------|-------|--------|----------------|------------|--------------|----------------|---------------------------------|----------------------|------------------|------------|--|--|
| 223 | 17-4-1 | BO-LBH771-H | 2.4 | 270 | | | | | | | | | | |
| 224 | 17-5 | BO-107(A2) | 3.3 | 350 | | | | | | | | | | |
| 225 | 19 | BO-112(2) | 4.6 | 495 | | | | | | | | | | |
| 226 | 19-2 | BO-112(A) | 2.1 | 245 | | | | | | | | | | |
| 227 | 19-3 | BO-112(3) | 4.6 | 495 | | | | | | | | | | |
| 228 | 19-6 | BO-112(6) | 4.4 | 475 | | | | | | | | | | |
| 229 | 19-7 | BO-112(A)M | 2.3 | 263 | | | | | | | | | | |
| 230 | 19-8 | BO-112(A)J | 2.2 | 260 | | | | | | | | | | |
| 231 | 19-9 | BO-B842(A)OH | 2.3 | 263 | | | | | | | | | | |
| 232 | 19-10 | BO-B842(A2)-H | 2.3 | 263 | | | | | | | | | | |
| 233 | 19-11 | BO-LX2(A)-H | 2.4 | 270 | | | | | | | | | | |
| 234 | 19-12 | BO-LX2(A2)-H | 2.3 | 263 | | | | | | | | | | |
| 235 | 19-13 | BO-112(A)MT-H | 4 | 440 | | | | | | | | | | |
| 236 | 19-14 | BO-112(7) | 4.2 | 450 | | | | | | | | | | |
| 237 | 21-5 | BO-DBM(1)N | 6 | 635 | | | | | | | | | | |
| 238 | 21-6 | BO-DBM(2)N | 6 | 635 | | | | | | | | | | |
| 239 | 21-7 | BO-DBM(3)N | 7.5 | 785 | | | | | | | | | | |
| 240 | 21-8 | BO-DBM(4)N | 5.1 | 545 | | | | | | | | | | |
| 241 | 22 | BO-DBM(A) | 2.2 | 255 | | | | | | | | | | |
| 242 | 22-1 | BO-DBM(A)BR-H | 3.8 | 420 | | | | | | | | | | |
| 243 | 22-2 | BO-DBM(A)SN | 2.6 | 300 | | | | | | | | | | |
| 244 | 22-4 | BO-DBM(A)J | 3.8 | 420 | | | | | | | | | | |
| 245 | 22-5 | BO-DBM(A)J2-H | 2.6 | 300 | | | | | | | | | | |
| 246 | 23-2 | BO-DBL(1)N | 7.6 | 795 | | | | | | | | | | |
| 247 | 24 | BO-PF130 | 4.1 | 442 | | | | | | | | | | |
| 248 | 24-2 | BO-PF130(A) | 2.1 | 243 | | | | | | | | | | |
| 249 | 25 | BO-144 | 15.5 | | | | | | | | | | | |
| 250 | 26-2 | BO-1215MM(A) | 3.6 | 405 | | | | | | | | | | |
| 251 | 26-2-1 | BO-1215MM(A)-H | 3.5 | 380 | | | | | | | | | | |
| 252 | 26-3 | BO-1215MM-N | 8.5 | 885 | | | | | | | | | | |
| 253 | 26-4 | BO-1215MMN-SN | 7 | 750 | | | | | | | | | | |
| 254 | 26-5 | BO-B872(A) | 3.5 | 380 | | | | | | | | | | |
| 255 | 27 | BO-LKB(A) | 2.2 | 255 | | | | | | | | | | |
| 256 | 27-2 | BO-LKB(A)-2 | 2.1 | 245 | | | | | | | | | | |
| 257 | 27-3 | BO-LKJ(A) | 2.3 | 265 | | | | | | | | | | |
| 258 | 27-4 | BO-LKJ(A)-H | 2.2 | 255 | | | | | | | | | | |
| 259 | 28 | DB-MTB | 4.3 | 465 | | | | | | | | | | |
| 260 | 29 | BO-DB200 | 4.3 | 462 | | | | | | | | | | |
| 261 | 30 | BO-LK210 | 5.2 | 555 | | | | | | | | | | |
| 262 | 31-2 | BO-1215L(A) | 3.7 | 420 | | | | | | | | | | |
| 263 | 31-3 | BO-1215L-N | 8 | 850 | | | | | | | | | | |
| 264 | 31-4 | BO-1215L(A)J-H | | | | | | | | | | | | |
| 265 | 32 | BO-66 | 5 | 528 | | | | | | | | | | |
| 266 | 34 | BO-17 | 3.9 | 418 | | | | | | | | | | |
| 267 | 35 | BO-132 | 15.4 | | | | | | | | | | | |

| ID | ITEM NO | | 1 pcs | 50 pcs | TENSION SPRING | NBL SPRING | LATCH SPRING | LATCH COMPLETE | TENSION SPRING REGULATING SCREW | TENSION SPRING SCREW | LATCH STOP SCREW | EXTRA PART | | |
|-----|---------|---------------|-------|--------|----------------|------------|--------------|----------------|---------------------------------|----------------------|------------------|------------|--|--|
| 268 | 38 | BO-45 | 9.7 | | | | | | | | | | | |
| 269 | 39 | BO-29L | 4.8 | 508 | | | | | | | | | | |
| 270 | 40 | BO-1215MM(A)M | 3.3 | 381 | | | | | | | | | | |
| 271 | 41 | BO-PF541 | 8.3 | 870 | | | | | | | | | | |
| 272 | 44 | BO-HUSQ | 4.2 | 440 | | | | | | | | | | |
| 273 | 45-1 | BO-TSS124(A) | 3.7 | 420 | | | | | | | | | | |
| 274 | 45-2 | BO-TSS125(A) | 3.2 | 350 | | | | | | | | | | |
| 275 | 45-3 | BO-TSS126(A) | 3.5 | 380 | | | | | | | | | | |
| 276 | 45-4 | BO-TSS134(A) | 5.4 | 560 | | | | | | | | | | |
| 277 | 45-5 | BO-TSS196(A) | 4.5 | 485 | | | | | | | | | | |
| 278 | 47 | BO-B484(A)-H | 4.2 | 450 | | | | | | | | | | |
| 279 | 47-1 | BO-B484(A)-H | 9.8 | 1015 | | | | | | | | | | |
| 280 | 48 | BO-HZL880 | 5.6 | 535 | | | | | | | | | | |
| 281 | 1 | TM-1 | 110 | 6000 | | | | | | | | | | |
| 282 | 2 | TM-2 | 110 | 6000 | | | | | | | | | | |
| 283 | 3 | TM-3 | 110 | 6000 | | | | | | | | | | |
| 284 | 4 | TM-4 | 110 | 6000 | | | | | | | | | | |
| 285 | 5 | TM-5 | 110 | 6000 | | | | | | | | | | |
| 286 | 6 | TM-6 | 110 | 6000 | | | | | | | | | | |