


EXPLODED VIEW



PARTS LIST OF SR-5000

No.	PART No.	DESCRIPTION	No.	PART No.	DESCRIPTION
1	70011	CASE	17	70071	P.C.B SENSOR(220V)
2	70048	WATER PAIL CAP	18	70040	BASE PLATE
3	70054	WATER PAIL	19	70041	WHEEL
4	70035	POWER CORD(220V)	20	70033	CORD PROTECTOR
	70035	POWER CORD(120V)	21	30165	CAP NUT(5/16)
5	70006	STEAM HOSE	22	70078	HANGER
6	70081	HANDLE ASSY	23	70058	HANGER CONNECTING ROD 3
7	70082	STEAMER NOZZLE	24	70060	CONNECTING NIPPLE 2
8	70023	STEAMER HEATER	25	19817	SCREW(M6×10)
9	70022	THERMOSTAT	26	70057	HANGER CONNECTING ROD 2
10	70020	LAMP SET(220V)	27	70059	CONNECTING NIPPLE 1
	70086	LAMP SET(120V)	28	70056	HANGER CONNECTING ROD 1
11	70018	L/O SWITCH	29	70076	C-RING
12	70038	LEAD WIRE(A)	30	70055	MOVABLE HANDLE
	70039	LEAD WIRE(B)	31	70084	HOSE CONNECTING RING
13	70031	ELBOW NIPPLE(A)	32	70064	M6×10 BOLT
14	70028	NUT(M14)	33	70053	HANGER CONNECTING PIPE
15	70083	SILICONE HOSE	34	70010	FIXED NUT
16	70031	ELBOW NIPPLE(AH)	35	70077	SENSOR TIE ROD(HAR)
17	70070	P.C.B SENSOR(120V)	36	70080	STAINLESS RING
					P.C.B센서(220V)
					베이스 밑판
					바퀴
					코오디션 풋싱
					캡너트(5/16)
					헝거
					헝거연결봉 3
					연결니플 2
					비스(M6×10)
					헝거연결봉 2
					연결니플 1
					헝거연결봉 1
					C링
					이동핸들
					호스연결링
					M6×10 볼트
					헝거연결파이프
					고정너트
					센서지지봉
					스텐링