

THREADING CHART

- Use any type thread which is suitable for the fabric being sewn. This includes mercerized, 00, silk and synthetic threads.
- The thread is passed through rear thread guide (A) then slides between two tension discs (B) through (C) through front thread guide (D)...then down through needle clamp hole (E)...and entering from the underside of needle hole (F).
- 3. Leave thread about 2 to 3 inches past needle hole.

THREADING NEEDLE

- 1. To thread needle at point (F)

 a. Swing work plate out of way
 - b. Depress cylinder out of way with knee lifter
 - c. Hold thread between index
 - finger and thumb

 d. End of thread must be stub
 - d. End of thread must be stubent feather edge.



2