

Needle threading





- Move needle bar to highest point @ Lead thread
 - through thread retainer
- Down through thread eyelet and thread guard.
- (a) Into and around
- tension assembly Over thread
- O Under slack thread regulator and up through thread eyelet and thread guard
- 2 To take-up lever eyelet and down through thread eyelet and thread guard
- To needle bar bushing thread eyelet or thread
- O To needle bar thread guard To needle-thread from left to right @ Spool pin on arm

To thread supply